

ASSIGNMENT

From: _____ Date: 22/4/19

Estimated Cost: _____

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGM 578Z

at Workshop m/s Ethoz

of 22 fampines st -92

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SGM 578Z Yr Regn: 30/11 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: VOLVO XC90 c.c. 2521

Colour Grey A/C: Insured / Std / NI / NA

Sp. Reading 135817 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YVIC25957A1536071

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size: F: 235/60R18

R: _____ MAXXIS

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: 35

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

Front 5 mm Rear 5 mm

R/Bal. 5 mm L/Bal. 5 mm

D.O.A. 22/4/19 D.O.I. 22/4/19

Survey held at _____

CA / REV / REP. / 24 HRS up L7A27382

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Lf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Dep 12/4/19 and next 7618</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____ S + RS, SI

Photos _____

Others _____

TOTAL _____

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	6208K
Vehicle Details	
Vehicle No.:	SGM578Z
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Apr 2019
Vehicle Make:	VOLVO
Vehicle Model:	XC90 2.5T A/T ABS D/AB 4WD 5DR TC
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	B5254T4392344
Chassis No.:	YV1CZ5957A1536071
Maximum Power Output:	154.0 kW (206 bhp)
Open Market Value:	\$52,413.00
Original Registration Date:	30 Nov 2009
First Registration Date:	30 Nov 2009
Transfer Count:	2
Actual ARF Paid:	\$52,413.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2019
PARF Rebate Amount:	\$26,206.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$19,901.00
COE Rebate Amount:	\$1,176.00
Total Rebate Amount:	\$27,382.00

The information contained herein is correct as at 22 Apr 2019

OK

