ASS. REC. BY: REF:

Adrian   <u>ASSIGNMENT</u>

From: Date: Veh No: SKT2171R , Yr Regn: 2015, May.

Estimated Cost: Type: (M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

<u>OD / TP / WS / TP RES / OD RES / EVA / INV / MV</u>   Truck / Trailer or

To Inspect Vehicle No: Make: Volkswagen - Touran. c.c 1598

at Workshop m/s   Colour White .   A/C: Insured / Std / NI / NA

of   Sp.Reading 174369   T/Radio: Insured / Std / NI / NA

Insured: Eng/No:

Policy No.   C/No: WVGZ221TZFW039383 .

Claims No.   Gen. Cond. Good / Fair / Poor / Burnt

Sum Insured: Excess: Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)   Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: Modi : Nil / S/Rim / STD A/Rim or

                                           Tyre Size: F: 225/45R17.
(Policy Condition)   R: 225/45R17 .

Remark: The veh had commenced its   BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
        repair at the time of inspection. TOYO / YOKO or   Fulken.

| | N/S | O/S |

Bal. or Market Value: | Front | | Rear | |

IDAC Accident Rport: Consistent? : Yes or No | R/Bal. | 06 | mm | R/Bal. | 06 | mm |

GIA / PR Seen: Consistent? : Yes or No | L/Bal. | 06 | mm | L/Bal. | 06 | mm |

Est. Repairs: days   Res.: Yes or No   D.O.A.   D.O.I. 18/02/19 .

Lum Sum: %   3 Val.: Yes or No Survey held at   Hua Meng :

CA / REV / REP. / 24 HRS   Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
                                            Front o/s u/c.
                         Vehicle: IN / OUT

Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP AXA.
	MV : 65K
	PV : 55.4K
	Nett: 9.6K

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:		Survey Fee:	Date:
1)	2)	IN	OUT	Basic & Add.	
3)	4)			__ S + RS, __ SI	
5)	6)			Photos	
Preli. Report:				Others	
Final Report:				TOTAL	