

ASS. REC. BY:

REF:

CS/MSG19003018/AUvd302

Special Instruction:

Survivor:

ASSIGNMENT (Office)From (Person): Merimen Christina Dong

of

MSG

Date/Time:

18/2/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJB 7118U

Insured:

GBE 2967Yat Workshop m/s Joo Hak Kee Auto

Tel:

of 3007 Ubi Rd 1 #01-406Policy No: 28821845 MKC

Claim No:

585161

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/2/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

18/2

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction () Estimate
	<u>SJB 7118U - X</u>
	<u>GBE 2967Y - X.</u>
<u>18/2/19</u>	<u>Recd file from assignment Team</u>
<u>18/2/19</u>	<u>Informed Christina pending workshop est via merimen</u>
<u>18/3/19</u>	<u>Adrian confirmed LS \$1050 (Red 1561.60, 60%)</u>

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJB 7118u. Yr Regn: 2011 / May.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota ALTIS c.c. 1598Colour: Gold A/C: Insured / Std / Nil / NASp. Reading 126273 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MRO53REE10416336Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 18/02/19.Survey held at JHK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s.


The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP MSG14/3/19 Send preli revised via merimenMV: 281cPV: 19.4k.Nett: 8.6k

RECEIVED 14 MAR 2019



14/3/2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 14/3 - typist

2) _____

3) _____

4) _____

5) _____

6) _____

Prel. Report: _____

Final Report: _____

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

15010160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Feb 2019		18 Feb 2019 09:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS		[Created by insurer]																						
Insured:	YW ENGINEERING SERVICES PTE LTD, Co. Reg. No.: 200719927C																							
Main Claimant:	CHUA LYE CHYE, ID: S1388259B																							
Vehicle Reg. No.:	SJB7118U	Date of Loss:	14/02/2019 00:00 - :59 [92 Months and 18 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / 585161	Policy/Cover Note No.:	28821845MKC Coverage: 19/10/2018 - 18/10/2019																					
Vehicle Reg. No. (Insured):	GBE2967Y	Policy No. (Claimant):																						
		Excess:																						
Repairer:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406, 408701 Ubi - Tel: 67431913																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/02/2019]																							
Adj Asg. Remarks:	on WP. Liability unclear. Non Reporting. TP want to use Marcus Chua frm LKK as the SJE. Car will be in on Monday Morning.																							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail																						
There are no mail for this case.																								
<div> ALL ASSOCIATED TASKS </div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Adrian

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 14 Mar 2019

Preliminary Advice

Insured Vehicle No : GBE2967Y

TP Vehicle No : SJB7118U

Accident Date : 14/02/2019

Make : TOYOTA COROLLA ALTIS

Assignment Date : 18/02/2019

Date of Inspection : 18/02/2019

Est. Duration of Repair : 3.00

Inspection At : JOO HAK KEE AUTO PTE LTD (HQ)
BLK 3007 UBI ROAD 1, #01-406
SINGAPORE 408701

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,611.60	
Revised Amount (estimated)	:S\$	1,050.00	(LUMP SUM)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	1,050.00	

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***SJB7118U (585161)**

[GBE2967Y]

TP

CHUA LYE CHYE

Feb 14 2019 12:00AM

[YW ENGINEERING SERVICES PTE LTD]

Joo Hak Kee Auto Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **28/02/2019 13:21 PM.**

To MSIG_CWSF1

Subject TP SURVEY SJB 7118U

Dear Christina,

Please be informed that we have inspected the vehicle SJB 7118U on 18/2/2019

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY


There are no documents.

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan

TAMPINES RD → KPE (JUNCTION).

Describe Circumstances of the Accident

I WAS TRAVELLING TAMPINES ROAD TOWARD KPE (JUNCTION). SOMEWHERE BEFORE KPE JUNCTION. I WAS THE 2ND VEHICLE DUE TO THE TRAFFIC RED LIGHT. ONCE THE TRAFFIC LIGHT CHANGED TO GREEN, VEHICLE AHEAD OF ME SUDDENLY STOPPED AND I ALSO APPLIED BRAKE AND MANAGED TO STOPPED. OUT OF SUDEN VEHICLE (B) CAME FROM THE REAR AND COULD NOT STOPPED IN TIME. THUS COLLIDED ONTO REAR PORTION OF MY VEHICLE.

A - GW 9816 A

B - 91R 3166 Y.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	8259B

Vehicle Details

Vehicle No.:	SJB7118U
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Beige
Manufacturing Year:	2011
Engine No.:	1ZR091544
Chassis No.:	MR053REE104116536
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$15,510.00
Original Registration Date:	27 May 2011
First Registration Date:	27 May 2011
Transfer Count:	1
Actual ARF Paid:	\$15,510.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 May 2021
PARF Rebate Amount:	\$9,306.00

Intended COE Rebate Details

COE Expiry Date:	26 May 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$44,790.00
COE Rebate Amount:	\$10,198.00
Total Rebate Amount:	\$19,504.00

The information contained herein is correct as at 16 Feb 2019

OK


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8259B
Vehicle Details	
Vehicle No.:	SJB7118U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Beige
Manufacturing Year:	2011
Engine No.:	1ZR091544
Chassis No.:	MR053REE104116536
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$15,510.00
Original Registration Date:	27 May 2011
First Registration Date:	27 May 2011
Transfer Count:	1
Actual ARF Paid:	\$15,510.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 May 2021
PARF Rebate Amount:	\$9,306.00
Intended COE Rebate Details	
COE Expiry Date:	26 May 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$44,790.00
COE Rebate Amount:	\$10,137.00
Total Rebate Amount:	\$19,443.00

The information contained herein is correct as at 21 Feb 2019

OK




ANNOUNCING Carway

as sgCarMart Premium Dealer for the 2nd Consecutive Year



CARWAY


Your Satisfaction Is Our Success




Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Coe Renewal Toyota Estima 2.4A.





2.38%P.a Lowest Interest@GV
Cars Financing. Monthly From \$938.
GV Credit Pte Ltd StarAd



HIN LUNG AUTO
Ho Bee Group

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years
of car sale

Browse by Category  Save Search  Print Sort by Date Posted 20 results/page

4 vehicles | **Search** [Advanced Search](#) [Search](#) [View All](#)

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota altis	Any	Any	2011	Any	Any	Any	Available



Toyota Corolla Altis 1.6A | **\$27,000** | **\$9,760 /yr** | **27-Jan-2011** | **1,598 cc** | **180,000 km** | **Sedan** | **Available**

★ Posted: 05-Jan-2019 Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

DIRECT OWNER



Toyota Corolla Altis 1.6A | **\$29,888** | **\$9,920 /yr** | **16-May-2011** | **1,598 cc** | **80,454 km** | **Sedan** | **Available**

100% Quality Buy! Drive With Assurance From CaseTrust Accredited Dealer. Vehicle Well Maintain By Agent (Borneo Motors) With Servicing History. Purchase Comes With 6 Months Engine And Gearbox Protect...

Sincere Motoring

★ Posted: 21-Feb-2019 Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM AD



Toyota Corolla Altis 1.6A | **\$33,800** | **\$10,650 /yr** | **15-Aug-2011** | **1,598 cc** | **83,534 km** | **Sedan** | **Available**

Well Known For Powerful Yet Fuel Economical, Clean And Neat Interior With Beautiful Paintwork, No Repairs Needed, Well Maintained Unit, Low Mileage, Full Leather Interior, Extremely Good Condition! Vi...

★ Posted: 24-Dec-2018 Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

DIRECT OWNER



Toyota Corolla Altis 1.6A (OPC) | **\$30,800** | **\$8,570 /yr** | **23-Nov-2011** | **1,598 cc** | **68,095 km** | **Sedan** | **Available**

1 Owner Only! Low Mileage Done, Well Maintained, Excellent Condition! Bank Or In House Loan Available. Call For More Enquiries!

★ Posted: 19-Feb-2019 Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.  Save Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#) 20 results/page

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	15/02/2019 11:55
Date Of Accident	14/02/2019 11:35
Exact Location Of Accident	BLK 19 JOO SENG RD CARPARK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJB7118U
Insured/Policyholder	
Name Of Registered Owner	CHUA LYE CHYE
NRIC No	S1388259B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96313393
Alternative Phone No	OFFICE-96313393
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107212229
Cover Note Number	
Driver	
Name of Driver	CHUA LYE CHYE
NRIC No	S1388259B
Date Of Birth	09/09/1959
Occupation	OUTDOOR
Date Of Driving Pass	21/11/1979
Driving Experience	39 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96313393
Fax Number	
Contact Number	OFFICE-96313393
Email Address	NOEMAIL

Address	BLK 19 JOO SENG RD #02-116
Postcode	1336
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ALJUNIED NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 13 JOO SENG ROAD , POSTCODE: 360013 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2809999 - FAX NO: 62815960
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT AND SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE2967Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	



Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

But 19 800 Lang Road



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report 4 for sketch plan

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Police Report



**SINGAPORE
POLICE FORCE**



T/20190214/2134

Police Station Of Origin:
Aljunied NPP
13 Joo Seng Road #01-89 SINGAPORE
360013
Tel No: 1800-2809999

1 of 3

Report No. T/20190214/2134

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/02/2019 18:16	Vide Report No.:	Station Diary No.: 19
--	------------------	--------------------------

Informant's Particulars

Name of Informant: CHUA LYE CHYE			Address: APT BLK 19 JOO SENG ROAD #02-116 SINGAPORE 360019		
ID Type / ID No.: NRIC NO / S1388259B			Contact No.: Home/Office: Mobile: 96313393		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 59	Date of Birth: 09/09/1959	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: PROPERTY AGENT			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 14/02/2019 11:35	Type of Location: Car Park
Location: JOO SENG ROAD BLK 19 JOO SENG ROAD CARPARK, LOT NO:242				
Weather:		Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE2967Y	Lorry					0
SJB7118U	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	Beige	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJB7118U	NTUC Income Insurance Co-Operative Limited	5107212229	29/01/2019	26/05/2020

Police Report



**SINGAPORE
POLICE FORCE**



T/20190214/2134

2 of 3

Police Station Of Origin:
Aljunied NPP
13 Joo Seng Road #01-69 SINGAPORE
360013
Tel No: 1800-2809999

Report No. T/20190214/2134

CONTINUATION OF REPORT

Brief Details.

On 14/02/2019 at about 10am, I had parked my vehicle bearing registration number: SJB7118U at my block carpark lot number: 241. Everything was intact when I left. On the same day at about 11.35am, when I went to retrieve my vehicle, I noticed that there were damages at the rear area of my vehicle. I made a check and there was no vehicle parked beside my vehicle. As I had an on-board camera install in my vehicle, I went to my work shop to enquire on the procedure for such incident and I went to accessory shop to assist me in viewing the footage. From the footage it was revealed that a lorry bearing registration number: GBE2967Y (number given by the accessory shop personnel) that the lorry had reserve into the lot and hit my right rear side. There was a lot sound. Upon hearing the sound, the vehicle just drove off. No note was left on my vehicle.

The damaged to my vehicle: Rear tail-light broken & rear bumper dislodged & dented inwards.

Police Report



**SINGAPORE
POLICE FORCE**



T/20190214/2134

Police Station Of Origin:
Aljunied NPP
13 Joo Seng Road #01-69 SINGAPORE
360013
Tel No: 1800-2809999

3 of 3

Report No. T/20190214/2134

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: E / Sgt 2 MUHAMMAD AL-RAZIF S/O G SUPPAIYAH MD FAIZAL	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 14/02/2019 18:16
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt IRMAN BIN MOHAMAD SAID Contact No.: 65476145	Classification Of Case:

Authentication Stamp
NP168

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: CHUA LYE CHYE
 INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD
 POLICY NO: 5107212229
 REFERENCE: TP CLAIM
 DOA: 14/02/2019

TP MSIG
 Veron

REPAIR ESTIMATE

Est. No. : E19020008
 Date : 16/02/2019
 Vehicle Num. : SJ87118U
 Make/Model : TOYOTA, COROLLA
 Chassis/Eng# : MR053REE104116536
 Yr. of Manu : 2011

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	REAR BUMPER <i>Red</i>	1.00	492.10	492.10
2	REAR BUMPER SIDE RETAINER <i>m</i>	1.00	65.10	65.10
3	RH TAILLAMP <i>cancel</i>	1.00	285.10	285.10
4	RH REAR FENDER <i>Rpr</i>	1.00	806.10	806.10
5	RH REAR FENDER AIR VENT <i>new</i>	1.00	100.40	100.40

Amt S\$ 1,748.80
 Discount (25.00%) S\$ 437.20
 Subtotal S\$ 1,311.60

Section: LABOUR

6	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	1.00	660.00	660.00
7	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	1.00	580.00	580.00
8	TO DISMANTLE AND REFIT REVERSE SENSOR	1.00	60.00	60.00

Amt S\$ 1,300.00
 Discount (0.00%) S\$ 0.00
 Subtotal S\$ 1,300.00


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Surveyed by/Company :
 CC/Authorised by Repairer :
 Date/Time :
 Date :
 Licensed Automotive Surveyor's Sign :

total: 1331.72
 w/s: 1050
 03 Days.

Admin LG
 L/S 19/02/19
 03 Days



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 1,311.60
 LABOUR Subtotal S\$ 1,300.00
 Total S\$ 2,611.60

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Feb 2019		18 Feb 2019 09:27 Edit Adj Rpt	S\$1,050.00 Edit Estimates	S\$1,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: YW ENGINEERING SERVICES PTE LTD , Co. Reg. No.: 200719927C									
Main Claimant: CHUA LYE CHYE , ID: S1388259B									
Vehicle Reg. No.: SJB7118U		Date of Loss: 14/02/2019 00:00 - :59 [92 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 585161		Policy/Cover Note No.: 28821845MKC Coverage: 19/10/2018 - 18/10/2019							
Vehicle Reg. No. (Insured): GBE2967Y		Policy No. (Claimant):							
		Excess:							
Repairer: Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406, 408701 Ubi - Tel: 67431913									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/03/2019]									
Adj Asg. Remarks: on WP. Liability unclear. Non Reporting. TP want to use Marcus Chua frm LKK as the SJE. Car will be in on Monday Morning.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJB7118U (585161)**
[GBE2967Y]
TP
CHUA LYE CHYE
Feb 14 2019 12:00AM
[YW ENGINEERING SERVICES PTE LTD]
Joo Hak Kee Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/19 11:03	Adjuster Immediate Advice	Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/19 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
2	13/03/19 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
3	13/03/19 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
4	13/03/19 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
5	13/03/19 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
6	13/03/19 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
7	13/03/19 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
8	13/03/19 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
9	13/03/19 14:28	General View	Load JPG	<input checked="" type="checkbox"/>
10	13/03/19 14:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
11	13/03/19 14:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
12	13/03/19 14:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
13	13/03/19 14:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
14	13/03/19 14:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/02/19 17:46	Email - PRI	Load PDF	
2	15/02/19 17:46	SJB7118U GIA Rpt	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19003018/AUVD3E2

Date: 15/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28821845MKC

Claimant Vehicle No: SJB7118U

Insured Vehicle No: GBE2967Y

Date of Loss: 14/02/2019

Nature of Claim: TP

Claim No: 585161

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJB7118U

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 1ZRX091544

Reg. Date: 27/05/2011 (Man. Year: 2011)

Chassis No: MR053REE104116536

Colour: Gold

Odometer: 126273 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,311.60	631.72	679.88	51.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	700.00	600.00	46.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,611.60	1,331.72	1,279.88	49.01
Approved Total (Overridden) (S\$)		1,050.00		
(S\$)	2,611.60	1,050.00	1,561.60	59.79
+ GST 7.00/7.00% (S\$)	182.81	73.50	109.31	59.79
Nett Amount (S\$)	2,794.41	1,123.50	1,670.91	59.79

INSPECTION

Date of Assignment: 18/02/2019

Date Inspected: 18/02/2019 Inspected At:

Joo Hak Kee Auto Pte Ltd (HQ)
Blk 3007 Ubi Road 1, #01-406
Singapore 408701

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2019)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJB7118U)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	492.10 FL	*492.10 FL
2	1		*REAR BUMPER SIDE RETAINER	Necessary	65.10 FL	*65.10 FL
3	1		*RH TAILLAMP	Cracked	285.10 FL	*285.10 FL
4	1		*RH REAR FENDER	Repair	806.10 FL	*- FL
5	1		*RH REAR FENDER AIR VENT	Not Necessary	100.40 FL	*- FL
					Sub Total (S\$)	1,748.80
					- List Item Discount on L Items 25.00/25.00% (S\$)	437.20
					Total Parts (S\$)	1,311.60
						842.30
						210.58
						631.72

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	New	660.00	250.00
2	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	New	580.00	400.00
3	TO DISMANTLE AND REFIT REVERSE SENSOR	New	60.00	50.00
Gross Labour Cost (S\$)			1,300.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >