

Hue De

REF:

INC

ASSIGNMENT

Form Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. PC 6401 G.

at Workshop no. SC Auto

at 81 Senoko Rd.

Insured

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

10-12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No. PC 6401 G

Regn 4 Oct 2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Golden Dragon

Colour: Silver

Sp. Reading: 71549

Eng/Ho:

C/No: LL3BDAD E2 HA 703574

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/75 R17.5

R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 6/2/19

D.O.A. 18/2/19

Survey held at

SC Auto

1213pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/3/19 Confirmed L/S \$4900/- with 3days of repair.
(Ref: 3644-32, 4210)

RECEIVED 27 MAR 2019

Date/Time, File Pass to?



Preli. Report

21/3 Typist



Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.L. (\$)

TP 4900

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

Transportation

1) S + R S

2) Photos

3) Others

TOTAL

290

290