

ASS. REC. BY:

REF:

CS/FCL19003047/Eq0301

Special Instruction:

Survivor:

aws

Steve

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCS

Date/Time:

15/2/19 @ 5:24pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

FBG 7492G

Insured:

SH 69975

at Workshop m/s

Karz Work

Tel:

68442475

of

53 ubi Ave 1 #02-24

Policy No:

Claim No:

D19000875MFS#

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/02/2019

CA / REV / REP. / REV 24 HRS

wup

H.O.D. Endorsement:

Date/Time:

5:47pm @ 15/2/19

Person Contacted:

Jumun

Vehicle IN/OUT

OUT

Date/Time

Action/Instruction

(✓)

Estimate

FBG 7492G-X

SH 69975-MSI-INC/80078UG/K1/bn2

DoA: 26/4/18

19/2/19 @ 4:27pm revised to Joanne Yong by email.

20/3/19 @ 2:36pm checked with Darren, they still awaiting few parts available.

04/10/19 @ 12:01pm Steve finalised LS \$3950, 3 days.

(Red \$13857.30, 78%)

Steve

REF

POLICY NO.

FBG 7492 G

9/11/12

Est. No. Date  
 Estimated Cost  
 ODI / TP / WS / TP RES / OD RES / EVA / INV / MV

Inspected Vehicle No.

At Work / Repairs

Est.

Insured

Policy No.

Claims No.

Sum Insured

Excess

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. repairs

3

days

Res.: Yes or No

Lump sum

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date Person Contacted

Veh No.

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Kawasaki 2R1000 E

CC

1043

Colour

Black

A/C: Insured / Std / NI / NA

Sp Reading

78407

T/Radio: Insured / Std / NI / NA

Eng/No

C/No

JKAZRT00DEA 035 756

Gen Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

170/50R18

120/70ZR17

R:

170/50R18

190/55ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

11/2/19

D.O.A.

18/2/19

Survey held at

Karlz works

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

Front, RH, rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

MV-9009

PV-819

NV-8181

RECEIVED 22 NOV 2019

Date/Time File Pass to:



: Preli. Report

B 22/11/12



: Final Report

Date/Time File Return to:

Days Of Repair:

3

Resurvey No. of Trip:

1

7x15 = 105

Survey Fee:

105+170

Transportation

50

Fuel

50

Tolls

121

Other

Total

496

Add Fee:



Site Insp. (\$) :



Interview (\$) :



Team Day (\$) :



Weekend (\$) :

Report Format

TP

Lump Sum / U/C

3950

**MOTOR SURVEY ASSIGNMENT**

Date	05-02-2019	Our Ref No. D19000875MFSH
Accident Date	01-02-2019	Claim Type. Third Party
Insured Vehicle	SH6997S	Third Party Vehicle. FBG7492G
Survey Location	53 UBI AVENUE 1 #02-24 PAYA UBI INDUSTRIAL PARK	
Contact Person.	LETITIA TAN	
Contact No.	68442475/ 0	Fax No. 68442474
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	KARZ WORK SOLUTIONS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Steve Chen (LKK Auto)

---

**From:** karzworks <karzworks.sg@gmail.com>  
**Sent:** Friday, October 04, 2019 12:01 PM  
**To:** Steve Chen (LKK Auto); karzworkssg@gmail.com  
**Cc:** karzworks  
**Subject:** RE: FBG7492G Finalize

Dear Steve,

We confirm COR @\$3950 and DOR @ 3 days.

Regards,

Shu Shan

KARZ WORKS PTE LTD

53 Ubi Avenue 1

#01-23 Paya Ubi Industrial Park

Singapore 408934

Tel: 6844 5938

Fax: 6844 2474

---

**From:** Steve Chen (LKK Auto)  
**Sent:** Tuesday, 6 August 2019 8:46 AM  
**To:** karzworkssg@gmail.com  
**Subject:** FBG7492G Finalize

Dear Sir,

Kindly follow up, any status.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Steve Chen (LKK Auto)  
**Sent:** Monday, February 25, 2019 4:17 PM  
**To:** 'karzworkssg@gmail.com'  
**Cc:** Shiau Chan (LKKAuto)  
**Subject:** FBG7492G Finalize

Hi Sir,

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 19 February 2019 4:27 PM  
**To:** 'CWS Motor Claims'; assignments  
**Cc:** 'Joanne Yong Lai fong'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19000875MFSH/1  
**Attachments:** CSFC119003047Eqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of FBG 7492G.

Best Regards,

**Shiau Chan (Ms) | Case Handler**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 19 February 2019 12:37 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Joanne Yong Lai fong' <[JoanneYong@msfirstcapital.com.sg](mailto:JoanneYong@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19000875MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

**G.Nivitha | Admin**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 15 February 2019 5:24 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Joanne Yong Lai fong <[JoanneYong@msfirstcapital.com.sg](mailto:JoanneYong@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19000875MFSH/1



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000875MFSH  
Our Ref: CS/FCI19003047/Eqd3

Date: 19 February 2019

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. FBG 7492G**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/02/2019 at the premises of M/s KARZ WORKS, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 17,807.30</u>
Revised Estimate Amount	: <u>S\$ 8,126.50</u>
"Check" Items Amount	: <u>S\$ 4,455.90</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

**Description of Damage:**

The vehicle sustained damages  
at the front & rear portion and o/s body.



Yours faithfully

Steve  
Automotive Assessor

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4710E
<b>Vehicle Details</b>	
Vehicle No.:	FBG7492G
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Feb 2019
Vehicle Make:	KAWASAKI
Vehicle Model:	ZR1000E
Primary Colour:	Orange
Manufacturing Year:	2012
Engine No.:	ZRT00DE045519
Chassis No.:	JKAZRT00DEA035756
Maximum Power Output:	-
Open Market Value:	\$13,063.00
Original Registration Date:	09 Nov 2012
First Registration Date:	09 Nov 2012
Transfer Count:	5
Actual ARF Paid:	\$1,960.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	08 Nov 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,959.00
COE Rebate Amount:	\$819.00
<b>Total Rebate Amount:</b>	<b>\$819.00</b>

The information contained herein is correct as at 18 Feb 2019

OK


## Beauty Premium Mall

Love Premium Beauty Products? Enjoy up to 50% Savings and Express S! Qoo10 Singapore

Home (/) > Motorbikes (/categories/motorbikes-108) > Motorbikes for Sale (/categories/motorbikes-108/motorbikes-for-sale-1592)  
> Class 2 (/categories/motorbikes-108/motorbikes-for-sale-1592/class-2-1593)



Share This Listing



([https://www.facebook.com/sharer/sharer.php?](https://www.facebook.com/sharer/sharer.php?u=https://sg.carousell.com/p/kawasaki-z1000-black-edition-2012-235933193/) ([http](https://sg.carousell.com/p/kawasaki-z1000-black-edition-2012-235933193/)  
[u=https://sg.carousell.com/p/kawasaki-z1000-](https://sg.carousell.com/p/kawasaki-z1000-black-edition-2012-235933193/) [url=](https://sg.carousell.com/p/kawasaki-z1000-black-edition-2012-235933193/)  
[black-edition-2012-235933193/](https://sg.carousell.com/p/kawasaki-z1000-black-edition-2012-235933193/)) [z100](https://sg.carousell.com/p/kawasaki-z1000-black-edition-2012-235933193/)

## Public Comments

Be the first to write a public comment. Ask a question or @mention a friend to check this out!

Post a New Comment

## Kawasaki Z1000 Black Edition 2012

♥ 28

Chat

Make Offer

🕒 1 month ago by fartlee (/fartlee/)

💰 S\$9,876

♥ 28 Likes

📦 Used

📁 In Class 2 (/categories/class-2-1593)

🕒 Letting go my z1000 black edition 2012  
COE ends July 2022

read more

Make

Kawasaki

Type

Road Bike



## Insurance

Insure this vehicle with AXA.  
Premiums start from S\$226.91

BUY AXA  
INSURANCE  
NOW

## Getting This

📍 Meet-up

Khatib Vale

(<https://www.google.com/maps/pla>)

Pm to discuss timing

## Meet The Seller



fartlee (/fartlee/)

Joined 4 years ago

Verified

Reviews

5.0 ★★★★★ (2)



mohammad\_fadir

5.0★

(/mohammad\_fadir) Great seller to deal with! Pleasant transaction! S...read more

🕒 11 months ago


## YOU MAY ALSO LIKE



Home (/) > Motorbikes (/categories/motorbikes-108) > Motorbikes for Sale (/categories/motorbikes-108/motorbikes-for-sale-1592)  
> Class 2 (/categories/motorbikes-108/motorbikes-for-sale-1592/class-2-1593)



Share This Listing



(https://www.facebook.com/sharer/sharer.php? (http  
u=https://sg.carousell.com/p/kawasaki-z1000- url=  
241312733/) z100

#### Public Comments

Be the first to write a public comment. Ask a question or @mention a friend to check this out!

Post a New Comment

### Kawasaki Z1000

♥ 36 Chat Make Offer

🕒 2 weeks ago by ric\_maxonline (/ric\_maxonline)

💰 S\$8,300

👍 36 Likes

🏷️ Used

📍 In Class 2 (/categories/class-2-1593)

🔥 URGENT SALE!  
Selling Cheap!

PM me if interested.

Bike is well maintain by fussy and OCD owner.

Pristine condition (View to believe)

COE expiry - 21 Nov 2020 (Best to renew)

Regularly serviced and very well taken care.

Comes with laser legal exhaust and many accessories (Too many to list).

Reason for selling - Driving most of the time.

PM me for viewing if the price is right or slight negotiable for a realistic price.

Bike is fully paid.

Low ballers will not be entertain.

#Kawasaki, #Yamaha, #Honda, #Suzuki, #Aprilia, #BMW, #mt10, #mt09, #mt07, #vfr, #fz1s, #fz, #st, #fjr, #sp, #cb, #cbr, #gsx, #gsr, #r1, #r6, #tmax, #rsv4 #super 4 #class2, #motorcycle, #motorbike

#### Make

Kawasaki

#### Type

Road Bike

#### Insurance

Insure this vehicle with AXA.  
Premiums start from S\$226.91

BUY AXA  
INSURANCE  
NOW

#### Getting This



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/02/2019 16:23
Date Of Accident	01/02/2019 08:30
Exact Location Of Accident	JALAN NOVENA BARAT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBG7492G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MATHIVANAN S/O ANDEE
NRIC No	S1374710E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93876247
Alternative Phone No	OTHERS-93876247

### Vehicle Particulars

Manufacturer	KAWASAKI
Model	ZR1000E
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	NAGAMUTHU S/O NAGAMUTHU RAJU
NRIC No	S7903139I
Date Of Birth	12/02/1979
Occupation	INDOOR
Date Of Driving Pass	02/09/2013
Driving Experience	5 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93396063
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	315A ANG MO KIO STREET 31 #02-339 SPORE 562315
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - U-TURN
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : DHURGASHREE D/O MOKHAN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH6997S
Vehicle Make/Model/Colour	HYUNDAI I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF INJURED PERSON 1**

Name	NAGAMUTHU S/O NAGAMUTHU RAJU
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBG7492G
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

**DETAILS OF INJURED PERSON 2**

Name	DHURGASHREE D/O MOKHAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBG7492G
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

## Sketch Plan

1. Please report accurately the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as accurate and complete as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind the policy or liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Part of the report will be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Research Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: SEBUN  
NRIC/FIN No.: S2040177

## Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Jalan Novena Barat, while I was travelling straight, Vehicle B is making a u-turn and He did not make sure the road is clear before turning and collided onto my vehicle.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: *S. Kumar*  
NRIC/FIN No.: *S8280377A*

KARZ WORKS PTE LTD

53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK

SINGAPORE 408934

(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

First Capital Insurance Ltd

6 Raffles Quay

Singapore 048580

## 3RD PARTY CLAIM ESTIMATION

Vehicle number FBG7492G  
 Make / Model KAWASAKI / ZR1000E  
 Chassis number : JKAZRT00DEA035756  
 Accident date 01 February 2019  
 Reference km1902-02

## Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		Unit Price - SGD \$
1	FRONT FENDER / CUT	550.00 320 ✓
1	FRONT LH FORK ASSY ? X NAI	990.00
1	FRONT RH FORK ASSY ? X NN	990.00
1 SET	STEERING HEADCROWM ? X NN	450.00
1 SET	STEERING STEM UNDERBRACKET ? X NN	630.00
1 SET	STEERING STEM BEARING ? X NN	520.00
1	FRONT RH SIGNAL LAMP / CUT	155.00 ✓
1	BALANCER RH / CUT	240.00 120 ✓
1	HANDLE BAR ? X NAI	900.00
1	HEADLAMP INNER GUIDE ? / BR	150.00 ✓
1	HEAD FAIRING ASSEMBLY / CUT	1050.00 600 ✓
1	HEADLAMP BRACKET ? X NN	321.00
1	HEADLAMP SIDE GARNISH / CUT	210.00 ✓
1	RH SIDE FAIRING / CUT	650.00 ✓
1	RH SIDE FAIRING INNER GUIDE (Black) / CUT	110.00 ✓
1	LOWER FAIRING X NN	490.00
1	RH FOOTREST / CUT	310.00 95 ✓
1	RH FOOTREST HOLDER X NAI	192.00
1	REAR TAILLAMP X NAI	730.00
1	REAR TAILLAMP GARNISH / BR	300.00 ✓
1	EXHAUST ASSY X NAI	1290.00
1	REAR SWING ARM X NAI	1559.00
1	FRONT FORK GARNISH RH / CUT	310.00 ✓
Less 10 %		13097.00
Subtotal		1309.70
Balance C/F		11787.30
Balance C/F		11787.30
PARTS REPLACEMENT - SPECIAL NETT ITEMS		Unit Price - SGD \$
Balance B/F		11787.30
1 SET	BRAKE LEVER / CUT	900.00 100 ✓
1	REAR EXHAUST UPPER CARBON FIBER HOUSING / CUT	1200.00 380 ✓
1	REAR EXHAUST LOWER CARBON FIBER HOUSING / CUT	900.00 350 ✓
1	FRONT TYRE 70% - TN	250.00 175 ✓
1	ENGINE COVER HOUSING RH / CUT	550.00 350 ✓
1 SET	SIDE MIRROR RH / LH X CUT	410.00 160 ✓
1 SET	HAND GUARD X NN	310.00
Subtotal		4520.00
Balance C/F		16307.30
LABOUR AND MISCELLANEOUS CHARGES		Unit Price - SGD \$
Balance B/F		16307.30
TO KNOCK, STRAIGHTEN CHASSIS, BODY BALANCING AND REPLACE DAMAGE PARTS		500.00 300 ✓
TO REMOVE/REFIT, REPLACE FRONT FORK TUDES		450.00 200 ✓
SPRAY PAINTING		550.00 200 ✓
Subtotal		1500.00
Grand total		17807.30

LKR

the Re.

S/No

• To

• Part

• The

• No

• Sup

is sub

Acknow

Signature

Date:






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003047/Eqd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-11-2019		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 6997S	Veh. Inspected	FBG 7492G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000875MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	13/02/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KAWASAKI ZR1000E	c.c	1043	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	JKAZRT00DEA035756	Colour	BLACK	
Odometer	78407	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	120/70Z R17	PIRELLI	7 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	190/55Z R17	PIRELLI	7 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	01/02/2019	Inspection Date	18/02/2019	
Survey held at	KARZ WORK SOLUTIONS 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 7492G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FENDER	CUT	550.00	320.00
1	FRONT LH FORK ASSY	NOT NECESSARY	990.00	-
1	FRONT RH FORK ASSY	NOT NECESSARY	990.00	-
1	SET STEERING HEADCROWN	NOT NECESSARY	450.00	-
1	SET STEERING STEM UNDER BRACKET	NOT NECESSARY	630.00	-
1	SET STEERING STEM BEARING	NOT NECESSARY	520.00	-
1	FRONT RH SIGNAL LAMP	CUT	155.00	155.00
1	BALANCER	CUT	240.00	120.00
1	HANDLE BAR	NOT NECESSARY	900.00	-
1	HEADLAMP INNER GUIDE	BROKEN	150.00	150.00
1	HEAD FAIRING ASSEMBLY	CUT	1,050.00	600.00
1	HEADLAMP BRACKET	NOT NECESSARY	321.00	-
1	HEADLAMP SIDE GARNISH	CUT	210.00	210.00
1	RH SIDE FAIRING	CUT	650.00	650.00
1	RH SIDE FAIRING INNER GUIDE	CUT	110.00	110.00
1	LOWER FAIRING	NOT NECESSARY	490.00	-
1	RH FOOTREST	CUT	310.00	95.00
1	RH FOOTREST HOLDER	NOT NECESSARY	192.00	-
1	REAR TAILLAMP	NOT NECESSARY	730.00	-
1	REAR TAILLAMP GARNISH	BROKEN	300.00	300.00
1	EXHAUST ASSY	NOT NECESSARY	1,290.00	-
1	REAR SWING ARM	NOT NECESSARY	1,559.00	-
1	FRONT FORK GARNISH	CUT	310.00	310.00
	LESS 10% DISCOUNT		-1,309.70	-302.00
			11,787.30	2,718.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET BRAKE LEVER (SN)	CUT	900.00	100.00
1	REAR EXHAUST UPPER CARBON FIBER HOUSING (SN)	CUT	1,200.00	380.00
1	REAR EXHAUST LOWER CARBON FIBER HOUSING (SN)	CUT	900.00	350.00
1	FRONT TYRE (70%)(SN)	TORN	250.00	175.00

Report Ref No. CS/FCI19003047/Eqd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ENGINE COVER HOUSING (SN)	CUT	550.00	350.00
1	SET SIDE MIRROR (SN)	CUT	410.00	160.00
1	SET HAND GUARD (SN)	NOT NECESSARY	310.00	-
			4,520.00	1,515.00
	<b>LABOUR</b>			
	TO KNOCK,STRAIGHTEN,CHASSIS,BODY BALANCING AND REPLACE DAMAGE PARTS.		500.00	300.00
	TO REMOVE/REFIT,REPLACE FRONT FORK TUDES.		450.00	200.00
	SPRAY PAINTING.		550.00	200.00
			1,500.00	700.00
<b>GRAND TOTAL</b>			<b>17,807.30</b>	<b>4,933.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,950.00</b>

Report Ref No. CS/FCI19003047/Eqd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.