

2103/1981

ASS. REC. BY:

REF:

CS/MC619003049/Gpd352

Special Instruction:

Surveyor

ASSIGNMENT (Office)

Date/Time: 15/2/2019

From (Person): Jasmine Lok

of MC16

Bill to:

Estimated Cost:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBA 816 J

Insured: SKV 7394X

Tel: 6338 8778

at Workshop m/s Comfort Delgro Engineering

of 45 Pandan Rd.

Policy No: A80453734 QMX

Claim No: 584032

Sum Insured:

Excess:

D.O.A. 30/1/2019

Make of Veh:  
(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Vehicle IN/OUT

Date/Time:

Person Contacted:

Date/Time Action/Instruction ( ) Estimate

GBA 816 J - X

SKV 7394X - X

14/2/19 @ 5:10 PM moved to Jasmine Lok via messenger.



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                             | Est Submitted                               | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'ed | Status                                               |
|------|------------------------------------------------------|---------------------------------------------|------------------------------------------------|---------|---------------|-------------|------------------------------------------------------|
| Main | 13 Feb 2019<br>17:35<br><a href="#">Sendback Est</a> | 13 Feb 2019<br>17:47<br><b>S\$15,347.32</b> | 15 Feb 2019<br>15:57<br><a href="#">Assign</a> |         |               |             | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

|                             |                                                                                                                                  |                        |                                                                               |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------|------------------------|-------------------------------------------------------------------------------|
| Insured:                    | <b>NG CHEE BOON</b> , ID: S8421443D                                                                                              |                        |                                                                               |
| Main Claimant:              | <b>SITI PATIMAH CATERING</b> , Co. Reg. No.: 53354855A                                                                           |                        |                                                                               |
| Vehicle Reg. No.:           | <b>GBA816J</b>                                                                                                                   | Date of Loss:          | 30/01/2019 16:00 - :59<br>[143 Months and 23 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | <b>TP / 584032</b>                                                                                                               | Policy/Cover Note No.: | A80453734QMX (Comprehensive)<br>Coverage: 24/02/2018 - 23/02/2019             |
| Vehicle Reg. No. (Insured): | <b>SKV7394X</b>                                                                                                                  | Policy No. (Claimant): |                                                                               |
|                             |                                                                                                                                  | Excess:                | S\$600.00                                                                     |
| Repairer:                   | <b>ComfortDelGro Engineering Pte Ltd (Pandan)</b> 45 Pandan Road, 609286 Eunos - Tel: 6338 8778                                  |                        |                                                                               |
| Handling Insurer:           | <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwei</b> - 6594 2550] |                        |                                                                               |
| Adjuster:                   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Imm.Advice due 16/02/2019]                                        |                        |                                                                               |
| Driver/Custodian (Insured): | NG CHEE BOON (), NRIC: S8421443D                                                                                                 |                        |                                                                               |
| Adj Asg. Remarks:           | Car in. on WP. Please contact us ASAP if you cannot attend this assignment. TP survey. Liab : clear                              |                        |                                                                               |

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 19 Feb 2019

**Preliminary Advice**

|                    |                                                                                    |                         |              |
|--------------------|------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SKV7394X                                                                         | Accident Date           | : 30/01/2019 |
| TP Vehicle No      | : GBA816J                                                                          | Assignment Date         | : 15/02/2019 |
| Make               | : FIAT DOBLO                                                                       | Est. Duration of Repair | : 5.00       |
| Date of Inspection | : 18/02/2019                                                                       |                         |              |
| Inspection At      | : COMFORTDELGRO ENGINEERING PTE LTD (PANDAN)<br>45 PANDAN ROAD<br>SINGAPORE 609286 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 15,347.32 |
| Revised Amount              | :S\$ | 5,739.32  |
| Check Items (Estimated)     | :S\$ | 3,099.00  |
| Total                       | :S\$ | 8,838.32  |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |  |
|--------------------|------|--|
| New for Old Value  | :S\$ |  |
| Pre-Accident Value | :S\$ |  |
| COE / PARF Rebate  | :S\$ |  |
| Salvage Value      | :S\$ |  |
| Margin for Repair  | :S\$ |  |

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 4855A

### Vehicle Details

Vehicle No.: GBA816J

Vehicle to be Exported: No

Intended Deregistration Date: 19 Feb 2019

Vehicle Make: FIAT

Vehicle Model: DOBLO CARGO 1.9MJTD

Primary Colour: Red

Manufacturing Year: 2006

Engine No.: 223B10005273931

Chassis No.: ZFA22300005479118

Maximum Power Output: -

Open Market Value: \$19,468.00

Original Registration Date: 07 Feb 2007

First Registration Date: 07 Feb 2007

Transfer Count: 2

Actual ARF Paid: \$0.00

### Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 06 Feb 2022

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$24,252.00

COE Rebate Amount: \$14,621.00

**Total Rebate Amount: \$14,621.00**

### Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 19 Feb 2019

OK

## ▶ Doblo Used Vehicle List (7 vehicles)

| Car Model                                                                                                                                                                                                                                                                               | Price           | Depreciation       | Reg Date           | Eng Cap         | Mileage           | Company                            | Availabi       |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|--------------------|--------------------|-----------------|-------------------|------------------------------------|----------------|
| <b>Fiat Doblo Cargo Maxi 1.9M (COE till 11/2021)</b> (Diesel)                                                                                                                                                                                                                           | <b>\$16,800</b> | <b>\$6,110 /yr</b> | <b>20-Nov-2006</b> | <b>1,910 cc</b> | <b>-</b>          | <b>SG Motor Link Pte Ltd</b>       | <b>Availal</b> |
| Super High Paper Value, Engine And Gear Smooth, Suitable For New Business, Call Now, Cheapest.<br>Office No. - 62508527<br>Jay Lee - 88693466   Ben Pang - 91122958   Cs - 86682223                                                                                                     |                 |                    |                    |                 |                   |                                    |                |
| <b>Fiat Doblo 1.3JTD (COE till 01/2022)</b> (Diesel)                                                                                                                                                                                                                                    | <b>\$16,700</b> | <b>\$5,670 /yr</b> | <b>30-Jan-2007</b> | <b>1,248 cc</b> | <b>-</b>          | <b>A&amp;L Automobile Pte Ltd</b>  | <b>Availal</b> |
| 💡 TABLE VALUE \$14,574<br>Office No. - 63627228<br>Alan - 90214919   Lynn Chia - 97779689   Chew - 90996676                                                                                                                                                                             |                 |                    |                    |                 |                   |                                    |                |
| <b>Fiat Doblo 1.9JTD (COE till 09/2023)</b> (Diesel)                                                                                                                                                                                                                                    | <b>\$16,800</b> | <b>\$3,640 /yr</b> | <b>28-Oct-2008</b> | <b>1,910 cc</b> | <b>-</b>          | <b>GF Motor Trading Enterprise</b> | <b>Availal</b> |
| -                                                                                                                                                                                                                                                                                       |                 |                    |                    |                 |                   |                                    |                |
| <b>Fiat Doblo 1.4M (New 5-yr COE)</b> (Petrol)                                                                                                                                                                                                                                          | <b>\$15,800</b> | <b>\$3,160 /yr</b> | <b>25-Nov-2008</b> | <b>1,368 cc</b> | <b>-</b>          | <b>Pioneer Auto</b>                | <b>Availal</b> |
| New 5 Years COE Selling At \$15,800, All In Original Condition, Well Kept Excellent Beauty, Budget Van, Suitable For Long Term Usage Or Renewal Upon COE. Confirm Cheaper Than Renting A Van, Well Mainta...<br>Office No. - 66849979<br>Jensen Chua - 97887307   Thomas Tan - 93839533 |                 |                    |                    |                 |                   |                                    |                |
| <b>Fiat Doblo 1.4M (COE till 12/2023)</b> (Petrol)                                                                                                                                                                                                                                      | <b>\$17,800</b> | <b>\$3,700 /yr</b> | <b>12-Dec-2008</b> | <b>1,368 cc</b> | <b>-</b>          | <b>Valley Trading</b>              | <b>Availal</b> |
| 2 Owner, Fiat Doblo Cargo Van 1.4 Petrol Engine. Very Economic And Low Depreciation. Original Condition. New 5 Years COE Just Renew.<br>Office No. - 63445088<br>Thomas - 96302490   Richard Teo - 90251988   Patrick Teo - 96681822                                                    |                 |                    |                    |                 |                   |                                    |                |
| <b>Fiat Doblo 1.3JTD (New 5-yr COE)</b> (Diesel)                                                                                                                                                                                                                                        | <b>\$19,800</b> | <b>\$3,960 /yr</b> | <b>31-Dec-2008</b> | <b>1,248 cc</b> | <b>168,000 km</b> | <b>COE Auto Trading</b>            | <b>Availal</b> |
| 1 Owner Only. Super Low Mileage Done. Genuine Mint Condition. Original Cushion And Interior Since Day 1. Highly Sought Panel Van In The Market. Guarantee Cheapest In The Market.<br>Office No. - 64589833 / 64571902<br>Mr Liauw - 96718933   Mr Chua - 98181643                       |                 |                    |                    |                 |                   |                                    |                |
| <b>Fiat Doblo Cargo Maxi 1.9M (COE till 01/2024)</b> (Diesel)                                                                                                                                                                                                                           | <b>\$17,500</b> | <b>\$3,570 /yr</b> | <b>14-Jan-2009</b> | <b>1,910 cc</b> | <b>120,000 km</b> |                                    | <b>Availal</b> |
| Come And Test Drive Now This Smooth, Quiet Powerful 1.9 Diesel Engine, Yet Economical, Easy Accessible Ample Cargo Space, Airbags, Reverse Sensors. Behind Come With Potable Sofa<br>Office No. - -<br>Wei Ming - 93376962                                                              |                 |                    |                    |                 |                   |                                    |                |

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.



# ComfortDelGro Engineering Pte Ltd

## Claim Reference:

Assessment number: GBA816J @ Pandan

Version: 1810

Date calculated: 02/13/2019 05:22 PM

Full Report

Registration: GBA816J

Printed: 13/02/2019 5:22 PM

## Summary Information

### Claim

|                        |                |                   |                                       |
|------------------------|----------------|-------------------|---------------------------------------|
| Location:              | Singapore (SG) | Work Provider:    | MSIG Insurance<br>(Singapore) Pte Ltd |
| Printed by:            | CDGE Pandan    | Currency:         | SGD                                   |
| Claim Reference:       |                | Date of Incident: | 2019-01-30                            |
| Estimated Repair Time: | 15             | Hire Car Start:   |                                       |
| Actual Repair Days:    |                | Hire Car End:     |                                       |

## Vehicle Details

### Vehicle

|                     |                   |
|---------------------|-------------------|
| Manufacturer:       | FIAT              |
| Model:              | DOBLO VAN         |
| Sub Model:          | CARGO             |
| Model Sheet Number: | 08 47 01          |
| Registration:       | GBA816J           |
| VIN number:         | ZFA22300005479118 |
| Odometer:           |                   |

### Model Specs

|                    |                      |                   |                     |
|--------------------|----------------------|-------------------|---------------------|
| TAILGATE           | FROM 12/2004         | AIR CONDITIONING  | REM CENTRAL LOCKING |
| ELECT DOOR MIRRORS | DRIVER'S PROT GRILLE | L/CTR SLDG WINDOW | R/CTR SLDG WINDOW   |
| REAR SIDE WINDOWS  | REAR SEAT BELT       | R/SLIDING DOOR    | L/SLIDING DOOR      |
| 5 SPEED GEARBOX    | TYRES 175/70 TR 14   | WHEELS 5.5J X 14  | TWO COAT METALLIC   |
| PAINTED BUMPER     |                      |                   |                     |

# ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: GBA816J @ Pandan

Version: 1810

Date calculated: 02/13/2019 05:22 PM

Full Report

Registration: GBA816J

Printed: 13/02/2019 5:22 PM

## Vehicle Condition


### Vehicle Status

Pre-Accident Damage:

Date of Inspection: 2019-02-13

### Damage Areas

All ☐  
Underbody ☐



## Labour

| Code      | Description                        | Time Base 10 WU/h | Price = 50.00 SGD/h |           |
|-----------|------------------------------------|-------------------|---------------------|-----------|
|           |                                    |                   | WU                  | Price SGD |
| 7604A 02  | VEHICLE PREPARATION TIME           |                   | 2.0                 | 10.00     |
| NO NUMBER | RENEW R/F WING                     |                   | 2.0                 | 10.00     |
| 7210E 18  | R + R R/F WING                     |                   | 6.0                 | 30.00     |
| 7620C 02  | R + R FRONT BUMPER                 |                   | 4.0                 | 20.00     |
| 7055B 45) | R + R R/R WHEELHOUSE COVER         |                   | 2.5                 | 12.50     |
| 7620C 68  | R + R BONNET LOCK                  |                   | 1.0                 | 5.00      |
| 5540B 79) | RENEW R/HEADLAMP                   |                   | 1.5                 | 7.50      |
| 7620G 04  | ADJUST HEADLAMP                    |                   | 2.0                 | 10.00     |
| 7620E 02  | R + R RIGHT HEADLAMP UNIT          |                   | 1.0                 | 5.00      |
| 7210L 50  | R + R R/SLIDING DOOR               |                   | 10.0                | 50.00     |
| 7205L 50  | CONVERT R/SLIDING DOOR             |                   | 10.5                | 52.50     |
| 7020C 22  | R + R R/SLIDING DOOR WINDOW        |                   | 3.0                 | 15.00     |
| 7020D 42  | R + R R/SLIDING DOOR LOCK PLATE    |                   | 1.5                 | 7.50      |
| 7660C 04  | R + R R/R SIDE BUMPER              |                   | 2.0                 | 10.00     |
| 4120A 10  | R + R STEERING GEAR CPL            |                   | 11.5                | 57.50     |
| 4450C 10) | R + R RIGHT FRONT STEERING KNUCKLE |                   | 3.0                 | 15.00     |



# ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: GBA816J @ Pandan

Version: 1810

Date calculated: 02/13/2019 05:22 PM

Full Report

Registration: GBA816J

Printed: 13/02/2019 5:22 PM

| Code         | Description                                                        | WU    | Price SGD |
|--------------|--------------------------------------------------------------------|-------|-----------|
|              | (WHEEL REMOVED)                                                    |       |           |
|              | INCLUDES: R + R BRAKE DISC AND BRAKE DISC PROTECTION PLATE         |       |           |
| 4450C 14)    | R + R FRONT STEERING KNUCKLE L+R                                   | 2.0   | 10.00     |
| 4450C 34     | R + R RIGHT FRONT WHEEL BEARING                                    | 3.0   | 15.00     |
| 4410B 40)    | R + R R/F CONTROL ARM (WHEEL REMOVED)                              | 3.0   | 15.00     |
| 4410A 10)    | R+R RIGHT FRONT SUSPENSION STRUT                                   | 3.0   | 15.00     |
| 4410A 14)    | R + R L/ R FRONT SUSPENSION STRUT                                  | 1.0   | 5.00      |
| 4410A 20/24  | R + R RIGHT FRONT SHOCK ABSORBER/SPRING (SUSPENSION STRUT REMOVED) | 3.0   | 15.00     |
| 4450B 42)    | ADD: BALANCE R/F ALU WHEEL                                         | 1.5   | 7.50      |
| 4420D 10     | R + R REAR AXLE                                                    | 14.5  | 72.50     |
| 4420D 20)    | RENEW REAR AXLE (REMOVED)                                          | 7.5   | 37.50     |
|              | INCLUDES: CONVERT PARTS FROM OLD TO NEW AXLE,                      |       |           |
|              | BLEED SYSTEM                                                       |       |           |
| 4450B 43)    | ADD R/R WHEEL BALANCE                                              | 1.5   | 7.50      |
| 4450B 29)    | R + R RIGHT FRONT TYRE                                             | 1.0   | 5.00      |
| 4450B 32)    | R + R R/R TYRE (WHEEL REMOVED)                                     | 1.0   | 5.00      |
| 4450B 26/27) | R + R TYRES                                                        | 1.0   | 5.00      |
| 3484         | R/R SIDE PANEL REPAIR                                              | 1.0   | 5.00      |
| 9902         | FRT VEHICLE ALIGN WITH ADJUST                                      | 30.0* | 150.00    |
|              |                                                                    |       | 80.00*    |
|              | <b>Labour Cost</b>                                                 |       |           |
|              | <b>Panel / Mechanical Labour</b>                                   | Hrs   | WU        |
|              | <b>Alignment</b>                                                   | 13.70 | 136.5     |
|              | <b>Fixed Rate</b>                                                  |       | 682.50    |
|              |                                                                    |       | 80.00     |
|              | <b>Total of Labour</b>                                             |       | 762.50    |

## Paint

| Code | Description - TWO COAT METALLIC      | WU   | Price SGD |
|------|--------------------------------------|------|-----------|
|      | R/F WING NEW PART PAINTING           | 10.0 |           |
|      | R/SLIDING DOOR NEW PART PAINTING     | 16.0 |           |
|      | FRONT BUMPER NEW PART PAINT K1R      | 15.0 |           |
|      | R/R BUMPER CORNER NEW PART PAINT K1R | 5.0  |           |
|      | R/R SIDE PANEL REPAIR PAINTING <50%  | 10.0 |           |

# ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: GBA816J @ Pandan

Version: 1810

Date calculated: 02/13/2019 05:22 PM

Full Report

Registration: GBA816J

Printed: 13/02/2019 5:22 PM

## Paint Material Per Part

| Code | Description                          | Price SGD |
|------|--------------------------------------|-----------|
| 0742 | R/F WING NEW PART PAINTING           | 21.67     |
| 1782 | R/SLIDING DOOR NEW PART PAINTING     | 45.92     |
| 0283 | FRONT BUMPER NEW PART PAINT K1R      | 73.80     |
| 2592 | R/R BUMPER CORNER NEW PART PAINT K1R | 11.32     |
| 3484 | R/R SIDE PANEL REPAIR PAINTING <50%  | 10.01     |

## Labour Cost - Paint

| Factor                         | 50.00 SGD/h    | Hrs         | WU          | Price SGD     |
|--------------------------------|----------------|-------------|-------------|---------------|
| Time Paint                     |                |             | 56.0        |               |
| Preparation Main Work Metal    |                | 2.10        | 21.0        | 105.00        |
| Preparation Comp. Work Plastic |                | 0.50        | 5.0         | 25.00         |
| <b>Total</b>                   | <b>10 WU/h</b> | <b>8.20</b> | <b>82.0</b> | <b>410.00</b> |

## Material Cost - Paint

|                                 | Price SGD     |
|---------------------------------|---------------|
| New Part Painting               | 67.59         |
| New Part Painting - Plastic K1R | 85.12         |
| Repair Painting                 | 10.01         |
| Material-constant Metal         | 18.10         |
| Material-constant Plastic       | 9.00          |
| <b>Total</b>                    | <b>189.82</b> |

## Spare Parts

| Code | Description          | Part Number   | Supplier | prices as at 2001-01-01 | Price SGD |
|------|----------------------|---------------|----------|-------------------------|-----------|
| 0283 | FRONT BUMPER         | 0000735401789 |          |                         | 850.00    |
| 0491 | FRONT LOCK SUPPORT   | 0000046790829 |          |                         | 80.00     |
| 0493 | BONNET LOCK          | 0000046747434 | NN       |                         | 250.00    |
| 0562 | RIGHT HEADLAMP ASSY  | 0000046807772 | NN       |                         | 350.00    |
| 0742 | R/F WING             | 0000098808122 |          |                         | 450.00    |
| 0842 | R/F WHEELHOUSE COVER | 0000046747451 |          |                         | 150.00    |
| 1782 | R/SLIDING DOOR       | 0000051847628 |          |                         | 2,500.00  |
| 1982 | R/SLDG DOOR MOULDING | 0000735294280 |          |                         | 250.00    |
| 2592 | R/R BUMPER CORNER    | 0000735371433 |          |                         | 180.00    |
| 7054 | R/F TRACK CONT ARM   | 0000051866700 |          |                         | 280.00    |
| 7078 | R/F SHOCK ABSORBER   | 0000051748514 |          |                         | 250.00    |
| 7082 | R/F STEERING KNUCKLE | 0000051721617 | NN       |                         | 450.00    |

# ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: GBA816J @ Pandan

Version: 1810

Date calculated: 02/13/2019 05:22 PM

Full Report

Registration: GBA816J

Printed: 13/02/2019 5:22 PM

| Code              | Description                     | Part Number   | Supplier | Price SGD |
|-------------------|---------------------------------|---------------|----------|-----------|
| 7100              | R/F S-ABS BRKT <del>X</del>     | 0000046760673 | GNN      | 180.00    |
| 7118              | R/INPUT SHAFT BRG <del>X</del>  | 0000046529970 |          | 150.00    |
| 7132              | R/F WHEEL HUB <del>X</del>      | 0000046798592 |          | 150.00    |
| 7202              | R/F WHEEL <del>cut</del>        | 0000046811700 |          | 250.00    |
| 7300              | STEERING GEAR ASSY <del>X</del> | 0000046833542 | } nn     | 2,800.00  |
| 9081              | REAR AXLE SUBFRAME <del>X</del> | 0000051758960 |          | 1,800.00  |
| 9182              | R/R WHEEL HUB <del>X</del>      | 0000051965295 |          | 480.00    |
| 9552              | R/R WHEEL <del>X cut</del>      | 0000046811700 |          | 250.00    |
| f: OEM Parts      |                                 |               |          | 0.00      |
| n: Non-OEM Parts  |                                 |               |          | 12,100.00 |
| u: Used parts     |                                 |               |          | 1,815.00  |
| Savings           |                                 |               |          |           |
| Subtotal          |                                 |               |          |           |
| Addition(+15.00%) |                                 |               |          |           |
| Total             |                                 |               |          | 13,915.00 |

## Extras

| Code                | Description                          | Price SGD    |
|---------------------|--------------------------------------|--------------|
| 1000                | SEALANT SEALANT <i>X NN</i>          | 40.00*       |
| 1001                | BODY LETTERING STICKER <i>- ncc.</i> | 30.00*       |
| <b>Total Extras</b> |                                      | <b>70.00</b> |

5 Days.

lumpsum repair

After repair photos.

Guo Qiang - 82880282

Guo Qiang @ lkk auto.com

**KKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

# ComfortDelGro Engineering Pte Ltd

Claim Reference:

Assessment number: GBA816J @ Pandan

Version: 1810

Date calculated: 02/13/2019 05:22 PM

Full Report

Registration: GBA816J

Printed: 13/02/2019 5:22 PM

## Final Calculation

|                                       | SGD       | SGD              |
|---------------------------------------|-----------|------------------|
| <b>Parts</b>                          |           |                  |
| Addition(+15.00%)                     | 12,100.00 |                  |
| <b>Total Parts</b>                    | 1,815.00  | <b>13,915.00</b> |
| <b>Labour Time Base 10 WU/h</b>       |           |                  |
| Total 136.5 WU X 50.00 SGD/h          | 682.50    |                  |
| Alignment                             |           |                  |
| Fixed Rate                            | 80.00     |                  |
| <b>Total of Labour</b>                |           | <b>762.50</b>    |
| <b>Total Of Extras</b>                |           | <b>70.00</b>     |
| <b>Paint Work Time Base 10 WU/h</b>   |           |                  |
| Labour Cost 82.0 WU X 50.00 SGD/h     | 410.00    |                  |
| Material Cost                         | 189.82    |                  |
| <b>Total Paint Including Material</b> |           | <b>599.82</b>    |
| <b>Repair Cost Excludes GST</b>       |           | <b>15,347.32</b> |
| GST (+7.0%)                           |           | <b>1,074.31</b>  |
| <b>Repair Cost Included GST</b>       |           | <b>16,421.63</b> |

## Comments

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS



## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

45 Pandan Road

Singapore 609286

Tel: 6338 8778 Email: denisteo@cdge.com.sg

**TP INSURER:**  
**NG CHEE BOON**  
 NIL  
 Singapore

**MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

|                               |                                            |                    |                   |
|-------------------------------|--------------------------------------------|--------------------|-------------------|
| Claim Type:                   | THIRD PARTY                                | Ref. No:           |                   |
| Policy No:                    |                                            | Date of Loss:      | 30/01/2019        |
| Vehicle Reg. No.:             | <b>GBA816J</b>                             | Driveable?         |                   |
| Party At Fault:               | UNKNOWN                                    |                    |                   |
| Driver (TP):                  | FADILAH BINTE GHABI                        | Driver (Insured):  | NG CHEE BOON      |
| Make/Model:                   | FIAT DOBLO, 1.9 D (M)                      | Vehicle Reg. Date: | 07/02/2007        |
| Vehicle Colour:               | RED                                        |                    |                   |
| Engine No:                    | 223B10005273931                            | Chassis No:        | ZFA22300005479118 |
| Odometer:                     | 0 KM                                       |                    |                   |
| Paint Type:                   |                                            |                    |                   |
| Total Loss?                   | <b>NO</b>                                  |                    |                   |
| Est. Duration of Repair (day) | 15                                         |                    |                   |
| Description of Accident/Loss  | REFER TO ATTACH DOCUMENT                   |                    |                   |
| Remarks:                      | VEHICLE IN FOR SURVEY                      |                    |                   |
| Present Location:             | COMFORTDELGRO ENGINEERING PTE LTD (PANDAN) |                    |                   |

| <b>COST OF CLAIMS</b>    | <b>Amount</b>    |
|--------------------------|------------------|
| Parts                    | 13,915.00        |
| Miscellaneous Items      | 70.00            |
| Paintwork Materials      | 189.82           |
| Labour                   | 762.50           |
| Paintwork Labour         | 410.00           |
| Towing                   | 0.00             |
| <b>Gross Total (S\$)</b> | <b>15,347.32</b> |
| <b>+ GST 7.00% (S\$)</b> | <b>1,074.31</b>  |
| <b>Nett Amount (S\$)</b> | <b>16,421.63</b> |

**This claim is handled by: WONG CHEE WEI**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 13 Feb 2019)**Parts:** M1-MPV      FIAT DOBLO 1.9 D (M) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/GBA816J/13/02/2019 17:47**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount                             |
|-----|-----|----------|-------------|-------|-------|------------------------------------|
| 1   | 1   |          | *PARTS      | 0.00  | 0.00  | *12,100.00 F                       |
|     |     |          |             |       |       | 4347                               |
|     |     |          |             |       |       | Sub Total (S\$)                    |
|     |     |          |             |       |       | 12,100.00                          |
|     |     |          |             |       |       | + Margin on L,N Items 15.00% (S\$) |
|     |     |          |             |       |       | 1,815.00                           |
|     |     |          |             |       |       | Total Parts (S\$)                  |
|     |     |          |             |       |       | 13,915.00                          |

ComfortDelGro Engineering Pte Ltd/GBA816J/13/02/2019 17:47. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS



## Estimates on Miscellaneous Items

| No                         | Qty | Particulars            | Amount        |
|----------------------------|-----|------------------------|---------------|
| <u>Materials</u>           |     |                        |               |
| 1                          | 1   | MATERIAL COST          | 179.81 189.82 |
| <u>Miscellaneous Items</u> |     |                        |               |
| 2                          | 1   | SEALANT                | 40.00         |
| 3                          | 1   | STICKER BODY LETTERING | 30.00         |
| Sub Total (S\$)            |     |                        | 259.82        |

## Estimates on Labour

| No                      | Particulars     | Lab.Type | Amount     |
|-------------------------|-----------------|----------|------------|
| <u>Paintwork Labour</u> |                 |          |            |
| 1                       | TOTAL OF LABOUR | New      | 300 410.00 |
| <u>Labour Items</u>     |                 |          |            |
| 2                       | TOTAL OF LABOUR | New      | 350 762.50 |
| Gross Labour Cost (S\$) |                 |          | 1,172.50   |

ComfortDelGro Engineering Pte Ltd/GBA816J/13/02/2019 17:47. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

**Claim Reference:**

**Assessment number: GBA816J @ Pandan**

**Version: 1810**

**Date calculated: 04/11/2019 01:57 PM**

**Full Report**

**Registration: GBA816J**

**Printed: 11/04/2019 1:57 PM**

---

**Summary Information**

**Claim**

|                        |                |                   |                                       |
|------------------------|----------------|-------------------|---------------------------------------|
| Location:              | Singapore (SG) | Work Provider:    | MSIG Insurance<br>(Singapore) Pte Ltd |
| Printed by:            | KK LAU         | Currency:         | SGD                                   |
| Claim Reference:       |                | Date of Incident: | 2019-01-30                            |
| Estimated Repair Time: | 15             | Hire Car Start:   |                                       |
| Actual Repair Days:    |                | Hire Car End:     |                                       |

---

**Vehicle Details**

**Vehicle**

|                     |                   |
|---------------------|-------------------|
| Manufacturer:       | FIAT              |
| Model:              | DOBLO VAN         |
| Sub Model:          | CARGO             |
| Model Sheet Number: | 08 47 01          |
| Registration:       | GBA816J           |
| VIN number:         | ZFA22300005479118 |
| Odometer:           |                   |

**Model Specs**

|                    |                      |                   |                     |
|--------------------|----------------------|-------------------|---------------------|
| TAILGATE           | FROM 12/2004         | AIR CONDITIONING  | REM CENTRAL LOCKING |
| ELECT DOOR MIRRORS | DRIVER'S PROT GRILLE | L/CTR SLDG WINDOW | R/CTR SLDG WINDOW   |
| REAR SIDE WINDOWS  | REAR SEAT BELT       | R/SLIDING DOOR    | L/SLIDING DOOR      |
| 5 SPEED GEARBOX    | TYRES 175/70 TR 14   | WHEELS 5.5J X 14  | TWO COAT METALLIC   |
| PAINTED BUMPER     |                      |                   |                     |

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Claim Reference:

Assessment number: GBA816J @ Pandan

Version: 1810

Date calculated: 04/11/2019 01:57 PM

Full Report

Registration: GBA816J

Printed: 11/04/2019 1:57 PM

## Vehicle Condition


### Vehicle Status

Pre-Accident Damage:

Date of Inspection: 2019-02-13

### Damage Areas

All ☐  
 Underbody ☐



## Labour

| Code      | Description                     | Time Base 10 WU/h | Price = 50.00 SGD/h |           |
|-----------|---------------------------------|-------------------|---------------------|-----------|
|           |                                 |                   | WU                  | Price SGD |
| 7604A 02  | VEHICLE PREPARATION TIME        |                   | 2.0                 | 10.00     |
| NO NUMBER | RENEW R/F WING                  |                   | 2.0                 | 10.00     |
| 7210E 18  | R + R R/F WING                  |                   | 6.0                 | 30.00     |
| 7620C 02  | R + R FRONT BUMPER              |                   | 4.0                 | 20.00     |
| 7055B 45) | R + R R/R WHEELHOUSE COVER      |                   | 2.5                 | 12.50     |
| 7620G 04  | ADJUST HEADLAMP                 |                   | 2.0                 | 10.00     |
| 7620E 02  | R + R RIGHT HEADLAMP UNIT       |                   | 1.0                 | 5.00      |
| 7055B 54  | R + R LOWER ENGINE PROTECTION   |                   | 2.5                 | 12.50     |
| 7210L 50  | R + R R/SLIDING DOOR            |                   | 10.0                | 50.00     |
| 7205L 50  | CONVERT R/SLIDING DOOR          |                   | 10.5                | 52.50     |
| 7020C 22  | R + R R/SLIDING DOOR WINDOW     |                   | 3.0                 | 15.00     |
| 7020D 42  | R + R R/SLIDING DOOR LOCK PLATE |                   | 1.5                 | 7.50      |
| 7660C 04  | R + R R/R SIDE BUMPER           |                   | 2.0                 | 10.00     |
| 4450B 42) | ADD: BALANCE R/F ALU WHEEL      |                   | 1.5                 | 7.50      |
| 4450B 08) | R + R R/REAR WHEEL              |                   | 1.0                 | 5.00      |
| 4450B 13) | R + R REAR WHEELS               |                   | 0.5                 | 2.50      |

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Claim Reference:

Assessment number: GBA816J @ Pandan

Version: 1810

Date calculated: 04/11/2019 01:57 PM

Full Report

Registration: GBA816J

Printed: 11/04/2019 1:57 PM

| Code               | Description                         | WU          | Price SGD     |
|--------------------|-------------------------------------|-------------|---------------|
| 4450B 29)          | R + R RIGHT FRONT TYRE              | 1.0         | 5.00          |
| 4450B 26/27)       | R + R TYRES                         | 1.0         | 5.00          |
| 9902               | FRT VEHICLE ALIGN ALIGN WITH ADJUST |             | 80.00*        |
| <b>Labour Cost</b> |                                     |             |               |
|                    | <b>Panel / Mechanical Labour</b>    | <b>Hrs</b>  | <b>WU</b>     |
|                    | <b>Alignment</b>                    | <b>5.40</b> | <b>54.0</b>   |
|                    | <b>Fixed Rate</b>                   |             | <b>80.00</b>  |
|                    | <b>Total of Labour</b>              |             | <b>350.00</b> |

**Paint**

| Code | Description - TWO COAT METALLIC      | WU   | Price SGD |
|------|--------------------------------------|------|-----------|
|      | R/F WING NEW PART PAINTING           | 10.0 |           |
|      | R/SLIDING DOOR NEW PART PAINTING     | 16.0 |           |
|      | FRONT BUMPER NEW PART PAINT K1R      | 15.0 |           |
|      | R/R BUMPER CORNER NEW PART PAINT K1R | 5.0  |           |

**Paint Material Per Part**

| Code | Description                          | Price SGD |
|------|--------------------------------------|-----------|
| 0742 | R/F WING NEW PART PAINTING           | 21.67     |
| 1782 | R/SLIDING DOOR NEW PART PAINTING     | 45.92     |
| 0283 | FRONT BUMPER NEW PART PAINT K1R      | 73.80     |
| 2592 | R/R BUMPER CORNER NEW PART PAINT K1R | 11.32     |

**Labour Cost - Paint**

|                                | Hrs         | WU          | Price SGD     |
|--------------------------------|-------------|-------------|---------------|
| Factor                         |             |             |               |
| Time Paint                     |             | 46.0        |               |
| Preparation Main Work Metal    | 0.90        | 9.0         | 45.00         |
| Preparation Comp. Work Plastic | 0.50        | 5.0         | 25.00         |
| <b>Total</b>                   | <b>6.00</b> | <b>60.0</b> | <b>300.00</b> |

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Claim Reference:  
 Assessment number: GBA816J @ Pandan  
 Version: 1810  
 Date calculated: 04/11/2019 01:57 PM

Full Report  
 Registration: GBA816J  
 Printed: 11/04/2019 1:57 PM

|                                 |                  |
|---------------------------------|------------------|
| <b>Material Cost - Paint</b>    | <b>Price SGD</b> |
| New Part Painting               | 67.59            |
| New Part Painting - Plastic K1R | 85.12            |
| Material-constant Metal         | 18.10            |
| Material-constant Plastic       | 9.00             |
| <b>Total</b>                    | <b>179.81</b>    |

**Spare Parts**

|                  |                          |               |          | prices as at 2001-01-01 |
|------------------|--------------------------|---------------|----------|-------------------------|
| Code             | Description              | Part Number   | Supplier | Price SGD               |
| 0742             | R/F WING                 | 0000098808122 |          | 450.00                  |
| 0842             | R/F WHEELHOUSE COVER     | 0000046747451 |          | 150.00                  |
| 1782             | R/SLIDING DOOR           | 0000051847628 |          | 2,500.00                |
| 1982             | R/SLDG DOOR MOULDING     | 0000735294280 |          | 250.00                  |
| 2592             | R/R BUMPER CORNER        | 0000735371433 |          | 180.00                  |
| 7202             | R/F WHEEL                | 0000046811700 |          | 250.00                  |
| f: OEM Parts     | <b>Savings</b>           |               |          | 0.00                    |
| n: Non-OEM Parts | <b>Subtotal</b>          |               |          | 3,780.00                |
| u: Used parts    | <b>Addition(+15.00%)</b> |               |          | 567.00                  |
|                  | <b>Total</b>             |               |          | <b>4,347.00</b>         |

**Extras**

| Code | Description            | Price SGD    |
|------|------------------------|--------------|
| 1001 | BODY LETTERING STICKER | 30.00*       |
|      | <b>Total Extras</b>    | <b>30.00</b> |

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Claim Reference:  
 Assessment number: GBA816J @ Pandan  
 Version: 1810  
 Date calculated: 04/11/2019 01:57 PM

Full Report  
 Registration: GBA816J  
 Printed: 11/04/2019 1:57 PM

**Final Calculation**

|                                       | SGD      | SGD             |
|---------------------------------------|----------|-----------------|
| <b>Parts</b>                          | 3,780.00 |                 |
| Addition(+15.00%)                     | 567.00   |                 |
| <b>Total Parts</b>                    |          | <b>4,347.00</b> |
| <b>Labour Time Base 10 WU/h</b>       |          |                 |
| Total 54.0 WU X 50.00 SGD/h           | 270.00   |                 |
| Alignment                             |          |                 |
| Fixed Rate                            | 80.00    |                 |
| <b>Total of Labour</b>                |          | <b>350.00</b>   |
| <b>Total Of Extras</b>                |          | <b>30.00</b>    |
| <b>Paint Work Time Base 10 WU/h</b>   |          |                 |
| Labour Cost 60.0 WU X 50.00 SGD/h     | 300.00   |                 |
| Material Cost                         | 179.81   |                 |
| <b>Total Paint Including Material</b> |          | <b>479.81</b>   |
| <b>Repair Cost Excludes GST</b>       |          | <b>5,206.81</b> |
| GST (+7.0%)                           |          | <b>364.48</b>   |
| <b>Repair Cost Included GST</b>       |          | <b>5,571.29</b> |

**Comments**

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

**ComfortDelGro Engineering Pte Ltd**

Corporate Office  
205 Braddell Road  
Singapore 579701  
Tel: 6338 8110  
Fax: 6338 8778  
Email: info@cdg.com.sg

Car Care Centres  
205 Braddell Road Singapore 579701  
50 Lanyang Drive Singapore 508269  
45 Pandan Road Singapore 609296  
181 Sun Ming Drive Singapore 575217  
7 Sungai Kadut Way Singapore 726791  
320 Ubi Road 4 Singapore 408649  
301 Vision Industrial Park A Singapore 706732  
www.spark.com.sg

Tel: 6338 8110  
Tel: 6214 8300  
Tel: 6338 8778  
Tel: 6553 0400  
Tel: 6369 7369  
Tel: 6348 5733  
Tel: 6757 7898



ComfortDelGro Engineering  
COMPANY REG. NO.: 199506048W  
GST REG. NO. M2-8921817-3

**TAX INVOICE**

8010130

MSIG INSURANCE (S) PTE LTD

4 SHENTON WAY SGX CENTRE 2 #23-01  
SINGAPORE 068807

CONTACT NO: 62212211

VEHICLE NO  
GBA 816J

MAKE  
FIAT

MODEL  
Doblo 1.9JTD

DATE OF REG

NO/DATE  
91428828 28.02.2019

JOB NO.  
305270157

ODOMETER READING

CHASSIS CODE JOB TYPE  
ZFA22300005479118

Description : TP CLAIMS AGAINST MSIG INS

**Invoice for Lump Sum Repair**

|                      |          |
|----------------------|----------|
| Lump Sum Amt         | 3,000.00 |
| Subtotal             | 3,000.00 |
| Add GST @ 7.000 %    | 210.00   |
| Total Invoice amount | 3,210.00 |

Issued by : DEASEX08 28.02.2019 15:47:06  
Repair Type : CPS0/52/5T  
Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd  
Member of COMFORTDELGRO

Head Office:  
5 Braddell Road  
C Ext 1 Level 2  
Singapore 579701

in: Finance Department

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

| ACCOUNT No. | INVOICE No. | AMOUNT | BANK/CHQ No. |
|-------------|-------------|--------|--------------|
|             |             |        |              |



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                             | Est Submitted                               | Adj Assigned                                         | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'd | Status                                                          |
|------|------------------------------------------------------|---------------------------------------------|------------------------------------------------------|------------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Main | 13 Feb 2019<br>17:35<br><a href="#">Sendback Est</a> | 13 Feb 2019<br>17:47<br><b>S\$15,347.32</b> | 15 Feb 2019<br>15:57<br><a href="#">Edit Adj Rpt</a> | <b>S\$3,000.00</b><br><a href="#">Edit Estimates</a> | <b>S\$3,000.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

|                             |                                                                                                                                          |                        |                                                                                              |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------|------------------------|----------------------------------------------------------------------------------------------|
| Insured:                    | <b>NG CHEE BOON</b> , ID: S8421443D                                                                                                      |                        |                                                                                              |
| Main Claimant:              | <b>SITI PATIMAH CATERING</b> , Co. Reg. No.: 53354855A                                                                                   |                        |                                                                                              |
| Vehicle Reg. No.:           | <b>GBA816J</b>                                                                                                                           | Date of Loss:          | 30/01/2019 16:00 - :59<br>[ <b>143</b> Months and <b>23</b> Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | <b>TP / 584032</b>                                                                                                                       | Policy/Cover Note No.: | A80453734QMX (Comprehensive)<br>Coverage: 24/02/2018 - 23/02/2019                            |
| Vehicle Reg. No. (Insured): | <b>SKV7394X</b>                                                                                                                          | Policy No. (Claimant): |                                                                                              |
|                             |                                                                                                                                          | Excess:                | S\$600.00                                                                                    |
| Repairer:                   | <b>ComfortDelGro Engineering Pte Ltd (Pandan)</b> 45 Pandan Road, 609286 Eunos - Tel: 6338 8778                                          |                        |                                                                                              |
| Handling Insurer:           | <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwei</b> - 6594 2550]         |                        |                                                                                              |
| Adjuster:                   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [ <b>Final Rpt</b> due 17/03/2019] |                        |                                                                                              |
| Driver/Custodian (Insured): | NG CHEE BOON (), NRIC: S8421443D Email:                                                                                                  |                        |                                                                                              |
| Adj Asg. Remarks:           | Car in. on WP. Please contact us ASAP if you cannot attend this assignment. TP survey. Liab : clear                                      |                        |                                                                                              |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |



## Claim Documents

GBA816J (584032)  
[SKV7394X]  
TP  
SITI PATIMAH CATERING  
Jan 30 2019 4:00PM  
[NG CHEE BOON]  
ComfortDelGro Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

| Assessment Reports |                |                                                                                           | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------------------------------------------------------------------|--------------|-------------------------------------|
| No                 | Finalized On   |                                                                                           | Thumbnail    | Print                               |
| 1                  | 13/02/19 17:47 | ComfortDelGro Engineering Pte Ltd (Pandan)<br><b>Repairer Estimates</b>                   | Load HTM     |                                     |
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ)                                                 | Thumbnail    | Print                               |
| 1                  | 15/02/19 11:14 | <b>Accident Statement</b><br>From: TP - Reg. No: GBA816J, Claimant: SITI PATIMAH CATERING | Load HTM     |                                     |
| No                 | Finalized On   | LKK Auto Consultants Pte Ltd (HQ)                                                         | Thumbnail    | Print                               |
| 1                  | 19/02/19 17:09 | <b>Adjuster Immediate Advice</b>                                                          | Load HTM     |                                     |

| Photos/Images |                 |                                                          | 3 per page ▼ | <input checked="" type="checkbox"/> |
|---------------|-----------------|----------------------------------------------------------|--------------|-------------------------------------|
| No            | Relabel/Reorder |                                                          | Thumbnail    | Print                               |
| 1             | 06/03/19 11:48  | LKK Auto Consultants Pte Ltd (HQ)<br><b>General View</b> | Load JPG     | <input checked="" type="checkbox"/> |
| 2             | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 3             | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 4             | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 5             | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 6             | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 7             | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 8             | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 9             | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 10            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 11            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 12            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 13            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 14            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 15            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 16            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 17            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 18            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 19            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 20            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 21            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 22            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 23            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 24            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 25            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 26            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 27            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |
| 28            | 06/03/19 11:48  | <b>General View</b>                                      | Load JPG     | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                                                                        | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|----------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | ComfortDelGro Engineering Pte Ltd (Pandan)                                             | Thumbnail                                                                                      | Print                               |
| 29                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 30                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 31                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 32                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 33                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 34                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 35                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 06/03/19 11:48 | General View                                                                           |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 06/03/19 11:48 | General View                                                                           |  Load JPG  | <input checked="" type="checkbox"/> |
| 48                 | 06/03/19 11:48 | General View                                                                           |  Load JPG | <input checked="" type="checkbox"/> |
| 49                 | 06/03/19 11:48 | General View                                                                           |  Load JPG | <input checked="" type="checkbox"/> |
| 50                 | 06/03/19 11:48 | General View                                                                           |  Load JPG | <input checked="" type="checkbox"/> |
| 51                 | 06/03/19 11:48 | General View                                                                           |  Load JPG | <input checked="" type="checkbox"/> |
| 52                 | 06/03/19 11:48 | General View                                                                           |  Load JPG | <input checked="" type="checkbox"/> |
| 53                 | 06/03/19 11:48 | General View                                                                           |  Load JPG | <input checked="" type="checkbox"/> |
| 54                 | 06/03/19 11:48 | General View                                                                           |  Load JPG | <input checked="" type="checkbox"/> |
| 55                 | 06/03/19 11:48 | General View                                                                           |  Load JPG | <input checked="" type="checkbox"/> |
| 56                 | 06/03/19 11:48 | General View                                                                           |  Load JPG | <input checked="" type="checkbox"/> |
| 57                 | 06/03/19 11:48 | General View                                                                           |  Load JPG | <input checked="" type="checkbox"/> |
| 58                 | 06/03/19 11:48 | General View                                                                           |  Load JPG | <input checked="" type="checkbox"/> |
| 59                 | 06/03/19 11:48 | General View                                                                           |  Load JPG | <input checked="" type="checkbox"/> |
| 60                 | 06/03/19 11:48 | Odometer Reading                                                                       |  Load JPG | <input checked="" type="checkbox"/> |
| 61                 | 06/03/19 11:48 | Chassis Number                                                                         |  Load JPG | <input checked="" type="checkbox"/> |
| 62                 | 06/03/19 11:49 | Reinspection Photo                                                                     |  Load JPG | <input checked="" type="checkbox"/> |
| 63                 | 06/03/19 11:49 | Reinspection Photo                                                                     |  Load JPG | <input checked="" type="checkbox"/> |
| 64                 | 06/03/19 11:49 | Reinspection Photo                                                                     |  Load JPG | <input checked="" type="checkbox"/> |
| 65                 | 06/03/19 11:49 | Reinspection Photo                                                                     |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation      |                |                                                                                        | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | ComfortDelGro Engineering Pte Ltd (Pandan)                                             | Thumbnail                                                                                      | Print                               |
| 1                  | 13/02/19 17:47 | Singapore Accident Statement                                                           |  Load PDF |                                     |
| 2                  | 13/02/19 17:47 | Repair Estimates                                                                       |  Load PDF |                                     |
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ)                                              | Thumbnail                                                                                      | Print                               |
| 1                  | 15/02/19 11:06 | LIABILITY CLEAR                                                                        |  Load PDF |                                     |
| 2                  | 15/02/19 11:14 | E-FILE REPORT (GBA816J)<br>From:TP - Reg. No: GBA816J, Claimant: SITI PATIMAH CATERING |  Load PDF |                                     |

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

#### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19003049/GQD3S2

Date: 12/04/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80453734QMX

Claimant Vehicle No: GBA816J

Insured Vehicle No: SKV7394X

Date of Loss: 30/01/2019

Nature of Claim: TP

Claim No: 584032

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBA816J

Make &amp; Model: FIAT DOBLO, 1.9 D (M)

Engine No: 223B10005273931

Reg. Date: 07/02/2007 (Man. Year: 2006)

Chassis No: ZFA22300005479118

Colour: Red

Odometer: 129155 km

Engine Capacity: 1910 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |      |                         |     |                          |     |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes  | Engine Modification:    | No  | Pre-accident Condition:  |     |

## CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 185/65 R15  | Rear Tyre Size:  | 185/65 R15  |
| Front Left Side:  | Falken 5 mm | Rear Left Side:  | Falken 5 mm |
| Front Right Side: | Falken 5 mm | Rear Right Side: | Falken 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's       | Adjuster's      | Difference       | Diff %       |
|------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                    | 13,915.00        | 4,347.00        | 9,568.00         | 68.76        |
| Miscellaneous Items                      | 70.00            | 30.00           | 40.00            | 57.14        |
| Paintwork Materials                      | 189.82           | 179.81          | 10.01            | 5.27         |
| Labour                                   | 762.50           | 350.00          | 412.50           | 54.10        |
| Paintwork Labour                         | 410.00           | 300.00          | 110.00           | 26.83        |
| Towing                                   | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>15,347.32</b> | <b>5,206.81</b> | <b>10,140.51</b> | <b>66.07</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>3,000.00</b> |                  |              |
| <b>(S\$)</b>                             | 15,347.32        | 3,000.00        | 12,347.32        | 80.45        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 1,074.31         | 210.00          | 864.31           | 80.45        |
| <b>Nett Amount (S\$)</b>                 | <b>16,421.63</b> | <b>3,210.00</b> | <b>13,211.63</b> | <b>80.45</b> |

## INSPECTION

|                             |            |                   |                                                                                  |
|-----------------------------|------------|-------------------|----------------------------------------------------------------------------------|
| Date of Assignment:         | 15/02/2019 | Present Location: | ComfortDelGro Engineering Pte Ltd (Pandan)                                       |
| Date Inspected:             | 18/02/2019 | Inspected At:     | ComfortDelGro Engineering Pte Ltd (Pandan)<br>45 Pandan Road<br>Singapore 609286 |
| Estimated Period of Repair: | 5.0 days   |                   |                                                                                  |

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

|                      |                                                                                                                                                                              |                                                        |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 12 Apr 2019)          |
| <b>Parts:</b>        | M1-MPV                                                                                                                                                                       | FIAT DOBLO 1.9 D (M) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                      |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GBA816J)                                                                                                                                     |                                                        |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                        |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                        |

## Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount      |
|-----|-----|----------|---------------------------------------|---------------|-------------|-------------|
| 1   | 1   |          | <b>*PARTS</b>                         |               | 12,100.00 F | -           |
| 2   | 1   |          | <b>*FRONT BUMPER</b><br>(WCP)         | Not Necessary | -           | *- F        |
| 3   | 1   |          | <b>*FRONT LOCK SUPPORT</b><br>(WCP)   | Not Necessary | -           | *- F        |
| 4   | 1   |          | <b>*BONNET LOCK</b><br>(WCP)          | Not Necessary | -           | *- F        |
| 5   | 1   |          | <b>*RIGHT HEADLAMP ASSY</b><br>(WCP)  | Not Necessary | -           | *- F        |
| 6   | 1   |          | <b>*R/F WING</b><br>(WCP)             | Buckled       | -           | *450.00 F   |
| 7   | 1   |          | <b>*R/F WHEELHOUSE COVER</b><br>(WCP) | Deformed      | -           | *150.00 F   |
| 8   | 1   |          | <b>*R/SLIDING DOOR</b><br>(WCP)       | Bent          | -           | *2,500.00 F |
| 9   | 1   |          | <b>*R/SLDG DOOR MOULDING</b><br>(WCP) | Cut           | -           | *250.00 F   |
| 10  | 1   |          | <b>*R/R BUMPER CORNER</b><br>(WCP)    | Cut           | -           | *180.00 F   |
| 11  | 1   |          | <b>*R/F TRACK CONT ARM</b><br>(WCP)   | Not Necessary | -           | *- F        |
| 12  | 1   |          | <b>*R/F SHOCK ABSORBER</b><br>(WCP)   | Not Necessary | -           | *- F        |
| 13  | 1   |          | <b>*R/F STEERING KNUCKLE</b><br>(WCP) | Not Necessary | -           | *- F        |
| 14  | 1   |          | <b>*R/F S-ABS BRKT</b><br>(WCP)       | Not Necessary | -           | *- F        |
| 15  | 1   |          | <b>*R/INPUT SHAFT BRG</b><br>(WCP)    | Not Necessary | -           | *- F        |
| 16  | 1   |          | <b>*R/F WHEEL HUB</b><br>(WCP)        | Not Necessary | -           | *- F        |
| 17  | 1   |          | <b>*R/F WHEEL</b><br>(WCP)            | Cut           | -           | *250.00 F   |
| 18  | 1   |          | <b>*STEERING GEAR ASSY</b><br>(WCP)   | Not Necessary | -           | *- F        |
| 19  | 1   |          | <b>*REAR AXLE SUBFRAME</b><br>(WCP)   | Not Necessary | -           | *- F        |
| 20  | 1   |          | <b>*R/R WHEEL HUB</b><br>(WCP)        | Not Necessary | -           | *- F        |
| 21  | 1   |          | <b>*R/R WHEEL</b><br>(WCP)            | Not Necessary | -           | *- F        |

F=Franchise part.

|                                                 |                  |                 |
|-------------------------------------------------|------------------|-----------------|
| <b>Sub Total (S\$)</b>                          | <b>12,100.00</b> | <b>3,780.00</b> |
| <b>+ Margin on L,N Items 15.00/15.00% (S\$)</b> | <b>1,815.00</b>  | <b>567.00</b>   |
| <b>Total Parts (S\$)</b>                        | <b>13,915.00</b> | <b>4,347.00</b> |

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

| No                         | Qty | Particulars                           | Repairer's | Amount |
|----------------------------|-----|---------------------------------------|------------|--------|
| <u>Materials</u>           |     |                                       |            |        |
| 1                          | 1   | MATERIAL COST                         | 189.82     | 179.81 |
| <u>Miscellaneous Items</u> |     |                                       |            |        |
| 2                          | 1   | SEALANT<br>(NOT NECESSARY)            | 40.00      | 0.00   |
| 3                          | 1   | STICKER BODY LETTERING<br>(NECESSARY) | 30.00      | 30.00  |
| Sub Total (\$\$)           |     |                                       | 259.82     | 209.81 |

## Recommended Labour

| No                       | Particulars     | Lab.Type | Repairer's | Amount |
|--------------------------|-----------------|----------|------------|--------|
| <u>Paintwork Labour</u>  |                 |          |            |        |
| 1                        | TOTAL OF LABOUR | New      | 410.00     | 300.00 |
| <u>Labour Items</u>      |                 |          |            |        |
| 2                        | TOTAL OF LABOUR | New      | 762.50     | 350.00 |
| Gross Labour Cost (\$\$) |                 |          | 1,172.50   | 650.00 |

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

&lt; END OF ESTIMATES &gt;