

ASS. REC. BY:

REF:

CS3/AIG/19003061/Beds 524

Special Instruction:

SURVEYOR: Mr Lim

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of AIG.

Date/Time: 18/2/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8LP3317R

Insured: SMG 7646 A

at Workshop m/s AF Motorworkz

Tel: 97530075

of 66 Kaki Bukit

Policy No: 1800156218

Claim No: 783471849486

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	8LP3317R - X
	SMG 7646A - X
	Dismantle: 19/2/19
	After repair: 20/2/2019

REF:

AIG

ASSIGNMENT

From:

Date: 18/2/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLP 3317 R

at Workshop m/s

AF Motorworkz

of

GG kaki Bukit Ave 6

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLP 3317 R

Yr Regn: 22/3/2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 520 L

C.C 1207

Colour:

Silver

A/C: Insured / Std / NI / N

Sp. Reading

13711

T/Radio: Insured / Std / NI / N

Eng/No:

A4150063N24B22B

C/No:

WBAXG120512W31202

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/55R17

R: 225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

r

L/Bal.

6

mm

L/Bal.

6

r

D.O.A.

13/2/17

D.O.I.

18/2/17

Survey held at

AF MOTORWORKS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

RECEIVED 10 APR 2019

MV 644,000/2
PV 52,000/2
NV 11,000/2

TOLIM 100/2
5/4/17

Date/Time, File Pass to?



Prel. Report

1)

Date/Time, File Return to?



Final Report

2)

Report Format:

DAR

Lump Sum / I.B.I. (\$)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$




Tech. Invs (\$



Weekend (\$

- Pre repair inspection request - SLP3317R VS SMG7646A (OI) DOA: 13/02/2019

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: Monday, 18 February, 2019 11:02:10 AM
Attachments:  tmp162A.TIF

mr Lim 18/2/19

Hi LKK,

Kindly assist to survey after 1pm today.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Veh In

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

<i>Please reply to our Branch Office for this matter</i>
--

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

⇔ Branch Office:

11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg
scrcnc.tan@mneduco.com.sg

Our Reference : MN/IG/A3/1912909A/st
Your Reference : SMG 7646A

Date : 13th February 2019

BY FAX 6835-7416 ONLY

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way, #07-16
Singapore 079120

Dear Sirs,

1. NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)
2. ACCIDENT ON 13/2/2019 INVOLVING VEHICLE NOS. SLP 3317R, SMG 7646A, SKN 1223M & SLR 3309D ALONG CTE TOWARDS ORCHARD ROAD.

We are instructed by ALDRICK LIM KUAN LIANG (owner of motor vehicle no. SLP 3317R) and/or AF MOTORWORKZ PTE LTD (the motor workshop for SLP 3317R) to notify you of a road traffic accident on 13/2/2019 at about 0905 hours along CTE TOWARDS ORCHARD ROAD involving our client's vehicle registration number [SLP 3317R] and [SMG 7646A] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

M NEDUMARAN & CO**M NEDUMARAN & CO - (Branch Office)**

Encl

c.c. 1) CHAN CHEE KENG

(Vehicle : SMG 7646A

)

2) NAME OF WORKSHOP :

AF Motorworkz Pte Ltd
66 Kaki Bukit Ave 6
Ark@KB
Singapore 417895
Telephone : 9753-0075
Facsimile : 6384-9932

(Vehicle : SLP 3317R

)

(Attention : Kenneth

)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2019 15:07
Date Of Accident	13/02/2019 09:05
Exact Location Of Accident	CTE TOWARDS ORCHARD RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP3317R
Insured/Policyholder	
Name Of Registered Owner	ALDRICK LIM KUAN LIANG
NRIC No	S8508826B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90465197
Alternative Phone No	OFFICE-90465197
Vehicle Particulars	
Manufacturer	BMW
Model	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ18-006201
Cover Note Number	
Driver	
Name of Driver	ALDRICK LIM KUAN LIANG
NRIC No	S8508826B
Date Of Birth	21/03/1985
Occupation	INDOOR
Date Of Driving Pass	14/08/2006
Driving Experience	12 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90465197
Fax Number	
Contact Number	OFFICE-90465197
Email Address	NOEMAIL

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLR3309D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SMG7646A
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver CHAN CHEE KENG
NRIC/Passport Number S1484554B
Contact Number 96962954
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)


DETAILS OF INJURED PERSON 1

Name ALDRICK LIM KUAN LIANG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLP3317R
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date &
Time 11:50 am 13/2/2019

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8826B
Vehicle Details	
Vehicle No.:	SLP3317R
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	B.M.W.
Vehicle Model:	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	A4150068N20B20B
Chassis No.:	WBAXG12050DW34262
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$42,532.00
Original Registration Date:	22 Mar 2012
First Registration Date:	22 Mar 2012
Transfer Count:	1
Actual ARF Paid:	\$42,532.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Mar 2022
PARF Rebate Amount:	\$27,645.00
Intended COE Rebate Details	
COE Expiry Date:	21 Mar 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$79,304.00
COE Rebate Amount:	\$24,452.00
Total Rebate Amount:	\$52,097.00

The information contained herein is correct as at 21 Feb 2019

OK

Dep 14,400/yr

MV 64,000/yr

PV 52,097/yr

NV 11,303/yr

hic
21/2/19

**BMW 5 Series 520i Highline**

-

N.A

24-Feb-2012

1,997 cc

-

Luxury

SOLD

1 Owner! Interest Rate At 2.18%! 100% Loan Approval Rate. Flexible Loan & Insurance Packages Available. In-house Loan Available. Call Us Now!

Motor Universe Credit Pte Ltd

Posted: 09-Jan-2019 Tags: 2012 BMW 520i, 2012 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW

**BMW 5 Series 520i**

-

N.A

19-Dec-2012

1,997 cc

-

Luxury

SOLD

1 Owner, Very Low Mileage Done At 69,000km, Accident Free, Road Tax Till June 2019, Excellent Driving Condition, Beautiful Interior, View To Believe, In House Financing Available, Please Call For View...

Horizon Motoring

Posted: 08-Jan-2019 Tags: 2012 BMW 520i, 2012 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW

**BMW 5 Series 520i****\$65,800****\$14,400 /yr**

16-Mar-2012

1,997 cc

-

Luxury

Available

1 Owner, Agent Maintain, Comes With 6 Months Warranty From Reputable Workshop, Low Mileage, Black On Black, Large Multimedia Screen With GPS Navigation. Contact Us For Viewing Right Now!

PREMIUM AD

Posted: 07-Jan-2019 Tags: 2012 BMW 520i, 2012 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW

**BMW 5 Series 520i**

-

N.A

21-Dec-2012

1,997 cc

-

Luxury

CLOSED**Auction Closing Time: 28th Dec 2018 at 05:00 PM**

This Is A Pre Owned Car For Sale, Depreciation Is Calculated Based On The Indicative Price But May Vary Depending On The Final Sale Price.

AUCTION VEN

Posted: 24-Dec-2018 Tags: 2012 BMW 520i, 2012 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW

**BMW 5 Series 520i**

-

N.A

28-Jun-2012

1,997 cc

-

Luxury

SOLD

1 Careful Owner Only With Genuine Low Mileage Done! Very Impressive Condition! Best In The Market! Be Gracious, By Appointment! Contact Our Appointed Sales Person Directly For Enquiry, Viewing And Tes...

Posted: 23-Dec-2018 Tags: 2012 BMW 520i, 2012 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW

**BMW 5 Series 520i Sunroof**

-

N.A

05-Apr-2012

1,997 cc

-

Luxury

SOLD

Brembo GT6 Brakes With 380mm And Upsize Rear Disk With 355mm, M4 Original Forged Wheels With Approved Eisenmann Quad Exhaust, Bilstein B8 With H&R Lower Spring, Wagner Intercooler, Charge, Boost, Turb...

DIRECT OWNER

Posted: 16-Dec-2018 Tags: 2012 BMW 520i, 2012 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW

**BMW 5 Series 520i Highline**

-

N.A

20-Jun-2012

1,997 cc

-

Luxury

SOLD

1 Owner! X'mas Promotion Interest Rate At 2.18%! 100% Loan Approval Rate. Flexible Loan & Insurance Packages Available. 10% Down-payment In-house Loan Available. Welcome High Trade In, STA Inspection ...

Posted: 07-Dec-2018 Tags: 2012 BMW 520i, 2012 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW

**BMW 5 Series 520i**

-

N.A

04-Sep-2012

1,997 cc

-

Luxury

SOLD

Rare Black With Black Interior! 1 Owner! Unit Not To Be Miss Good Condition! Well Maintained. High Paper Value Of \$60,500 Plus Body Value \$9K! Very Safe Buy! No Sticky Panels No Leakage High Loan Avail...

Posted: 30-Nov-2018 Tags: 2012 BMW 520i, 2012 bmw 520i, BMW 520i, bmw 520i, BMW, 520i, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

100 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used BMW, BMW Singapore, used BMW Singapore, used BMW, used vehicles Singapore or even buy used BMW Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

MOTORCAR (Rear)

(1)Replaced (2)Repaid (3)Check (4)Not Consistent (5)Not Working

Vehicle No: SLP 3317 R

Rear Portion

NAC	INC	Item	CON	ACQ	QTY
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	ACQ	QTY
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 7

Assessor: [Signature]

26/3/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2019 Edit Reg		18 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	CHAN CHEE KENG, ID: S14845548		
Main Claimant:	ALDRICK LIM KUAN LIANG, ID: S85088268		
Vehicle Reg. No.:	SLP3317R	Date of Loss:	13/02/2019 09:00 - :59 [82 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7834718494SG	Policy/Cover Note No.:	1800156218 (Comprehensive)
Vehicle Reg. No. (Insured):	SMG7646A	Policy No. (Claimant):	
		Excess:	
Repairer:	Af Motorworkz Pte Ltd (HQ) 66 KAKI BUKIT AVE 6, ARK@KB, 417895 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@alg.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 16/04/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (08/04/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLP3317R (7834718494SG)**
[SMG7646A]

TP
ALDRICK LIM KUAN LIANG
Feb 13 2019 9:00AM
[CHAN CHEE KENG]
Af Motorworkz Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Assessment Reports

1 per page
 ☒

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	08/04/19 11:23	Accident Statement From:OD - Reg. No: SMG7646A, Claimant: CHAN CHEE KENG	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images

3 per page
 ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
2	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
3	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
4	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
5	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
6	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
7	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
8	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
9	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
10	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
11	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
12	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
13	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
14	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
15	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
16	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
17	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
18	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
19	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
20	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
21	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
22	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
23	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
24	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
25	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
26	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
27	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
28	08/04/19 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
29	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	08/04/19 16:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	08/04/19 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	08/04/19 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	08/04/19 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	08/04/19 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	08/04/19 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19003061/BCD3S2

Date: 12/04/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800156218
Claimant Vehicle No :	SLP3317R	Insured Vehicle No :	SMG7646A
Date of Loss:	13/02/2019	Nature of Claim:	TP
		Claim No:	7834718494SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP3317R	Engine No:	A4150068N20B20B
Make & Model:	BMW 520I, 2.0 D/AB 2WD 4DR GAS/D NAV (A)	Chassis No:	WBAXG12050DW34262
Reg. Date:	22/03/2012 (Man. Year: 2011)	Odometer:	113114 km
Colour:	Silver		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	18/02/2019		
Date Inspected:	18/02/2019	Inspected At:	AF Motorworkz Pte Ltd (HQ) 66 KAKI BUKIT AVE 6, ARK@KB Singapore 417895
Estimated Period of Repair:	4.0 days		

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER TOW COVER	Dislodged	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
6	1		*REAR BUMPER SPONGE	Broken	0.00 F	*- F
7	2		*REVERSE SENSOR	Missing	0.00 F	*- F
				Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >