

REF: AIG

ASSIGNMENT

From:

Date: 18/2/19

Veh No: SLP 3317 R

Yr Regn: 22/3/2012

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SLP 3317 R

Make: BMW 520 L

C.C 1997

at Workshop m/s

AF Motorworkz

Colour: SILVER

A/C: Insured / Std / NI / N

of

66 Kaki Bukit Ave 6

Sp. Reading 113114

T/Radio: Insured / Std / NI / N

Insured:

Eng/No: A4150068N20B20B

Policy No.

C/No: WBAKG12050PW34262

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:


Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 225/55R17

R: 225/55R17

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal. 6 mm

R/Bal. 6

GIA / PR Seen:

Consistent? : Yes or No

L/Bal. 6 mm

L/Bal. 6

Est. Repairs:

4 days

Res.: Yes or No

D.O.A. 13/2/19

D.O.I. 18/2/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

AF MOTORWORKS

CA / REV / REP. / 24 HRS ^{up}

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time | Action / Instruction

RECEIVED 10 APR 2019

MV 64,000/2

PV 52,097/2

NV 11,903/2

T. G. Lim

5/4/19

Date/Time. File Pass to?

☐

: Preli. Report

Days Of Repair: 4

1)

☐

: Final Report

Resurvey No. of Trip: 2

Survey Fee:

Date/Time. File Return to?

Transportation:

2)

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format: DAR

Lump Sum / I.B.I. (\$

TOTAL

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8826B
Vehicle Details	
Vehicle No.:	SLP3317R
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	B.M.W.
Vehicle Model:	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	A4150068N20B20B
Chassis No.:	WBAXG12050DW34262
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$42,532.00
Original Registration Date:	22 Mar 2012
First Registration Date:	22 Mar 2012
Transfer Count:	1
Actual ARF Paid:	\$42,532.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Mar 2022
PARF Rebate Amount:	\$27,645.00
Intended COE Rebate Details	
COE Expiry Date:	21 Mar 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$79,304.00
COE Rebate Amount:	\$24,452.00
Total Rebate Amount:	\$52,097.00

The information contained herein is correct as at 21 Feb 2019

OK

Dep 14,400/yr

MV 64,000/2

PV 52,097/2

NV 11,903/2

hi

21/2/19

(1) Deformed (2) Shifted (3) Buckled (4) Broken (5) Necessary
(6) Missing (7) Torn (8) Unconfined (9) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (✓) (3) Check (✓)
(4) Not Consistent (✓)

Rear Portion

Vehicle No: SLP 3317R

NAC	INC	Item	CON	AC	Qt
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD ✓		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	DL ✓		
1146	992341	Rear Bumper Clips	NEC ✓		
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NEC ✓		
1149	993045	Rear Bumper Reinforcement	DD ✓		
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	BR ✓		
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	MB ✓	2	
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qt
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1195	990247	Sticker			

No of Items: 7

Assessor: J. Brown

26/3/19