

22/03/2017

ASS. REC. BY:

REF:

CS/CT119003064/Jgd312

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

18/2/2019.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 8942D

Insured:

GBJ1166Y

at Workshop m/s

World Auto.

Tel:

62247175

63621776 Daniel

of

No. 1 Kranji Loop.

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/1/2019.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction () Estimate

SLK 8942D - X

GBJ1166Y - X

28/2/19 @ 4.09 PM confirmed with Daniel vs \$1800, 3 days.

(Red \$3594, 67%)

Hwee Jie

REI CTI

Date 19/02/19

Sub No. SLK 8942 D

Report 3 Feb 2019

Inspected by

On ☒ W/S / ☐ P/R/S / ☐ D/R/S / ☐ LVA / ☐ H/V / ☐ M/V

Vehicle Used Vehicle No.

SLK 8942 D

at Work Report

World Auto (Kranji)
1 Kranji loop

or

Insured

Policy No.

Claim No.

Sum Insured

Excess

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value

IDAC Accident Report

Consistent? Yes or No

GIA / PIR Seen

Consistent? Yes or No

Est. Repair

3

days

Res: Yes or No

Est. Sum

%

3 Val: Yes or No

CA / REV / REP / 24 HRS

wp

Vehicle IN / OUT

Date

Person Contacted

Type ☒ Car / ☐ Motorcycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make

white

CC 1496

Colour

Honda Vezel

AP Insured / Std / NI / NA

Sp. Decoding

143641

Vehicle Insured / Std / NI / NA

Eng/No

C/N

RU11206695

Gen. Cond. ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: ☒ Nil / ☐ R/R / ☐ STD A/Rim or

Tyre Size

F: 215/60R16

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A.

25/1/19

D.O.I

19/2/19

Survey held at

World Auto

Des. of Damages: Frt / Rear / O/S / ☒ M/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 01 MAR 2019

Police Time / File Pass to?



: Prelim. Report

in 2/3 hours



: Final Report

Police Time / File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation

Police Fee

Police Fee

Police Fee

Police Fee

Police Fee

Add Fee:



Site Insp. (\$)



Interview (\$)



Police Insp. (\$)



Workshop (\$)

Report Format

WP

Lump Sum / U/C

1800

220

Catherine Chong (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, 18 February, 2019 11:51 AM
To: assignments
Subject: FW: Request for Third Party Motor Claim Survey (SLK8942D) DOA: 25-01-2019
Attachments: SLK8942D 25012019 TP.PDF

18/2/19 @ 4:25pm An Ping Said veh IN
Survey on 19/2/19

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 18 February 2019 11:47 AM
To: ainee31@worldauto.com.sg
Cc: worldautopl@yahoo.com.sg; 'Kana' <kana@worldauto.com.sg>; daniel@worldauto.com.sg; geraldine@worldauto.com.sg; Admin A <admin-a@lkkauto.com>
Subject: RE: Request for Third Party Motor Claim Survey (SLK8942D) DOA: 25-01-2019

Without Prejudice

Dear Sir,

We will appoint LKK.

Dear LKK,

Pls PRI.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: ainee31@worldauto.com.sg [mailto:aine31@worldauto.com.sg]
Sent: Monday, 18 February, 2019 10:50 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: worldautopl@yahoo.com.sg; 'Kana' <kana@worldauto.com.sg>; daniel@worldauto.com.sg; geraldine@worldauto.com.sg
Subject: RE: Request for Third Party Motor Claim Survey (SLK8942D) DOA: 25-01-2019

Dear Boon Sen

CHUA WEIJIE

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, February 18, 2019 10:33 AM
To: ainee31@worldauto.com.sg
Cc: worldautopl@yahoo.com.sg; 'Kana' <kana@worldauto.com.sg>; daniel@worldauto.com.sg; geraldine@worldauto.com.sg
Subject: RE: Request for Third Party Motor Claim Survey (SLK8942D) DOA: 25-01-2019

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: ainee31@worldauto.com.sg [<mailto:ainee31@worldauto.com.sg>]
Sent: Monday, 18 February, 2019 10:26 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: worldautopl@yahoo.com.sg; 'Kana' <kana@worldauto.com.sg>; daniel@worldauto.com.sg;
geraldine@worldauto.com.sg
Subject: RE: Request for Third Party Motor Claim Survey (SLK8942D) DOA: 25-01-2019

Dear Boon Sen

Please do a necessary follow up

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

From: ainee31@worldauto.com.sg <ainee31@worldauto.com.sg>
Sent: Monday, February 18, 2019 10:06 AM
To: 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>; 'Irene Tay' <irene.tay@sg.cntaiping.com>
Cc: 'worldautopl@yahoo.com.sg' <worldautopl@yahoo.com.sg>; 'Kana' <kana@worldauto.com.sg>;
'daniel@worldauto.com.sg' <daniel@worldauto.com.sg>; 'geraldine@worldauto.com.sg'
<geraldine@worldauto.com.sg>
Subject: RE: Request for Third Party Motor Claim Survey (SLK8942D) DOA: 25-01-2019

Dear All,

Any reply???

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

From: ainee31@worldauto.com.sg <ainee31@worldauto.com.sg>
Sent: Thursday, February 14, 2019 3:15 PM
To: 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>; 'Irene Tay' <irene.tay@sg.cntaiping.com>
Cc: 'worldautopl@yahoo.com.sg' <worldautopl@yahoo.com.sg>; 'Kana' <kana@worldauto.com.sg>
Subject: RE: Request for Third Party Motor Claim Survey (SLK8942D) DOA: 25-01-2019

Dear All,

Any reply on this??

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

From: aine31@worldauto.com.sg <aine31@worldauto.com.sg>
Sent: Monday, February 11, 2019 3:23 PM
To: 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>
Cc: 'worldautopl@yahoo.com.sg' <worldautopl@yahoo.com.sg>; 'Kana' <kana@worldauto.com.sg>
Subject: Request for Third Party Motor Claim Survey (SLK8942D) DOA: 25-01-2019

Good morning/afternoon,

We would like to request for a third party motor claim survey, details as follow;
Our Vehicle: SLK8942D
Your Insured: GBJ1166Y
DOA: 25-01-2019

Our vehicle is currently in the workshop, address as follow;
World Auto Pte Ltd
No.1, Kranji Loop
Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.
Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 28 February 2019 4:09 PM
To: 'daniel@worldauto.com.sg'
Subject: RE: TP VEHICLE SLK 8942D / OI VEHICLE GBJ 1166Y (DOA: 25/01/2019)

Dear Daniel,

WITHOUT PREJUDICE

Confirm Lump Sum \$1,800.00 before GST and 3 repair days.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: daniel@worldauto.com.sg <daniel@worldauto.com.sg>
Sent: Wednesday, 27 February 2019 3:32 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: TP VEHICLE SLK 8942D / OI VEHICLE GBJ 1166Y (DOA: 25/01/2019)

Dear Shiau Chan,
We propose Lump Sum \$1800 for closure.

Thks & Rgds,
Daniel
World Auto Pte Ltd
Tel: 63621776

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Wednesday, 27 February 2019 3:31 PM
To: daniel@worldauto.com.sg
Subject: RE: TP VEHICLE SLK 8942D / OI VEHICLE GBJ 1166Y (DOA: 25/01/2019)

Dear Daniel,

As per your requested.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

china Taripia

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/01/2019 11:05
Date Of Accident	25/01/2019 08:30
Exact Location Of Accident	21A LORONG GEYLANG & SIM AVE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLK8942D
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL-1.5 HYBRID (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995011
Cover Note Number	
Driver	
Name of Driver	ONG TECK SOON
NRIC No	S1756050F
Date Of Birth	07/04/1966
Occupation	OUTDOOR
Date Of Driving Pass	22/08/2003
Driving Experience	15 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92723520
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH (REMARKS : TP MOVING OUT OF PARKING LOT)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO OVERWRITTEN
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ1166Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims (including the settlement of the claims) and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time

25.01.18
10:30 AM

Reporting Centre Personnel's Signature
Name
NRIC/FIN NO:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25th Friday about 8:30 am in this morning
 When I driving across straight on Gaylang Lwy ~~21A~~ 21A.
 Suddenly a Lorry from my left side come out and
 Know my left hand side door

DECLARATION

I/We declare the foregoing particulars are true in every respect.






Policyholder's Signature
 Date & Time:

[Signature] 25.01.18
 10:30 am
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No:

Sketch Plan #3



WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE PTE LTD
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER 079909

Attention : Motor Claim Department
 Contact : 6389 6111

Estimate : ES190060

Date : 11/02/2019
 Vehicle Num. : SLK 8942D (LCR)
 Make/Model : HONDA VEZEL
 Chassis/Eng# :
 Accident Date : 25/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR DOOR - LH <i>DD</i>		<i>990</i> 1,500.00 ✓
2.	1	REAR FENDER LH <i>NN</i>		950.00 X
3.	1	REAR WHEEL ARCH MOULDING - LH <i>SCR</i>		250.00 ✓
4.	1	SIDE SKIRT RH <i>NN</i>		430.00 X
5.	1	REAR SIDE BUMPER - LH <i>BEF</i>		250.00 ✓
List Total S\$:				3,380.00
20.00% Discount S\$:				676.00
				<hr/> 2,704.00

SPECIAL NETT ITEMS :				
1.	1	REAR WHEEL ARCH MOULDING CLIPS <i>NEC</i>		<i>20</i> 40.00 ✓
2.	1	SIDE SKIRT CLIPS <i>NN</i>		40.00 X
Special Nett Total S\$:				<hr/> 80.00

LABOUR :				
TRANSFER DOOR MECHANISM			<i>60</i>	180.00 ✓
TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.			<i>30</i>	180.00 ✓
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS			<i>450</i>	900.00 ✓
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)			<i>480</i>	1,100.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE PTE LTD
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER 079909

Attention : Motor Claim Department
 Contact : 6389 6111

Estimate : ES190060

Date : 11/02/2019
 Vehicle Num. : SLK 8942D (LCR)
 Make/Model : HONDA VEZEL
 Chassis/Eng# :
 Accident Date : 25/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REMOVE AND REFIT FUEL TANK TO FACILITATE THE PANEL AND CUT OUT DAMAGED PANELS.		250.00
		Labour Total S\$:		2,610.00

E. & O.E.**Total S\$: 5,394.00**

=====

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee Jie - LKK

19/2/19

c/s 3 days.

 22/2/19

...CLAIM SUBFOLDER...(Pending for Survey Report)


















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Mar 2019 13:59		28 Feb 2019 17:43 Edit Adj Rpt	S\$1,800.00 Edit Estimates	S\$1,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: LCRF PTE LTD, Co. Reg. No.: 201624597K									
Vehicle Reg. No.: SLK8942D		Date of Loss: 25/01/2019 08:00 - :59 [23 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): GBJ1166Y		Policy No. (Claimant): 999995011							
		Excess: S\$0.00							
Repairer: World Auto Pte Ltd - Halcyon 2 (HQ) 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG, 577200 Bishan - Tel: 6451 3933									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 11/03/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















Claim Documents


*SLK8942D
[GBJ1166Y]
TP
LCRF PTE LTD
Jan 25 2019 8:00AM
[-]
World Auto Pte Ltd - Halcyon 2

Upload Documents		Upload Photos	Compose New Letter	View		View in Browser	
Letters/Correspondences				1 per page			
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	28/02/19 17:44	PRI CONTACT DETAILS		1 Load PDF			
Assessment Reports				1 per page			
No	Finalized On	World Auto Pte Ltd (HQ)		Thumbnail	Print		
1	25/01/19 11:15	Accident Statement		1 Load HTM			
Photos/Images				3 per page			
No	Finalized On	World Auto Pte Ltd (HQ)		Thumbnail	Print		
1	25/01/19 11:13	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
2	25/01/19 11:13	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
3	25/01/19 11:13	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
4	25/01/19 11:13	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
5	25/01/19 11:13	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
6	25/01/19 11:13	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
7	25/01/19 11:13	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
8	25/01/19 11:14	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
9	25/01/19 11:14	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
10	25/01/19 11:14	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
11	25/01/19 11:14	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
12	25/01/19 11:14	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
13	25/01/19 11:14	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
14	25/01/19 11:14	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
15	25/01/19 11:14	Accident Photo [Linked Accident Report Documents]		1 Load JPG			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	01/03/19 09:33	Odometer Reading		1 Load JPG			
2	01/03/19 09:33	Chassis Number		1 Load JPG			
3	01/03/19 09:33	General View		1 Load JPG			
4	01/03/19 09:33	General View		1 Load JPG			
5	01/03/19 09:33	General View		1 Load JPG			
6	01/03/19 09:33	General View		1 Load JPG			
7	01/03/19 09:33	General View		1 Load JPG			
8	01/03/19 09:33	General View		1 Load JPG			
9	01/03/19 09:33	General View		1 Load JPG			

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
10	01/03/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	01/03/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	01/03/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	01/03/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	01/03/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	01/03/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	01/03/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	01/03/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	01/03/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	01/03/19 09:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
20	01/03/19 09:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
21	01/03/19 09:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
22	01/03/19 09:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
23	01/03/19 09:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	World Auto Pte Ltd (HQ)	Thumbnail	Print	
1	25/01/19 11:14	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
2	25/01/19 11:14	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
3	25/01/19 11:14	Sketch Plan #3 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	

Linked Accident Report Documents

Assessment Reports				View	View in Browser
No	Finalized On	World Auto Pte Ltd (HQ)	Thumbnail	Print	
1	25/01/19 11:15	Accident Statement	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	World Auto Pte Ltd (HQ)	Thumbnail	Print	
1	25/01/19 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
2	25/01/19 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
3	25/01/19 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
4	25/01/19 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
5	25/01/19 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
6	25/01/19 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
7	25/01/19 11:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
8	25/01/19 11:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
9	25/01/19 11:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
10	25/01/19 11:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
11	25/01/19 11:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
12	25/01/19 11:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
13	25/01/19 11:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
14	25/01/19 11:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
15	25/01/19 11:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	World Auto Pte Ltd (HQ)	Thumbnail	Print	
1	25/01/19 11:14	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>	
2	25/01/19 11:14	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	World Auto Pte Ltd (HQ)		Thumbnail	Print
3	25/01/19 11:14	Sketch Plan #3		 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19003064/JQD3E2

Date: 04/03/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle No : SLK8942D

Insured Vehicle No : GBJ1166Y

Date of Loss: 25/01/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK8942D	Engine No:	L15B4406696
Make & Model:	HONDA VEZEL, 1.5 HYBRID (A)	Chassis No:	RU11206695
Reg. Date:	03/02/2017 (Man. Year: 2016)	Odometer:	143641 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,784.00	1,212.00	1,572.00	56.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,610.00	1,020.00	1,590.00	60.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,394.00	2,232.00	3,162.00	58.62
Approved Total (Overridden) (\$\$)		1,800.00		
(\$\$)	5,394.00	1,800.00	3,594.00	66.63
+ GST 7.00/7.00% (\$\$)	377.58	126.00	251.58	66.63
Nett Amount (\$\$)	5,771.58	1,926.00	3,845.58	66.63

INSPECTION

Date of Assignment: 28/02/2019

Date Inspected: 19/02/2019 Inspected At:

No. 1 Kranji Loop
Repairer : World Auto Pte Ltd - Halcyon 2
(HQ)

Estimated Period of Repair: 3.0 days

Adjuster: ONG HWEE JIE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK8942D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Dented	1,500.00 FL	*990.00 FL
2	1		*REAR FENDER LH	Not Necessary	950.00 FL	*- FL
3	1		*REAR WHEEL ARCH MOULDING - LH	Scratched	250.00 FL	*250.00 FL
4	1		*SIDE SKIRT RH	Not Necessary	430.00 FL	*- FL
5	1		*REAR SIDE BUMPER - LH	Deformed	250.00 FL	*250.00 FL
6	1		*REAR WHEEL ARCH MOULDING CLIPS	Necessary	40.00 FS	*20.00 FS
7	1		*SIDE SKIRT CLIPS	Not Necessary	40.00 FS	*- FS
					Sub Total (\$\$)	3,460.00 1,510.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	676.00 298.00
					Total Parts (\$\$)	2,784.00 1,212.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER DOOR MECHANISM	New	180.00	60.00
2	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS	New	180.00	30.00
3	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	New	900.00	450.00
4	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	New	1,100.00	480.00
5	TO REMOVE AND REFIT FUEL TANK TO FACILITATE THE PANEL AND CUT OUT DAMAGED PANELS	New	250.00	0.00
Gross Labour Cost (\$\$)			2,610.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >