

2/03/2002

ASS. REC. BY:

REF:

C83/AIG19003067/Gcd307

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

18/2/2019

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGK 779 X

Insured:

SKK 2155K

at Workshop m/s

Freemion Autodrive

Tel:

of

25 Kaki Bukit Rd #03-33

Policy No:

1800114692

Claim No:

9833535734SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction ( X ) Estimate

SGK 779X - X

SKK 2155K - X

Dismantle: 20/2/2019

After repair: 21/2/2019

shl.  
PRI

AIG

6857F

Form No. \_\_\_\_\_ Date \_\_\_\_\_

Insured's Name: **SGK 779X**

Vehicle No: **SGK 779X**

Model: **Freemion AutoDrive**

Address: **25 Kaki Bukit Rd 4 #03-33**

Phone No: **67023533**

Engine No: \_\_\_\_\_

Chassis No: \_\_\_\_\_

Year of Manufacture: \_\_\_\_\_

Year of Registration: \_\_\_\_\_

Insurance Policy No: \_\_\_\_\_

Client's Record: \_\_\_\_\_

Make of Vehicle: \_\_\_\_\_

Vehicle Condition: \_\_\_\_\_

Remarks: The veh had commenced its repair at the time of inspection.

Est. or Market Value: \_\_\_\_\_

ROAC Accident Report: \_\_\_\_\_

GIA / PR Seen: \_\_\_\_\_

Est. Repair: **2** days Res: Yes or No


Est. Cost: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle IN / OUT

Date / Time: \_\_\_\_\_ Action / Inspection: \_\_\_\_\_



Sch No: **SGK 779X** Date: **23 Oct 2018**

Type: **MC / Motorcycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or \_\_\_\_\_

Make: **Merce A200** CC: **1333**

Colour: **Red** A/C: \_\_\_\_\_ Insured / 3rd / NI / NA

Sp Reading: **6096** T/Mile: Insured / 3rd / NI / NA

Eng/Ho: \_\_\_\_\_

Chassis: **WDD1770872N 005152**

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Insider / Jammed / Leaked / Burnt or**

Brake: **Insider / Jammed / Leaked / Burnt or**

Mod: **Nil / STD / STD A/Rim or**

Tyre Size: F: **25/45 R18**

R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHSU / PIR / SUMI /

TOYO / YOKO or **Hankook**

Front: **8** mm R/Bal: **8** mm

L/Bal: **8** mm L/Bal: **8** mm

D.O.A: **10/2/19** w/s D.OI: **19-02-19** 5pm

Survey held at \_\_\_\_\_

Des. of Damages: **Front / Rear / O/S / N/S / U/C / Rooftop or**

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to: ☐ : Prelim. Report

File: ☐ : Final Report

Date/Time: File Return to: \_\_\_\_\_

Days Of Repair: **2**

Resurvey No. of Trip: **2**

Add Fee: ☐ Site Insp: 1%

☐ Inter. Insp: 1%

☐ Team Insp: 1%

☐ Weekend: 1%

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

180

10

190

Report Format: **DAR**

Lump Sum / U/C: \_\_\_\_\_

**Nivitha (LKK Auto)**

---

**From:** Chin, Lee-Ying <Lee-Ying.Chin@aig.com>  
**Sent:** Monday, 18 February 2019 12:07 PM  
**To:** assignments; Admin A  
**Cc:** Fong, Andy-SY  
**Subject:** - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKK2155K AND SGK779X ON 10/02/2019  
**Attachments:** SecureMessageAtt.html



19/2/19 @ morning

x Estimada

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ  
เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을  
읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,  
membuka attachment.


[Click here](#) by 2019-02-25 12:07 +08 to read your message.  
After that, open the attachment.

[More Info](#)

**Disclaimer:** This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: 18/2/2019 12:06:39 PM  
Attachments:  SGK779X DOA10022019 NOA GIA.PDF

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# FREESION AUTODRIVE

25 KAKI BUKIT ROAD 4 SYNEGRY @KB #03-33 SINGAPORE 417800

TEL: 6702 3533 FAX: 6702 3577

Email: freesionautodrive@gmail.com

Date: 16/2/2019

To Alfa Asia Pacific Insurance Pte Ltd  
Motor Claims Department  
78 Shenton Way #07-16  
079120  
Singapore

By fax only

Tel: 6493000

Fax: 68353727

Yokeshi Chan @ asig.com

Dear Sir/Mdm,

## NOTIFICATION OF ACCIDENT

Please be informed that an accident involving my/our vehicle no. SGK779X and vehicle(s) no. SKK2155K had taken place at / along Marine Parade Road on date 10-02-2019 at time 16:20.

Kindly let us know within 2 working days from the date of this notice if you wish to carry out or waive a pre-repair inspection.

If we do not hear from you within 2 working days, we shall proceed to repair the vehicle without further notice and our client shall claim for the additional loss of use arising from the giving of this notification to you.

Please contact our workshop at 6702 3533 before attending the inspection.

Yours sincerely,



### PRI

Date / Time	
Company Name	
Surveyor	
Contact No.	
Signature	

### DISMANTLED PARTS

Date / Time	
Surveyor	

### AFTER REPAIR

Date / Time	
Surveyor	

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6857F
Vehicle Details	
Vehicle No.:	SGK779X
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Feb 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	A200 AMG LINE AUTO
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	28291480013527
Chassis No.:	WDD1770872N005152
Maximum Power Output:	120.0 kW (160 bhp)
Open Market Value:	\$34,790.00
Original Registration Date:	23 Oct 2018
First Registration Date:	23 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$40,706.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Oct 2028
PARF Rebate Amount:	\$30,529.00
Intended COE Rebate Details	
COE Expiry Date:	22 Oct 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,302.00
COE Rebate Amount:	\$30,275.00
<b>Total Rebate Amount:</b>	<b>\$60,804.00</b>

The information contained herein is correct as at 20 Feb 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/02/2019 13:32
Date Of Accident	10/02/2019 16:20
Exact Location Of Accident	MARINE PARADE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGK779X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HANZARI ISA PHANG @PHANG KIN CHOONG
NRIC No	S8516857F
Email Address	HANZP13@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-94743924
Alternative Phone No	OFFICE-94743924

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	A200 A-CLASS AMG PREMIUM 1.3 1332CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10876442
Cover Note Number	

### Driver

Name of Driver	HANZARI ISA PHANG @PHANG KIN CHOONG
NRIC No	S8516857F
Date Of Birth	13/05/1985
Occupation	INDOOR
Date Of Driving Pass	13/08/2004
Driving Experience	14 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94743924
Fax Number	
Contact Number	OFFICE-94743924
Email Address	HANZP13@HOTMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : FIONA GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	MARINE PARADE NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20190210/2092 LODGED AT MARINE PARADE NPC. ON 10/02/2019 AT ABOUT 1620HRS, I WAS DRIVING AT THE MULTI STOREY CARPARK OF PARKWAY PARADE SHOPPING CENTRE, TO LOOK FOR A PARKING LOT. MY WIFE WAS SEATED NEXT TO ME AT THAT POINT OF TIME. WHILE WE WERE DRIVING UP FROM LEVEL 2 TO LEVEL 3 OF THE CARPARK, THE OTHER PARTY THAT WAS IN FRONT OF MINE, SUBSEQUENTLY STOPPED AND STARTED REVERSING. HE DID NOT TURN ON ANY HAZARD LIGHT OR SIGNAL LIGHT BEFORE REVERSING. I THEN HONKED TO GET THE OTHER PARTY'S ATTENTION, HOWEVER, HE CONTINUED REVERSING AND EVENTUALLY HIT ONTO THE FRONT BUMPER OF MY VEHICLE. I THEN ALIGHTED FROM MY VEHICLE AND OBSERVED DENTS AND SCRATCHES ON THE FRONT BUMPER OF MY VEHICLE. I THEN EXCHANGED PARTICULARS WITH THE OTHER DRIVER, WHO HAD CLAIMED THAT I WAS THE ONE AT FAULT. I THEN INFORMED HIM THAT I WILL LODGE A POLICE REPORT. I ALSO WISH TO INFORM THAT I HAVE AN IN-CAR CAMERA IN MY VEHICLE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO UPLOADED INTO FILE ZILLA
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKK2155K
Vehicle Make/Model/Colour	MERCEDES BENZ/GLC200 (R18 LED)
Details Of Properties	
Vehicle Category	PRIVATE CAR



Name of Driver	RONG SIKAI
NRIC/Passport Number	S8573072Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving, and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 

I understand, acknowledge, agree and consent that:

  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS  
REPORTING OFFICER  
MOHAMED SHARIL  
BIN SATAR

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

### Sketch Plan

A-54K779X

B-5KK2155K

Reverse

Partway  
Arade  
SHIPPED  
CTR





**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Marine Parade N.P.C  
300 Marine Parade Road SINGAPORE  
449296  
Tel No: 1800-4428999



Report No: T/20190216/392

**CONTINUATION OF REPORT**

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	HANZARI ISA PHANG	ID No.	S8516857F
Related Vehicle	SGK77BX (Car)	Contact No.	84743924
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	RONG SIKAI	ID No.	S8573072Z
Related Vehicle	SKK2155K (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 10/02/2019 at about 1620hrs, I was driving at the multi storey carpark of Parkway Parade Shopping Centre, to look for a parking lot. My wife was seated next to me at that point of time. While we were driving up from level 2 to level 3 of the carpark, the other party that was in front of mine, subsequently stopped and started reversing. He did not turn on any hazard light or signal light before reversing. I then honked to get the other party's attention, however, he continued reversing and eventually hit onto the front bumper of my vehicle.

I then alighted from my vehicle and observed dents and scratches on the front bumper of my vehicle. I then exchanged particulars with the other driver, who had claimed that I was the one at fault. I then informed him that I will lodge a police report. I also wish to inform that I have an in-car camera in my vehicle.





**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Marine Parade N.P.C  
300 Marine Parade Road SINGAPORE  
449298  
Tel No: 1800-4428999



T120190210/2092  
18/3  
Report No. T120190210/2092

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
G /  
Sgt 2 KHAIRUL HANIS BINTE RUSLI

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIA /  
Staff Sgt WONG SIEU LUI  
Contact No.: 65476151

Signature Of Informant:

Date/Time:  
10/02/2019 20:16

Classification Of Case:

Authentication Stamp  
NP168



**SINGAPORE  
POLICE FORCE**

SIGNATURE

SK 779X

Tr4 Bumper X repair.

" " Sponge / CCA

" " Garnish LH - Re

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Feb 2019 <a href="#">Edit Reg</a>		18 Feb 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>RONG SIKAI</b> , ID: S8573072Z									
Main Claimant: <b>HANZARI ISA PHANG @ PHANG KIN CHOONG</b> , ID: S8516857F									
Vehicle Reg. No.: <b>SGK779X</b>		Date of Loss:	10/02/2019 16:00 - :59 [3 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type: <b>TP / 9833535734SG</b>		Policy/Cover Note No.:	1800114692 (Comprehensive)						
Vehicle Reg. No. (Insured): <b>SKK2155K</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Freesion Autodrive (Kaki Bukit)</b> 25 Kaki Bukit Rd 4, Synergy @KB #03-33, 417800 Kaki Bukit - Tel:									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Loh, Chee-Heng</b> ] Chee-Heng.Loh@aig.com									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 05/03/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (25/02/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All Search Tasks Create New Task Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGK779X (9833535734SG)

[SKK2155K]



































TP

HANZARI ISA PHANG @ PHANG KIN CHOONG

Feb 10 2019 4:00PM

[RONG SIKAI]

Freesion Autodrive

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	23/02/19 15:17	General View													Load JPG	<input checked="" type="checkbox"/>		
2	23/02/19 15:17	General View													Load JPG	<input checked="" type="checkbox"/>		
3	23/02/19 15:17	General View													Load JPG	<input checked="" type="checkbox"/>		
4	23/02/19 15:17	General View													Load JPG	<input checked="" type="checkbox"/>		
5	23/02/19 15:17	General View													Load JPG	<input checked="" type="checkbox"/>		
6	23/02/19 15:17	General View													Load JPG	<input checked="" type="checkbox"/>		
7	23/02/19 15:17	General View													Load JPG	<input checked="" type="checkbox"/>		
8	23/02/19 15:17	General View													Load JPG	<input checked="" type="checkbox"/>		
9	23/02/19 15:17	General View													Load JPG	<input checked="" type="checkbox"/>		
10	23/02/19 15:17	General View													Load JPG	<input checked="" type="checkbox"/>		
11	23/02/19 15:17	General View													Load JPG	<input checked="" type="checkbox"/>		
12	23/02/19 15:17	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
13	23/02/19 15:17	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
14	23/02/19 15:17	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
15	23/02/19 15:17	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
16	23/02/19 15:17	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
17	23/02/19 15:17	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
18	23/02/19 15:17	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
19	23/02/19 15:17	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
20	23/02/19 15:17	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
21	23/02/19 15:17	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
22	23/02/19 15:17	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>		
23	23/02/19 15:18	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>		
24	23/02/19 15:18	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>		
25	23/02/19 15:18	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>		
26	23/02/19 15:18	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>		
27	23/02/19 15:18	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>		
28	23/02/19 15:18	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>		
29	23/02/19 15:18	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>		
30	23/02/19 15:18	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>		
31	23/02/19 15:18	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>		
32	23/02/19 15:18	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>		
Documentation															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print		
1	25/02/19 10:23	OI GIA REPORT													Load PDF			
2	05/03/19 17:09	TP GIA													Load PDF			



## Documents Checklist

**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19003067/GCD3E2

Date: 03/04/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1800114692

Claimant Vehicle No : SGK779X

Insured Vehicle No : SKK2155K

Date of Loss: 10/02/2019

Nature of Claim: TP

Claim No: 9833535734SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGK779X

Make &amp; Model: MERCEDES-BENZ A200, 1.6 FL AMG LINE (A)

Engine No: 28291480013527

Reg. Date: 23/10/2018 (Man. Year: 2018)

Chassis No: WDD1770872N005152

Colour: Red

Odometer: 6096 km

Engine Capacity: 1333 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Hankook 8 mm

Rear Left Side: Hankook 8 mm

Front Right Side: Hankook 8 mm

Rear Right Side: Hankook 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 18/02/2019

Date Inspected: 19/02/2019 Inspected At:

Freesion Autodrive (Kaki Bukit)  
25 Kaki Bukit Rd 4, Synergy @KB #03-33  
Singapore 417800

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair	0.00 F	*- F
2	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
3	1		*FRT BUMPER GARNISH LH	Deformed	0.00 F	*- F
				<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >