

ASS. REC. BY:

REF:

CC3/19003072/Gcd301

Special Instruction:

ASSIGNMENT (Office)From (Person): Gabriel Lee of AI Date/Time: 18/2/2019

Estimated Cost: _____ Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLQ3452C Insured: SHA 1542Xat Workshop m/s D's Graffiti Tel: 8608 3456of 25 Kaki Bukit Rd 4 #06-26

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 4/2/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SLQ3452C - X</u>
	<u>SHA 1542X - CC3/AIG17002688/H1ya392 DOA: 5/2/2017.</u>
	<u>Dismantle: 20/2/2019 @ 01:35pm</u>
	<u>After repair: 22/2/2019 @ 12:55pm</u>

PRS
KRL.

REF:

III

Date: _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____
 (Client's Record)
 Make of Veh: _____

Sub No: **SLQ 3452C** Date: **Jul 17**
 Type: **Motor Cycle / Bus / Van / Lorry / Taxi / Private Motor**
 Truck / Trailer or _____
 Make: **Honda HRV 1.5** CC: **1496**
 Colour: **white** A/C: _____ Insured / Std / HI / NA
 Sp Reading: **15247** T/Cable: Insured / Std / HI / NA
 Eng/Ho: _____
 C/Bio: **THMPU1810 EX 202778**
 Gen. Cond: **Good / Fair / Poor / Burnt**
 Steering: **Insider / Jammed / Leaked / Burnt** or
 Brake: **Insider / Jammed / Leaked / Burnt** or
 Mod: **Nil / S/Rim / STD / Rim** or
 Tyre Size: F: **215/60 R16**
 R: **11**

(Policy Condition) **all again but go down**
 Remark: The veh had commenced its repair at the time of inspection.

BS / **DAI** / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: **6/19** D.O.I: **13-02-19**
 Survey held at: **W/S** **8:20 pm**
 Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or
FA O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: _____
 IDAC: Accident Report Consistent? Yes or No
 GIA / PR: Seen Consistent? Yes or No
 Est. repairs: **3** days Res: Yes or No
 Est. sum: **20** % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle IN / OUT

Date / Time: _____ Action / Instruction: **\$2000 - \$3000**

RECEIVED 22 MAR 2019

Date/Time: File Pass to: ☐ : Preli. Report
☐ : Final Report

Days Of Repair: **3**
 Resurvey No. of Trip: **2**

Date/Time: File Reference:

Add Fee: ☐ Site Insp. (\$) ☐
☐ Interview (\$) ☐
☐ Tech. Insp. (\$) ☐
☐ Witness (\$) ☐

Survey Fee: _____
 Transportation: _____

Report Format: **PRS**

Lump Sum / LB H. etc.

120
10
130

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 18 February 2019 2:10 PM
To: Dorothy Dylegal; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: David Yong; Sherini Pillai; Zuhaidah Samsuri
Subject: RE: DY.02.0018.2019.dc - Pre-Repair Survey - Notification of Inspection
Attachments: SCAN_20190218_130824999.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SLQ3452C
III INSURED VEHICLE NO. : SHA1542X
DATE OF LOSS : 06.02.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sherini**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Dorothy Dylegal [mailto:admin@dylegal.asia]
Sent: 18 February, 2019 1:59 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: David Yong <dy@dylegal.asia>
Subject: Re: DY.02.0018.2019.dc - Pre-Repair Survey - Notification of Inspection

Dear Gabriel,

*Call Mr Dave at
86083456
19/2/19 morning
again before survey.
Calli Bulat Butday
#0159*

1. Your email of this instant refers.
2. Pursuant to the State Courts Practice Directions Amendment No. 1 of 2016, our client is not agreeable to your list of surveyors. Our client's appointed surveyor is Mr Fong Kok Heng (Automax Survey).
3. Please contact and liaise with the workshop directly to arrange for the pre-repair survey of our client's damaged vehicle and obtain the requisite documents from them.

Workshop	M/s D's Graffiti Concepts Pte Ltd
Address	25 Kaki Bukit Road 4 #06-26 Synergy @KB Singapore 417800
Contact Person	Mr Dave
Contact No.	8608 3456

4. Thank you.

Regards,
Dorothy Chang
(Secretary to Mr David Yong)

DY & Associates

883 North Bridge Road
#05-03 Southbank
Singapore 198785
Tel: 6292 2388
Fax: 6292 2088
Email: admin@dylegal.asia
UEN No. 53388398M

On Mon, Feb 18, 2019 at 1:53 PM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Dorothy Dylegal [mailto:admin@dylegal.asia]

Sent: 18 February, 2019 1:15 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: David Yong <dy@dylegal.asia>

Subject: DY.02.0018.2019.dc - Pre-Repair Survey - Notification of Inspection

Re: Accident involving SLQ 3452C and SHA 1542X at Blk 114 Ang Mo Kio Ave 4 Carpark on 06.02.2019

Dear Sirs,

1. The above subject matters refers.
2. Please find attached herewith our Pre-Repair Survey - Notification of Inspection of 18 February 2019 for your retention and necessary actions.

Regards,

Dorothy Chang

(Secretary to Mr David Yong)

DY & Associates

883 North Bridge Road

#05-03 Southbank

Singapore 198785

Tel: 6292 2388

Fax: 6292 2088

Email: admin@dylegal.asia

UEN No. 53388398M

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

DY
DY & Associates
Advocates & Solicitors

Our Ref: DY.02.0018.2019.dc

Your Ref: Please advise

18 February 2019

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
#04/#05 IOB Building
Singapore 049711

VIA EMAIL & POST

(Email: motorclaim@iii.com.sg)

Attention: Pre Repair Survey

Dear Sirs

PRE-REPAIR SURVEY – NOTIFICATION OF INSPECTION

CLAIMANT: LOH HANG CHOO

**ACCIDENT INVOLVING SLQ 3452C AND SHA 1542X AT BLK 114 ANG MO KIO AVE 4
CARPARK ON 06.02.2019**

We are instructed by M/s D's Graffiti Concepts Pte Ltd to notify you of a road traffic accident on 2 February 2019 along Punggol Road towards TPE involving our client's vehicle registration number **SLQ 3452C** and vehicle registration number **SHA 1542X** driven by your insured at the material time. A copy of the Singapore Accident Statement is enclosed herewith.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know **within two (2) working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully



DAVID YONG KHUNG LIN

(YANG KONGLIN)

Encl.

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLQ3452C		
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	HRV 1.5 DX CVT		
Chassis No. :	JHMRU1810GX202778		
Propellant :	Petrol		
Engine No. :	L15B4532778		
Engine Capacity :	1496 cc		
Maximum Power Output :	96.0 kW (128 bhp)		
Maximum Laden Weight :	1760 kg		
Unladen Weight :	1185 kg		
Year Of Manufacture :	2017		
Original Registration Date :	05 Jul 2017		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$42,801.00		
COE Expiry Date :	04 Jul 2027		
Road Tax Expiry Date :	04 Jul 2019		
PARF Eligibility Expiry Date :	04 Jul 2027		
Inspection Due Date :	04 Jul 2020		
Intended Transfer Date :	23 Feb 2019		
CO2 Emission :	129.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$5,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3772E
Vehicle Details	
Vehicle No.:	SLQ3452C
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 DX CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	L15B4532778
Chassis No.:	JHMRU1810GX202778
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,909.00
Original Registration Date:	05 Jul 2017
First Registration Date:	05 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$14,909.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jul 2027
PARF Rebate Amount:	\$11,181.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$35,796.00
Total Rebate Amount:	\$46,977.00

The information contained herein is correct as at 23 Feb 2019

OK



SINGAPORE POLICE FORCE



T/20190207/2058

1 of 3

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

Report No. T/20190207/2058

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/02/2019 13:06	Vide Report No.:	Station Diary No.: 8
--	------------------	-------------------------

Informant's Particulars

Name of Informant: LOH HANG CHOO			Address: APT BLK 117 ANG MO KIO AVENUE 4 #06-441 SINGAPORE 560117		
ID Type / ID No.: NRIC NO / S1823772E			Contact No.: Home/Office:		Mobile: 97441946
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 51	Date of Birth: 29/07/1967	Type of Informant: Vehicle Owner		
Race: Chinese			Language:		Institution / School Name:
Occupation: Hair stylist/Hairdresser			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

General Information of the Accident		Type of Location:	
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 06/02/2019 00:00
Location: Along Road 1 ANG MO KIO AVENUE 4			
Blk 114 Ang Mo Kio ave 4 car park, beside shelter.			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow:	Traffic Control:	Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle		Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLQ3452C	Car				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999



T/20190207/2058

2 of 3

Report No. T/20190207/2058

CONTINUATION OF REPORT

Vehicle Owner			
Name	LOH HANG CHOO	ID No.	S1823772E
Related Vehicle	SLQ3452C (Car)	Contact No.	97441946
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 04/02/2019 at about 1000hrs, I parked my vehicle SLQ3452C at a car park lot located at block 114 Ang Mo Kio ave 4. Everything was intact,

On 06/02/2018 morning, while my maid was washing my car, she discovered a big dented on the right portion area of my car. A passer-by uncle who stay nearby told me was a comfort taxi who hit my vehicle. He was unable to provide the full details of the taxi plate number. He only remembered is SH?1542X.

I wish to state that the driver who hit my vehicle did not leave any note that he or she hit onto my vehicle. I have in-car camera installed but I have not check the footage yet.

I am lodging this traffic report for assistance. That's all.



**SINGAPORE
POLICE FORCE**



T/20190207/2058

3 of 3

Report No T/20190207/2058

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 TAN CHING LIN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / HRT /

SI KALESWARI PALANI

Contact No.: 65476902

Signature Of Informant:

Date/Time:

07/02/2019 13:06

Classification Of Case:

Authentication Stamp

NP158

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Mar 2019 13:52 Edit Reg		18 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	SLQ3452C	Date of Loss:	04/02/2019 00:00 - :59 [18 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHA1542X	Policy No. (Claimant):							
		Excess:							
Repairer:	D's Graffiti Concepts (HQ) 25 Kaki bt Road 4 #06-26 Synergy @ KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ3452C
[SHA1542X]






































TP





















-

Feb 4 2019 12:00AM

[-]

D's Graffiti Concepts

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
2	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
3	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
4	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
5	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
6	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
7	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
8	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
9	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
10	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
11	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
12	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
13	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
14	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
15	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
16	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
17	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
18	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
19	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
20	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
21	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
22	22/03/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
23	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	22/03/19 09:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	22/03/19 09:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	22/03/19 09:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	22/03/19 09:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	22/03/19 09:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	22/03/19 09:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	22/03/19 09:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	22/03/19 09:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	22/03/19 09:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	22/03/19 09:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	22/03/19 08:44	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			
Remarks from India International Insurance Pte Ltd (HQ) Third party accident report has the wrong accident date. Accident should be on 04.02.19. -WH			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19003072/GCD3E2

Date: 22/03/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle
No : SLQ3452C

Insured Vehicle No : SHA1542X

Date of Loss: 04/02/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ3452C

Make & Model: HONDA HR-V, 1.5 DX CVT (A)

Engine No: L15B4532778

Reg. Date: 05/07/2017 (Man. Year: 2017)

Chassis No: JHMRU1810GX202778

Colour: White

Odometer: 15247 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/02/2019

Date Inspected: 19/02/2019 Inspected At:

D's Graffiti Concepts (HQ)
25 Kaki bt Road 4 #06-26 Synergy @ KB
Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Mar 2019)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ3452C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >