


CHUNNI MOTOR WORK
PTE LTD



Date : 18.02.19

To : Lonpac Insurance Bhd

No of Pages : 6

Re : Accident involving veh no: SHC 8179E & GBB 9075R Along
T-Junction of Choa Chu Kang North 7 / Choa Chu Kang Crescent
On 18.02.19

We refer to the above mention matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey at AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 65427162. Email : chunnimotor@gmail.com

Thank you for your kind assistance.

LONPAC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet			\$ 2,265.90
	Bonnet Hinge (LH/RH)		\$ 41.00	\$ 82.00
	Bonnet Lock			\$ 36.90
	Bonnet Insulator			\$ 196.50
	Bonnet Insulator Clips			\$ 8.40
	Radiator Grille			\$ 1,110.10
	Radiator Grille H Emblem			\$ 120.30
	Front Bumper Cover			\$ 1,052.20
	Front Bumper Sponge			\$ 99.20
	Front Bumper Reinforcement			\$ 402.10
	Front Bumper Bracket Top (RH)			\$ 22.40
	Front Bumper Bracket (RH)			\$ 24.60
	Headlamp Support Top Cover			\$ 222.60
	Headlamp Support Panel Assy			\$ 907.40
	Headlamp (LH/RH)		\$ 1,388.00	\$ 2,776.00
	Radiator			\$ 698.30
	Radiator Fan Blade,Cowling,Motor Assy			\$ 792.95
	Radiator Bracket (RH)			\$ 6.50
	Radiator Guard			\$ 20.00
	Horn Unit (RH)			\$ 73.80
	Front Fender (RH)			\$ 566.30
	Front Fender Apron Panel (RH)			\$ 637.00
	Front Fender Shield (RH)			\$ 174.90
	Aircon Condenser			\$ 927.50
	Aircon Suction & Liquid Hose			\$ 624.00
	Aircon Discharge Hose			\$ 162.60
	Aircon Compressor			\$ 2,578.00
	Inter Cooler			\$ 1,032.50
	Inter Cooler Mounting (2 PCS)			\$ 25.90
	SUB TOTAL			\$ 17,646.85
	LESS 20%			\$ 3,529.37
	DISCOUNTED TOTAL			\$ 14,117.48
	Labour Charge			
	Panel Beating			\$ 1,500.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Towing Charge			\$ 50.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 3,330.00
	ESTIMATE TOTAL			\$ 17,447.48

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

MCD610022264 / ComfortDolGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 18/02/2019 13:03
 SUBMITTED BY: Catherine Per May Jun

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/02/2019 13:03
Date Of Accident	18/02/2019 04:40
Exact Location Of Accident	CHOA CHU KANG NORTH 7 AND CHOA CHU KANG CRES
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8179E
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	WONG KOK WAI
NRIC No	S1627763J
Date Of Birth	18/12/1964
Occupation	OUTDOOR
Date Of Driving Pass	29/12/1984
Driving Experience	34 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97802148
Fax Number	
Contact Number	
Email Address	WONGKOKWAI726@YAHOO.COM.SG

Address 513 03-40 CHOA CHU KANG STREET 51
 Postcode 680513
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) Involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : -
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBB9075R
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver GUO CHUANG HONG
 NRIC/Passport Number G2025526P
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage REAR LEFT

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


CHUNNI MOTOR WORKS PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 18.02.2019@0845


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June Tan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18.02.2019 @ 0440HRS I was travelling along Choa Chu Kang North 7 T Junction of Chao Chu Kang Cresment with one male passenger onboard.

As I was travelling straight and suddenly Veh(B) GBB 9075R dashed out from my front while making a right turn out. My vehicle front right portion was damaged.

As the accident took place too fast I could not take evasive action to prevent the accident.

I have company video and photos at scene to support my claims .

No injury in this accident .


Veh(B) GBB 9075R MR Guo Chuang Hong G 2025526P


DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 18.02.2019@0845


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June Tan