

72001

REC. BY:

REF:

CS/FW19003095/GV03

Special Instruction:

Survivor:

Quodony

ASSIGNMENT (Office)

From Person:

Lionel fun

of

PWD

Date/Time: 18/2/19 @ 5:02pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 5018D

Insured:

at Workshop m/s

Torque 5

Tel:

91478841

8131 6518

of

No. 81 Cali Bkt Ave 4 #01-50

Policy No:

PNPV2018-00006213

Claim No:

1201900004704

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A.

17/02/2019

(Client's Record)

20/2/19

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

3:25pm @ 19/2/19

Person Contacted:

Stephene

Vehicle

IN OUT

Date/Time	Action/Instruction
	(✓) Estimate Requir agreed survey on 20/2/19 SLD 5018D - NA / INC19003095 / 24 DVA: 17/2/19
21/2/19	Revert via merimen
21/2/19	Rece approved from Lionel by merimen
21/2/19	Informed Stephaine c/A ex \$500 by email
1/3/19	Final fig \$ 3130 (Red 695, 1890) confirmed by email

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV
 To Inspect Vehicle No: _____
 at Workshop m/s Torque 5
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	
N/S	O/S

Bal. or Market Value: \$55k
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLD5d8D Yr Regn: 20 Jun 2016
 Type: ☒ M/Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or

Make: Toyota AX 10 c.c. 1496
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 70869 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: NRE1610014379

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 175/65 R15
 R: "

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
 TOYO / YOKO or

<u>Front</u>	<u>Rear</u>
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>20-02-19</u>

Survey held at W/S 5:30 pm

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 01 MAR 2019

1/3/2019

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 1/3 - typist

Report Format: meimen

Lump Sum / I.B.I: (\$) 3130 F

Days Of Repair: 4

Resurvey No. of Trip: 3

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS ☐ SI

☐ Photos

☐ Others

TOTAL

200
50
50 + 50 + 50
10
410

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Feb 2019 Sendback Est	18 Feb 2019 15:01 \$2,435.00	18 Feb 2019 17:02 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	ZACCHAEUS SIEW YONG PAU , ID: S7176796E, Tel: +6598796781, Email: NOEMAIL		
Vehicle Reg. No.:	SLD5018D	Date of Loss:	17/02/2019 17:00 - :59 [31 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900004704	Policy/Cover Note No.:	PNPV2018-00006213 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/02/2019]		
Driver/Custodian:	ZACCHAEUS SIEW YONG PAU (47 / Male), NRIC: S7176796E, Tel: +6598796781		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)

Search Tasks

Create New Task

Complete

No results.

View Received Message

This mail is associated with :

SLD5018D (1201900004704)

OD

Feb 17 2019 5:00PM

[ZACCHAEUS SIEW YONG PAU]

Torque 5 Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 22/02/2019 11:32 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$3545.00) - SLD5018D - Claim Handler: Lionel Tan

Approved:3545.00:Please provide photographs of damaged supplementary items.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Lionel Tan	Date: 22 Feb 2019

Preliminary Advice

Vehicle No	: SLD5018D	Accident Date	: 17/02/2019
Make	: TOYOTA AXIO	Policy No.	: PNPV2018-00006213
Assignment Date	: 18/02/2019	Excess	: S\$500.00
Date of Inspection	: 20/02/2019	Est. Duration of Repair	: 4.00
Inspection At	: TORQUE 5 PTE LTD (KAKI BUKIT) NO. 8 KAKI BUKIT AVE 4,, #01-50 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,825.00	(incl.supplementary \$1390.00)
Revised Amount	:S\$	3,545.00	(incl.supplementary \$1390.00)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	3,545.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$		
Pre-Accident Value	:S\$	55,000.00	
COE / PARF Rebate	:S\$	43,169.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	11,831.00	

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 21 February 2019 1:11 PM
To: SUR; assessment (assessment@torque5.com)
Subject: SLD 5018D-DOA: 17/2/2019 (FWD OD)

Dear Stephanie,

As instructed by our client , please proceed to repair the **insured vehicle SLD 5018D (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SLD5018D (1201900004704)

OD

Feb 17 2019 5:00PM

[ZACCHAEUS SIEW YONG PAU]

Torque 5 Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on **21/02/2019 12:10 PM.**

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$2265.00) - SLD5018D - Claim Handler: Lionel Tan

Approved:2265.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 21 Feb 2019

Preliminary Advice

Vehicle No	: SLD5018D	Accident Date	: 17/02/2019
Make	: TOYOTA AXIO	Policy No.	: PNPV2018-00006213
Assignment Date	: 18/02/2019	Excess	: S\$500.00
Date of Inspection	: 20/02/2019	Est. Duration of Repair	: 4.00
Inspection At	: TORQUE 5 PTE LTD (KAKI BUKIT) NO. 8 KAKI BUKIT AVE 4,, #01-50 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,435.00
Revised Amount	:S\$	2,265.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,265.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	43,169.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,831.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

MTOR19022103 / Torque 5 Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 18/02/2019 11:03
 SUBMITTED BY: Peach Ang Siew Hui

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 18/02/2019 11:03
 Date Of Accident 17/02/2019 17:30
 Exact Location Of Accident CTE TOWARDS PIE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLD5018D
Insured/Policyholder
 Name Of Registered Owner ZACCHAEUS SIEW YONG PAU
 NRIC No S7176796E
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-98796781
 Alternative Phone No Office-98796781

Vehicle Particulars

Manufacturer TOYOTA
 Model AXIO-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company FWD SINGAPORE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number PNPV2018-00006213
 Cover Note Number

Driver

Name of Driver ZACCHAEUS SIEW YONG PAU
 NRIC No S7176796E
 Date Of Birth 17/04/1971
 Occupation INDOOR
 Date Of Driving Pass 12/09/2003
 Driving Experience 15 YEARS AND 5 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-98796781

Fax Number
Contact Number OFFICE-98796781
Email Address NOEMAIL
Address 45 TAMPINES AVE 1 #03-11 S529763
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 4
Passenger 1 Name: : CHUA HUI KIAN
Gender: : Female
Passenger 2 Name: : SIEW HUI XIN
Gender: : Female
Passenger 3 Name: : SIEW QING AN
Gender: : Male

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GV1009X
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

Accident occurred on 17th Feb (\approx 5.30 pm), at CTE south bound exit to PIE (Changi).

It was raining heavily and I was behind a pick-up lorry driven by a foreign driver (Indian or Bangladeshi) from Ricco Engineering Pte Ltd. The driver braked all of a sudden but his brake light was not working. I tried to brake but could not stop in time and collided into the pick-up.

We exchange particulars (attached). The driver could not provide his driving license and I got his work permit instead (attached). I noted that the pick-up has 4 workers sitting in front as well as numerous others sitting at the pick-up section.



Sketch Plan #2

SKETCH PLAN

A sketch plan on graph paper. A vertical line is drawn. To the left of the line, there is a small box containing the letters A, B, and A from top to bottom. To the right of the line, the following text is written:
V.A) SLD508D
V.B) 6V1009X
CTE TWHS PIE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- refer to Attached -

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Sketch Plan #3

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated;
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6796E
Vehicle Details	
Vehicle No.:	SLD5018D
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	2NR8568349
Chassis No.:	NRE1610014379
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$15,086.00
Original Registration Date:	20 Jun 2016
First Registration Date:	20 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$5,086.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2026
PARF Rebate Amount:	\$3,814.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,694.00
COE Rebate Amount:	\$39,355.00
Total Rebate Amount:	\$43,169.00

The information contained herein is correct as at 21 Feb 2019

OK

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Torque 5 Pte Ltd (Co.Reg.No.201313221G)

No. 8 Kaki Bukit Ave 4., #01-50

Singapore 415875

Tel: 64524457 Fax: 64524584 Email: sam.chang@torque5.com

INSURER: **FWD Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SLD 5018 D
Policy No:	PNPV2018-00006213	Date of Loss:	17/02/2019
Vehicle Reg. No.:	SLD5018D	Driveable?	
Driver Age/Info:	47 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ZACCHAEUS SIEW YONG PAU	Contact No:	+6598796781
Driver:	ZACCHAEUS SIEW YONG PAU		

Make/Model:	TOYOTA AXIO, 1.5 (A)	Vehicle Reg. Date:	20/06/2016
Vehicle Colour:	BLACK		
Engine No:	2NR8568349	Chassis No:	NRE1610014379
Odometer:	0 KM		

Paint Type:
Total Loss?
Est. Duration of Repair
(day)

NO**5**

Description of Accident/Loss: REFER TO ATTACHMENT

Remarks: VEHICLE CURRENTLY IN WORKSHOP.. KINDLY MAKE NECESSARY ARRANGEMENT..

Present Location: TORQUE 5 PTE LTD (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	1,020.00
Miscellaneous Items	85.00
Labour	1,330.00
Paintwork Labour	0.00
Towing	0.00
	3825
Gross Total (S\$)	2,435.00
+ GST 7.00% (S\$)	170.45
Nett Amount (S\$)	2,605.45

This claim is handled by: STEPHANIE TEO WAN TING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Feb 2019)
Parts: 143 TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLD5018D)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET / <i>Bul</i>	0.00	0.00	*220.00 F
2	1		*RADIATOR GRILLE / <i>BR</i>	0.00	0.00	*160.00 F
3	1		*FRONT BUMPER / <i>BR</i>	0.00	0.00	*180.00 F
4	2		*FRONT BUMPER RETAINER (LH+RH) <i>X BR X NN</i>	0.00	0.00	*50.00 F
5	1		*FRONT BUMPER LOWER GRILLE / <i>BR</i>	0.00	0.00	*110.00 F
6	1		*HEAD LAMP (RH) / <i>CRA</i>	0.00	0.00	*300.00 F

F=Franchise part.

Total Parts (S\$)

1,020.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT BUMPER CLIP SET / AC	45.00
2	1	FRONT NUMBER PLATE & CASING / COA.	40.00
Sub Total (S\$)			85.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING & LIGHTING SYSTEM & FOCUS HEAD LAMP	New	20 40.00
2	TO PERFORM ANTI-RUST, UNDERCOATING ON AFFECTED AREAS	New	30.00
3	TO REPAIR, REPLACE & REALIGN DAMAGED AREAS	New	600 660.00
4	TO SPRAY PAINTING ON AFFECTED AREAS	New	500 600.00
Gross Labour Cost (S\$)			1,330.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

4 Days.

part by part


before paint photos.

Gmo Qiq

20/2/19.

Not Authorised.

Excess \$500.



(SUPPLEMENTARY)

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	SLD 5018 D
Policy No:	PNPV2018-00006213	Date of Loss:	17/02/2019
Vehicle Reg. No.:	SLD5018D	Driveable?	
Driver Age/Info:	47 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ZACCHAEUS SIEW YONG PAU	Contact No:	+6598796781
Driver:	ZACCHAEUS SIEW YONG PAU		

Make/Model:	TOYOTA AXIO, 1.5 (A)	Vehicle Reg. Date:	20/06/2016
Vehicle Colour:	Black		
Engine No:	2NR8568349	Chassis No:	NRE1610014379
Odometer:	0 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 5

Description of Accident/Loss REFER TO ATTACHMENT

Present Location: TORQUE 5 PTE LTD (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	880.00
Miscellaneous Items	310.00
Labour	200.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,390.00
+ GST 7.00% (S\$)	97.30
Nett Amount (S\$)	1,487.30
+ Previous Estimates (S\$)	2,605.45
Claim Total (S\$)	4,092.75

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Feb 2019)

Parts: 143 TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Torque 5 Pte Ltd/SLD5018D/21/02/2019 11:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Radiator / <i>CAF</i> 195	0.00	0.00	*285.00 F
2	1		*Condenser / <i>BT</i> 180	0.00	0.00	*375.00 F
3	1		*Condenser piping clips 2pcs X <i>MM</i>	0.00	0.00	*65.00 F
4	1		*Radiator top air guide / <i>RL</i>	0.00	0.00	*65.00 F
5	1		*Front support top panel / <i>BUC</i> 85	0.00	0.00	*90.00 F
Total Parts (S\$)						880.00

F=Franchise part.

Torque 5 Pte Ltd/SLD5018D/21/02/2019 11:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Canal
21/2/19