ASS. REC. BY:	REF: 033/11/9003099/Gcd	307 Special Instruction:	
Minen (Person): Gubril	ASSIGNMENT (Office)		19/2/19012:18pm
OD TP WS/TP RES/	OD RES / EVA / INV / MY / CS		
To Inspect Vehicle No: at Workshop m/s of	MTA Auto Solutions	Tel: 826 6	C 8234D C 6377
Policy No: Sum Insured:	25 Kaki Blet Rd A Syreogy Claim No:	401 74	·
Make of Veh: (Client's Record)	Excess:	D.O.A.	13/02/2019
CA / REV / REP. / RIDate/Time: 12-24pm		H.O.D. Endo	
Date/Time Action/Inst	ruction (x) Estimate		
SJL. SAC 8	22746-NA/INC19002636/r3 234D-MA/MC19002636/r3	Dur. 13	1.13/2/2019
	utle: 20/2/2019 @ 0622 PM		

AS	SSIGNMENT		(-202
Pake:	Veh No: _ <3(2274	6 Yr Regn: 15A	1011
From: Date:	Type: M.Cap/ M.Cycle / Bus / Van	/ I orry / Taxi / Prime Move	or J
Estimated Cost:	Truck / Trailer or	Long Hants Fillio more	45.50
OD THE WS I TP RES I OD RES I EVA I INV I MV	The second of th	1 v s .	1106
To Inspect Vehicle No:	Make: Toyota		496
at Workshop m/s MTA Auto Selution	S Colour Blue	A/C: Insured / Si	
of	Sp.Reading 314030	T/Radio: Insured / S	td/NI/NA
Insured:	Eng/No:		
Policy No.	C/No: NZEIY	16100576	
Claims No.	Gen. Cond: Good / Fair / Poor / Bu	ırnt	
Sum Insured: Excess:	Steering: Inorder / Jammed / Leak	ed / Burnt or	
(Client's Record)	Brake: In Ger / Jammed / Leak	red / Burnt or	
Make of Veh:	Modi: Nil / S/Rim / STD A/Rib	n or	
	Tyre Size: F: IS	5/60R15	
(Policy Condition)	Ř:		
	S DUN / EXNOVA / GY / FS / LI	ZA / MIC / OHTSU / PIR / S	SUMI/
repair at the time of inspection.	TOYO / YOKO or		
Bal. or Market Value:	Front	Rear	
	D/Del (*	R/Bal.	
To Thomas Transfer to the second seco		L/Bal.	m
(0	D.O.A.	- 5	m
Est. Repairs:		. 11 D.O.I. 19-0	-
Lum Sum: % 3 Val.: Yes or No		N/S	5 2/3
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Reas / C	DIS / N/S / U/C / Roofto	p or
Vehicle: IN / C	250/11		
	The U/C / Chassis frame / E	Body Structure affected di	Je to collisi
Date / Time Action / Instruction			
\$ 2000 - \$4000.			
		0	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:		
: Final Report	Resurvey No. of Trip:	Survey Fee:	120
Date/Time, File Return to?	instantial transit title	Transportation	100
2) Add	Fee: Site Insp (\$)S+RSSI	
	promote the second) Photos	
	: Interview (\$	J. EHMINE	
Report Format: PRS.	: Tech, Invs (\$) Others	10

Nivitha (LKK Auto)

From:

Motor Claim - III <motorclaim@iii.com.sg>

Sent:

Tuesday, 19 February 2019 12:15 PM

To:

Huiling; 'sur@lkkauto.com'; admin-d@lkkauto.com

Cc:

Pooi Chin Han Daniel

Subject:

RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJL2274G (Accident involving

SJL2274G and SHC8234D on 13.02.2019)

Attachments:

shc8234d_20190219101148.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO.

SJL2274G

III INSURED VEHICLE NO.

SHC8234D

DATE OF LOSS

13.02.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

:

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANT to conduct the pre-repair survey.

This claim is handled by Daniel.

Please let us have your client's <u>accident report and repair estimate</u> for our appointed surveyor to conclude his report.

**We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.

**Surveyor kindly upload this assignment to Merimen.

Thank You.

Best Regards, Gabriel Wee



64 Cecil Street; #05 - IOB Building Singapore 049711 Tel: 6347 6100, Ext – 248

From: Huiling [mailto:riaz@justice.com.sg]

Sent: 19 February, 2019 10:26 AM

To: Motor Claim - III < motorclaim@iii.com.sg>

Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJL2274G (Accident involving SJL2274G and SHC8234D on

13.02.2019)

WITHOUT PREJUDICE

Dear sirs,

We refer to your below email.

On behalf of our client, we disagree with your appointment and nominates as the surveyor.

Please choose one out of the surveyor from the list below:-

- 1. Chang Fuh Keong, Dave
- Ho Joo Loong, Danny
- Dennis Yap
- Michael Yap
- 5. Lee Kok Weng
- 6. Winson Goh
- Ong Ah Keng, Kent
- Ong Poh Meng
- 9. Seah Kwang Boon
- Thor Teck Soon, David

Kindly revert within the allotted time pursuant to NIMA protocol.

Thanks & Best Regards,

RIAZ LLC

Huiling

133 NEW BRIDGE ROAD # 09-09 CHINATOWN POINT SINGAPORE 059413

TEL: 6534-0110 FAX: 6534-0220

Disclaimer: This message is privileged and confidential and is intended solely for the named recipient. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is strictly prohibited. If this e-mail has reached you in error, please delete the e-mail immediately and inform us of the error by sending an e-mail to riaz@justice.com.sg. though internet communications cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost or infected with viruses, we have scanned this message to minimise the possibility of corruption.

From: Motor Claim - III < motorclaim@iii.com.sg > Sent: Tuesday, 19 February 2019 10:19 AM

To: Huiling <riaz@justice.com.sg>

Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJL2274G (Accident involving SJL2274G and SHC8234D on 13.02.2019)

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We proprose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards, Gabriel Wee



64 Cecil Street; #05 - IOB Building Singapore 049711

Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling

and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

ACRA NUMBER - 200911678H

OST REGISTRATION NUMBER : 200011078H

18/02/2019

Our Ref: SJL 2274G (V) MTA AUTO


Your Ref: SHC 8234D

TO: Ind

India International Insurance Pte Ltd

64 Cecil Street #04/#05 IOB Building Singapore 049711

Attn: Motor Claims Department



NOTICE OF ACCIDENT

Dear Sir

We are instructed by our client to *notify* you of a road traffic accident on <u>13 February 2019</u> at about <u>1140</u> hours along <u>Mt Elizabeth towards Orchard Road</u> involving our client's vehicle registration number <u>SJL 2274G</u> and vehicle registration number <u>SHC 8234D</u> driven by you or your authorized driver at the material time. A copy of Singapore accident statement / traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop

MTA AUTO SOLUTIONS PTE LTD

Address

25 Kaki Bukit Road 4 Synergy @ KB #07-47

Singapore 417800

Telephone no.

8265 8352 AH WAI

Fax No.: 6384 7231

8266 6377 CARMEN

Please let us hear from you by the stipulated time.

Yours faithfully

Kluz

encs

cc. Client

FOR SURVEYOR

Please initial here after completion of prerepair inspection. Thank you.

Appointed surveyor (Name & signature)

Date & time of inspection

133 NEW BRIDGE ROAD #09-09 CHINATOWN POINT SINGAPORE 059413
TEL: 65340110 FAX: 65340220 EMAIL: RIAZ@JUSTICE.COM.5G
(PLEASE NOTE THAT OUR FAX IS NOT FOR SERVICE OF COURT DOCUMENTS)

WWW.INJURYCLAIMS.5G



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	1256W
/ehicle Details /ehicle No.:	CH 2274C
	SJL2274G
/ehicle to be Exported:	No
ntended Deregistration Date:	20 Feb 2019
/ehicle Make:	TOYOTA
/ehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Blue
Manufacturing Year:	2008
ngine No.:	1NZD226060
Chassis No.:	NZE1416100576
Aaximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$13,589.00
Original Registration Date:	19 Nov 2008
irst Registration Date:	19 Nov 2008
ransfer Count:	2
actual ARF Paid:	\$13,589.00
ntended PARF Rebate Details	
ARF Eligibility:	Forfeited
ARF Eligibility Expiry Date:	-
ARF Rebate Amount:	\$0.00
ntended COE Rebate Details	
OE Expiry Date:	18 Nov 2023
OE Category:	A - Car (1600cc & below)
OE Period(Years):	5
QP Paid:	\$14,835.00
OE Rebate Amount:	\$14,082.00
otal Rebate Amount:	\$14,082.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Feb 2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	13/02/2019 14:59
Date Of Accident	13/02/2019 11:40
Exact Location Of Accident	MOUNT ELIZABETH TWDS ORCHARD ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJL2274G
Insured/Policyholder	
Name Of Registered Owner	EVE TRANSPORT
Co Reg No	53361256W
Email Address	MAX9452002@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-90607158
Vehicle Particulars	
Manufacturer	TOYOTA
Model	AXIO
Exact Purpose for which vehicle was being used at time of accident	GRAB
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091384730-01
Cover Note Number	
Driver	
Name of Driver	ADAM BIN ABDUL RAHIM
NRIC No	S1250664C
Date Of Birth	27/11/1957
Occupation	OUTDOOR
Date Of Driving Pass	07/07/1980
Driving Experience	38 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90607158
Fax Number	

MAX9452002@GMAIL.COM

BLK 520 WOODLANDS DRIVE 4 Address

#02-301

730520 Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: UNKNOWN

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

MY VEH WAS STATIONARY ALONG MOUNT ELIZABETH DUE TO THE TRAFFIC CONGESTED AHEAD.SUDDENLY VEH(B)BEARING REG NO SHC8234D CAME FROM BEHIND AND HIT ONTO MY REAR PORTION OF MY VEH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FRONT ONLY

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

SHC8234D

Details Of Properties

TAXI

Vehicle Category Name of Driver

NRIC/Passport Number

TAY HOCK PENG JERRY

S6902791A

Contact Number

87509925

Address

Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

EVE Transport

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: NRIC/FIN No :

Accident Sketch Plan

SKETCH PLAN		
51122749	MOUNT ELIZA	CHIE RO
SHC8234D		
	ब । च । ब	ARE 4
DESCRIBE CIRCUMSTANCES	OF THE ACCIDENT	
Pls refu	to the statement	į.
,		
DECLARATION		
I/We declare the foregoing partie E Transport	tulars are true in every respect.	Sym 13/02/19
Policyholder's Signature	Driver's Signature (If driver is not the policyholder)	Reporting Centre Personnel's Signature

Date & Time:

NRIC/FIN No.:

Page 1 of 1 Merimen e-Claims

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRAC	KING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitte	ed Ins Auth'ed	Status	
Main	27 Feb 2019 09:52 Edit Reg		19 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending f Report Cancel Ca	or Survey
	Main	Refe	erence	Claim Det	ails	Documents	\Box	Show All
CLAIM SL	JBFOLDER DET	AILS			[Created	d by adjuster]		
Insured:	-, Co. Reg.	. No.: -			11:00			
Main Claimant:								
Vehicle Reg	9. SJL22740	SJL2274G				s: 13/02/2019 00:00 - :59 [122 Months and 25 Days From LTA Reg Date (
Claim Type	aim Type: TP			Policy/C Note No				
Vehicle Reg No. (Insured):	SHC8234D		Policy N (Claima					
				Excess:				
Repairer:	Mta Auto S	olutions Pte Ltd	(HQ) 25 KAKI BUKI	T ROAD 4, #07-47	SYNERGY, 4178	B00 Kaki Bukit - Tel:		
Handling Insurer:	India Inter	national Insuran	ce Pte Ltd (HQ) -	Tel: 63476100	[Handled by Poc	oi Chin Han Daniel]		
Adjuster:	LKK Auto C	onsultants Pte L	td (HQ) - Tel: 6256	5-3561 [Handled	by XING GUO	QIANG] [Final F	Rpt due 28/0	2/2019]
ASSOCIA	TED MAIL REC	EIVED				View	All Compos	e Case Mail
There are i	no mail for this c	ase.						
ALL ASS	OCIATED TASK	ß∃			View All	Search Tasks Cre	ate New Task	Complete
Due Dat		Type Task G	roup Subject	Handler A	ssigned By	Completed On	Created Or	Done?

Claim Documents

*SJL2274G [SHC8234D] TP

Feb 13 2019 12:00AM [-] Mta Auto Solutions Pte Ltd

Pho	otos/Images		3 per page	V	~
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thur	mbnail	
1	23/02/19 15:29	General View	1 Loa	d JPG	∀
2	23/02/19 15:29	General View	1 Loa	d JPG	✓
3	23/02/19 15:29	General View	1 Loa	d JPG	V
4	23/02/19 15:29	General View	1 Loa	d JPG	V
5	23/02/19 15:29	General View	1 Loa	d JPG	V
6	23/02/19 15:29	General View	1 Loa	d JPG	✓
7	23/02/19 15:29	General View	1 Loa	d JPG	✓
8	23/02/19 15:29	General View	1 Loa	d JPG	V
9	23/02/19 15:29	General View	1 Loa	d JPG	~
10	23/02/19 15:29	General View	1 Loa	d JPG	V
11	23/02/19 15:29	General View	1 Loa	d JPG	✓
12	23/02/19 15:29	General View	1 Loa	d JPG	V
13	23/02/19 15:29	General View	1 Loa	d JPG	✓
14	23/02/19 15:29	General View	1 Loa	d JPG	~
15	23/02/19 15:29	General View	1 Loa	d JPG	V
16	23/02/19 15:29	General View	1 Loa	d JPG	V
17	23/02/19 15:29	General View	1 Loa	d JPG	V
18	23/02/19 15:29	General View	1 Loa	d JPG	V
19	23/02/19 15:29	General View	1 Loa	d JPG	~
20	23/02/19 15:29	General View	1 Loa	d JPG	V
21	23/02/19 15:29	General View	1 Loa	d JPG	✓
22	23/02/19 15:29	General View	1 Loa	d JPG	V
23	23/02/19 15:29	General View	1 Loa	d JPG	V
24	23/02/19 15:29	General View	1 Loa	d JPG	~
25	23/02/19 15:29	General View	1 Loa	d JPG	V
26	23/02/19 15:29	General View	1 Loa	d JPG	~
27	23/02/19 15:29	General View	1 Loa	d JPG	V
28	23/02/19 15:29	General View	1 Loa	d JPG	V
29	23/02/19 15:29	General View	1 Loa	d JPG	V
30	23/02/19 15:29	General View	1 Loa	d JPG	V
31	23/02/19 15:29	General View	1 Loa	d JPG	V
32	23/02/19 15:29	General View	1 Loa	d JPG	V
33	23/02/19 15:29	General View	1 Loa	d JPG	V
34	23/02/19 15:29	General View	1 Loa	d JPG	V
35	23/02/19 15:29	General View	1 Loa	d JPG	V
36	23/02/19 15:29	Photographs of Damaged Parts	1 Loa	d JPG	V
37	23/02/19 15:29	Photographs of Damaged Parts	① Loa	d JPG	V

Merimen e-Claims Page 2 of 2

Pho	otos/Images		3 per j	page 🗸	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	23/02/19 15:29	Photographs of Damaged Parts	Ð	Load JPG	✓
39	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	✓
40	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	▼
41	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	✓
42	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	✓
43	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	✓
44	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	V
45	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	~
46	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	V
47	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	✓
48	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	✓
49	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	V
50	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	~
51	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	V
52	23/02/19 15:29	Photographs of Damaged Parts	0	Load JPG	✓
Doc	cumentation		1 per	page 🔻	V
No.	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	20/02/19 08:38	Singapore Accident Statement	O	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			V
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/III19003099/GCD3E2

Date:

27/02/2019

REFERENCE

Date of Loss:

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle

SJL2274G

Insured Vehicle No:

No

SHC8234D

No:

13/02/2019

Nature of Claim:

TP

Claim No:

N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJL2274G

Make & Model:

TOYOTA COROLLA, 1.5 X AXIO (A) 19/11/2008 (Man. Year: 2008)

Engine No: Chassis No: Odometer:

1NZD226060 NZE1416100576

Reg. Date: Colour:

Blue

Engine Capacity: Market Value/New Car Price:

1496 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

314030 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

195/60 R15

Rear Tyre Size:

195/60 R15

Front Left Side:

Bridgestone 5 mm

Rear Left Side:

Bridgestone 5 mm

Front Right Side:

Bridgestone 5 mm

Rear Right Side:

Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

19/02/2019

Date Inspected:

19/02/2019 Inspected At:

Mta Auto Solutions Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #07-47

SYNERGY

Singapore 417800

Estimated Period of Repair:

0.0 days

Adjuster: XING GUO QIANG

CELINE FONG Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
- THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Feb 2019)

Parts: 143 TOYOTA COROLLA 1.5 X AXIO (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJL2274G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >