

ASSIGNMENT (Office)

REF: CS/FCT19003114/ R13d3²²

Special Instruction

Surveyor

CWS

Eileen Lee

of

FCT

Date/Time: 4:16pm @ 18/2/19

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTCS

To Inspect Vehicle No:

S/Q 3863Z

Insured

SH 6088R

at Workshop m/s

Comfort Dellgro
45 pendon Road

Tel:

68676919

of

Policy No:

Claim No:

D19061115MFSH

Sum Insured

Excess:

Make of Veh:

D.O.A.

12/02/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS 1DS

20/2/19 @ 2pm

H.O.D. Endorsement

Date/Time:

2:19pm @ 19/01/19

Person Contacted

Mr. Chen

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	S/Q 3863Z - (C3/ASM19002816/Kha3 D.O.A: 12/2/2019
	SH 6088R - CS/FCT18005997/Kvbn2 D.O.A: 28/3/18
22/02/19 @ 16:41 p.m.	revised PA to Eileen via email.

Pan

2296B
COPY: 2019/may
2009 may

SJQ 3863Z

REG / OD / IS / VA / INV / MV

Vehicle No: SJQ 3863Z

Contract: 1
Pan

FCU

Policy No.

Claim No.

Sum Insured: Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: 14K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / FR Seen: Consistent? : Yes or No

Est. Repair: days Res: Yes or No

Turn Over: % 3 Val: Yes or No

CA / REV / REP: / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Engine: SJQ 3863Z
Type: M/C / 4 Cycle / Bus / Van / Lorry / Taxi / Power Mower /

Truck / Trailer :

Make: Honda PRECO / SGA 1496

Colour: Red A/C Insured / S/D / N / NA

Sp Reading: 132038 O/Radio: Insured / S/D / N / NA

Engine:

C/Ho: QB31021692

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 195/60R15
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or DAYTON

Front

Rear

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A: 12/02/19 D.O.L: 20/02/19

Survey held at: Comfort Pan

Des. of Damage: C / R / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

repair limit 3K. Vehicle is uneconomical to repair
refer to email

Submit Total loss as uneconomical for repair.

MV - \$1412

LTA - \$10,821.00

NCH - \$3,179.00

RECEIVED 26 FEB 2019

End Time: 1st Pass by: ☐ : Prelim. Report

26/02/19 ☒ : Final Report

Typ. 34
End Time: 2nd Return by:

Days Of Repair: 14

Resurvey No. of Trip: /

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp: \$

☐ Interview: \$

☐ Tech Insp: \$

☐ Well-land: \$

24 Hrs: \$

5 Hrs: \$

3 Hrs: \$

1 Hr: \$

Report Format: Total Loss

Lump Sum / L.B. / C.S.

2x15=30
30+170=200

200
50
73
323

MOTOR SURVEY ASSIGNMENT

Date	14-02-2019	Our Ref No. D19001115MFSH
Accident Date	12-02-2019	Claim Type. Third Party
Insured Vehicle	SH6088R	Third Party Vehicle. SJQ3863Z
Survey Location	45 PANDAN ROAD	
Contact Person.	CHEN CHEE KIONG	
Contact No.	68676919/ 68676919	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	COMFORTDELGRO ENGINEERING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Rasul (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Friday, 22 February, 2019 9:42 AM
To: 'CDGE Pandan Private Cars Crash Repair Counter'
Subject: SJQ 3863Z DOA : 12/02/19

Hi Wong,

As spoken the repair limit for this vehicle is 3K. Due to repair cost is more than the repair limit, we as the opinion treat this vehicle as uneconomical to repair

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 22 February 2019 4:41 PM
To: 'Eileen Lee'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19001115MFSH/1
Attachments: SJQ 3863Z - Preli Advise .pdf

Dear Eileen,

Enclosed preliminary revised of vehicle SJQ 3863Z
Date of survey: 20/02/2019

Vehicle recommended Total Loss.

We will submit our report accordingly.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 19 February 2019 2:22 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001115MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 18 February 2019 4:16 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001115MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001115MFSH

Date: 22 February 2019

Our Ref: CS/FCI19003114/R1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJQ 3863Z .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/02/2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 12,056.24</u> .
Revised Estimate Amount	: <u>S\$ 7,834.16</u> .
"Check" Items Amount	: <u>S\$ 1,964.16</u> .
Total	: <u>S\$ 9,798.32</u> .
Market Value	: <u>S\$ 14,000.00</u> .
LTA Reimbursement Value	: <u>S\$ 10,821.00</u> .
Nett Value	: <u>S\$ 3,179.00</u> .

Description of Damage:

The vehicle sustained damages at the rear & front portion .



Comments/ Present Status:

Damages Consistent.

Vehicle recommended total loss due to uneconomical to repair.

Repair days: 14 days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2019 15:20
Date Of Accident	12/02/2019 17:30
Exact Location Of Accident	ECP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ3863Z
Insured/Policyholder	
Name Of Registered Owner	ONG KAI YONG
NRIC No	S7932296B
Email Address	KAI.YONG.ONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97939880
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	HONDA
Model	FREED-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA242420/1
Cover Note Number	

Driver

Name of Driver	ONG KAI YONG
NRIC No	S7932296B
Date Of Birth	02/11/1979
Occupation	INDOOR
Date Of Driving Pass	05/05/2000
Driving Experience	18 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97939880
Fax Number	
Contact Number	OFFICE-NOPHONE
EEmail Address	KAI.YONG.ONG@GMAIL.COM

Vehicle Make/Model/Colour	HYUNDAI I40
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	KWAN KAR WAI
NRIC/Passport Number	S1736980F
Contact Number	
Address	BLK 7 UPPER ALJUNIED LANE #14-67
Postcode	360007
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan #2

EEP



YES - THIS IS AN INSTANCE OF THE ACCIDENT

I am travelling along EEP, lane 3; the speed is around 70-80 ~~Vehicle A~~

I am supposed to pick up wife from church around 5:45-6 pm. Vehicle A did a emergency brake, I saw the brake lights of the vehicle A blinking and I noticed he is braking very hard. I immediately step on my brakes and the abs of my car did come in. I was able to brake in time to come to a complete stop. My car is vehicle (B) as per above.

Just a second later vehicle C knocked my car (B) from behind. Even with my legs on the brake the impact from behind pushed my car forward to ram into vehicle A.

IMPORTANT NOTE

Under General Conditions - Contract of Carriage, if the Motor Vehicle, you have to receive within 24 days of a notice -
- insurance, if damage otherwise or not by law under the policy. Please check your policy for more information.

DECLARATION

I hereby declare that the above is true and correct.

[Signature] *[Signature]*

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

CHARTERED BY THE CHARTERED FLEET LTD

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2296B

Vehicle Details

Vehicle No.: SJQ3863Z
Vehicle to be Exported: Yes
Intended Deregistration Date: 20 Feb 2019
Vehicle Make: HONDA
Vehicle Model: FREED 1.5G A
Primary Colour: Purple
Manufacturing Year: 2008
Engine No.: L15A2330059
Chassis No.: GB31029692
Maximum Power Output: 87.0 kW (116 bhp)
Open Market Value: \$21,324.00
Original Registration Date: 07 May 2009
First Registration Date: 07 May 2009
Transfer Count: 2
Actual ARF Paid: \$21,324.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 06 May 2019
PARF Rebate Amount: \$10,662.00

Intended COE Rebate Details

COE Expiry Date: 06 May 2019
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$7,789.00
COE Rebate Amount: \$159.00
Total Rebate Amount: \$10,821.00

The information contained herein is correct as at 20 Feb 2019

OK

14,000
10,821

3,179
//

- Crazy weather in Singapore ?
- 2019 Toyota RAV4
- Girl who joined ISIS group in Syria to lose UK citizen,,

honda freed

Price Range ▾

Depreciation ▾

2009 ▾

Vehicle Type ▾



Advanced Search

Home » Used Cars » Autolynx Pte Ltd » Honda Freed 1.5A G (New 5-yr COE)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Mentco

70%OFF

Free Shipping



Bon

Honda Freed 1.5A G (New 5-yr COE)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$34,800	?
Depreciation	\$6,960 /yr	?
Reg Date	15-Apr-2009 (5yrs COE left)	?
Manufactured	2008	?
Mileage	138,000 km (14k /yr)	?
Transmission	Auto	?
Engine Cap	1,496 cc	?
Road Tax	\$682 /yr	?
Power	87.0 kW (116 bhp) View specs of the Honda Freed (2009-2010)	?
Curb Weight	1,310 kg	?
Features	Fuel Efficiency And Yet Powerful 1.5L I-Vtec Engine, Smooth CVT Transmission, 2 x Airbags, ABS, Auto Digital Aircon.	?
Accessories	Leather Seats, Sports Rims, DVD Audio System, Reverse Camera/Sensors, Alarm And Remote, Side Mirrors Signal Indicators.	?
Description	Consignment Unit In Excellent Condition For Coe Renewal. Original Paintwork. Well Kept & Regularly Serviced. High Loan And Trade In Welcome. Call Now For Viewing!	?
COE	-	?
OMV	\$19,997	?
ARF	\$19,997	?
No. of Owners	1	?
Type of Veh	MPV	?
Category	COE Car, Premium Ad Car	?
Availability	Available	PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Posted on: 20-Feb-2019 | Last Updated on: 20-Feb-2019

Tags: Honda Freed, honda freed, 2009 Honda Freed, 2009 honda freed, Honda, Freed, freed, Used Honda

Upfront Payment

Interest Financial info

Transfer Fee	\$25	?
Down Payment	\$10,440 (change)	Maximum 70% Loan ?
1st Instalment	\$482	?
Total Upfront Payment	\$10,947 (excluding insurance)	?

* 70% loan at 3.75% interest rate, Check with seller for exact figure.



Seller Information

Company	Autolynx Pte Ltd • dealer's pricelist • 21 vech sold 11 vech available	
Address	265 Serangoon Central Drive #02-269 Search cars nearby this location	
Office No	62808291	
Contact Person(s)	Jason Lau	96883010
	Ben	81892386
	Chris	82531131

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Compare

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ☐ Own Damage
☒ 3rd Party
☐ Windscreen

Vehicle No. : **SJQ3863Z**
Make & Model : **HONDA / FREED 1.5G A**
Year of Manufacture : **2008**
Chassis No. : **GB31029692**
Engine No. : **L15A2330059**
Policy No. :
Time of Accident : **17:30**

Ins Company : **Ms first**

Excess :

Date of Accident : **12/02/2019**

Suggested Days of Repair :

In-house Vehicle Assessor

Repair Estimates

Name : **WONG CHEE WEI / CK**

Signature :

Contact No : **68676919**

Parts (a) List Price Items **\$8,407.80**

LESS 20 % **\$(1,681.56)**

(b) Nett Price Items

Less %

(c) Special Nett Items **\$190.00**

Total Parts Cost (Appendix A) **\$6,916.24**

Labour (Appendix B) **\$5,140.00**

Total Repair Cost **\$12,056.24**

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : **Rasul - Hp 90010018**

Company : **LKL 6256 3561**

Survey conducted on : **20/02/19** at **1546**

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : **14** day(s)

(c) Resurvey **after repair** : ☒ Required ☐ Not Required

(d) Excess : \$

(e) Signature of surveyor : **Rasul** Date: **20/02/19**

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandna Road S (609286)

Tel: 68676919 Fax: 62626950

Appendix A

Spare Parts

Vehicle No. : **SJQ3863Z** Submit By : **WONG CHEE WEI / CK**
 Make & Model : **HONDA FREED 1.5G A** Year Manufacture : **2008**
 Chassis No. : **GB31029692** Engine No. : **L15A2330059**
TP
S/Order : **_____**

S/No.	Part Description	Qty	Cost Price	Nett Price	List Price	S- Nett Price
1	FRONT BUMPER <i>DE</i>	1			\$324.00	
2	FRONT BUMPER REINFORCEMENT <i>BA</i>	1			\$297.00	
3	FRONT BUMPER SPONGE <i>?</i>	1			NA	
4	FRONT GRILLE <i>CRA</i>	1			\$270.00	
5	FRONT BUMPER LHS TOWING CAP <i>MIS</i>	1			\$23.40	
6	FRONT BUMPER LHS BRACKET <i>neu</i>	1			\$18.00	
7	FRONT BUMPER RHS BRACKET <i>neu</i>	1			\$18.00	
8	FRONT LHS HEADLAMP <i>CRA</i>	1			\$612.00	
9	FRONT BONNET <i>BA</i>	1			\$504.00	
10	FRONT BONNET LHS HINGE <i>?</i>	1			\$50.40	
11	FRONT BONNET RHS HINGE <i>?</i>	1			\$50.40	
12	FRONT LHS FENDER <i>BA</i>	1			\$630.00	
13	FRONT LHS FENDER LINER <i>X</i>	1			\$122.40	
14	FRONT FENDER LINER CLIP <i>neu</i>	10			\$18.00	
15	REAR TAIL GATE <i>BA</i>	1			\$1,224.00	
16	REAR WINDSCREEN MOULDING <i>neu</i>	4			\$108.00	
17	REAR BUMPER <i>DE</i>	1			\$324.00	
18	REAR LHS BUMPER BRACKET <i>neu</i>	1			\$21.60	
19	REAR RHS BUMPER BRACKET <i>neu</i>	1			\$21.60	
20	REAR TAIL LAMP RHS <i>CRA</i>	1			\$252.00	
21	REAR TAIL LAMP LHS <i>CRA</i>	1			\$252.00	
22	REAR TAIL GATE CENTER MOULDING (NUMBER PLATE LAMP) <i>CRA</i>	1			\$234.00	
23	REAR NUMBER PLATE LAMP <i>neu</i>	1			\$45.00	
24	REAR BUMPER TOWING CAP <i>DE</i>	1			\$21.60	
25	REAR END PANEL <i>BA</i>	1			\$342.00	
26	REAR TAIL GATE INNER TRIM <i>?</i>	1			\$189.00	
27	REAR REVERSE SENSOR <i>neu</i>	2			\$180.00	
28	REAR HONDA LOGO <i>neu</i>	1			\$32.40	
29	FREED LOGO <i>neu</i>	1			\$57.60	
30	REAR END PANEL TRIM <i>?</i>	1			\$68.40	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SJQ3863Z**
 Make & Model : **HONDA FREED 1.5G A**
 Chassis No. : **GB31029692**

Submit By : **WONG CHEE WEI / CK**
 Year Manufacture : **2008**
 Engine No. : **R18A14016759**

Pages 2

S/No.	Part Description	Qty	Cost Price	Nett Price	List Price	S- Nett Price
31	REAR END PANEL FLOOR TRIM ?	1			NA	
32	FRONT RHS HEADLAMP ?	1			\$612.00	
33	WASHER TANK ?	1			\$45.00	
34	A/C CONDERSER ?	1			\$810.00	
35	RADIATOR ?	1			\$630.00	
36	WINDSCREEN SEAALNT <i>ne /</i>	2				\$40.00
37	FRONT NUMBER PLATE <i>CR /</i>	1				\$35.00
38	REAR NUMBER PLATE <i>SCR /</i>	1				\$35.00
39	BODY SEALANT <i>ne /</i>	1				\$80.00
40						
41						
42						
43						
44						
45						
46						
47						
48						
49						
50						
51						
52						
53						
54						
55						
56						
57						
58						
59						
60						
61						
62						
63						
64						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Appendix B

Tel: 68676919 Fax: 62626950,68676903

Vehicle No. : **SJQ3863Z**
Make & Model : HONDA

Year of Manufacture 2008

[illegible]