

22/03/2002

ASS. REC. BY:

REF:

03/ASM19063120/Gcd3et

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

of

ASMC(AA)

Date/Time:

19/2/19 @ 2.18pm

Estimated Cost:

Bill to:

OD

TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 2420P

Insured:

SKP5771K

at Workshop m/s

Hiap Tek Automobile

Tel:

96601347

of

160 Sin Ming Drive # 05-17

Policy No:

Claim No:

89MOIEGU

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17/02/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

cup

20/2/19

H.O.D. Endorsement:

Date/Time:

3.46pm @ 19/2/19

Person Contacted:

Mr. Ong

Vehicle

IN/OUT

Date/Time

Action/Instruction

(X)

Estimate

agreed

Smy on

20/2/19

SJS 2420P-NA/EQT11018461/wl

DOA: 9/9/11

SKP5771K-X

Diamond: 21/2/2019

XKL

REF: ASM(CAXA)

00236

(C-2019)

20/2/19

SJS2420P

04 Aug 2009

Type

Date

Veh No

To From

Estimated Cost

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

On (TP) / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No.

SJS2420P

Make

Honda Fit

C.C. 1339

at Workshop with

Hiap Lck

Colour

Grey

A/C

Insured / Std / NI / NA

at

160 Sin Ming Drive #05-17

Sp/Reading

334/61

I/Radio: Insured / Std / NI / NA

Insured

Eng/No

Policy No

C/No

GEG/205623

Claims No

Gen Cond: Good / Fair / Poor / Burnt

Sum Insured

Excess

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh

Mod: M / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size

F:

175/70R14

R:

11

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value

\$11K.

Front

Rear

IDAC Accident Report

Consistent? Yes or No

R/Bal.

6 mm

R/Bal.

6 mm

GIA / PR Seen

Consistent? Yes or No

L/Bal.

6 mm

L/Bal.

6 mm

Est. Repair:

8

days

Res.: Yes or No

D.O.A.

D.O.I

20-02-19

Lump Sum:

20

%

3 Val.: Yes or No

Survey held at

w/s

upm

CA / REV / REP. / 24 HRS up

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$5000 - \$6000

Date/Time: File Pass to?

☐

: Preli. Report

Days Of Repair:

8

B

☐

: Final Report

Resurvey No. of Trip:

1

Survey Fee:

Date/Time: File Return to?

Transportation:

B

Add Fee:

☐

Site Insp (\$

) : () : ()

☐

Interview (\$

) : () : ()

☐

Tech Insp (\$

) : () : ()

☐

Weekend (\$

) : () : ()

Report Format

PRS

Lump Sum / L.B. (\$)

100
100



Service Request Details

Claim

S9M01E6U

Reference

CS3/ASM19003120/d3 

Loss Date

February 17, 2019

Report Date

Feb 18, 2019 2:50:00 PM

Request Date

February 19, 2019

Due Date

February 19, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pre-Repair Survey

Actions

Next Step

Finish the work

Complete Work

More ▾

Vehicle Information

Incident Vehicle Registration #

SJS2420P

Model

FIT

Service Address

...

Primary Contact/Insured

WONG WEE KIANG (YUAN WEIQIANG)
61 SUNSET WAY, 02-03, 597086, Singapore
97342011
MD_DSGN@YAHOO.COM.SG

Claim Handler

WONG Wee Fu
6568804888
weefu.wong@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 19 February 2019 2:18 PM
To: assignments
Subject: FW: (URGENT) ARRANGE FOR PRE-REPAIR INSPECTION Our Ref: SJS2420P, Your Ref: SKP5771K

Hi Nivitha

TP smart. PRI case.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Christine <christineloh@rlc.com.sg>
Sent: Monday, 18 February, 2019 1:37 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: hiaplek@hotmail.com
Subject: (URGENT) ARRANGE FOR PRE-REPAIR INSPECTION Our Ref: SJS2420P, Your Ref: SKP5771K

Our Ref. : SJS2420P

Writer : Raymond Lam

Your : SKP5771K

Direct : christineloh@rlc.com.sg

Ref.

Email

18 February 2019

URGENT

M/s AXA Insurance Singapore Pte Ltd WITHOUT PREJUDICE

8 Shenton Way By Email only

#27-01 AXA Tower

Singapore 068811

Attention: Motor Claims Department

Dear Sir,

TRAFFIC ACCIDENT ON 17 FEBRUARY 2019 ALONG PIE TOWARDS TUAS NEAR EXIT 12 KPE (ECP) INVOLVING M/CAR NO. SJS2420P, M/CAR NO. SKP5771K, M/CAR NO. SDS31M, M/CAR NO. SGP9894K AND M/CAR NO. SJT1285P AT ABOUT 1200HRS

We act for **ENG LIM KEE** who has appointed the under mentioned workshop to repair the motor vehicle no. **SJS2420P**.

Please contact the garage directly to arrange for pre-repair inspection at:-

M/s Hiap Lek Automobile Trading

160 Sin Ming Drive
#05-17 Sin Ming Autocity
Singapore 575722
Contact person: Mr Ong Han Wei
Tel: 6453 1743/9660 1347
Fax: 6457 6181

If you fail to conduct the pre-repair inspection within the next (2) working days excluding any intervening Saturday, Sunday or Public Holiday, we will commence repairs thereafter without further reference to you.

Please inform us as to whether you will or will not be conducting a pre-repair inspection. If we do not receive any response from you, we will assume that you do not intend to conduct said inspection.

Yours faithfully,

Christine Loh
Legal Executive

Messrs Raymond Lam & Co.
48B Temple Street
Singapore 058593
TEL: 6227 1021
DID: 6220 7492
Fax: 6220 7806

CONFIDENTIALITY NOTE: This e-mail is intended only for the individual or entity named above and may contain information that is confidential and privileged. If you are not the intended recipient, you are hereby notified that any distribution, copying or dissemination of this e-mail is strictly prohibited. If you have received this e-mail in error or are not the named recipient, please notify me immediately by return e-mail and destroy the original message. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0023G
Vehicle Details	
Vehicle No.:	SJS2420P
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	L13A4223211
Chassis No.:	GE61205623
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,900.00
Original Registration Date:	04 Aug 2009
First Registration Date:	04 Aug 2009
Transfer Count:	0
Actual ARF Paid:	\$14,900.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Aug 2019
PARF Rebate Amount:	\$7,450.00
Intended COE Rebate Details	
COE Expiry Date:	03 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,291.00
COE Rebate Amount:	\$690.00
Total Rebate Amount:	\$8,140.00

The information contained herein is correct as at 21 Feb 2019

OK

▶ fit Used Vehicle List (19 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabl
Honda Fit 1.3A G (COE till 01/2024)	\$24,800	\$5,040 /yr	22-Jan-2009	1,339 cc	-	GV Credit Pte Ltd	Availabl
Office No. - 63443344 Eugene - 86218538 Monthly From \$468 Onwards With 2.38% Lowest Interest In Town. No Admin Fees With 2 Years Warranty Engine And Gearbox. Additional A On Available. Feel Free To Contact Us For More Info.							
Honda Fit 1.3A G	\$13,500	\$9,140 /yr	24-Dec-2009	1,339 cc	150,000 km	GV Credit Pte Ltd	Availabl
Office No. - 63443344 Gem - 81371653							
Honda Fit 1.3A G (New 5-yr COE)	\$15,588	\$3,120 /yr	16-Jul-2009	1,339 cc	-	Wheels Singapore Pte Ltd	Availabl
1 Owner Consignment. Best Condition Fit! Original Low Mileage. Owner Wanted To Renew Himself, In July Did 2k + Of Preventive Maintenance. Paintwork Is Not Perfect As 10yrs Already. 100% Accident Free... Office No. - 66815662 Jacson - 87881825 JJ - 91172361 ZJ - 97590007 Mr Ng - 86857799							
Honda Fit 1.3A GF (New 5-yr COE)	\$23,800	\$4,760 /yr	23-Mar-2009	1,339 cc	92,000 km	Feliks Automobile	Availabl
Regular Servicing. Low Mileage Done. Spacious Boot. Flexible Bank And In House Loan Available. Call For Enquires Or A Non Obligational Viewing. Office No. - 64692427 Jacky - 98309977							
Honda Fit 1.3A G (New 5-yr COE)	\$23,800	\$4,760 /yr	11-Feb-2009	1,339 cc	-	Car World Automobile	Availabl
(Price \$23,800) Comes With 6 Months Engine And Gearbox Warranty, All Our Quality Preowned Car Are Selling At Low Depreciation Price. STA/VICOM/AA Are Welcome, Bank Loan Or In House Financing Available. Vie... Office No. - 64712822 Thomas Hii - 88383233 Mark Tan - 96839955 Vincent Lim - 96338877 Mr Koh - 97912121							
Honda Fit 1.3A G (New 5-yr COE)	\$23,800	\$4,760 /yr	29-Apr-2009	1,339 cc	-		Availabl
Low Selling Price! Sporty Red, Low Fuel Consumption, Low Maintenance Cost, Well Maintained. Office No. - - DQ - 87689926							
Honda Fit 1.3A G (COE till 02/2024)	\$24,000	\$4,820 /yr	12-Feb-2009	1,339 cc	140,000 km	Golden Charter Pte Ltd	Availabl
Fresh \$3K Silver Paintwork! Cheapest Depreciation In The Car Market! 6 Months Warranty! Re-Conditioned Showroom Upholstery! 120 Point Check Done, STA Welcomed! Loan Available With Low Interest. Office No. - 62545410 Den - 97736360 Jon - 83561434							
Honda Fit 1.3A (New 5-yr COE)	\$24,800	\$4,960 /yr	20-Jan-2009	1,339 cc	-	GV Credit Pte Ltd	Availabl
Monthly From \$468 Onwards With 2.38% Lowest Interest In Town. No Admin Fees With 2 Years Warranty Engine And Gearbox. Additional A On Available. Feel Free To Contact Us For More Info. Office No. - 63443344 Edmund - 96395444							
Honda Fit 1.3A G (New 5-yr COE)	\$24,800	\$4,960 /yr	20-Jan-2009	1,339 cc	120,000 km	Precise Auto Trading Pte Ltd	Availabl

Interest From 3.18%. Bank Loan And In House Loan Available. Lowest Monthly Installment \$500 And More. Vehicle Checked By In House

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	18/02/2019 12:12
Date Of Accident	17/02/2019 12:00
Exact Location Of Accident	PIE TOWARDS TUAS NEAR EXIT 12 (KPE/ECP)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJS2420P
Insured/Policyholder	
Name Of Registered Owner	ENG LIN KEE
NRIC No	S2620023G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90228622
Alternative Phone No	OFFICE-90228622
Vehicle Particulars	
Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5072979184-03
Cover Note Number	
Driver	
Name of Driver	ENG LIN KEE
NRIC No	S2620023G
Date Of Birth	26/02/1958
Occupation	INDOOR
Date Of Driving Pass	01/08/1997
Driving Experience	21 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90228622
Fax Number	
Contact Number	OFFICE-90228622
EEmail Address	NOEMAIL

Address	BLK 451 #10-224 TAMPINES STREET 42
Postcode	520451
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP5771K
Vehicle Make/Model/Colour	LEXUS 15250
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG WEE KIANG
NRIC/Passport Number	S7340365J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJT1285P
Vehicle Make/Model/Colour	BMW 320i
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SGP9894K
Vehicle Make/Model/Colour	HYUNDAI SONATA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SDS31M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN PENG WEE
NRIC/Passport Number	S8634337A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

18 FEB 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



NG WING KIN JAMES
S7927881E

Sketch Plan #2 Pg. 1

(A) SJ52P20P


(D) SGP4894K

(B) SKP5771K

(E) SDS31M

PIE (Taus) (C) STT1285P

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17/02/19, @ about 12pm, I am travelling PIE (Taus), near Exit 12 (KPE/ECP) / Bendemer / Kallang. The car ahead of me on lane (1) slow down and stopped. I too stopped with safe keeping distance. When suddenly, I felt an impact on my rear portion and the strong impact cause my vehicle to surge forward and hit on the front vehicle. When I get down, I found myself in a 5 cars chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

18 FEB 2019

Driver's Signature

If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

NG WING KIN JAMES


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM19003120/Gcd3e2		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date: 27-02-2019		
ATTN : WONG WEE FU		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SKP 5771K	Veh. Inspected	SJS 2420P	
Policy No.		Coverage (\$)	0.00	
Claim No.	S9M01E6U	Excess (\$)	0.00	
Assign From	WONG WEE FU	Assign Date	19/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	GE61205623	Colour	GREY	
Odometer	334161 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	BRIDGESTONE	6 mm	
L/H Front Tyre	175/70 R14	BRIDGESTONE	6 mm	
R/H Rear Tyre	175/70 R14	BRIDGESTONE	6 mm	
L/H Rear Tyre	175/70 R14	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
5. General Information				
Accident Date	17/02/2019	Inspect Date / Time	20/02/2019 (04:00 PM)	
Survey held at	160 SIN MING DRIVE#05-17			
Repairer	HIAP LEK AUTOMOBILE TRADING			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		

Report Ref No. CS3/ASM19003120/Gcd3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.