

22/03/2002

ASS. REC. BY:

REF:

CS3/MSG 19003183/Gcd302

Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

menmen

From (Person):

Chhia Nyule Pui

of

MSG

Date/Time:

20/1/19 @ 9.42am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBA 113D

Insured:

SME 9645A

at Workshop m/s

Xin Yun Auto

Tel:

98391666

of

Blk 8 Kaki Bkt Ave 4 # 05-23

Policy No:

29112616MCY

Claim No:

585367

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/02/2019

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

1.54pm @ 20/1/19

Person Contacted:

Yi shih

Vehicle (IN) OUT

Date/Time

Action/Instruction (X) Estimate

SBA 113D - NBA / AIG 15001581/x

D.O.A. 14/3/15

SME 9645A - *

08/11/13

Surveyor: KRS

REF:

MSG

3287H

ASSIGNMENT

(-2021)

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Xin Yun Auto

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SBAN3D Yr Regn: 23 Dec 2011Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X6 M C.C. 4395Colour: white A/C: Insured / Std / NI / NASp.Reading: 98960 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBSG 802040LJ89096Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S Rim / STD A/Rim orTyre Size: F: 315/25 R23R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mm

D.O.A. _____

D.O.I. 20-02-19Survey held at W/S 5pmDes. of Damages: Frt / Rear / C/S / N/S / U/C / Rooftop orThe U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$3000 - \$4000

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 4

1)

☐ : Final ReportResurvey No. of Trip: -

Date/Time, File Return to?

Survey Fee:

120

Transportation:

2)

Add Fee: ☐ : Site Insp (\$)- S + RS, - SI☐ : Interview (\$)

Photos

☐ : Tech. Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

130Report Format : PRS

Lump Sum / I.B.I. (\$) _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Feb 2019		20 Feb 2019 09:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BLUECAR EAST ASIA PTE LTD, Co. Reg. No.: 201617259H		
Main Claimant:	LIM BOON HUAT, ID: S1583287H		
Vehicle Reg. No.:	SBA113D	Date of Loss:	16/02/2019 13:00 - :59 [85 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 585367	Policy/Cover Note No.:	29112616MCY (Comprehensive) Coverage: 01/01/2019 - 31/12/2019
Vehicle Reg. No. (Insured):	SME9645A	Policy No. (Claimant):	
		Excess:	
Repairer:	Xin Yun Auto Pte Ltd (HQ) BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @KAKI BUKIT, 415675 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/02/2019]		
Driver/Custodian (Insured):	KOH HWEE LIN (), NRIC: S7612300D, Tel: +6590492477		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK, LIABILITY: UNCLEAR. CONTACT: FABIEN TEO/YI XIN 9839 1666/9839 1555		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3287H
Vehicle Details	
Vehicle No.:	SBA113D
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	B.M.W.
Vehicle Model:	X6 M AT ABS D/AB 4WD TC 5DR GAS/D SR HUD
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	20150001S63B44A
Chassis No.:	WBSGZ02040LJ89096
Maximum Power Output:	408.0 kW (547 bhp)
Open Market Value:	\$111,904.00
Original Registration Date:	23 Dec 2011
First Registration Date:	23 Dec 2011
Transfer Count:	1
Actual ARF Paid:	\$111,904.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Dec 2021
PARF Rebate Amount:	\$67,142.00
Intended COE Rebate Details	
COE Expiry Date:	22 Dec 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$70,003.00
COE Rebate Amount:	\$19,853.00
Total Rebate Amount:	\$86,995.00

The information contained herein is correct as at 21 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	18/02/2019 15:26
Date Of Accident	16/02/2019 12:40
Exact Location Of Accident	JOO CHIAT PLACE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SBA113D
Insured/Policyholder	
Name Of Registered Owner	LIM BOON HUAT
NRIC No	S1583287H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98310138
Alternative Phone No	OTHERS-98310138
Vehicle Particulars	
Manufacturer	BMW
Model	X6 M AT ABS D/AB 4WD TC 5DR GAS/D SR HUD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V14087/VPE/R00
Cover Note Number	
Driver	
Name of Driver	LIM BOON HUAT
NRIC No	S1583287H
Date Of Birth	23/10/1963
Occupation	INDOOR
Date Of Driving Pass	04/07/1985
Driving Experience	33 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98310138
Fax Number	
Contact Number	OTHERS-98310138
EMail Address	NOEMAIL

Address	31 CHAPEL ROAD
Postcode	429537
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME9645A
Vehicle Make/Model/Colour	BLUECAR BLUECAR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH HWEE LIN
NRIC/Passport Number	S7612300D
Contact Number	90492477
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

x 

Policyholder's Signature
Date & Time:

x 

Driver's Signature
(If driver is not the policyholder)
Date & Time:

18 FEB 2019

IDAC KAKI BUKIT (VAC)

Reporting Centre Personnel's Signature
Name: 
Singapore 415933
Tel: 67416697
NRIC/FIN No.:
Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN



A: SBA113D

B: SME9645A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Kerb

My vehicle was stationary at Joo Chiat place, in front of
 ferfei wan tan mee store, car park lot No. 32.

Vehicle B was travelling at Joo Chiat place. Suddenly vehicle B
 swung ^{swung} ~~squeezed~~ in and hit my vehicle, and push it moving ~~towards~~ to the kerb.

I came out found that vehicle B hit my vehicle from driver side
 and in the result, my vehicle can't move.

Signature

DECLARATION

I/We declare the foregoing particulars are true in every respect.

18 FEB 2010

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

IDAC KAKI BUKIT(VAC)
 23 KAKI BUKIT AVE 4
 Singapore 415933
 Reporting Centre Person's Signature
 Name: Tel: 67416697
 NRIC/FIN No.: Fax: 67492305
 Email: vackb@singnet.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Feb 2019		20 Feb 2019 09:42 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

BLUECAR EAST ASIA PTE LTD, Co. Reg. No.: 201617259H

Main Claimant:

LIM BOON HUAT, ID: S1583287H

Vehicle Reg. No.:

SBA113D

Date of Loss:

16/02/2019 13:00 - :59
[85 Months and 24 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 585367

Policy/Cover Note No.:

29112616MCY (Comprehensive)
Coverage: 01/01/2019 - 31/12/2019

Vehicle Reg. No. (Insured):

SME9645A

Policy No. (Claimant):

Excess:

Repairer:

Xin Yun Auto Pte Ltd (HQ) BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @KAKI BUKIT, 415675 Kaki Bukit - Tel:

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 21/02/2019]

Driver/Custodian (Insured):

KOH HWEE LIN (), NRIC: S7612300D, Tel: +6590492477 Email:

Adj Asg. Remarks:

SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: UNCLEAR. CONTACT: FABIEN TEO/YI XIN 9839 1666/9839 1555

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


Claim Documents




***SBA113D (585367)**
[SME9645A]
TP
LIM BOON HUAT
Feb 16 2019 1:00PM
[BLUECAR EAST ASIA PTE LTD]
Xin Yun Auto Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	19/02/19 13:48	Accident Statement From: SC - Reg. No: SME9645A, Claimant: BLUECAR EAST ASIA PTE LTD		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
2	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
3	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
4	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
5	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
6	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
7	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
8	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
9	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
10	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
11	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
12	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
13	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
14	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
15	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
16	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
17	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
18	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
19	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
20	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
21	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
22	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
23	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
24	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
25	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
26	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
27	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
28	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
29	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
30	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
31	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
32	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>
33	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
34	23/02/19 15:49	General View		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	19/02/19 13:48	SBA113D TP E-FILE REPORT		Load PDF	
2	19/02/19 13:48	EMAIL FROM TP TO ARRANGE SURVEY		Load PDF	
3	19/02/19 15:54	SURVEY DISAGREE ON SJE - ASSIGN LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19003183/GCD3E2

Date: 26/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29112616MCY

Claimant Vehicle No : SBA113D

Insured Vehicle No : SME9645A

Date of Loss: 16/02/2019

Nature of Claim: TP

Claim No: 585367

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBA113D

Make & Model: BMW X6, 4.4 (M)

Engine No: 20150001S63B44A

Reg. Date: 23/12/2011 (Man. Year: 2011)

Chassis No: WBSGZ02040LJ89096

Colour: White

Odometer: 98960 km

Engine Capacity: 4395 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 315/25Z R23

Rear Tyre Size: 315/25Z R23

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/02/2019

Date Inspected: 20/02/2019 Inspected At:

Xin Yun Auto Pte Ltd (HQ)
BLK 8 KAKI BUKIT AVE 4 #05-23
PREMIER @KAKI BUKIT
Singapore 415675

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2019)
Parts:	M1-SUV	BMW X6 4.4 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBA113D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >