

23002901

ASS. REC. BY:

REP

CS3/MSG/19003195/R/cd3^{sr}

Special Instruction:

Surveyor
Menmen

Resul

ASSIGNMENT (Office)

Christina Wong

of

MSG

Date/Time: 19/2/19 @ 4:35pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTCS

To Inspect Vehicle No.

SJR 82522

Insured:

GV 9927T

at Workshop m/s

V-Tech Auto

Tel:

6264 6211

of

1 Soon Lee street # 06-04

Policy No:

288 41717

Claim No:

58329B

Sum Insured:

Excess:

Make of Veh:

D.O.A

2019/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

230pm 20/2/19

Person Contacted:

Ms. Chong

Vehicle:

IN/OUT

Date/Time

Action/Instruction (x) Estimate

SJR 82522 - X

GV 9927T CF/AK/10030565/1ca-f2

D.O.A: 19/5/2010

Dismantle: 21/2/2019

After repair: 25/2/2019

Rosme


43886
LOE XDRM - 2019/July

SYR 82522

2009 July

Type: Car / Cycle / Bus / Van / Utility / Taxi / Prime Mover / Truck / Trailer
 Make: **2.M.W 520L A**
 Colour: **BLUE**
 Sp. Reading: **197556**
 Eng. No.:
 CRIC: **WBANT12090CX30209**
 Gen. Cond: Good / **Fair** / Poor / Burnt
 Steering: **Normal** / Jammed / Leaked / Burnt or
 Brake: **Normal** / Jammed / Leaked / Burnt or
 Mod: Nil / **S/Rim** / STD A/Rim or
 Tyre Size: F: **245/40ZR18**
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / **MIC** / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: R/Bal: **6** mm L/Bal: **6** mm
 D.O.A.: **20/01/19**
 Survey held at: **U-TECH**
 Des. of Damages: **F/F** / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision
 Date: Person Contacted: Vehicle: IN / OUT

(C) W/S / T/RES / O/D RES / EVA / HV / MV
 Vehicle No: **SJR 82522**
 V-TECH
1, SOON LET ST #06-04
MS14



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **27K**
 IDAC / Accidnt Rpt: Consistent? : Yes or No
 GIA / FR Seen: Consistent? : Yes or No
 Est. Repairs: **4** days Res: Yes or No
 Lump Sum: % 3 Val: Yes or No

CA / REV / RES / 24 HRS

Date / Time Action / Instruction

repair limit 4k

Estimated repair range \$4,000 - \$5,000

RECEIVED 27 FEB 2019

[Signature]
27/2/2019

Date/Time: File Pass to: : Prel. Report
 : Final Report

Days Of Repair: **4**
 Resurvey No. of Trip: **2**

Survey Fee:	
Transportation:	
Site Insp:	
Interview:	
Test Insp:	
Workshop:	
TOTAL:	

Add Fee: Site Insp (\$)
 Interview (\$)
 Test Insp (\$)
 Workshop (\$)

Report Format: **PRE**
 Lump Sum / LB: (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jan 2019		19 Feb 2019 16:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TIAN SIANG MOTOR , Co. Reg. No.: 33293000M								
Main Claimant:	ISMAIL BIN MOHAMAD YASIN , ID: S1424388G								
Vehicle Reg. No.:	SJR8252Z	Date of Loss:	20/01/2019 11:00 - :59 [114 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 583293	Policy/Cover Note No.:	28841717 (Third Party Only) Coverage: 20/10/2018 - 19/10/2019						
Vehicle Reg. No. (Insured):	GV9927T	Policy No. (Claimant):							
		Excess:							
Repairer:	V-Tech Auto Service (HQ) No.1 Soon Lee Street, #06-04 Pioneer Center, 627605 Pioneer - Tel: 62646211								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/02/2019]								
Driver/Custodian (Insured):	LOW WENG PENG (), NRIC: S1292822Z, Tel: +6593658311								
Adj Asg. Remarks:	Car in on 20/02/19, survey anytime after 10am. Liability down. TP disagree with our SJE list, proceed to appoint LKK. Contact No: 6264 6211.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/01/2019 15:07
Date Of Accident	20/01/2019 10:30
Exact Location Of Accident	BLK 840 JURONG WEST 81
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR8252Z
Insured/Policyholder	
Name Of Registered Owner	ISMAIL BIN MOHAMAD YASIN
NRIC No	S1424388G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90750130
Alternative Phone No	OFFICE-90750130

Vehicle Particulars

Manufacturer	BMW
Model	520I
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102194431
Cover Note Number	

Driver

Name of Driver	ISMAIL BIN MOHAMAD YASIN
NRIC No	S1424388G
Date Of Birth	17/08/1958
Occupation	INDOOR
Date Of Driving Pass	29/10/1996
Driving Experience	22 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90750130
Fax Number	
Contact Number	OFFICE-90750130
Email Address	NOEMAIL

Address	BLK 840 JURONG WEST ST 81 #0-119
Postcode	640840
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HONG KAH SOUTH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 510 JURONG WEST STREET 52 , POSTCODE: 640510 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5648999 - FAX NO: 66655797
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GV9927T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Printed Name: _____
Date: _____

Printed Name: _____
Date: _____

Printed Name: _____
Date: _____



**SINGAPORE
POLICE FORCE**



T/20190120/2117

1 of 3

Police Station Of Origin:
Hong Kah South NPP
510 Jurong West Street 52 #01-90
SINGAPORE 640510
Tel No: 1800-5648999

Report No. T/20190120/2117

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/01/2019 20:40	Vide Report No.:	Station Diary No.: 28
--	------------------	--------------------------

Informant's Particulars

Name of Informant: ISMAIL BIN MOHAMAD YASIN		Address: APT BLK 840 JURONG WEST STREET 81 #07-119 SINGAPORE 640840	
ID Type / ID No.: NRIC NO / S1424388G		Contact No.:	Mobile: 90750130
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 60	Date of Birth: 17/08/1958	Type of Informant: Driver
Race: Malay		Language:	Institution / School Name:
Occupation: DRIVER		Driving Licence Information: Class: 2B,3	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 20/01/2019 11:30	Type of Location: Car Park
Location: Along Road 1 JURONG WEST STREET 81 CARPARK/SERVICE RD OF 840 JURONG WEST ST 81				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GV9927T	Van					0
SJR8252Z	Car	BMW	520I AUTO ABS AIRBAG 2WD XENON HEADLAMP	Blue	Slightly Damaged	0



Police Station Of Origin:
Hong Kah South NPP
510 Jurong West Street 52 #01-90
SINGAPORE 640510
Tel No: 1800-5648999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJR8252Z	NTUC Income Insurance Co-Operative Limited	5102194431	11/07/2018	14/07/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ISMAIL BIN MOHAMAD YASIN	ID No.	S1424388G
Related Vehicle	SJR8252Z (Car)	Contact No.	90750130
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 20/01/2019 at about 1030hrs, I parked my vehicle at the service road near my block as I needed to unload some items from my car to my house.

Later on at about 1330hrs, I received a call from my neighbor (HP: 84983267 / 91053267) informing me that he saw my car being hit by another vehicle GV9927T. The vehicle immediately left the vicinity and did not leave any information behind on my car. My neighbor said that the incident happened at about 1130hrs earlier.

Due to the collision, my front bumper and bonnet was badly dented in. I do not have any CCTVs in my vehicle.



**SINGAPORE
POLICE FORCE**



T/20190120/2117

3 of 3

Police Station Of Origin:
Hong Kah South NPP
510 Jurong West Street 52 #01-90
SINGAPORE 640510
Tel No: 1800-5648999

Report No. T/20190120/2117

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Staff Sgt IQBAL PRATAMA PUTRA BIN AZMAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

20/01/2019 20:40

Officer In Charge Of Case:

TP / HRT /

Sr Staff Sgt TAN JEOK LENG

Contact No.: 65476144

SN 125

Classification Of Case:

Authentication Stamp

NP168

Signature :

Singapore Police Force

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4388G
Vehicle Details	
Vehicle No.:	SJR8252Z
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Feb 2019
Vehicle Make:	B.M.W.
Vehicle Model:	520I AUTO ABS AIRBAG 2WD XENON HEADLAMP
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	A240I477N46B20BE
Chassis No.:	WBANT12090CX30209
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$43,770.00
Original Registration Date:	15 Jul 2009
First Registration Date:	15 Jul 2009
Transfer Count:	1
Actual ARF Paid:	\$43,770.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jul 2019
PARF Rebate Amount:	\$21,885.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jul 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$17,501.00
COE Rebate Amount:	\$660.00
Total Rebate Amount:	\$22,545.00

The information contained herein is correct as at 22 Feb 2019.

OK

27,000
 22,545

 4,455

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jan 2019		19 Feb 2019 16:35 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TIAN SIANG MOTOR , Co. Reg. No.: 33293000M		
Main Claimant:	ISMAIL BIN MOHAMAD YASIN , ID: S1424388G		
Vehicle Reg. No.:	SJR8252Z	Date of Loss:	20/01/2019 11:00 - :59 [114 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 583293	Policy/Cover Note No.:	28841717 (Third Party Only) Coverage: 20/10/2018 - 19/10/2019
Vehicle Reg. No. (Insured):	GV9927T	Policy No. (Claimant):	
		Excess:	
Repairer:	V-Tech Auto Service (HQ) No.1 Soon Lee Street, #06-04 Pioneer Center, 627605 Pioneer - Tel: 62646211		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 20/02/2019]		
Driver/Custodian (Insured):	LOW WENG PENG (), NRIC: S1292822Z, Tel: +6593658311 Email:		
Adj Asg. Remarks:	Car in on 20/02/19, survey anytime after 10am. Liability down. TP disagree with our SJE list, proceed to appoint LKK. Contact No: 6264 6211.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJR8252Z (583293)**
[GV9927T]
TP
ISMAIL BIN MOHAMAD YASIN
Jan 20 2019 11:00AM
[TIAN SIANG MOTOR]
V-Tech Auto Service

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/01/19 18:09	Accident Statement <small>From: SC - Reg. No: GV9927T, Claimant: TIAN SIANG MOTOR</small>	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
30	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
31	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
33	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
34	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
35	25/02/19 10:32	General View	 Load JPG	<input checked="" type="checkbox"/>
36	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	25/02/19 10:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	27/02/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	27/02/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	27/02/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	27/02/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	27/02/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	27/02/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	27/02/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	27/02/19 12:40	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/01/19 18:11	SJR8252Z GIA Rpt	 Load PDF	
2	28/01/19 18:22	PRI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19003195/R1CD3S2
Date: 28/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28841717
Claimant Vehicle No : SJR8252Z **Insured Vehicle No :** GV9927T
 Date of Loss: 20/01/2019 Nature of Claim: TP Claim No: 583293

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR8252Z**
 Make & Model: BMW 520I, 2.0 ABS AIRBAG 2WD XENON HEADLAMP (A) Engine No: A240I477N46B20BE
 Reg. Date: 15/07/2009 (Man. Year: 2009) Chassis No: WBANT12090CX30209
 Colour: Blue Odometer: 197556 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40ZR18 Rear Tyre Size: 245/40ZR18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/02/2019
 Date Inspected: 21/02/2019 Inspected At: V-Tech Auto Service (HQ)
 No.1 Soon Lee Street, #06-04 Pioneer Center
 Singapore 627605
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Feb 2019)

Parts: 143 BMW 520I 2.0 ABS AIRBAG 2WD XENON HEADLAMP (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJR8252Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >