

ASS. REC. BY

REF C83/ALG/19003216/ Gcd3et

Surveyor

From (Person)

Chn Lee Ying

ASSIGNMENT (Office)

of

ALG

Date/Time

19/2/2019 @ 4:00pm

Estimated Cost

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SGK 8159 H

Insured

SLG 5835X

at Workshop m/s

SS Ong Motor

Tel:

6783 2118 / 9733 2118

of

9002 Jampines Ind. Park A #01-40

Policy No.

0999994761

Claim No.

9004964372SG

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/2/19

CA / REV / REP. / REV 24 HRS

I.O.D. Endorsement:

Date/Time:

10:31am @ 20/2/19

Person Contacted:

Ah Chew

Vehicle: IN/OUT

Date/Time

Action/Instruction (X) Estimate

SGK 8159 H -X

SLG 5835X -X

Dismantle: 21/2/2019

Xhl.


REF: ALG

2012/19

SGK 8159H

Aug 16

Insured: ☒ WS / TP RES / OD ISS / EVA / INV / MV  
To inspect Vehicle No: SGK 8159H  
at Workshop No: Ong Motor  
at: BUC 9002, Tampines Ind. Park A # 01-40  
Insured:   
Policy No:   
Claims No:   
Sum Insured:   
Excess:   
(Client's Record)   
Make of Veh: Ah Chew



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:   
IUAC Accident Rpt. Consistent? : Yes or No   
GIA / PR Seen: Consistent? : Yes or No   
Est. Repairs: 6 days Res.: Yes or No   
Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Vehicle No: SGK 8159H at Regn: Aug 16  
Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

Make: Toyota Altis 6C 1598  
Colour: Brown A/C Insured / Std / Nil / NA  
Sp Reading: 33334 T/Radio: Insured / Std / Nil / NA

Eng No:   
C/No: MRO53REH104553999  
Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45 R17  
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front Rear  
R/Bal: 6 mm R/Bal: 6 mm  
L/Bal: 6 mm L/Bal: 6 mm  
D.O.A. D.O.A. 20-2-19

Survey held at: w/s 4240pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time: File Pass to: ☐ : Prel. Report

1) ☐ : Final Report

Date/Time: File Return to:

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation

1) : S & R St

1) : Hotel

1) : Other

1) : Taxi

1) : Other

Add Fee: ☐ Site Insp. (\$)

☐ Interview (\$)

☐ Tech. Insp. (\$)

☐ Weekend (\$)

Report Format: DAR

Lump Sum / L.B.L. (\$)

180
10
190

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments@lkkauto.com, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 19/2/2019 4:00:33 PM  
Attachments:  tmp1DAC.TIF

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**TOMMY CHOO, MARK GO LLC**

**Advocates & Solicitors UEN NO : 201523418E**  
**(a law corporation with limited liability)**

151 CHIN SWEE ROAD #14-15/16  
MANHATTAN HOUSE  
SINGAPORE 169878  
TEL : (65) 6532 2455  
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: [lhling@tcmg.com.sg](mailto:lhling@tcmg.com.sg); [mdmling@tcmg.com.sg](mailto:mdmling@tcmg.com.sg)  
Our Ref: TCMG/SGK8159H/0219/SSO

Your Ref: SLG 5835 X

19 February 2019

**BY FAX NO. 6835-7416 ONLY**

M/s AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way#07-16  
AIG Building  
Singapore 079120

**Attn: Motor Claims Department**

Dear Sirs,


**PRE-REPAIR INSPECTION NOTICE**

We act for **Ng Chee Keong**, the owner and/or driver of motor vehicle no. **SGK 8159 H**, which was involved in an accident along Thomson Exit to Sembawang on 18 February 2019 at 07:20 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SLG 5835 X** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s SS Ong Motor, (9002 Tampines Industrial Park A, #01-40, Singapore 528836 - Ah Chew @ 6783 2118/ 9733 2118).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,  


**MR LING LEONG HUI**

cc. M/s SS Ong Motor  
(Yref : SGK8159H)

**BY FAX NO. 6789 2118 ONLY**

[> Back to OneMotoring](#)

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SGK8159H		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	COROLLA ALTIS 1.6 CVT		
Chassis No. :	MR053REH104553999		
Propellant :	Petrol		
Engine No. :	1ZRY312467		
Engine Capacity :	1598 cc		
Maximum Power Output :	90.0 kW ( 120 bhp )		
Maximum Laden Weight :	1650 kg		
Unladen Weight :	1215 kg		
Year Of Manufacture :	2016		
Original Registration Date :	25 Aug 2016		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$52,503.00		
COE Expiry Date :	24 Aug 2026		
Road Tax Expiry Date :	24 Aug 2019		
PARF Eligibility Expiry Date :	24 Aug 2026		
Inspection Due Date :	24 Aug 2019		
Intended Transfer Date :	23 Feb 2019		
CO2 Emission :	151.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

[OK](#)
[Print](#)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9365E
<b>Vehicle Details</b>	
Vehicle No.:	SGK8159H
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 CVT
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	1ZRY312467
Chassis No.:	MR053REH104553999
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,990.00
Original Registration Date:	25 Aug 2016
First Registration Date:	25 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$19,990.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Aug 2026
PARF Rebate Amount:	\$14,992.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,503.00
COE Rebate Amount:	\$39,391.00
<b>Total Rebate Amount:</b>	<b>\$54,383.00</b>

The information contained herein is correct as at 23 Feb 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	18/02/2019 15:57
Date Of Accident	18/02/2019 07:20
Exact Location Of Accident	THOMSON EXIT TO SEMBAWANG
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGK8159H
Insured/Policyholder	
Name Of Registered Owner	NG CHEE KEONG
NRIC No	S7409365E
Email Address	XL_74@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97436841
Alternative Phone No	OFFICE-97436841
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100480104
Cover Note Number	
Driver	
Name of Driver	NG CHEE KEONG
NRIC No	S7409365E
Date Of Birth	24/03/1974
Occupation	INDOOR
Date Of Driving Pass	12/01/1993
Driving Experience	26 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97436841
Fax Number	
Contact Number	OFFICE-97436841
EEmail Address	XL_74@YAHOO.COM.SG

Address	BLK 2 TANJONG PAGAR PLAZA #13-35
Postcode	082002
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MY VEHICLE WAS STATIONARY. SUDDENLY, VEHICLE B HIT ONTO MY VEHICLE REAR.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG5835X
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	YAP TING YEW
NRIC/Passport Number	S7803364I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

NG CHEE KEONG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SGK8159H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

## Sketch Plan Pg. 1


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

my VEHICLE WAS STATIONARY. SUDDENLY VEHICLE B HIT  
 INTO my VEHICLE REAR

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



SINGAPORE ARMED FORCES  
IDENTITY CARD

Name  
NG CHEE KEONG

NRIC No  
S7409365E



This card is the property of the Singapore Armed Forces. Any person finding this card is requested to forward it without delay to Central Manpower Base or any Police Station.

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 12 Jan 1993



NP 428A

GEVALTOSGPV100671081208

0000006008244

NRIC No/Colour  
S7409365E/ PINK

Race  
CHINESE

Date Of Birth  
24/03/1974

Service Status  
REGULAR

Blood Group  
O (+)

Country Of Birth  
SINGAPORE

Military Rank Status  
MILITARY EXPERT M03387

Sex  
M

ADDRESS: 2 TANJONG PAGAR PLAZA #13-35  
SINGAPORE 082002 DATE: 18.07.2012 S7409365E





## POLICY SCHEDULE

## AUTOPLUS PRIVATE VEHICLE

Policy No. : 2100480104-02

Period of Insurance : 25 Aug 2018 to 24 Aug 2019

Issued Date : 18 Jul 2018

## ABOUT THE POLICYHOLDER

Name of Policyholder : Ng Chea Keong  
 Address : 2 Tanjong Pagar Plaza  
 #13-35  
 SINGAPORE 082002  
 Occupation/Nature of Business : Uniformed Group

## ABOUT THE VEHICLE

Registration No. : SGK8159H Engine Capacity/Tonnage : 1,598.00 CC  
 Chassis No. : MR053REH104553999 Engine No. : 12RY312467  
 Seating Capacity : 4 First Year of Registration : 2016 Body Type : Sedan  
 Make/Model : TOYOTA COROLLA ALTIS 1.6 DUAL  
 Hire Purchase Company/Employer's Loan : United Overseas Bank Limited

## ABOUT THE COVER

Sum Insured : Market Value Off Peak Car : No  
 Driver Restriction : NA Insuring with COE/PARF : Yes

## Person or Classes of Persons Entitled to Drive :

a) The Policyholder  
 b) Any other person who is driving on the Policyholder's order or with his/her permission.  
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$2,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

## Limitation as to use

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving school, driving test, racing, pace-making, reliability test or speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

## Other Key Policy Benefits :

Act of God, PA to Authorised Driver / Unnamed Passengers - \$10000, NCD Protector, Loss of Use 1500cc - 1600cc Optional, Dealer (First 3 years from original registration) - AIG Authorised Workshop, PA Insured - \$50000, Waiver of Excess, Strike, Riot and Civil Commotions, Key Replacement Cover - \$800, New Car Oil (36 months), 24-Hour Domestic Express Repair.

## EXCESS

Section 1  
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2  
 Property Damage - \$0

Windscreen - \$100

Named Driver  
 Ng Chea Keong - \$600 (Own Damage)

## PREMIUM

Premium : \$ 686.78  
 GST (7%) : \$ 48.07

Total : \$ 734.85

Total Premium includes the following discounts:

Multi Driver Discount - 5.00%, Group Discount - 10.00%, New Carlet Discount - 50%

## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190218/7022

1 of 4

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190218/7022

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/02/2019 21:05	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars			
Name of Informant: NG CHEE KEONG		Address: 2 TANJONG PAGAR PLAZA #13-35 SINGAPORE 082002	
ID Type / ID No.: NRIC NO / S7409365E		Contact No.: Home/Office: Mobile: 97436841	
Nationality: SINGAPORE CITIZEN		Email: xl_74@yahoo.com.sg	
Sex: Male	Age: 44	Date of Birth: 24/03/1974	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Other government associate professionals nec		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/02/2019 07:20	Type of Location: X-Junction
Location:  SELETAR EXPRESSWAY				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit: 60 Km/h	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGK8159H	Car	TOYOTA	COROLLA ALTIS 1.6 CVT	Brown		0
SLG5835X	Car	TOYOTA	PRIUS			0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



**SINGAPORE  
POLICE FORCE**



T/20190218/7022

2 of 4

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190218/7022

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGK8159H	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100480104-02	25/08/2018	24/08/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	NG CHEE KEONG		ID No.	S7409365E
Related Vehicle	SGK8159H (Car)		Contact No.	97436841
Hospital/Clinic	RAFFLES MEDICAL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	18/02/2019		Date Discharge	18/02/2019
No. of Days granted Medical Leave		03	Degree of Injury	Slight
Driver				
Name	Yap Ting Yew		ID No.	S7803364I
Related Vehicle	SLG5835X (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

## Brief Details.

At around 0720H on 18 Feb 2019 (Monday), my vehicle SGK8159H was at stationary in front of the traffic light (RED) at the Thomson exit toward Sembawang Road. Suddenly, I felt a bang from behind and resulted a strain on my neck.

I have filed an incident report with IDAC. As advised by doctor, I was given 3 days medical leave and a referral letter for physio.

Accordingly to IDAC, I was advised to make a police report due to 3 or more medical leave given.

Details of vehicle involved : SGK8159H (self)

Name of Driver : Ng Chee Keong

Third party vehicle : SLG5835X

Name of Driver : Yap Ting Yew

NRIC : S7803364I



**SINGAPORE  
POLICE FORCE**



T/20190218/7022

3 of 4

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190218/7022

CONTINUATION OF REPORT





**SINGAPORE  
POLICE FORCE**



T/20190218/7022

4 of 4

Report No. T/20190218/7022

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
MOHAMAD ZULFAZDLI BIN ABDULLAH  
Contact No.: 65476204

Authentication Stamp  
NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
18/02/2019 21:05

Classification Of Case:

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched  
(7) Deformed (8) Shifted (9) Buckled (10) Broken (11) Necessary  
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

## MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (X) (3) Check (P)  
(4) Not Consistent (NC)

### Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket	DD	✓	2
1148	993068	Rear Bumper Side Retainer	DIS	✓	2
1149	993045	Rear Bumper Reinforcement	DD	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	CRA	✓	2
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel	RA	✓	
1160	993339	Rear End Panel Top Garnish	RA	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD R	✓	
1171	991328	Bootlid Emblem	NEC	✓	3
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH	CRA	✓	
1176	992899	Bootlid Lamp RH	CRA	✓	
1177	995243	Bootlid Lock	BT	✓	
1178	990377	Bootlid Rubber	DD	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: **SGK 8159 H**

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel	BUC	✓	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw	BT	✓	
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	DD R	✓	
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting	DIS	✓	2
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Feb 2019 <a href="#">Edit Reg</a>		19 Feb 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>




































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>LCRF PTE LTD</b> , Co. Reg. No.: 201624597K									
Main Claimant: -									
Vehicle Reg. No.: <b>SGK8159H</b>		Date of Loss: 18/02/2019 00:00 - :59 [29 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 9004964372SG</b>		Policy/Cover Note No.: 0999994761 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SLG5835X</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Ss Ong Motor Works (HQ)</b> BLK 9002 TAMPINES STREET 93 #01-40 (INDUSTRIAL PARK A), 67832118 Tampines - Tel: 67832118									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chew, Mavis</b> ] Chew.Mavis@aig.com									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 01/03/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (21/02/2019): Request to upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

































## Claim Documents

**\*SGK8159H (9004964372SG)  
[SLG5835X]**

TP

Feb 18 2019 12:00AM  
[LCRF PTE LTD]  
Ss Ong Motor Works

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images												3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print
1	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
2	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
3	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
4	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
5	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
6	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
7	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
8	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
9	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
10	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
11	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
12	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
13	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
14	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
15	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
16	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
17	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
18	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
19	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
20	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
21	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
22	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
23	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
24	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
25	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
26	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
27	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
28	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
29	23/02/19 15:36	General View											Load JPG	<input checked="" type="checkbox"/>
30	23/02/19 15:36	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
31	23/02/19 15:36	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
32	23/02/19 15:36	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
33	23/02/19 15:36	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
34	23/02/19 15:36	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
35	23/02/19 15:36	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
36	23/02/19 15:36	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
37	23/02/19 15:36	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	23/02/19 15:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	23/02/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	23/02/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	23/02/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	23/02/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	23/02/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	23/02/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	23/02/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	23/02/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	23/02/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	23/02/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/02/19 09:13	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19003216/GCD3E2

Date: 01/03/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994761  
 Claimant Vehicle No: SGK8159H Insured Vehicle No: SLG5835X  
 Date of Loss: 18/02/2019 Nature of Claim: TP Claim No: 9004964372SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGK8159H  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) Engine No: 1ZRY312467  
 Reg. Date: 25/08/2016 (Man. Year: 2016) Chassis No: MR053REH104553999  
 Colour: Brown Odometer: 33334 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 19/02/2019  
 Date Inspected: 20/02/2019 Inspected At: Ss Ong Motor Works (HQ)  
 BLK 9002 TAMPINES STREET 93 #01-40  
 (INDUSTRIAL PARK A)  
 Singapore 67832118  
 Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER BRACKET	Dented	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
6	2		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
7	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
8	1		*REAR END PANEL	Buckled	0.00 F	*- F
9	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
10	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
11	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
12	1		*BOOTLID	Repair	0.00 F	*- F
13	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
14	1		*BOOTLID LAMP LH	Cracked	0.00 F	*- F
15	1		*BOOTLID LAMP RH	Cracked	0.00 F	*- F
16	1		*BOOTLID LOCK	Bent	0.00 F	*- F
17	1		*BOOTLID RUBBER	Dented	0.00 F	*- F
18	1		*SPARE TYRE PANEL	Buckled	0.00 F	*- F
19	1		*SPARE TYRE LOCK SCREW	Bent	0.00 F	*- F
20	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
21	2		*REAR EXHAUST MOUNTING	Distorted	0.00 F	*- F
F=Franchise part.						
				<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >