

15/5/2010

INS. CASE OWNER:

CC⁶ /AIG1900

LKK:

IDAC:

Surveyor:

MARFUS

DOI:

ASSIGNMENT

Date / Time :

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

Excess Sec II : \$\$

Is driver the owner?

(YES / NO)

HP:

D.O.A :

Nature of Accident :

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	STAGE	DATE / PIC
SJM 3821R STH 1920D	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☐
	Authorisation To Act:	☐
	Release Voucher:	☐
	Final Repair Bill:	☐
	Car Rental Invoice:	☐
	Towing Invoice	☐
	LTA / GIA :	☐
Medical Bill:	☐	
PIR:	☐	
Mandate/Reject Instruction:	☐	
LOD	☐	
Payment Breakdown Form:	☐	
PRELIMINARY ADVICE Date/Time:	Sent By:	Post-Repair Photos: ☐
		Others: ☐

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$	(days) Reduction:	% Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost:	\$		
Loss of Rental (LOR):	\$	(days)	
Loss of Use (LOU):	\$	(\$ x days)	
Loss of Income (LOI):	\$	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐		[Tick only one]	
GIA/LTA Search	\$		
Medical:	\$		1) Claim status: Normal/Reject/Private Settle
Disbursement:	\$	(e.g. Tow/ Independent)	2) Report Format:
Legal Cost	\$		3) Survey fee:
Total:	\$	Global Sum \$:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	\$	Name 1:	
Payee 2: (Strike if N.A.)	\$	Name 2:	
Payee 3: (Strike if N.A.)	\$	Name 3:	

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

A16/
ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SM 3821R
24.

at Workshop m/s

of

Insured:

SLH 1920D

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$166.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1109D

Vehicle: IN / OUT

Date:

Person Contacted:

244 5161

Date / Time

Action / Instruction

20-6-2021LA 1083924/RS 4nt. house 6.1A

Veh No:

SM 3821R

Yr Regn:

61 06Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Taylor & Co. Ltd. A115.c.c 1598

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

212271

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR 0532EC107122562Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NH LS/Rim / STD A/Rim or

Tyre Size:

F:

125/70 214

R:

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

18/2/19

D.O.I.

20/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

) S + RS \$☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

TOTAL