



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19003249/K1pa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 17-04-2020



ATTN:KIAN CHUAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|------------|----------------|------------|
| Insured Veh. | SJT 6847K | Veh. Inspected | SHB 8778G |
| Policy No. | GA003790/1 | Coverage (\$) | 0.00 |
| Claim No. | S9M01EJF | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 20/02/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|--------------------|
| Make & Model | HYUNDAI I30 | c.c | 1582 |
| Engine No. | HIDDEN | Year of Reg. | 2017 |
| Chassis No. | TMAD281UVHJ142091 | Colour | SILVER |
| Odometer | 107418 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 195/65 R15 | MAXXIS | 7 mm |
| L/H Front Tyre | 195/65 R15 | MAXXIS | 7 mm |
| R/H Rear Tyre | 195/65 R15 | MAXXIS | 7 mm |
| L/H Rear Tyre | 195/65 R15 | MAXXIS | 7 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 19/02/2019 | Inspection Date | 20/02/2019 |
| Survey held at | PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|