

ASS. REC. BY:

REP:

es/FCI 19003270/Uqd3er

Special Instruction:

SMV/Veh/Vol  
CWS

Marius

ASSIGNMENT (Office)

From (Person):

Meina Chia

of

FCI

Date/Time:

12.52p m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

FBE 7162U

Insured:

SHA 8824L

at Workshop m/s:

Erofina Motor

Tel:

6752 7740

of

1 kaki Blk Ave 6 # 02-62

Policy No.:

Claim No.:

D19001274MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/01/2019

22/2/19

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

1up

Date/Time:

2:25pm @ 21/2/19

Person Contacted:

Lee Lee

Vehicle:

IN/OUT

| Date/Time | Action/Instruction (✓) Estimate                 |
|-----------|---|
|           | FBE 7162U - CS/INC 12080300/Ufd1 DUA: 19/12/11  |
|           | SHA 8824L - CC3/FCI 74018496/Kvm3d1 DUA: 5/6/14 |
| 25/2/19 @ | 10.05am revised to Meina Chia by email.         |
|           |   |
|           |   |
|           |   |

REF: FCE

INSURANCE

Team Date 22/2/19

Estimated Cost

OD (TP) RES / TP RES / OD RES / EVA / INV / MV

Inspected Vehicle No. FBE 71624

at Workshop no. Erofia Motor

at 1 kaki Bkt Ave 6 #02-62

Insured

Policy No.

Claims No.

Sum Insured. Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: S5500

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

GA / REV / REP. / 24 HRS (up) 9/9/2024

Date Person Contacted. Vehicle IN/OUT

Date/Time Action/Intruction

26/2/19 LTA 2477 5 yrs. Fullnet 3023

L/S & 1500 confirmed with AM heavy

Chgd to 3053.40, 61%

RECEIVED 27 FEB 2019

Veh No. FBE 71624 Regn 9 04

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kawasaki KRR 2X650M 149

Colour: s.lver A/S Insured / Std / NI / NA

Sp. Reading: 53967 I/Radio Insured / Std / NI / NA

Eng/No.

C/No: KR150 KA 60658

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80/90-17

R: 100/70-17

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. mm R/Bal. mm

L/Bal. mm L/Bal. mm

D.O.A. 26/1/19 D.O.I 22/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt n/s, 2/s 3/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to:  Prel. Report  Final Report

Date/Time: File Return to?

Report Format TP

Lump Sum / L/P: S500

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee:  Site Insp. \$  Interview \$  Tech. Inv. \$  Weekend \$

|                 |     |
|-----------------|-----|
| Survey Fee:     | 100 |
| Transportation: | 50  |
| Food:           | 68  |
| Other:          |     |
| TOTAL:          | 218 |

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Monday, 25 February 2019 10:05 AM  
**To:** 'CWS Motor Claims'; assignments  
**Cc:** 'Merina Chia San San'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19001274MFSH/1  
**Attachments:** CSFCI19003270Uqd3.pdf

Dear Merina,

Enclosed herewith preliminary advice of FBE 7162U.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 21 February 2019 2:30 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Merina Chia San San' <[MerinaChia@msfirstcapital.com.sg](mailto:MerinaChia@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19001274MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Thursday, 21 February 2019 12:52 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Merina Chia San San <[MerinaChia@msfirstcapital.com.sg](mailto:MerinaChia@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19001274MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001274MFSH

Date: 25 February 2019

Our Ref: CS/FCI19003270/Uqd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. FBE 7162U .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/02/2019 at the premises of M/s EROFIA MOTOR. and have the following to report:-

|                          |                         |
|--------------------------|-------------------------|
| Workshop Estimate Amount | : S\$ <u>5,011.90</u> . |
| Revised Estimate Amount  | : S\$ <u>1,958.50</u> . |
| "Check" Items Amount     | : S\$ <u>-</u> .        |
| Market Value             | : S\$ <u>-</u> .        |
| LTA Reimbursement Value  | : S\$ <u>-</u> .        |
| Nett Value               | : S\$ <u>-</u> .        |

Description of Damage:

The vehicle sustained damages at the front n/s portion & o/s body.



Yours faithfully

CHUA KANG SENG  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

**Date** 20-02-2019 **Our Ref No.** D19001274MFSH

**Accident Date** 26-01-2019 **Claim Type.** Third Party

**Insured Vehicle** SHA8824L **Third Party Vehicle.** FBE7162U

**Survey Location** 1 KAKI BUKIT AVE 6 #02-62

**Contact Person.** LEELEE TAN

**Contact No.** 67527740/ 0 **Fax No.** 67528669

**Survey Type** WITHOUT PREJUDICE:

**Appointed Surveyor** LKK AUTO CONSULTANTS PTE LTD

**Contact Person** NA **Fax No.** 68416315

**Contact Number.** NA

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

**Cc : Workshop** EROFIA MOTOR **Attention.** NIL  
TRADING PTE LTD

**Cc : TP Solicitor** NA **TP Solicitor Fax No.** NA

**Officer Incharge** MERINA CHIA SAN SAN

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

| <b>Vehicle Owner Particulars</b>    |                   |
|-------------------------------------|-------------------|
| Owner ID Type:                      | Singapore NRIC    |
| Owner ID:                           | 1602C             |
| <b>Vehicle Details</b>              |                   |
| Vehicle No.:                        | FBE7162U          |
| Vehicle to be Exported:             | No                |
| Intended Deregistration Date:       | 22 Feb 2019       |
| Vehicle Make:                       | KAWASAKI          |
| Vehicle Model:                      | KRR ZX150 M       |
| Primary Colour:                     | Blue              |
| Manufacturing Year:                 | 2004              |
| Engine No.:                         | KR150EEA60658     |
| Chassis No.:                        | KR150KA60658      |
| Maximum Power Output:               | -                 |
| Open Market Value:                  | \$2,840.00        |
| Original Registration Date:         | 10 Sep 2004       |
| First Registration Date:            | 10 Sep 2004       |
| Transfer Count:                     | 5                 |
| Actual ARF Paid:                    | \$426.00          |
| <b>Intended PARF Rebate Details</b> |                   |
| PARF Eligibility:                   | No                |
| PARF Eligibility Expiry Date:       | -                 |
| PARF Rebate Amount:                 | \$0.00            |
| <b>Intended COE Rebate Details</b>  |                   |
| COE Expiry Date:                    | 09 Sep 2024       |
| COE Category:                       | D - Motorcycle    |
| COE Period(Years):                  | 10                |
| PQP Paid:                           | \$4,157.00        |
| COE Rebate Amount:                  | \$2,477.00        |
| <b>Total Rebate Amount:</b>         | <b>\$2,477.00</b> |

The information contained herein is correct as at 22 Feb 2019

OK

# Kawasaki KRR ZX150

|                   |  |
|-------------------|--|
| Listing Type      | Paid Ad  |
| Brand             | Kawasaki (/listing/usedbike/brand/kawasaki/)                     |
| Model             | Kawasaki KRR ZX150 (/listing/usedbike/model/kawasaki-krr-zx150/) |
| Engine Capacity   | 148cc  |
| Classification    | Class 2B   |
| Registration Date | 15/02/2003   |
| COE Expiry Date   | 14/02/2023 (3 years 11 months left)                              |
| Mileage           | -  |
| No. of owners     | -  |
| Type of Vehicle   | Sport Bikes (/listing/usedbikes/listing/?bike_type=8)            |

**Price: SGD \$6800**

## DETAILS

Kawasaki KRRZX150. Come to Yong Seng Heng Motor! Price is Neg! Trade in/Loan Available!

## SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](/LISTING/USEDBIKES/LISTING/)



Kawasaki KRR ZX150

[\(/listing/usedbike/kawasaki-kawasaki-krr-zx150/5729/\)](/listing/usedbike/kawasaki-kawasaki-krr-zx150/5729/)



Kawasaki KRR ZX150

[\(/listing/usedbike/kawasaki-kawasaki-krr-zx150/4868/\)](/listing/usedbike/kawasaki-kawasaki-krr-zx150/4868/)

**REPUBLIC OF SINGAPORE**  
IDENTITY CARD NO. S1331602C



Name  
**NASIL BIN MOODOO AHAMAD**



Race  
**INDIAN**

Date of Birth  
**14-04-1958**

Sex  
**M**

Country of Birth  
**SINGAPORE**



**REPUBLIC OF SINGAPORE** **DRIVING LICENCE**

License Number **S1331602C**

Name  
**NASIL BIN MOODOO AHAMAD**



Birth Date **14 Apr 1958**

Issue Date **22 Jul 2010**



001877107A

1017192



NRIC No: S1331602C



Blood Group Date of issue  
B+ 10-06-1993

APT BLK 62 TEBAN GARDENS ROAD #03-627  
SINGAPORE 600062  
NRIC No: S1331602C Date: 27/02/2011 (R) No: 8570895

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

|                                | EFFECTIVE DATE |
|--------------------------------|----------------|
| Class 2B Motorcycles =< 200 cc | 22 Jul 2010    |

NP 428A

Licence No: S1331602C



MVA119016002 / VAC - Bukit Batok  
 ENTRY DATE & TIME: 02/02/2019 15:06  
 SUBMITTED BY: SUSAN SEAH SOH ENG

Your NCD will be affected due to late reporting  
 Actual e-Filing Submission Date & Time: 02/02/2019 15:26

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

|                            |                  |
|----------------------------|------------------|
| Date Of Report             | 02/02/2019 15:06 |
| Date Of Accident           | 26/01/2019 13:00 |
| Exact Location Of Accident | ALIWAL STREET    |
| Country/State of Loss      | SINGAPORE        |

#### DETAILS OF OWN VEHICLE

|                             |                         |
|-----------------------------|-------------------------|
| Vehicle Registration Number | FBE7162U                |
| <b>Insured/Policyholder</b> |                         |
| Name Of Registered Owner    | NSAIL BIN MOODOO AHAMAD |
| NRIC No                     | S1331602C               |
| Email Address               | NOEMAIL                 |
| Mobile Phone No             | (LOCAL) +65-93921433    |
| Alternative Phone No        | OFFICE-93921433         |

#### Vehicle Particulars

|              |                       |
|--------------|-----------------------|
| Manufacturer | KAWASAKI              |
| Model        | KRR ZX150 M-149CC (M) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

#### Insurance Company

|                           |                                      |
|---------------------------|--------------------------------------|
| Name of Insurance Company | MSIG INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage          | THIRD PARTY                          |
| Fleet Policy              | NO                                   |
| Policy Number             | MSD/MT/19-394507-CA                  |

Cover Note Number

#### Driver

|                      |                         |
|----------------------|-------------------------|
| Name of Driver       | NSAIL BIN MOODOO AHAMAD |
| NRIC No              | S1331602C               |
| Date Of Birth        | 14/04/1958              |
| Occupation           | INDOOR                  |
| Date Of Driving Pass | 22/07/2010              |
| Driving Experience   | 8 YEARS AND 6 MONTHS    |
| Gender               | MALE                    |
| Mobile Number        | (LOCAL) +65-93921433    |
| Fax Number           |                         |
| Contact Number       | OFFICE-93921433         |
| E-Mail Address       | NOEMAIL                 |

Address 62 TEBAN GARDENS ROAD  
#03-627  
Postcode S600062  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name CLEMENTI N.P.C  
Police Station Address ROAD: 20 CLEMENTI AVE 5, POSTCODE: 129858, COUNTRY: SINGAPORE  
Police Station Contact TEL NO: - FAX NO:  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

PLEASE SEE ATTACHED POLICE REPORT

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHA8824L  
Vehicle Make/Model/Colour TAXI  
Details Of Properties  
Vehicle Category TAXI  
Name of Driver CHUA CHONG BEE  
NRIC/Passport Number S0186032A  
Contact Number 93550088  
Address  
Postcode  
Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

|   |                         |
|---|-------------------------|
| Name  | NASIL BIN MOODOO AHAMAD |
| Approximate Age                                     |                         |
| Injuries Sustain                                    | REFER TO POLICE REPORT  |
| Injured person in which vehicle?                    | FBE7162U                |
| Were seat belts worn?                               |                         |
| Was this injured conveyed to hospital by ambulance? | NO                      |
| Address   |                         |
| Postcode  |                         |

## Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC BUKIT BAYOK (VAC)  
511 Bukit Batok Street 23  
Singapore 659545  
Tel: 6560 3312 Fax: 6569 0722  
Email: vacbh@singnet.com.sg


- 2 FEB 2019

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A large rectangular area with horizontal lines for text. A diagonal line is drawn across the area from the bottom-left to the top-right. The word 'None' is written in the center, with a signature next to it.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

- 2 FEB 2019

IDAC BUKIT BATOK  
 511 Bukit Batok Street 23  
 Singapore 659545  
 Tel: 6560 3312 Fax: 6560 0700  
 Email: info@idac.com.sg

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:


**SINGAPORE  
POLICE FORCE**


T/20190127/2010

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

1 of 3

Report No. T/20190127/2010

**REPORT OF A TRAFFIC ACCIDENT**

|   |            |   |                             |                            |
|---|------------|---|-----------------------------|----------------------------|
| Date/Time Report Made:<br>27/01/2019 04:12    |            | Vide Report No.:  |                             | Station Diary No.:<br>33   |
| <b>Informant's Particulars</b>                |            |   |                             |                            |
| Name of Informant:<br>NASIL BIN MOODOO AHAMAD |            | Address:<br>APT BLK 62 TEBAN GARDENS ROAD #03-627 SINGAPORE<br>600062 |                             |                            |
| ID Type / ID No.:<br>NRIC NO / S1331602C      |            | Contact No.:<br>Home/Office: Mobile: 93921433                         |                             |                            |
| Nationality:<br>SINGAPORE CITIZEN             |            | Email:  |                             |                            |
| Sex:<br>Male                                  | Age:<br>60 | Date of Birth:<br>14/04/1958  | Type of Informant:<br>Rider |                            |
| Race:<br>Indian                               |            | Language:<br>English  |                             | Institution / School Name: |
| Occupation:<br>UNEMPLOYED                     |            | Driving Licence Information:<br>Class: 2B Date of Expiry:             |                             |                            |

|  |                  |                                    |  |                                    |
|--|------------------|------------------------------------|--|------------------------------------|
| <b>General Information of the Accident</b>                   |                  |                                    |  |                                    |
| Type of Accident:  | Injury<br>Others | Drink Drive:<br>No                 | Date/Time of Accident:<br>26/01/2019 13:00 | Type of Location:<br>Straight Road |
| Location:<br>Along Road 1<br>ALI WAL STREET                  |                  |                                    |  |                                    |
| Towards Beach Road, near Alsagoff Arab School                |                  |                                    |  |                                    |
| Weather:<br>Clear  |                  | Road Surface:<br>Dry               | Road Speed Limit:                          |                                    |
| Traffic Flow:<br>One Way                                     |                  | Traffic Control:<br>Not Controlled | Traffic Volume:<br>No Traffic              |                                    |
| Type of Collision:<br>Between Moving Vehicles - Head To Rear |                  |                                    | Anyone conveyed by ambulance:<br>No        |                                    |

| <b>Details of Vehicle Involved</b> |            |          |                |       |                   |                 |
|------------------------------------|------------|----------|----------------|-------|-------------------|-----------------|
| Vehicle No.                        | Type       | Make     | Model          | Color | Condition         | No of Passenger |
| FBE7162U                           | Motorcycle | KAWASAKI | KRR ZX150<br>M | Blue  | Seriously Damaged | 0               |
| SHA8824L                           | Car        |          |                |       | Slightly Damaged  | 0               |

| <b>Details of Vehicle Insurance</b> |   |                |            |             |
|-------------------------------------|---|----------------|------------|-------------|
| Vehicle No.                         | Insurance Company                       | Insurance No.  | Effective  | Expiry Date |
| FBE7162U                            | MSIG INSURANCE (SINGAPORE)<br>PTE. LTD. | MSDTMT19394507 | 27/01/2019 | 26/01/2020  |



**SINGAPORE  
POLICE FORCE**



T/20190127/2010

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

2 of 3

Report No. T/20190127/2010

## CONTINUATION OF REPORT

|                                   |                              |  |                                   |
|-----------------------------------|------------------------------|--|-----------------------------------|
| Any Pedestrian Involved: No       |                              |  |                                   |
| No. of Pedestrians Injured: NIL   |                              | Use of Pedestrian Crossing: NA         |                                   |
| Name                              | NASIL BIN MOODOO AHAMAD      | ID No.                                 | S1331602C                         |
| Related Vehicle                   | FBE7162U (Motorcycle)        | Contact No.                            | 93921433                          |
| Hospital/Clinic                   | NATIONAL UNIVERSITY HOSPITAL | Class of Driving Licence & Expiry Date | Class: 2B<br>Date of Expiry: NIL  |
| Date Treatment                    | 27/01/2019                   | Date Discharge                         | 27/01/2019                        |
| No. of Days granted Medical Leave | 05                           | Degree of Injury                       | Slight                            |
| Name                              | Chua Chong Bee               | ID No.                                 | S0186032A                         |
| Related Vehicle                   | SHA8824L (Car)               | Contact No.                            | 93550088                          |
| Hospital/Clinic                   | NIL                          | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                    | NIL                          | Date Discharge                         | NIL                               |
| No. of Days granted Medical Leave | NIL                          | Degree of Injury                       | NIL                               |

**Brief Details.**

On 26/01/19, at about 1300hrs, I was on my-bike, riding along Aliwal Street, near the Alsagoff Arab school, when I saw one taxi reversing ahead of me, at the parking lot along the side of the road. Hence, I stopped my bike and I waited for him to reverse. However, the taxi driver in front, kept reversing and eventually collided into my bike, causing my bike to fall over, towards the right. I tried to get out of the way, resulting in an minor injury to my left leg as I fell trying to get out of the way. The taxi driver, upon realizing that he had collided into my bike, got down from the taxi. Passers-by helped me to stand up. No ambulance was called as only minor injuries involved. The taxi driver gave me his particulars and I took them down along with his vehicle registration no. SHA 8824L. However, later on in the evening, I went to NUH as the pain in my left leg was too much and I wanted to see a doctor to get help. The doctor gave me 5 days MC from 28/01/19 to 01/02/19. There were damages to the right-side and front part of the fairing, front wind screen and the front part of the body of my bike and my left side mirror.



**SINGAPORE  
POLICE FORCE**



T/20190127/2010

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

3 of 3

Report No. T/20190127/2010

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

|   |
|---|
| Signature Of Officer Recording The Report:<br>D /<br>Insp MENAKAH D/O THIAGARAS                 |
| Signature Of Interpreter:<br>Not applicable   |
| Officer In Charge Of Case:<br>TP / AEIT /<br>SSI 2 JUREMAH BINTE AHMAD<br>Contact No.: 65472076 |

|  |
|--|
| Signature Of Informant:<br><i>Mali</i> |
| Date/Time:<br>27/01/2019 04:12         |
| Classification Of Case:                |

Authentication Stamp  
NP168

|             |                           |       |
|-------------|---------------------------|-------|
|             | SINGAPORE<br>POLICE FORCE | SN 37 |
| <i>Mali</i> |                           |       |
| SIGNATURE   |                           |       |

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

*First*

Owner : Nsail Bin Moodoo Ahamad

Accident Date : 26-Jan-19

Vehicle No : FBE 7162 U

Vehicle Model : KAWASAKI KRR

## Estimated Repair Costs

| Qty      | Description<br><u>List Items</u> | Amount S(\$)  |
|----------|----------------------------------|---------------|
| 1        | Front fender                     | \$ 75.00 X    |
| 1        | Top cowling                      | \$ 210.00     |
| 1        | Windshield                       | \$ 95.00      |
| 2        | Fork inner tubes                 | \$ 300.00 X   |
| 2        | Fork outer tubes                 | \$ 320.00 X   |
| 1        | Fork under bracket               | \$ 155.00 X   |
| 1        | Front rim shaft                  | \$ 38.00 X    |
| 1        | Front brake disc                 | \$ 165.00 X   |
| 1        | Front sport rim                  | \$ 320.00 X   |
| 1        | Lampstay                         | \$ 100.00 X   |
| 2        | Front signals                    | \$ 90.00      |
| 2        | Side mirrors                     | \$ 120.00     |
| 1        | Handle bar                       | \$ 90.00 X    |
| 1        | Hand grip (1 set)                | \$ 80.00 X    |
| 1        | Brake lever                      | \$ 32.00      |
| 1        | Clutch lever                     | \$ 32.00 X    |
| 1        | Air intake duct -L/H             | \$ 85.00 X    |
| 2        | Side fairings                    | \$ 320.00 1pc |
| 1        | Front footrest -R/H              | \$ 38.00      |
| 1        | Front footrest bracket           | \$ 60.00 X    |
| 1        | Brake pedal                      | \$ 45.00      |
| 1        | Rear footrest -R/H               | \$ 40.00      |
| 1        | Rear tailboard -R/H              | \$ 148.00 X   |
| 1        | Rear signal -R/H                 | \$ 38.00 X    |
| 1        | Exhaust pipe                     | \$ 485.00     |
|          |                                  | \$ 3,481.00   |
| Less 10% |                                  | \$ 348.10     |
|          |                                  | \$ 3,132.90   |

*Not Allowed*

*2000*

*H/S \$1500*

*4 day*

*Take up to 10% off*

*22/1/19*

*m.s/*

*o/s*

*1315*

*11835*

c/f: \$ 3,132.90

**Special Nett Items**

|   |                       |    |     |               |    |
|---|-----------------------|----|-----|---------------|----|
| 1 | Number plate (1 set)  | \$ | 111 | 28.00         | 10 |
| 2 | Fork oils             | \$ | 11  | 30.00         | X  |
| 2 | Fork oil seals        | \$ | 11  | 56.00         | X  |
| 1 | Steering cone (1 set) | \$ | 11  | 75.00         | X  |
| 1 | Rear box              | \$ | CU7 | 180.00        | —  |
| 1 | Rear box bracket      | \$ | 11  | 100.00        | X  |
| 1 | Helmet                | \$ | 11  | 150.00        | X  |
|   |                       | \$ |     | <u>619.00</u> |    |

**S/No. Labour**

|   |  |    |  |                 |     |
|---|--|----|--|-----------------|-----|
| 1 | To provide towing service.                   | \$ |  | 50.00           | 35  |
| 2 | To check wiring and reset headlamp focusing. | \$ |  | 80.00           | X   |
| 3 | To provide labour.                           | \$ |  | 380.00          | 250 |
| 4 | To respray painting.                         | \$ |  | 750.00          | 300 |
|   |  | \$ |  | <u>1,260.00</u> |     |

**Grand Total** \$ 5,011.90

1558.5

Dollars: Five Thousand Eleven And Ninety Cents Only.

**EROFIA MOTOR TRADING PTE LTD**

Let us know if you have any queries notify  
 any feedback or complaints to:

- \* Customer Service Department - Writing
- \* Transport Department - Towing recovery
- \* Sales and Marketing Department - Information
- \* Fleet Management Department - "Without Prejudice" basis
- \* Insurance Department - Claims handling

\* All services are provided on a "Without Prejudice" basis  
 and are subject to the approval of the insurance company.

Acknowledged by Repaire:  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                             |   |
|--|---|-----------------------------|---|
| MS FIRST CAPITAL INSURANCE LTD   |   | Ref : CS/FCI19003270/Uqd3e2 |   |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877  |   | Date : 28-02-2019           |  |
|  |   | Code : FCI2                 |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |                             |   |
| Insured Veh.   | SHA 8824L   | Veh. Inspected              | FBE 7162U   |
| Policy No.   |   | Coverage (\$)               | 0.00  |
| Claim No.  | D19001274MFSH   | Excess (\$)                 | 0.00  |
| Assign From  | MERINA CHIA   | Assign Date                 | 21/02/2019  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                             |   |
| Make & Model   | KAWASAKI KRR ZX150 M  | c.c                         | 149   |
| Engine No.   | HIDDEN  | Year of Reg.                | 2004  |
| Chassis No.  | KR150KA60658  | Colour                      | SILVER  |
| Odometer   | 53967   | Steering                    | IN ORDER  |
| Brakes   | IN ORDER  | Modification                | SPORTS RIM  |
| General  | GOOD  |                             |   |
| <b>3. Conditions of Tyres</b>  |   |                             |   |
|  | Size  | Make                        | Balance   |
| R/H Front Tyre   | 80/90-17  | DUNLOP                      | 6 mm  |
| L/H Front Tyre   |   |                             | mm  |
| R/H Rear Tyre  | 100/70-17   | DUNLOP                      | 6 mm  |
| L/H Rear Tyre  |   |                             | mm  |
| <b>4. Description of Damages</b>   |   |                             |   |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT N/S PORTION.<br>DAMAGES SEE DETAILS.   |   |                             |   |
| <b>5. General Information</b>  |   |                             |   |
| Accident Date  | 26/01/2019  | Inspection Date             | 22/02/2019  |
| Survey held at   | EROFIA MOTOR TRADING PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#02-62<br>SINGAPORE 417883 |                             |   |
| <b>5a. Remarks</b>   |   |                             |   |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                             |   |
| <b>5b. Estimate Days of Repair</b>   |   |                             |   |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | <b>4 Working Days</b>       |   |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 7162U

| Qty                         | Description of Parts   | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                        |                      |                           |                   |
| 1                           | FRONT FENDER           | TO REPAIR SEE LABOUR | 75.00                     | -                 |
| 1                           | TOP COWLING            | CRACKED              | 210.00                    | 210.00            |
| 1                           | WINDSHIELD             | CRACKED              | 95.00                     | 95.00             |
| 2                           | FORK INNER TUBES       | TO REPAIR SEE LABOUR | 300.00                    | -                 |
| 2                           | FORK OUTER TUBES       | TO REPAIR SEE LABOUR | 320.00                    | -                 |
| 1                           | FORK UNDER BRACKET     | NOT NECESSARY        | 155.00                    | -                 |
| 1                           | FRONT RIM SHAFT        | NOT NECESSARY        | 38.00                     | -                 |
| 1                           | FRONT BRAKE DISC       | NOT NECESSARY        | 165.00                    | -                 |
| 1                           | FRONT SPORT RIM        | TO REPAIR SEE LABOUR | 320.00                    | -                 |
| 1                           | LAMPSTAY               | NOT NECESSARY        | 100.00                    | -                 |
| 2                           | FRONT SIGNALS          | SCRATCHED            | 90.00                     | 90.00             |
| 2                           | SIDE MIRRORS           | MISSING / CUT        | 120.00                    | 120.00            |
| 1                           | HANDLE BAR             | TO REPAIR SEE LABOUR | 90.00                     | -                 |
| 1                           | SET HAND GRIP          | NOT NECESSARY        | 80.00                     | -                 |
| 1                           | BRAKE LEVER            | SCRATCHED            | 32.00                     | 32.00             |
| 1                           | CLUTCH LEVER           | SERVICEABLE          | 32.00                     | -                 |
| 1                           | AIR INTAKE DUCT - L/H  | NOT NECESSARY        | 85.00                     | -                 |
| 2                           | SIDE FAIRINGS          | O/S CUT              | 320.00                    | 160.00            |
| 1                           | FRONT FOOTREST - R/H   | CUT                  | 38.00                     | 38.00             |
| 1                           | FRONT FOOTREST BRACKET | NOT NECESSARY        | 60.00                     | -                 |
| 1                           | BRAKE PEDAL            | BENT                 | 45.00                     | 45.00             |
| 1                           | REAR FOOTREST - R/H    | CUT                  | 40.00                     | 40.00             |
| 1                           | REAR TAILBOARD - R/H   | TO REPAIR SEE LABOUR | 148.00                    | -                 |
| 1                           | REAR SIGNAL - R/H      | NOT NECESSARY        | 38.00                     | -                 |
| 1                           | EXHAUST PIPE           | DENTED / BENT        | 485.00                    | 485.00            |
|                             | LESS 10% DISCOUNT      |                      | -348.10                   | -131.50           |
|                             |                        |                      | 3,132.90                  | 1,183.50          |

Report Ref No. CS/FCI19003270/Uqd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
|     | <b>SPECIAL NETT ITEMS</b>   |                      |                           |                   |
| 1   | SET NUMBER PLATE (SN)   | NECESSARY            | 28.00                     | 10.00             |
| 2   | FORK OILS (SN)  | NOT NECESSARY        | 30.00                     | -                 |
| 2   | FORK OIL SEALS (SN)   | NOT NECESSARY        | 56.00                     | -                 |
| 1   | SET STEERING CONE (SN)  | NOT NECESSARY        | 75.00                     | -                 |
| 1   | REAR BOX (SN)   | CUT                  | 180.00                    | 180.00            |
| 1   | REAR BOX BRACKET (SN)   | TO REPAIR SEE LABOUR | 100.00                    | -                 |
| 1   | HELMET (SN)   | TO REPAIR SEE LABOUR | 150.00                    | -                 |
|     |   |                      | 619.00                    | 190.00            |
|     | <b>LABOUR</b>   |                      |                           |                   |
|     | TO PROVIDE TOWING SERVICE.  |                      | 50.00                     | 35.00             |
|     | TO CHECK WIRING AND RESET HEADLAMP FOCUSING.  | NOT NECESSARY        | 80.00                     | -                 |
|     | TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT FENDER, FORK INNER TUBES, FORK OUTER TUBES, FRONT SPORT RIM, HANDLE BAR, REAR TAILBOARD - R/H, REAR BOX BRACKET AND HELMET. |                      | 380.00                    | 250.00            |
|     | TO RESPRAY PAINTING.  |                      | 750.00                    | 300.00            |
|     |   |                      | 1,260.00                  | 585.00            |
|     | <b>GRAND TOTAL</b>  |                      | <b>5,011.90</b>           | <b>1,958.50</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>   |                      |                           | <b>1,500.00</b>   |

Report Ref No. CS/FCI19003270/Uqd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.