

12/03/2002

ASS. REC. BY:

REF: 03/SMO19003274/Bsd3

Special Instruction:

Surveyor
Munmen

ASSIGNMENT (Office)

Date/Time: 21/2/2019 @ 11:59am

From (Person): Ruth chug

of SMO

Bill to:

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MY / CS

Insured:

PC317IP

To Inspect Vehicle No:

SLT533SD

Tel:

66791146

at Workshop m/s

Allswell Motor

of

25 Defutene 9

Policy No:

D18MTSCB4000698

Claim No:

CMTD1901001

Sum Insured:

Excess:

Make of Vch:

D.O.A

20/02/2019

(Client's Record)

23/2/19 @ p (ow)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

208pm @ 21/2/19

Person Contacted:

chen yue

Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

SLT533SD-X

PC317IP-CS/FCI-17002438/K1th3n2

DVA: 22/1/17

04/03/19

@ 09:33 a.m. revised IA to Ruth chug Gede the Tiary
via munmen.

REF: SMO

ASSIGNMENT

Form Date: 28/2/19

Estimated Cost

OD: ☒ WBS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 8LT 5335D

at Workshop no: Allswell

of 25 Defu Lane 9

Insured

Policy No.

Claims No.

Sum Insured

Excess:


(Client's Record)

Make of Vehicle

1pm @ owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repair:

4 days Res: Yes or No

Lump Sum:

3 Val: Yes or No

CA / REV / REP. / 24 HRS lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: 8LT 5335D

Reg No: 31/16/2017

Type: ☒ Car / ☐ M/Cycle / ☐ Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA VEZEL

CC: 1496

Colour: Silver

A/C: Insured / Std / Nil / NA

Sp Reading: 137850

T/Radio: Insured / Std / Nil / NA

Eng No: LEB5961916

Chassis: RU3 1261899

Gen Cond: Good / Fair / Poor / Burnt

Steering: ☒ Order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ R/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXIMUS

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 20/2/19

D.O.I: 25/2/19

Survey held at Allswell

Des. of Damages: Fnt / Rear / ☒ N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Range 2,000/2 - 3,000/2

Part by Part repair

Repair Cost - 1,532.50

(\$ 2,615.00 Red - 63%) 27/9/19

MV 78,000/2

PV 45,418/2

NV 32,582/2

RECEIVED 30 SEP 2019

Finalised with Chai Yee

on 27/9/19 @ 0902 hrs

TGRM 27/9/19

TGRM 1/3/19

Date/Time: File Pass to:

27/09/19

Code/Time: File Return to:

Typist



Prel. Report



Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

Y: S + RS: 0

Y: Helos

Y: Other

Y: Other

TOTAL

Add Fee:



Site Insp: \$



Interview: \$



Tech. Inv: \$



Weekend: \$

Report Format:

Lump Sum: 1.532.50 P/P

\$1,532.50 P/P

250
11

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Feb 2019		21 Feb 2019 11:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LAY GEOK SERVICES, Co. Reg. No.: 53275719W		
Main Claimant:	ALLSWELL MOTOR TRADERS, Co. Reg. No.: 53192889J		
Vehicle Reg. No.:	SLT5335D	Date of Loss:	20/02/2019 01:00 - :59
Claim Type:	TP / CMTD1901001	Policy/Cover Note No.:	D18MTSCBU000698 (Comprehensive)
Vehicle Reg. No. (Insured):	PC3171P	Policy No. (Claimant):	
		Excess:	
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/03/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 04 Mar 2019

Preliminary Advice

Insured Vehicle No : PC3171P
TP Vehicle No : SLT5335D
Make : HONDA VEZEL
Date of Inspection : 25/02/2019
Inspection At : Allswell Motor Traders (HQ)
25 Defu Lane 9
Singapore 539266

Accident Date : 20/02/2019
Assignment Date : 21/02/2019
Est. Duration of Repair : 4 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,147.50
Revised Amount	:S\$	1,532.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,532.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/02/2019 15:23
Date Of Accident	20/02/2019 01:25
Exact Location Of Accident	CHOA CHU KANG DR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT5335D
Insured/Policyholder	
Name Of Registered Owner	ALLSWELL MOTOR TRADERS
Co Reg No	53192889J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64625405

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 HYBRID X (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999994368
Cover Note Number	06 NOV 2018 TO 05 NOV 2019

Driver

Name of Driver	ANG SING HONG
NRIC No	S0207064B
Date Of Birth	10/07/1952
Occupation	OUTDOOR
Date Of Driving Pass	20/12/2010
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82734311
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	APT BLK 505 TAMPINES CETRAL 1 #02-345
Postcode	520505
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER & LEASEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER WITH ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC3171P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	91050791
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name

ANG SING HONG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

20/02/17

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20/02/19 about 1.25 am. I was travelling along
Chia Chu Kang br and moving straight. Suddenly a
van PC 3771P banged my car rear right side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 20/02/19

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2889J
Vehicle Details	
Vehicle No.:	SLT5335D
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	LEB5961916
Chassis No.:	RU31261899
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$25,290.00
Original Registration Date:	31 Oct 2017
First Registration Date:	31 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,109.00
COE Rebate Amount:	\$41,668.00
Total Rebate Amount:	\$45,418.00

The information contained herein is correct as at 01 Mar 2019

OK

Avg Dep 8,000/2

MV 78,000/2

PV 45,418/2

NV 32,582/2

hi
1/3/18



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

July 2014 Audi Q3 2.0A TFSI Quattro, 56000Km Only



Fully Agent Maintain, Car In Tip
Top Condition, View And Test
Drive To Believe!
Auto Zoom Enterprise [StarAd](#)



Browse by Category

« Back (1 2 3 4 5 ... 21) Next »

Sort by Date Posted

20 results/page

Advanced Search



403 vehicles

Honda Vezel

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Vezel		Any	Any	Any	Any	Any	Any	All
	Honda Vezel	1.5A X	\$62,000	\$8,610 /yr	26-Oct-2015	1,496 cc	33,000 km	SUV	Available
Well Taken Care Of Interior And Exterior As Good As New! Excellent Fuel Efficiency, Reliable SUV For Your Daily Driving. Comes With GPS System! Flexible Loan And Trade In Options Available. Call Or Me...									
Posted: 01-Mar-2019 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel	1.5A X	\$62,800	\$8,340 /yr	23-Feb-2016	1,496 cc	-	SUV	Available
3 Warranty From Our In House Workshop. Excellent Condition, Accident Free, No Repairs Needed. Bank Loan/In House Loan Available, Trade In Welcome. Call Our Senior Consultant For More Photos And Detail...									
Posted: 28-Feb-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel	1.5A X Honda Sensing	\$73,800	\$8,680 /yr	25-Oct-2016	1,496 cc	48,566 km	SUV	Available
One And Only One Nicely Done Up Vezel With More Than \$10k Worth Accessories. One Regular Officer Selling Due To Oversea Posting. Well Maintain With No Touchup Needed. Honda Sensing Model.									
Posted: 28-Feb-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel	1.5A X	\$66,800	\$8,400 /yr	22-Jul-2016	1,496 cc	33,222 km	SUV	Available
Up To 90% Loan Available, Low Mileage Done, Vehicle Inspected And Checked, No Repair Needed, Trade In Welcome, View Now!									
Posted: 28-Feb-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Santa Fe takes on Honda and Mitsubishi Is the new Hyundai Santa Fe good enough to beat the well-rounded Honda CR-V and the value-for-money Mitsubishi Outlander? Read this article								
	Honda Vezel	1.5A X	-	N.A	09-Jun-2016	1,496 cc	-	SUV	SOLD
Please Contact For Viewing.									
Posted: 28-Feb-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel	1.5A X	\$72,800	\$8,250 /yr	26-Apr-2017	1,496 cc	32,000 km	SUV	Available
Very Low Mileage With Servicing Record! Come With One Year Premium Warranty. Brand New Tyres! Perfect Condition! Look Like Brand New! High Loan At Low Interest Rate! Trade In Available. Viewing By App...									
Posted: 28-Feb-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel	Hybrid 1.5A X	\$78,800	\$9,210 /yr	06-Jun-2017	1,496 cc	31,652 km	SUV	Available
Fuel Type: Petrol-Electric Low Interest Rate. In-house Financing Available. Consignment Unit. Viewing By Appointment Only. Just Been Serviced And Replaced Transmission Oil. Balloon Scheme, In House Financing Options Available. ... GOWHEELER Pte Ltd									
Posted: 28-Feb-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									

Compare

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email:ben@allswellmotor.com.sg

(3rd party claim against Sampo Insured PC3171P
(DOA: 20.02.2019)

Estimate repair

Vehicle No. : SGT 5335 D

Submitted by :

Make & Model : Honda Vezel

COE expiry :

Chassis No. : Hybrid 1.5X Auto

Engine No. :

Date of survey : 25/2/19

Ben

30-10-2027

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	RH rear top bumper (side)	01	#293.00	CUT ✓	
02	RH rear fender	01	#695.00	R X	* repair
03	RH rear fender arc	01	#197.50	SCR ✓	
04	RH rear door	01	#960.00	R X	* repair
			490.50		
	Special net				
01	Clips / retainer studs for bumper, fender, fender arc @ #42/pkt	01	#42.00	NEC ✓	
	Labour Description				
01	Panel knocking on RH rear fender inclusive removing / assemble of interior upholstery	01	#660.00	300.00	
02	Panel / touchup of RH rear door	01	#150.00	100.00	
03	Disassemble / Assembly of side near RH bumper & fender arc	01	#150.00	180.00	
04	Spray painting of all affected parts including anti-rust paint, polish & wash	01	#1,000.00	500.00	
			4,142.50	1600	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

Repair Days 4 days
Part by part repair

Lim Teow Guan
him

1318 hrs

25/2/19

Repair cost 1532.50

Parts 490.50
SN 42.00
Labour 1000.00
1532.50

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Feb 2019		21 Feb 2019 11:59 Edit Adj Rpt	S\$1,532.50 Edit Estimates	S\$1,532.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LAY GEOK SERVICES, Co. Reg. No.: 53275719W		
Main Claimant:	ALLSWELL MOTOR TRADERS, Co. Reg. No.: 53192889J		
Vehicle Reg. No.:	SLT5335D	Date of Loss:	20/02/2019 01:00 - :59 [15 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1901001	Policy/Cover Note No.:	D18MTSCBU000698 (Comprehensive)
Vehicle Reg. No. (Insured):	PC3171P	Policy No. (Claimant):	
		Excess:	
Repairer:	Allswell Motor Traders (HQ) 25 Defu Lane 9, 539266 Defu Lane - Tel: 66791146		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 04/03/2019]		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLT5335D (CMTD1901001)**
[PC3171P]

TP

ALLSWELL MOTOR TRADERS

Feb 20 2019 1:00AM

[LAY GEOK SERVICES]

Allswell Motor Traders

Upload Documents Upload Photos Compose New Letter			View View in Browser	
			1 per page	<input checked="" type="checkbox"/>
Assessment Reports				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/03/19 09:33	Adjuster Immediate Advice	Load HTM	<input checked="" type="checkbox"/>
			3 per page	<input checked="" type="checkbox"/>
Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
2	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
3	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
4	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
5	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
6	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
7	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
8	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
9	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
10	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
11	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
12	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
13	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
14	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
15	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
16	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
17	27/09/19 13:31	General View	Load JPG	<input checked="" type="checkbox"/>
18	27/09/19 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	27/09/19 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	27/09/19 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	27/09/19 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
22	27/09/19 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
23	27/09/19 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
24	27/09/19 17:42	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
			1 per page	<input checked="" type="checkbox"/>
Documentation				
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	21/02/19 11:16	Pre-Repair Survey - SAS	Load PDF	<input checked="" type="checkbox"/>
2	21/02/19 11:59	Pre-Repair Survey - AGREED LKK	Load PDF	<input checked="" type="checkbox"/>
3	21/02/19 14:23	Certificate of Insurance	Load PDF	<input checked="" type="checkbox"/>
4	21/02/19 14:30	SIU checklist	Load PDF	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19003274/BSD3S2
Date: 02/10/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTSCBU000698
Claimant Vehicle No : SLT5335D **Insured Vehicle No :** PC3171P
Date of Loss: 20/02/2019 **Nature of Claim:** TP **Claim No:** CMTD1901001

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT5335D **Engine No:** LEB5961916
Make & Model: HONDA VEZEL, 1.5 HYBRID X (A) **Chassis No:** RU31261899
Reg. Date: 31/10/2017 (Man. Year: 2017) **Odometer:** 137850 km
Colour: Silver
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 215/60R16 **Rear Tyre Size:** 215/60R16
Front Left Side: MAXIMUS 6 mm **Rear Left Side:** MAXIMUS 6 mm
Front Right Side: MAXIMUS 6 mm **Rear Right Side:** MAXIMUS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,187.50	532.50	1,655.00	75.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,000.00	960.00	48.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	4,147.50	1,532.50	2,615.00	63.05

INSPECTION

Date of Assignment: 21/02/2019
Date Inspected: 25/02/2019 **Inspected At:** 25 Defu Lane 9
Singapore 539266
Repairer: Allswell Motor Traders
Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT5335D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR TOP BUMPER (SIDE)	Cut	293.00 F	*293.00 F
2	1		*RH REAR FENDER	Repair	695.00 F	*- F
3	1		*RH REAR FENDER ARC	Scratched	197.50 F	*197.50 F
4	1		*RH REAR DOOR	Repair	960.00 F	*- F
5	1		*CLIPS/RETAINER STUDS FOR BUMPER,FENDER,FENDER ARC	Necessary	42.00 FS	*42.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					2,187.50	532.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL KNOCKING ON RH REAR FENDER INCLUSIVE REMOVING/ASSEMBLE OF INTERIOR UPHOLSTERY	New	660.00	300.00
2	PANEL/TOUCH UP OF RH REAR DOOR	New	150.00	100.00
3	DISMANTLE/ASSEMBLY OF SIDE REAR RH BUMPER & FENDER ARC	New	150.00	100.00
4	SPRAY PAINTING OF ALL AFFECTED PARTS INCLUDING ANTI-RUST PAINT POLISH & WASH	New	1,000.00	500.00
Gross Labour Cost (S\$)			1,960.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >