

22/02/2019

ASSIGNMENT BY

REP

CS/FWD19003291/Fwd3

Special Instruction

SAI Vajid merimen

Stave Jusy loh

ASSIGNMENT (Office)

of PWD

Date/Time: 20/2/19 @ 3:05pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SKL 8139M

Insured:

at Workshop n/s

Fthoz

Tel:

9624 8656

of

30 Bukit Batok

Policy No:

PMPV2018-00016750

Claim No:

1201900004748

Sum Insured:

Excess:

\$600.00

Make of Veh:
(Client's Record)

D.O.A.

17/02/2019

21/2/19
H.O.D. Endorsement

CA / KEV REP. / REV 24 HRS

Date/Time:

12:47pm @ 21/2/19

Person Contacted:

Shah

Vehicle:

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKL 8139M - x
22/2/19	Revert via merimen
22/2/19	Rece approved \$ 6617.50 from Jusy by merimen
22/2/19	Informed Shahh c/A ex \$600 by email
7/3/19	@ 350pm Shahh said vehicle pending for spare parts

Steve

REF: FWD

INSURANCE

File 21/2/19

Vehicle No SKL 8139M

Reg No 26/12/13

Type Car / Motorcycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make AUDI A6

CC 201984

Colour White

AC Insured / STD / NI / NA

Sp Reading 99485

TK/Ado Insured / STD / NI / NA

Eng/No

CRNo W44 222 40 8EN 060155

Gen. Cond Good / Fair / Poor / Burnt

Steering Inorder / Jammed / Leaked / Burnt or

Brake Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size F: 225/55R17

R: .1

BS / DUN / EXNOVA / GY / FS / LIZA MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal 8 mm R/Bal 8 mm

U/Bal 8 mm U/Bal 8 mm

D.O.A. 17/2/19 D.O.I. 21/2/19

Survey held at Etho2

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front RH, RH Side

The UIC / Chassis frame / Body Structure affected due to collision.

Insured Cost

TP/WS / TP/RES / OD/RES / EVA / HIV / MV

Insured Vehicle No

SKL 8139M

Insured Workshop No

Etho2

Insured

30 Blk Butok Crescent

Insured Policy No

Insured Claim No

Insured Sum Insured


Excess: \$60000

(Client's Record)

Make of Vehr

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. of Market Value

\$83K.

IDAC Accident Report

Consistent? : Yes or No

GTA / PH Seen

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lump Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

28/3/19 Recd approved \$12,094 from Josey by merimen

29/3/19 Final fig \$12,094 (Recd 1685, 1290) confirmed by email 28/3/2019

RECEIVED 29 MAR 2019

Date/Time: File Pass to?

Profi. Report

Days Of Repair: 5

Date/Time: File Return to?

Final Report

Resurvey No. of Trip: 2

Survey Fee

Transportation

29/3- typist

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Insp (\$)

Workshop (\$)

Report Format:

merimen

Lump Sum / L.B.F. (\$)

12,094 / 2

250
150
50+50
10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Feb 2019 Sendback Est	20 Feb 2019 12:10 S\$8,328.00	20 Feb 2019 15:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: **PANG CHONG NING**, ID: S1785889J, Tel: +6581213112, Email: NOEMAIL

Vehicle Reg. No.: SKL8139M	Date of Loss: 17/02/2019 07:00 - :59 [61 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type: OD / 1201900004748	Policy/Cover Note No.: PNPV2018-00016750 (Comprehensive)
	Excess: S\$600.00

Repairer: **ETHOZ Protect Pte Ltd (Bukit Batok)** 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51

Handling Insurer: **FWD Singapore Pte. Ltd. (HQ)** - Tel: 6727 5700 ... [Handled by **Josey Loh**]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Final Rpt due 01/03/2019]

Driver/Custodian: **PANG CHONG NING (52 / Male)**, NRIC: S1785889J, Tel: +6581213112

Vehicle Source:	Tow-In/Call-man
-----------------	-----------------

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :
SKL8139M (1201900004748)
OD
Feb 17 2019 7:00AM
[PANG CHONG NING]
ETHOZ Protect Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 28/03/2019 16:50 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12094.00) - SKL8139M - Claim Handler: Josey Loh

Approved:12094.00.

DOCUMENTS SUMMARY
There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Josey Loh	
Date: 28 Mar 2019	
<h3 style="margin: 0;">Preliminary Advice</h3>	

Vehicle No	: SKL8139M	Accident Date	: 17/02/2019
Make	: AUDI A6	Policy No.	: PNPV2018-00016750
Assignment Date	: 20/02/2019	Excess	: S\$600.00
Date of Inspection	: 21/02/2019	Est. Duration of Repair	: 5.00
Inspection At	: ETHOZ PROTECT PTE LTD (BUKIT BATOK) 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,779.00 (incl.supplementary \$5451)
Revised Amount	:S\$	12,094.00 (incl.supplementary \$5451)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,094.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	63,689.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,311.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

View Sent Message

This mail is associated with :

SKL8139M (1201900004748)

OD
Feb 17 2019 7:00AM
[PANG CHONG NING]
ETHOZ Protect Pte Ltd

Resend View Recipients Print Message Delete Message Forward

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 27/03/2019 12:33 PM.
To josey.loh@fwd.com
Subject SKL 8139M-SUPPLEMENTARY

Dear Josey,

We have received supplementary from repairer and it is still economical to repair.

Please refer supplementary uploaded.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 22 February 2019 4:34 PM
To: SUR; Selamatshahh Zainal
Subject: SKL 8139M-DOA: 17/2/2019 (FWD OD)

Dear Shahh,

As instructed by our client , please proceed to repair the **insured vehicle SKL 8139M (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SKL8139M (1201900004748)

OD

Feb 17 2019 7:00AM

[PANG CHONG NING]

ETHOZ Protect Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on **22/02/2019 16:04 PM.**
To LKK_HQ
Subject **Alert - Adj Mandate Approved (S\$6617.50) - SKL8139M - Claim Handler: Josey Loh**

Approved:6617.50:Hi! Please re-seek mandate on check items after being verified

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Josey Loh	Date: 22 Feb 2019
<u>Preliminary Advice</u>	

Vehicle No	: SKL8139M	Accident Date	: 17/02/2019
Make	: AUDI A6	Policy No.	: PNPV2018-00016750
Assignment Date	: 20/02/2019	Excess	: S\$600.00
Date of Inspection	: 21/02/2019	Est. Duration of Repair	: 5.00
Inspection At	: ETHOZ PROTECT PTE LTD (BUKIT BATOK) 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,328.00
Revised Amount	:S\$	5,767.00
Check Items (Estimated)	:S\$	1,701.00
Total	:S\$	7,468.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	63,689.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,311.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/02/2019 10:29
Date Of Accident	17/02/2019 07:00
Exact Location Of Accident	NILAI/SEREMBAN E2 NORTH SOUTH HIGHWAY 265.1KM
Country/State of Loss	MALAYSIA/NEGERI SEMBILAN DARUL KHUSUS

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL8139M
Insured/Policyholder	
Name Of Registered Owner	PANG CHONG NING
NRIC No	S1785889J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81213112
Alternative Phone No	OFFICE-81213112

Vehicle Particulars

Manufacturer	AUDI
Model	A6-2.0 TFSI MU (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00016750
Cover Note Number	26/12/2018-25/12/2019

Driver

Name of Driver	PANG CHONG NING
NRIC No	S1785889J
Date Of Birth	01/01/1967
Occupation	INDOOR
Date Of Driving Pass	20/04/1989
Driving Experience	29 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81213112
Fax Number	
Contact Number	OFFICE-81213112
EEmail Address	NOEMAIL

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims.
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 18/2
 9:30am

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


 Kenneth

Reporting Centre Personnel's Signature
Name: Kenneth
NRIC/FIN No.:

Seremban

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Early drive from Klang Malaysia to Singapore starts 6.30 am.
 At about 81.1 km point toward Singapore (E2 265.1 km), a large lorry tire appeared in the middle lane where I am negotiating a bend. Try to avoid the tired from a full frontal collision, I swayed left but still hit the idle tire. The car went in a left-right spin and after straightening the car, I have to stop and inspect. The car has a bad knock on bumper and coolant is leaking. The engine starts to heat up and I called FWD Emergency immediately before the local Police appears minutes later.

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

	- Reporting Only
✓	- Claim OD
	- Claim TP
	- Claim OD/ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Rayon 18/2
9-30 am.

Policyholder's signature
Date & Time

Driver's Signature
(if driver not the policyholder)
Date & Time

Kenneth

Reporting Centre Personnel's Signature
Name: **Kenneth**
Nric/Fin No.



**SINGAPORE
POLICE FORCE**



J/20190218/2039

1 of 2

POLICE REPORT (NP299)

Report No. J/20190218/2039

Police Station Of Origin
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

Date/Time Report Made 18/02/2019 12:54		Vide Report No.		Station Diary No. 47	
Name Of Informant PANG CHONG NING		Address APT BLK 50 CHOA CHU KANG NORTH 6 #15-04 SINGAPORE 689574			
ID Type / ID No. NRIC NO / S1785889J		Contact No. Home/Office Mobile 81213112			
Nationality SINGAPORE CITIZEN		Email Address			
Occupation PURCHASING DIRECTOR		Sex Male	Age 51	Date of Birth 01/06/1967	Race Chinese
Institution/School Name		Language			
Date/Time Of Incident 17/02/2019 07:00 - 17/02/2019 07:00		Location Of Incident 265.1KM point of north-South Highway, Seremban MALAYSIA			

Brief details.

On 17/02/2019 at about 0700hrs, I was driving my vehicle bearing the plate number of SKL8139M from Klang towards Singapore. I was driving along the North-South highway. Weather was clear and the road surface is dry. there was no passenger. I was driving along the middle lane. While I was engaging the bend, I observed there was one big tire believed to be from a truck was at the lane that I was driving. I tried to swerve but to no avail. my vehicle subsequently went above the tire and my front bumper suffered serious damages from the impact. My car sustained the following damages;

Signature Of Officer Recording The Report: J / Staff Sgt AHMAD ADHA BIN SAHARI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 18/02/2019 12:54
Officer In-Charge Of Case: J / Bukit Panjang N.P.C / Sgt 2 CHIN WEI JIE Contact No. 67910000	Classification Of Case:
Authentication Stamp Signature:	
Singapore Police Force	



SINGAPORE
POLICE FORCE



J/20190218/2039

2 of 2

POLICE REPORT (NP299)


CONTINUATION OF REPORT

Report No. J/20190218/2039

-driver side bumper was damaged;

-coolant leaked due to the impact;

There was No in-car camera installed in my car. I am lodging this report for the insurance to follow up.

Signature Of Officer Recording The Report: J / Staff Sgt AHMAD ADHA BIN SAHARI 	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 18/02/2019 12:54
Officer In-Charge Of Case: J / Bukit Panjang N.P.C / Sgt 2 CHIN WEI JIE Contact No.: 67910000	Classification Of Case:
Authentication Stamp  Signature: 	
Singapore Police Force	



**CAWANGAN TRAFIK
IBUPEJABAT POLIS DAERAH SEREMBAN 2,
70300, SEREMBAN
POLIS DIRAJA MALAYSIA
06-6033222**

POL.316

Resit Akuan Penerimaan Repot Polis :

Nama Pengadu : PANG CHONG NING
No Kad Pengenalan / Paspot : S1785889J
No Repot Polis : TRAFIK SEREMBAN/002830/19
Tarikh @ Masa Repot Polis : 17/02/2019 @ 08:42
Pengesahan Penerimaan Repot :

KPL 187095
NURAZLYZA B. MOHD. HUSAINI
WJG. SASANTAN & KECAMUKAN CAWANGAN TRAFIK
Tandatangan Ketua Pejabat Pertanyaan

Pegawai Penyiasat :

Nama Pegawai Penyiasat : (R127125) SJN AZMI BIN OMAR
Tempat Tugas : BUKIT AMAN , Bukit Aman
No Telefon Pejabat : No Telefon Bimbit : 019-3023255
Tarikh @ masa Perjumpaan :
Pengesahan Penerimaan Repot :

Tandatangan Pegawai Penyiasat

Juru Gambar :

Nama : No Badan : Pangkat :
Tarikh @ Masa Gambar Diambil :
Pengesahan Gambar Diambil :

Tandatangan Juru Gambar

Unit Pembekalan Dokumen Siasatan :

No Telefon Unit Pembekalan Dokumen :

Waktu Pejabat :

Isnin - Khamis :
08:00 Pagi - 01:00 Tengah Hari
02:00 Petang - 04:30 Petang
Jumaat :
08:00 Pagi - 12:00 Tengah Hari
03:00 Petang - 4:30 Petang
Cuti Umum / Khas : Tutup

Jenis Dokumen Dibekal Kepada Pengadu :

1. Salinan Repot Polis
2. Gambar Kenderaan
3. Rajah Kasar Kemalangan
4. Keputusan Siasatan
5. Lain-lain Dokumen

Tarikh @ Masa Dokumen Diserah :
Pengesahan Kaunter Pembekalan Dokumen :

Tandatangan Pegawai Kaunter Pembekalan Dokumen

> Back to OneMotoring

O.O.A. 17/2/2019
Bal: 4yrs 10.3 mths

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5889J
Vehicle Details	
Vehicle No.:	SKL8139M
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	AUDI
Vehicle Model:	A6 2.0 TFSI MU
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	CDN379977
Chassis No.:	WAUZZZ4G8EN060155
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$38,187.00
Original Registration Date:	26 Dec 2013
First Registration Date:	26 Dec 2013
Transfer Count:	1
Actual ARF Paid:	\$40,462.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2023
PARF Rebate Amount:	\$28,323.00
Intended COE Rebate Details	
COE Expiry Date:	25 Dec 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$73,010.00
COE Rebate Amount:	\$35,366.00
Total Rebate Amount:	\$63,689.00

The information contained herein is correct as at 21 Feb 2019

OK

20,231

Tempat Keterangan Kemalangan


- 1. KES LANGGAR BELAKANG / MEMOTONG DI JLN SEHALA (PEMANDU MELANGGAR)
- 2. KES LANGGAR BELAKANG / MEMOTONG DI JLN SEHALA (PEMANDU DILANGGAR)
- 3. KES KELUAR / MASUK SIMPANG
- 4. KES TERBĀBAS SENDIRI
- 5. KES LANGGAR DEPAN DGN DEPAN (PEMANDU BERADA DI JLN NYA)
- 6. KES LANGGAR DEPAN DGN DEPAN (PEMANDU MASUK JLN ORANG ATAU MEMOTONG)
- 7. POLIS TERIMA MAKLUMAT MELALUI TELEFON
- 8. LAPORAN CAM MAYAT
- 9. PEMANDU MABUK

PADA 17/02/2019 JAM LEBIH KURANG 0700 HRS SEMASA SAYA MEMANDU KERETA NO: SKL 8139M JENIS AUDI AGDARIMUANG HENDAK KE SINGAPURA SEORANG DIRI. TIBA DI KM 265.1 (S) LEBUHRAYA UTARA SELATAN SAYA MEMANDU DI LORONG KANAN, TIBA-TIBA SAYA TERLIHAT SERPIHAN TAYAR LORI DI TENGAH JALAN DAN SAYA TIDAK SEMPAT MENGELOK (ALU) TERLANGGAR SERPIHAN TAYAR TERSEBUT. KEROSAKAN KERETA SAYA ADALAH: BUMPER DEPAN, RADIATOR, PINTU DEPAN KANAN, DAN LAIN-LAIN KEROSAKAN TIDAK PASTI. SEKIAN LAPORAN SAYA.

Keluar Sambung

pan Butir-Butir Repot Sementara







CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.
All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00016750 (Comprehensive - Prestige Plan)

Car plate number: SKL8139M

Your name (As the policyholder): Pang Chong Ning

Coverage start date: 26/12/2018

Coverage end date: 25/12/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 13/12/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.



INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00016750	Date of Loss:	17/02/2019
Vehicle Reg. No.:	SKL8139M	Driveable?	
Driver Age/Info:	52 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PANG CHONG NING	Contact No:	+6581213112
Driver:	PANG CHONG NING		
Make/Model:	AUDI A6, 2.0 TFSI MU (A)	Vehicle Reg. Date:	26/12/2013
Vehicle Colour:	WHITE		
Engine No:	CDN379977	Chassis No:	WAUZZZ4G8EN060155
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO THE POLICE REPORT		
Remarks:	VEHICLE IN ETHOZ BUKIT BATOK		
Present Location:	ETHOZ PROTECT PTE LTD (BUKIT BATOK)		

COST OF CLAIMS	Amount
Parts	5,798.00
Miscellaneous Items	60.00
Labour	2,470.00
Paintwork Labour	0.00
Towing	0.00
	<u>13,779</u>
Gross Total (S\$)	8,328.00
+ GST 7.00% (S\$)	582.96
Nett Amount (S\$)	8,910.96

This claim is handled by: KENNETH CORNELIUS / SHAH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference *Shah*

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Feb 2019)

Parts: 143 AUDI A6 2.0 TFSI MU (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ETHOZ Protect Pte Ltd/SKL8139M/20/02/2019 12:10

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

*Steve (CLK) 21/2/19 5:30pm
83298813
DD not Airhaise P/P 5 days
Excurs - 609
22/2/19*

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>BR ✓</i>	0.00	0.00	*980.00 F
2	1		*FRONT BUMPER RETAINER RH <i>BR ✓</i>	0.00	0.00	*32.00 F
3	1		*FRONT BUMPER CLIPS <i>NEC ✓</i>	0.00	0.00	*85.00 F
4	1		*FRONT ENGINE LOWER DUST COVER <i>BR ✓</i>	0.00	0.00	*310.00 F
5	1		*FRONT GRILLE ASSY <i>BR ✓</i>	0.00	0.00	*550.00 F
6	1		*FRONT BUMPER SIDE GARNISH RH <i>MIS ✓</i>	0.00	0.00	*90.00 F
7	1		*FRONT AIRGUIDE RH <i>BR ✓</i>	0.00	0.00	*36.00 F
8	1		*INTERCOOLER ASSY <i>BT ✓</i>	0.00	0.00	*480.00 F
9	1		*INTERCOOLER HOSE RH <i>NI ✓</i>	0.00	0.00	*245.00 F
10	1		*AIRCON CONDENSER <i>NI ✓</i>	0.00	0.00	*580.00 F
11	1		*RADIATOR ASSY <i>DD ✓</i>	0.00	0.00	*320.00 F
12	1		*SUPPORT PANEL ASSY <i>BR ✓</i>	0.00	0.00	*520.00 F
13	1		*FRONT DOOR RH <i>DD ✓</i>	0.00	0.00	*1,450.00 F
14	1		*FRONT DOOR WEATHERSTRIP RH <i>NEC ✓</i>	0.00	0.00	*120.00 F
15	1		*REAR DOOR RH <i>R</i>	0.00	0.00	-
			REPAIR			
16	1		*ROCKER PANEL RH <i>x R</i>	0.00	0.00	-
			REPAIR			

F=Franchise part.

Total Parts (S\$) 5,798.00

ETHOZ Protect Pte Ltd/SKL8139M/20/02/2019 12:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS