

ASS. REC. BY:

REF:

C8/CTI 19003293/And3ⁿ²

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Ong chin kiat

of

CTI

Date/Time:

20/2/19 @ 3:46pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SME 3176B

Insured:

PC 6643A

at Workshop m/s:

BW Workshop

Tel:

66920125

of

30 Ubi Rd 4

Policy No.:

DMBISN17660318011

Claim No.:

SNM19D200795C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.:

5/2/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:17am 21/2/19

Person Contacted:

Justin

Vehicle:

IN OUT

Date/Time

Action/Instruction (✓) Estimate

SME 3176B - NBA / CTI 19003241 / y

D.O.A. 5/2/19

PC 6643A - NBA / CTI 19003241 / y

D.O.A. 5/2/19

Kual Bg \$13886.20, 14 days Ured \$6519.20, 32%.

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SME31768 Yr Regn: 2018 1 Sept.Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit Hybrid cc 1496Colour: Red. A/C: Insured / Std / Nil / NASp. Reading: - T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: GPS3416212Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 135/60R15R: 135/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 22/02/19.Survey held at BW.Des. of Damages: Fit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 21 MAY 2019

Date / Time Action / Instruction

TP Chua

MV:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1) 21/5 14:54

2) _____

3) _____

4) _____

5) _____

6) _____

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Feb 2019		20 Feb 2019 15:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	VIKAR TRANSPORT SERVICES, Co. Reg. No.: 53346871W		
Main Claimant:	LIM CHEE ANG (LIN JIHONG), ID: S7630374F		
Vehicle Reg. No.:	SME3176B	Date of Loss:	05/02/2019 14:00 - :59
Claim Type:	TP / SNM19D200795C02	Policy/Cover Note No.:	DMB1SN17660318011 (Third Party Only) Coverage: 09/11/2018 - 08/11/2019
Vehicle Reg. No. (Insured):	PC6643A	Policy No. (Claimant):	GA401743/1
		Excess:	S\$0.00
Repairer:	Bw Workshop Services Pte Ltd (HQ) 30 UBI ROAD 4, 408615 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/03/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0374F
Vehicle Details	
Vehicle No.:	SME3176B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT HYBRID 1.5F AUTO
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	LEB6070995
Chassis No.:	GP53416212
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,113.00
Original Registration Date:	26 Sep 2018
First Registration Date:	26 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$11,559.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Sep 2028
PARF Rebate Amount:	\$8,669.00
Intended COE Rebate Details	
COE Expiry Date:	25 Sep 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,307.00
COE Rebate Amount:	\$25,045.00
Total Rebate Amount:	\$33,714.00

The information contained herein is correct as at 15 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/02/2019 09:40
Date Of Accident	05/02/2019 14:20
Exact Location Of Accident	TPE TOWARDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME3176B
Insured/Policyholder	
Name Of Registered Owner	LIM CHEE ANG (LIN JIHONG)
NRIC No	S7630374F
Email Address	CATLIM2609@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81894867
Alternative Phone No	OTHERS-81894867

Vehicle Particulars

Manufacturer	HONDA
Model	FIT-1.5 HYBRID (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA401743/1
Cover Note Number	

Driver

Name of Driver	LIM CHEE ANG (LIN JIHONG)
NRIC No	S7630374F
Date Of Birth	26/09/1976
Occupation	INDOOR
Date Of Driving Pass	08/07/1999
Driving Experience	19 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81894867
Fax Number	
Contact Number	OTHERS-81894867
Email Address	CATLIM2609@GMAIL.COM

Address

BLK 203B PUNGGOL FIELD #12-326
SINGAPORE

Postcode

822203

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own
Vehicle

-
-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)
involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by
ambulance?

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s)
soliciting/offering accident claims assistance.

YES

Number of Passengers (Including Driver)

3

Passenger 1

NAME: : EE SOOK KEIA

GENDER: : FEMALE

Passenger 2

NAME: : CHOO CHENG YEN JANINE

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

ANG MO KIO POLICE DIVISIONAL HQ (F DIVISION)

Police Station Address

ROAD: 51 ANG MO KIO AVENUE 9 , POSTCODE: 569929 , COUNTRY:
SINGAPORE

Police Station Contact

TEL NO: 1800-2180000 - FAX NO: 64814246

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

PC6643A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

BUS

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SGN4911M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

EE SOOK KEIA

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SME3176B

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

CHOO CHENG TEN JANINE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SME3176B

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescindate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the KIA Feloas Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available should be.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, decide and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicles involved in this accident (all insurer(s) who have insured vehicles) involved in this accident and the affectedly affected insurer(s), the insurers' lawyers/law firms, the Insurer's Authority of Singapore and any other of insurer's agents, including such as the police, for the purposes of:
 - (i) processing, handling or dealing with my claims involving the assessment of the claims and any necessary investigations relating to the claim;
 - (ii) investigating the accident and/or claims;
 - (iii) carrying out and/or dealing with the instructions or responses to any enquiries relating;
 - (iv) administering my claims including the handling of correspondence, notices, reports or notices to me, which need to be disclosed or readily available data about my being about delivery of the same as well as on the external case of an individual's coverage; and/or
 - (v) complying with a third party's request for information, handling and/or dealing with my claims (collectively the "purpose").
- (b) all insurer(s) who have written vehicles involved in this accident and the insurer's lawyers/law firms, may/are permitted to collect, use, decide and/or process my Personal Information by use at work of the above purposes and
- (c) my Personal Information may, will be disclosed by me to the insurer(s) and to their third party service providers or representatives of their insurers/law firms, which may be used outside or otherwise for one or more of the above purposes.
- (d) my Personal Information may be collected and used to compile, disseminate for the purpose of fraud detection, investigation and/or payment to insurer and/or lawyer/law firm.
- (e) the information or information or documents may be shared/ disclosed:
 - (i) to all insurers and/or any other third parties that assist in settling, investigating, handling or managing fraud, regulation, law enforcement and government agencies or reasonably required for the purpose stated, or
 - (ii) for complying with a third party's request for information, handling and/or dealing with my claims (collectively the "purpose").

Policyholder's Signature

Date & Time:

9/1/19

9:30am

Driver's Signature

If driver is not the policyholder

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Person

Sketch Plan #2

SKETCH PLAN

	Vehicle
	A - SWE 2768
	B - PC 6643A
	C - SGN 491m
	Legend
	Vehicle Motorcycle

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a fourteen (14) day time bar whereby this claim against your policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

7/21/9
9:30am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

permen

⑥ SGN 411M

THIS IS NOT AN admission of blame / liability, but a statement of concerns and facts which will speed up the settlement of claims.

↓ Registration No. **PC 6643A**
(VEHICLE 5)
Insured (policyholder (see Insurance card))
B
1- Name _____
2- Payable interest _____
3- _____
4- Address _____
5- _____
6- INFC 1 (Insurance No) _____
7- Tel. no. (please write 40 500) _____
8- ZIP _____
9- ☒ Vehicle
10- Make, type _____
11- ☒ Insurance company _____
12- ☐ C ☐ INT ☐ PRO
13- Does the policy cover damage to vehicle 8? _____
14- No ☐ Yes ☐ _____
15- Make for 12 (optional) _____
16- ☒ Driver (See driving license)
17- (if different from subject B above)
18- Name _____
19- Nationality _____
20- INFC 1 (Insurance No) _____
21- Date of license _____
22- Sex ☐ Male ☐ Female ☐

REFER TO ATTACHED

Individual Statement

syndicate@bw.com.sg

INDIVIDUAL STATEMENT (Part II)		To be completed and submitted within 24 hours to your insurer or filer or appointed workshop (Use a separate sheet of paper where necessary)									
Insured	1. Occupation (if more than one, state all)	2. Vehicle registration no. <u>CC</u>									
	3. Is driver the owner? ☒ Yes ☐ No ☐ If no, state relationship in column with serial	3. If commercial vehicle, state permissible carrying capacity									
	4. Exact purpose for which vehicle was being used at time of accident ☐ Private use ☐ Commercial use ☐ Hire & reward ☐ Private Hire	5. Is the vehicle still in use? ☐ Yes ☐ No ☐ If no, state where it is at present To no									
	6. Are you claiming under your own insurance policy for repair to your vehicle? ☐ Yes ☒ No	7. Date of birth <u>26/9/76</u> Occupation <u>Indoor</u> <u>Outdoor</u> Date of license first <u>8/7/1999</u> Was vehicle driven with the insured's permission? ☐ Yes ☒ No									
	8. If no, state action to be taken ☐ Third Party ☐ Reporting Only ☒ Third Party (Own Workshop)	9. Was driver an employee of the insured's company? ☐ Yes ☒ No									
Driver (a person in charge of vehicle at the time of accident (including himself))	10. Give details of any pre-existing impairment of sight or hearing or of any other disability										
	11. Give details of all driving convictions, including pending prosecutions in the last 36 months										
	<table border="1"> <thead> <tr> <th>Date</th> <th>Offence</th> <th>Penalty</th> </tr> </thead> <tbody> <tr> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table>			Date	Offence	Penalty					
Date	Offence	Penalty									
Witness (person)	12. Name(s), addresses and approximate parties	13. Name(s) and addresses of contacts	14. Name(s) and addresses of contacts								
	15. Name(s) and addresses of contacts	16. Name(s) and addresses of contacts	17. Name(s) and addresses of contacts								
Police action	18. Was the accident reported to the Police? ☒ Yes ☐ No	19. If yes, please state which police station									
	20. Was notice of intended prosecution given? ☐ Yes ☒ No	21. If yes, please state when									
Accident details	22. Weather conditions ☒ Dry ☐ Rain ☐ Wind ☐ Fog	23. Road surface ☒ Wet ☐ Dry	24. State of vehicle ☐ A ☒ B								
	25. State of vehicle ☐ A ☒ B	26. State of vehicle ☐ A ☒ B	27. State of vehicle ☐ A ☒ B								
	28. Were front seats illuminated? ☐ Yes ☒ No	29. Were rear seats illuminated? ☐ Yes ☒ No									
	30. State how accident happened, width of road, speed limits, etc. (Driver is directed)	31. State number of passengers (including driver) <u>3</u>									
Declaration	32. State name of witnesses (including driver) <u>DEE Sook Kera</u> <u>CHEO CHENG YEN</u> <u>JANINE</u>										
	33. State name of witnesses (including driver) <u>DEE Sook Kera</u> <u>CHEO CHENG YEN</u> <u>JANINE</u>										
Declaration	34. State name of witnesses (including driver) <u>DEE Sook Kera</u> <u>CHEO CHENG YEN</u> <u>JANINE</u>										
	35. State name of witnesses (including driver) <u>DEE Sook Kera</u> <u>CHEO CHENG YEN</u> <u>JANINE</u>										



**SINGAPORE
POLICE FORCE**



F/20190206/7000

1 of 3

POLICE REPORT (NP299)

Report No. F/20190206/7000

Police Station Of Origin
Ang Mo Kio Division HQ
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No:1800-2180000

Date/Time Report Made 06/02/2019 00:08	Vide Report No.	Station Diary No.
Name Of Informant LIM CHEE ANG	Address APT BLK 203B PUNGGOL FIELD #12-326 SINGAPORE 822203	
ID Type / ID No. NRIC NO / S7630374F	Contact No. Home/Office: Mobile: 81894867	
Nationality SINGAPORE CITIZEN	Email Address catlim2609@gmail.com	
Occupation Teacher	Sex Female	Age 42
	Date of Birth 26/09/1976	Race Chinese
Institution/School Name	Language English	
Date/Time Of Incident 05/02/2019 14:20 - 05/02/2019 14:30	Location Of Incident TPE 11KM	

Brief details.

I, Lim Chee Ang (S7630374F), was travelling along TPE towards SLE in my car (SME3176B) on 5 Feb 2019 at about 2.23p.m. with my mother and my youngest daughter. When I was near TPE(SLE) 11km LP586, the car in front of me (SGN4911M) applied emergency brake to prevent collision with the cars in front. The cars in front had braked suddenly due to a skidded motorbike (2 cars ahead) where the motorist fell onto Lane 1. (Please refer to diagram attached) I quickly stepped on the brake of my car and managed come to a stop with a distance between my car and the back of SGN4911M. Shortly after, mini-bus PC6643A crashed into the back (left) of my car and due to the impact from PC6643A, my car

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 06/02/2019 00:08
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



F/20190206/7000

2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20190206/7000

swerved forward to the right and hit into the rear of SGN4911M.

My mother (Ee Sook Keia, S1851413C) was hurt from the impact and was taken to Sengkang General Hospital for investigation. My youngest daughter appears alright. The wind screen at the back of my car was shattered and the door to the car boot could not be opened. The left side of my car was badly damaged that disallowed the doors on the left to be open. (Refer to photos of the damages).

A report was made with Traffic Investigation Branch (Report no.: F/20190205/0140).

Subjects Involved			
Victim			
Person Name	LIM CHEE ANG		
ID Type	NRIC NO	ID No	S7630374F
Gender	Female	Age	42
Race	Chinese	Language	English
Occupation	Teacher	Address Type	
Address	APT BLK 203B PUNGGOL FIELD #12-326 SINGAPORE 822203		Mobile No 81894867
Is Informant A Victim?	Yes		
Person Name	Ee Sook Keia		
ID Type	NRIC NO	ID No	S1851413C
Gender	Female	Age	66
Race	Chinese	Language	Chinese
Signature Of Officer Recording The Report:		Signature Of Informant:	
Not applicable		The identity of the person making this report has been authenticated by SingPass. No signature is required.	
Signature Of Interpreter:		Date/Time:	
Not applicable		06/02/2019 00:08	
Officer In-Charge Of Case:		Classification Of Case:	
Authentication Stamp			



**SINGAPORE
POLICE FORCE**



F/20190206/7000

3 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20190206/7000

Occupation	Housewife	Address	413 Hougang Ave 10 #13-1218 SINGAPORE 530413
Mobile No	81278825	Relation To Informant	Mother
Person Name	LIM CHEE ANG (Informant)		

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this
report has been authenticated by
SingPass. No signature is required.

Date/Time:

06/02/2019 00:08

Classification Of Case:

BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615

TEL: 5289 8800 FAX: 6858 2120

GST REG NO : 201504834E

Estimate

To	: CHINA TAIPING INSURANCE PTE LTD	DATE	: 19/2/2019
Attn	: Claims Officer		
CC	: 1499	VEHICLE NO	: SME 3176 B
YEAR	: 2018	CHASSIS NO	: GP53416212
MODEL	: HONDA FIT HYBRID 1.5F	PAGE	: 1 OF 2

Please quote the following items listed.

Third Party Claims

S/NO	ITEMS	Qty	Price
1	Front bumper <i>Replaced</i>	1	<i>645</i> \$1,180.00 <i>755</i>
2	Front grille <i>Replaced</i>	1	\$375.00
3	Front grille - upper - chrome <i>Replaced</i>	1	\$240.00
4	Front grille - lower - chrome <i>Replaced</i>	1	\$195.00
5	Front grille logo - Honda chrome <i>Replaced</i>	1	\$45.00
6	Front bumper lower centre grille <i>Replaced</i>	1	\$320.00
7	Front bumper fog lamp cover - LH <i>Replaced</i>	1	\$55.00 ✓
8	Front bumper side retainer - LH <i>Replaced</i>	1	\$15.00
9	Front headlamp bracket - LH <i>Replaced</i>	1	\$58.00 ✓
10	Front reinforcement <i>Replaced</i>	1	\$290.00 ✓
11	Front headlamp - LH <i>Replaced</i>	1	\$890.00 ✓
12	Front fender - LH <i>Replaced</i>	1	\$195.00 ✓
13	Front support panel <i>Replaced</i>	1	\$865.00 ✓
14	Battery + red cover <i>Replaced</i>	1	\$28.00 ✓
15	Rear tailgate <i>Replaced</i>	1	\$790.00 ✓
16	Rear tailgate centre chrome <i>Replaced</i>	1	\$395.00 ✓
17	Rear tailgate 'FIT' chrome logo - <i>Replaced</i>	1	\$45.00 ✓
18	Rear bumper <i>Replaced</i>	1	\$680.00 ✓
19	Rear bumper centre lining <i>Replaced</i>	1	\$70.00 ✓
20	Rear bumper LH lining <i>Replaced</i>	1	\$45.00 ✓
21	Rear bumper LH reflector <i>Replaced</i>	1	\$55.00 ✓
22	Rear tailgate lamp - LH <i>Replaced</i>	1	\$480.00 ✓
23	Rear fender - LH <i>Replaced</i>	1	\$790.00 ✓
24	Rear end panel <i>Replaced</i>	1	\$550.00 ✓
25	Rear LH lamp panel <i>Replaced</i>	1	\$200.00 ✓
26	Rear bumper LH retainer <i>Replaced</i>	1	\$20.00 ✓
TOTAL :			\$8,871.00

Parts: \$7,476.00

BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615

TEL: 5289 8800 FAX: 6858 2120

GST REG NO : 201504834E

Estimate

To :	CHINA TAIPING INSURANCE PTE LTD	DATE :	19/2/2019
Attn :	Claims Officer		
CC :	1499	VEHICLE NO :	SME 3176 B
YEAR :	2018	CHASSIS NO :	GP53416212
MODEL :	HONDA FIT HYBRID 1.5F	PAGE :	2 OF 3

Please quote the following items listed.

Third Party Claims

S/NO	ITEMS	Qty	Price
27	Rear fender air duct assy - LH <i>Del'd</i>	1	\$35.00 ✓
28	Rear bumper sponge - LH <i>Del'd</i>	1	\$85.00 ✓
29	Rear wheel side sill - LH - rear <i>3 Del'd</i>	1	\$25.00 ✓
30	Rear wheel side sill - LH - front <i>Del'd</i>	1	\$95.00 ✓
31	Rear tyre - LH - 185/60R15 <i>new</i> → take picture Admin	1	\$195.00 ✓
32	Rear tailgate garnish - inner <i>Del'd</i>	1	\$135.00 ✓
33	Rear fender LH garnish - upper <i>Del'd</i>	1	\$145.00 ✓
34	Rear fender LH garnish - lower <i>Del'd</i>	1	\$280.00 ✓
35	Rear tailgate lock <i>Found</i>	1	\$98.00 ✓
36	Rear tailgate catch <i>new</i>	1	\$29.00 ✓
37	Rear spare tyre board <i>Del'd</i>	1	\$450.00 ✓ <i>295</i>
38	Rear spare tyre tray - centre <i>Del'd</i>	1	\$245.00 ✓
39	Spare tyre tray - LH <i>new</i>	1	\$195.00 ✓
40	Rear tailgate weathership <i>at</i>	1	\$65.00 ✓
41	Rear tailgate damper - LH & RH <i>2 new</i>	1	\$250.00 X
42	Rear windscreen <i>shattered</i>	1	\$850.00 ✓
43	Rear windscreen moulding <i>new</i>	1sets	\$120.00 ✓
44	Rear fender quarter glas moulding - LH <i>new</i>	1	\$25.00 ✓
45	Rear end panel centre garnish - inner <i>Del'd</i>	1	\$185.00 ✓
			\$12,378.00
Discount 20%			\$2,475.60
TOTAL :			\$9,902.40

10854
8683.20

Parts \$3,228.00
Pagel Parts: \$7,476.00
\$10,704.00
- 20%
\$8,563.20

BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615

TEL: 5289 8800 FAX: 6858 2120

GST REG NO : 201504834E

Estimate

To : CHINA TAIPING INSURANCE PTE LTD DATE : 19/2/2019
Attn : Claims Officer
CC : 1499 VEHICLE NO : SME 3176 B
YEAR : 2018 CHASSIS NO : GP53416212
MODEL : HONDA FIT HYBRID 1.5F PAGE : 3 OF 3

Please quote the following items listed.

Third Party Claims

S/NO	SPECIAL ITEMS	Qty	Price
1	Rear number plate c/w casing <i>new</i>	1	\$65.00
2	Rear bumper sensor <i>new</i>	1	\$190.00
3	Rear camera <i>new</i>	1	\$200.00 X
4	Rear windscreen sealant <i>new</i>	1	\$50.00
5	Rear reverser camera <i>new</i>	1	TBC X
			\$505.00
Parts Total :			\$9,902.40
S/P Item :			\$505.00
TOTAL :			\$10,407.40

Parts: \$8,563.20

S/N: \$240.00

Supplementary Item: \$603.00

\$9,406.20

Labour: \$4,360.00

\$13,766.20 - 24 GST - (22 Days)

BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615

TEL: 5289 8800 FAX: 6858 2120

GST REG NO : 201504834E

Estimate

To : CHINA TAIPING INSURANCE PTE LTD DATE : 19/2/2019
 Attn : Claims Officer
 CC : 1499 VEHICLE NO : SME 3176 B
 YEAR : 2018 CHASSIS NO : GP53416212
 MODEL : HONDA FIT HYBRID 1.5F PAGE : 1 OF 1

Third Party Claims

S/NO	LABOURS	AMOUNT	
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS. \$300/Per Days	\$ 3,900.00	180
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS. \$280/ Per Panel	\$ 3,360.00	160
3	DISCONNECT AND CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS,ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 120.00	60
4	TO REMOVE AND RENEW REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	\$ 120.00	✓
5	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.	\$ 100.00	80
6	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS, VACUUM AND RECHARGE GAS.	\$ 150.00	70
7	REFIT SOLAR CONTROL FILM ON REAR WINDSCREEN.	\$ 180.00	✓
8	TO APPLY UNDERSEALING.	\$ 100.00	60
9	TO CHECK AND REALIGNMENT ON CHASSIS MEMBER.	\$ 250.00	150
10	TO REMOVE AND REFIT PETROL/DIESEL TANK IN ORDER TO FACILITATE REPAIRING WORKS.	\$ 150.00	80
11	TO TRANSFER TAILGATE'S FITTINGS.	\$ 100.00	80
12	TO REMOVE AND TOP UP RADIATOR COOLANT.	\$ 100.00	X
13	REMOVE AND REPLACE BUMPER SENSOR.	\$ 120.00	50

Working Days : 19 Days.

Labour = \$4360

NOTE: ALL QUOTED PRICE IS SUBJECT TO 7% GST

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

TOTAL : \$8,750.00
 PARTS TOTAL : \$10,407.40
 GRAND TOTAL : \$19,157.40

Adrian Li
 P/P 22/02/19

148mp : Supplementary : 603

total: 13886.20 ✓
 (P/P)

20276.40

BW WORKSHOP SERVICES PTE LTD

30 UBI ROAD 4

Singapore 408615

6289 8800

workshop_admin@bw.com.sg

GST Registration No. : 201504834E

Company Registration No. 201504834E

**ESTIMATES***Xiao Chun***ADDRESS**CHINA TAIPING INSURANCE
(SINGAPORE) PTE LTD**ESTIMATES NO. 1063****DATE 02/05/2019****VIN NUMBER**

SME3176B / GP53416212

MAKE & MODEL

HONDA FIT HYBRID 1.5F

MILEAGE

-

ACTIVITY**QTY****RATE****AMOUNT****SUPPLEMENTY ITEM**

AIRCOND CONDENSER @ \$420.00

Bent

1

336.00

336.00 ✓

FRONT BUMPER LOWER GRILLE @ \$290.00

deband

1

232.00

232.00 ✓

Subtotal: 568.00

FRONT BUMPER CLIPS - S/N @ \$3.50

new

10

3.50

35.00 ✓

Subtotal: 35.00

PARTS : \$710.00 - 20% = \$568.00

SUBTOTAL

603.00

GST TOTAL

0.00

TOTAL**SGD 603.00**

Accepted By

Accepted Date

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119003293/AQD3N2

Date: 23/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN17660318011
Claimant Vehicle No :	SME3176B	Insured Vehicle No :	PC6643A
Date of Loss:	05/02/2019	Nature of Claim:	TP
		Claim No:	SNM19D200795C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME3176B	Engine No:	LEB6070995
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Chassis No:	GP53416212
Reg. Date:	26/09/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	135/60R15	Rear Tyre Size:	135/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,526.40	9,526.20	2,000.20	17.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,750.00	4,360.00	4,390.00	50.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,276.40	13,886.20	6,390.20	31.52
+ GST 7.00/7.00% (S\$)	1,419.35	972.03	447.32	31.52
Nett Amount (S\$)	21,695.75	14,858.23	6,837.52	31.52

INSPECTION

Date of Assignment:	20/02/2019	
Date Inspected:	22/02/2019	Inspected At:
		BW Workshop Services Pte Ltd (HQ)
		30 Ubi Road 4
		Singapore 408615

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2019)
Parts:	144	HONDA FIT 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME3176B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Dented	645.00 FL	*645.00 FL
2	1	*FRONT BUMPER	Deformed	1,180.00 FL	*755.00 FL
3	1	*FRONT GRILLE	Deformed	375.00 FL	*375.00 FL
4	1	*FRONT GRILLE-UPPER-CHROME	Cracked	240.00 FL	*240.00 FL
5	1	*FRONT GRILLE-LOWER-CHROME	Cracked	195.00 FL	*195.00 FL
6	1	*FRONT GRILLE LOGO-HONDA CHROME	Necessary	45.00 FL	*45.00 FL
7	1	*FRONT BUMPER LOWER CENTRE GRILLE	Deformed	320.00 FL	*320.00 FL
8	1	*FRONT BUMPER FOG LAMP COVER-LH	Deformed	55.00 FL	*55.00 FL
9	1	*FRONT BUMPER SIDE RETAINER-LH	Necessary	15.00 FL	*15.00 FL
10	1	*FRONT HEADLAMP BRACKET-LH	Cracked	58.00 FL	*58.00 FL
11	1	*FRONT REINFORCEMENT	Bent	290.00 FL	*290.00 FL
12	1	*FRONT HEADLAMP-LH	Cracked	890.00 FL	*890.00 FL
13	1	*FRONT FENDER-LH	Repair	195.00 FL	*- FL
14	1	*FRONT SUPPORT PANEL	Repair	865.00 FL	*- FL
15	1	*BATTERY+RED COVER	Deformed	28.00 FL	*28.00 FL
16	1	*REAR TAILGATE	Distorted	790.00 FL	*790.00 FL
17	1	*REAR TAILGATE CENTRE CHROME	Cracked	395.00 FL	*395.00 FL
18	1	*REAR TAILGATE FIT CHROME LOGO	Necessary	45.00 FL	*45.00 FL
19	1	*REAR BUMPER	Distorted	680.00 FL	*680.00 FL
20	1	*REAR BUMPER CENTRE LINING	Deformed	70.00 FL	*70.00 FL
21	1	*REAR BUMPER LH LINING	Deformed	45.00 FL	*45.00 FL
22	1	*REAR BUMPER LH REFLECTOR	Not Necessary	55.00 FL	*- FL
23	1	*REAR TAILGATE LAMP-LH	Cracked	480.00 FL	*480.00 FL
24	1	*REAR FENDER-LH	Distorted	790.00 FL	*790.00 FL
25	1	*REAR END PANEL	Distorted	550.00 FL	*550.00 FL
26	1	*REAR LH LAMP PANEL	Distorted	200.00 FL	*200.00 FL
27	1	*REAR BUMPER LH RETAINER	Necessary	20.00 FL	*20.00 FL
28	1	*REAR FENDER AIR DUCT ASSY-LH	Deformed	35.00 FL	*35.00 FL
29	1	*REAR BUMPER SPONGE-LH	Deformed	85.00 FL	*85.00 FL
30	1	*REAR WHEEL SIDE SILL-LH-REAR	Deformed	25.00 FL	*25.00 FL
31	1	*REAR WHEEL SIDE SILL-LH-FRONT	Deformed	95.00 FL	*95.00 FL
32	1	*REAR TYRE-LH-185/60R15	Cut	195.00 FL	*195.00 FL
33	1	*REAR TAILGATE GARNISH-INNER	Deformed	135.00 FL	*135.00 FL
34	1	*REAR FENDER LH GARNISH-UPPER	Deformed	145.00 FL	*145.00 FL
35	1	*REAR FENDER LH GARNISH-LOWER	Deformed	280.00 FL	*280.00 FL
36	1	*REAR TAILGATE LOCK	Jammed	98.00 FL	*98.00 FL
37	1	*REAR TAILGATE CATCH	Not Necessary	29.00 FL	*- FL
38	1	*REAR SPARE TYRE BOARD	Deformed	450.00 FL	*295.00 FL
39	1	*REAR SPARE TYRE TRAY-CENTRE	Deformed	245.00 FL	*245.00 FL
40	1	*SPARE TYRE TRAY-LH	Not Necessary	195.00 FL	*- FL
41	1	*REAR TAILGATE WEATHERSTRIP	Cut	65.00 FL	*65.00 FL
42	2	*REAR TAILGATE DAMPER-LH & RH	Not Necessary	250.00 FL	*- FL
43	1	*REAR WINDSCREEN	Shattered	850.00 FL	*850.00 FL
44	1	*SETS REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*REAR FENDER QUARTER GLASS MOULDING-LH	Necessary	25.00 FL	*25.00 FL
46	1	*REAR END PANEL CENTRE GARNISH-INNER	Deformed	185.00 FL	*185.00 FL
47	1	*AIRCOND CONDENSER	Bent	420.00 FL	*420.00 FL
48	1	*FRONT BUMPER LOWER GRILLE	Deformed	290.00 FL	*290.00 FL
49	1	*REAR NUMBER PLATE C/W CASING	Not Necessary	65.00 FS	*- FS
50	1	*REAR BUMPER SENSOR	Damaged	190.00 FS	*190.00 FS
51	1	*REAR CAMERA	Not Necessary	200.00 FS	*- FS
52	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
53	1	*REAR REVERSE CAMERA (NPA)	Not Necessary	0.00 FS	*- FS
54	10	*FRONT BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,273.00	11,839.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,746.60	2,312.80
Total Parts (\$\$)	11,526.40	9,526.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIT AND TO RENEW AFFECTED PARTS	New	3,900.00	1,800.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	3,360.00	1,600.00
3	DISCONNECT AND CHECK ELECTRICAL WIRING,HARNESS,WIRE SOCKETS,ETC,REMOVE AND REINSTALL DAMAGED PARTS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	120.00	60.00
4	TO REMOVE AND RENEW REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00	120.00
5	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING,ROOF LINING,SEATS,SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS	New	100.00	80.00
6	TO REMOVE AIRCON CONDENSER,PIPES AND DRIERS,VACUUM AND RECHARGE GAS	New	150.00	100.00
7	REFIT SOLAR CONTROL FILM ON REAR WINDSCREEN	New	180.00	180.00
8	TO APPLY UNDERSEALING	New	100.00	60.00
9	TO CHECK AND REALIGNMENT ON CHASSIS MEMBER	New	250.00	150.00
10	TO REMOVE AND REFIT PETROL/DIESEL TANK IN ORDER TO FACILITATE REPAIRING WORKS	New	150.00	80.00
11	TO TRANSFER TAILGATES FITTINGS	New	100.00	80.00
12	TO REMOVE AND TOP UP RADIATOR COOLANT	New	100.00	0.00
13	TO REMOVE AND REPLACE BUMPER SENSOR	New	120.00	50.00
Gross Labour Cost (\$\$)			8,750.00	4,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >