

FORM 1001

ASS. POLICY

REF

CS3/A1619003313/Gcd3^{sr}

Report of Instruction

Surveyor

Guo Ding

ASSIGNMENT (Office)

Front End

Chin Lee Ying

of

AIG

Date/Time

21/2/19 @ 11:57am

Estimated Cost

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 662G

Insured

EY 11194

at Workshop in/s

Sunday plus Auto

Tel:

64514933

of

Blk 4003, Amek Ind. Park 1 Ave 10 # 01-116/118

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Vch:

D.O.A

25/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

up)

H.O.D. Endorsement:

Date/Time:

12:15pm @ 21/2/19

Person Contacted

Ms. Yeo

Vehicle (IN) / (OUT)

Date/Time

Action/Instruction (X) Estimate

SLV 662G-X

EY 11194 - CS3/A1617021920 / M / ea3s2

D.O.A: 14/11/2017

Surveyor

PAS
Xml

REF:

AL6

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Sunday plus Auto

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLV662G

Yr Regn:

21 Dec 2017

Type: M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 5 wagon c.c 1998

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

130 1/2

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

IM6CW107/H0127420

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

205/55 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

21-02-19

Survey held at

w/s

1pm

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

O/S Rear

The UIC/ Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$200 - \$300

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

-

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

PRO

Lump Sum / I.B.I. (\$

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 21/2/2019 11:57:38 AM
Attachments:  90172 (our ltr dd 19219 Notice of Accident).pdf

Hi LKK,

Kindly assist to survey today, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Wednesday, February 20, 2019 10:51 AM
To: Abu Kassim, Noor Mariesa
Cc: Fong, Andy-SY; Chin, Lee-Ying; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Azlan, Syazairdina; Hor, Yinrul
Subject: Re: Our ref: LCH.jp/AMK05-90172.19 Your ref: 3125596372SG003 - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE EY1119U AND SLV662G ON 25/01/2019

Dear Sirs

We refer to the above matter and to your e-mail of even date below.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors as stated in your aforesaid e-mail.

We are further instructed to append below our client's 10 proposed surveyors as follows :-

- (1) Liaw Leong San
- (2) Lee Kok Weng
- (3) Patrick Ng Kong Beng
- (4) How Andrew
- (5) Chang Fuh Keong
- (6) Philip Foo
- (7) Ong Ah Keng, Kent
- (8) Ong Poh Meng
- (9) Ng Soon Aik Francis
- (10) Ng Soon Chuan Louis

If you are not agreeable to our list of surveyors above, kindly liaise with our client's repairer workshop for arrangement of the pre-repair survey ("PRS") of our client's vehicle no. SLV 662 G, the details are as follows :-

Sunday Plus Auto Computerised Service Centre Pte Ltd
Blk 4003 Ang Mo Kio Industrial Park 1 Ave 10 #01-116/118
Singapore 569624

Contact : Mrs Yeo (tel: 64514933 / 64514261)

Kindly acknowledge.

Thank you.

Regards,
Jennifer
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 63378700
Fax: 63373700

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/01/2019 10:12
Date Of Accident	25/01/2019 18:00
Exact Location Of Accident	UPPER SERNGOON RD-SENGKANG NEAR TOU MU KUNG TEMPLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV662G
Insured/Policyholder	
Name Of Registered Owner	LEE HWEE ENG
NRIC No	S7730758C
Email Address	CECILIALHE@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98506225
Alternative Phone No	OTHERS-98506225

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800002369
Cover Note Number	

Driver

Name of Driver	LEE HWEE ENG
NRIC No	S7730758C
Date Of Birth	17/10/1977
Occupation	INDOOR
Date Of Driving Pass	26/12/2008
Driving Experience	10 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98506225
Fax Number	
Contact Number	OTHERS-98506225
Email Address	CECILIALHE@YAHOO.COM.SG

Address	BLK 108B MCNAIR ROAD #08-210
Postcode	323108
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	POTONG PASIR NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 142 POTONG PASIR AVENUE 3 , POSTCODE: 350142 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2829999 - FAX NO: 62815964
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	EY1119U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	AIG ASIA PACIFIC INSURANCE PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LEE HWEE ENG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLV662G

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0758C
Vehicle Details	
Vehicle No.:	SLV662G
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Feb 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 WAGON 2.0 AT EU6
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	PE10539441
Chassis No.:	JM6CW1071H0127420
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$17,222.00
Original Registration Date:	21 Dec 2017
First Registration Date:	21 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$17,222.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Dec 2027
PARF Rebate Amount:	\$12,916.00
Intended COE Rebate Details	
COE Expiry Date:	20 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$47,405.00
Total Rebate Amount:	\$60,321.00

The information contained herein is correct as at 22 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/01/2019 10:12
Date Of Accident	25/01/2019 18:00
Exact Location Of Accident	UPPER SERNGOON RD-SENGKANG NEAR TOU MU KUNG TEMPLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV662G
Insured/Policyholder	
Name Of Registered Owner	LEE HWEE ENG
NRIC No	S7730758C
Email Address	CECILIALHE@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98506225
Alternative Phone No	OTHERS-98506225

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800002369
Cover Note Number	

Driver

Name of Driver	LEE HWEE ENG
NRIC No	S7730758C
Date Of Birth	17/10/1977
Occupation	INDOOR
Date Of Driving Pass	26/12/2008
Driving Experience	10 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98506225
Fax Number	
Contact Number	OTHERS-98506225
EEmail Address	CECILIALHE@YAHOO.COM.SG

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LEE HWEE ENG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLV662G

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SUV 662G

rear Bumper ~~x repair~~ ✓ Cut
" " clips - mtc

rear RH Fender x repair.

rear RH Taillamp - SCR

rear RH wheel Rim x repair.

rear RH shock ~~asborter~~ absorber ?

rear RH Lower Arm ?

rear RH Knock Arm ?

" " " " bearing ?

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Feb 2019 11:36 Edit Reg		21 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TAY AH LEK, ID: S2060442E		
Main Claimant:	LEE HWEE ENG, ID: S7730758C		
Vehicle Reg. No.:	SLV662G	Date of Loss:	25/01/2019 17:00 - :59 [13 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3125596372SG	Policy/Cover Note No.:	2100483569 (Comprehensive) Coverage: 27/09/2018 - 26/09/2019
Vehicle Reg. No. (Insured):	EY1119U	Policy No. (Claimant):	
		Excess:	
Repairer:	Sunday Plus Auto Computerised Services Centre Pte Ltd (HQ) BLK 4003 ANG MO KIO INDUSTRIAL PARK 1 AVE 10, #01-116/118, 569624 Ang Mo Kio - Tel: 64514933/64514261		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJlQian.Ler@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 04/03/2019]		
Claimant's Solicitor:	CHEONGHOH LAW CORPORATION - Tel: 63378700		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (22/02/2019): Request to upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLV662G (3125596372SG)**

[EY1119U]
























TP

LEE HWEE ENG

Jan 25 2019 5:00PM

[TAY AH LEK]

Sunday Plus Auto Computerised Services Centre Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
2	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
3	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
4	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
5	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
6	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
7	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
8	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
9	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
10	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
11	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
12	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
13	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
14	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
15	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
16	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
17	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
18	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
19	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
20	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
21	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
22	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
23	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
24	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
25	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
26	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
27	23/02/19 16:15		General View													Load JPG		<input checked="" type="checkbox"/>		
Documentation															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail		Print		
1	22/02/19 10:04		OI GIA REPORT													Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST																		Reset	Save	Print
There are no document checklists configured.																				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19003313/GCD3S2

Date: 26/02/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100483569
Claimant Vehicle No :	SLV662G	Insured Vehicle No :	EY1119U
Date of Loss:	25/01/2019	Nature of Claim:	TP
		Claim No:	3125596372SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV662G	Engine No:	PE10539441
Make & Model:	MAZDA 5, 2.0 (A)	Chassis No:	JM6CW1071H0127420
Reg. Date:	21/12/2017 (Man. Year: 2017)	Odometer:	13042 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	21/02/2019	Sunday Plus Auto Computerised Services Centre Pte Ltd (HQ)
Date Inspected:	21/02/2019 Inspected At:	BLK 4003 ANG MO KIO INDUSTRIAL PARK 1 AVE 10, #01-116/118
Estimated Period of Repair:	4.0 days	Singapore 569624

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR RH FENDER	Repair	0.00 F	*- F
4	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
5	1		*REAR RH WHEEL RIM	Repair	0.00 F	*- F
6	1		*REAR RH SHOCK ABSORBER	*Check	0.00 F	*- F
7	1		*REAR RH LOWER ARM	*Check	0.00 F	*- F
8	1		*REAR RH KNOCK ARM	*Check	0.00 F	*- F
9	1		*REAR RH KNOCK ARM BEARING	*Check	0.00 F	*- F
				Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >