



Your Ref: 19.26429 PD-O

Date: 08th Mar 2019

Our Ref : CS3/ASM18021033/T1td3e2-1

M/s AXA Insurance Pte Ltd

C/O: Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKE 1421E

INSURED VEHICLE: XE 3309E

ACCIDENT DATE: 19/11/2018

We thank you for your instruction on 19/02/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKE 1421E from M/s S K Auto Consultants.
- b) Singapore Accident Statement and Police Report of Vehicle SKE 1421E.
- c) Colour damaged vehicle photographs of SKE 1421E.

Pre-Repair Inspection Date : 26/11/2018 at M/s Ama Automotive Pte Ltd, 36 Toh Guan Road East #03-36, Singapore 608580.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKE 1421E
Make & Model	: Toyota Corolla Altis 1.6 Auto
Year of Registration	: 2012
Chassis Number	: MR053REE104129404
Engine Capacity	: 1598 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.