

ASA REC BY:

REP: CS/SMO19 003373/ Utd3

n2

Special Instruction:

Surveyor: menmen Marcus

ASSIGNMENT (Office)

From (Person): Chunshuhuiagnes of SMO

Date/Time: 2/12/19 @ 3:45pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 814M Insured: GU 51139

at Workshop m/s: Tick Hai Motor Tel: 6747 4676

of: 11caki Bkt Ave 6 # 01-54

Policy No: D18M7 PCVE001770 Claim No: CMTD1900972

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 18/02/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{lup} H.O.D. Endorsement: _____

Date/Time: 11:20am @ 22/2/19 Person Contacted: Connie Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	PC 814M - NS/INC 1301803/H1242 DVA: 28/1/2013
	GU 51139 - CS3/INC 11017509/Kum-1 DVA: 28/8/2011
JSP-	Pending estimate revert via menmen

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

SMO

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: PCP/4M
 at Workshop m/s: Tide Lee
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: PCP/4M Yr Regn: 71 11
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CAI
 Make: Toyota Hiace Hirofco 2982
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 614272 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: YTFST22P000010721
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195-215
 R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 30%
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or condor
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. _____ mm L/Bal. 6 mm
 D.O.A. 18/2/19 D.O.I. 22/2/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S ft.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
27/2/19 ATA 6964 rep 12h. 2hrs. Snd.
4/5 @ 3100 confirmed with Connie. Cred: 2723.13, 46%

RECEIVED 28 FEB 2019

Date/Time, File Pass to? Preli. Report
 Final Report
 1) 28/2 Typist
 Date/Time, File Return to?

Days Of Repair: 4
 Resurvey No. of Trip: 1

Report Format: TP
 Lump Sum / I.B.I: (\$ 3100/-)

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee:	250
Transportation:	10
) S + RS, SI	
) Photos	
) Others	
TOTAL	260

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	19 Feb 2019		21 Feb 2019 15:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	FANCO FAN MARKETING PTE LTD, Co. Reg. No.: 201313448W		
Main Claimant:	AURORA WORLD PTE. LTD., Co. Reg. No.: 201002992D		
Vehicle Reg. No.:	PC814M	Date of Loss:	18/02/2019 10:00 - :59
Claim Type:	TP / CMTD1900972	Policy/Cover Note No.:	D18MTPCVE001770 (Third Party Only)
Vehicle Reg. No. (Insured):	GU5113G	Policy No. (Claimant):	
		Excess:	
Repairer:	Tick Hai Motor & Welding Services - Kaki Bukit (HQ) BLK 1 KAKI BUKIT AVE 6, #01-54 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 6747 4676, 68429089		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/03/2019]		
Driver/Custodian (Insured):	PHANG YAP CHIN (), NRIC: G2795765Q, Tel: +6583716557		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***PC814M (CMTD1900972)**
[GU5113G]

TP

AURORA WORLD PTE. LTD.

Feb 18 2019 10:00AM

[FANCO FAN MARKETING PTE LTD]

Tick Hai Motor & Welding Services - Kaki Bukit

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **25/02/2019 09:56 AM.**

To agnes.chan@sompo.com.sg

Subject

Dear Sir/Madam,

Please be informed that we have inspected the vehicle PC 814M on 22/2/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

159 Tick Hai Motor

ACCIDENT STATEMENT

Date Of Report	19/02/2019 09:21
Date Of Accident	18/02/2019 10:10
Exact Location Of Accident	YISHUN AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC814M
Insured/Policyholder	
Name Of Registered Owner	AURORA WORLD PTE. LTD.
Co Reg No	201002992D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91188517
Alternative Phone No	OFFICE-91188517

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE COMMUTER BUS (D)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101288407 (COMP)
Cover Note Number	

Driver

Name of Driver	MUHAMAD NOOR BIN A RASHID
NRIC No	S7939798I
Date Of Birth	10/12/1979
Occupation	OUTDOOR
Date Of Driving Pass	21/11/2011
Driving Experience	7 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87533140
Fax Number	
Contact Number	OTHERS-87533140
EMail Address	NOEMAIL

Address	BLK 124 BEDOK NORTH ROAD #03-131 (OLD ADDRESS) BLK 461B YISHUN AVE 6 #08-1047 S(762461) (NEW MAILING ADDRESS)
Postcode	460124
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UNABLE TO UPLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GU5113G
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	PANG YAP CHIN
NRIC/Passport Number	G2795765Q
Contact Number	83716557
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

19 FEB 2019


Handwritten signature

Driver's Signature
(If driver is not the policyholder)
Date & Time: 19-02-19 - 0956 AM



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A - PC 814M
 B - GU 5113G
 DOA - 18/2/19

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AROUND 10.12AM I WAS TRAVELLING ALONG YISHUN AVE 1, ALMOST NEAR TRAFFIC LIGHT JUNCTION. I WAS AT 2ND LANE THE MINI VAN WAS TRAVELLING AT 3rd LANE, ONCE THE TRAFFIC LIGHT CHANGE TO GREEN ALL MOVE AS PER NORMAL. ON THAT TIME THERE IS A TRAILER IN FRONT OF THE MINI VAN. SO ~~THE~~ THE DRIVER HAS NO PATIENCE HE DECIDE TO CHANGE TO 2nd LANE WITHOUT SIGNALING AND JUST CHANGE. HE CLAIM THAT HE CAN'T SEE MY VEHICLE.

DECLARATION

I/We declare the foregoing particulars are true in every respect. 19 FEB 2019


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 19-2-19-0936am


 Reporting Centre Personnel's Signature
 Name:
 NRIC/PIN No.:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 2992D

Vehicle Details

Vehicle No.: PC814M
Vehicle to be Exported: No
Intended Deregistration Date: 22 Feb 2019
Vehicle Make: TOYOTA
Vehicle Model: TOYOTA HIACE HIROOF AUTO 14 SEATER
Primary Colour: White
Manufacturing Year: 2011
Engine No.: 1KD2096537
Chassis No.: JTFST22P000010721
Maximum Power Output: -
Open Market Value: \$37,122.00
Original Registration Date: 08 Jul 2011
First Registration Date: 08 Jul 2011
Transfer Count: 2
Actual ARF Paid: \$1,857.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 07 Jul 2021
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$29,006.00
COE Rebate Amount: \$6,964.00
Total Rebate Amount: \$6,964.00

The information contained herein is correct as at 22 Feb 2019

OK


WORLD UNIVERSITY EXPO
 Specially for Sec 4 / 5, N, O, A, JC 1 / 2 / IB/ Diploma Students


22ND FRI 3-9PM & **23RD SAT 12-7PM**
FEBRUARY


SUNTEC CONVENTION HALL 303-304

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Toyota Corolla Altis 1.6 Auto



Old But Reliable Car In Excellent
 Condition
 Direct Owner StarAd


Think One Automobile

NEW & USED COMMERCIAL VEHICLES



[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Browse by Category

Sort by Date Posted 20 results/page

11 vehicles

hiace

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	hiace		Any	Any	2011	Any	Any	Any	Available
	Toyota	Hiace	\$30,800	\$11,950 /yr	21-Sep-2011	2,982 cc	-	Van	Available
	Fuel Type: Diesel 100% Loan Available! Comes With Brand New Coated Of Paint/Newly Wrap Seats/Serviceing And Most Importantly Reliability! 4DR Agent Toyota Hiace Panel Van! The Most Sellable Unit In Town. Highest Body Va...								
	Car (S) Pte Ltd Posted: 22-Feb-2019 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota	Hiace	\$31,777	\$12,230 /yr	28-Sep-2011	2,982 cc	150,230 km	Van	Available
	Fuel Type: Diesel Best Selling 5 Doors Van In The Market. No Repair Needed! Buy With A Peace Of Mind. Well Maintained! Handle By A Careful Driver! Door Step Viewing Can Be Arranged. Call Our Sales Person Now For A No Q...								
	KSL Automotive Pte Ltd Posted: 19-Feb-2019 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota	Hiace Commuter	\$30,800	\$14,050 /yr	03-May-2011	2,982 cc	-	Bus	Available
	Fuel Type: Diesel 13+1 Seater Toyota Hi Roof.1 Owner Only.Pte Hire And Private Bus Can Be Arrange.We Provide Flexible In House Loan Up To 100%.Price Negotiable Till Sold.pls Call For A Non Obligation Discussion								
	ABWIN Bus Pte Ltd Posted: 18-Feb-2019 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota	Hiace	\$21,800	\$9,760 /yr	18-May-2011	2,494 cc	-	Van	Available
	Fuel Type: Diesel Best Selling In Market, Price Negotiable! 1 Owner! Original Condition, Servicing No Repairs Needed, In House, Welcome Trade In, And Call For Viewing.								
	Posted: 16-Feb-2019 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Toyota	Hiace	\$30,800	\$11,290 /yr	15-Nov-2011	2,982 cc	-	Van	Available
	Fuel Type: Diesel Best Offer In Town! Best Selling 5 Door Van! 100% Loan Available, View To Believe! No Repair Needed! High Trade In Offer! Call For Appointment Now!								
	ABWIN (1994) Pte Ltd Posted: 13-Feb-2019 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota								
	Toyota	Hiace	\$30,800	\$11,420 /yr	03-Nov-2011	2,982 cc	-	Van	Available
	Fuel Type: Diesel								

Compare

159 TICK HAI MOTOR
1 KAKI BUKTI AVE 6 #01-20 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 53033608A

not allowed
4/5 # 3100/2
22/2/19
Hdy.

Vehicle Number: PC814M
 Vehicle Model : Toyota Hiace Hiroof Auto 14 Seater
 Manufacturing Year : 2011
 Chassis : JTFST22P000010721

S/N.	Item Description	Amount (\$)
1	Front Bumper <i>Dis</i>	\$ 500.30
2	Front Bumper Side Bracket (LH) <i>one</i>	\$ 198.77
3	Front Bumper Clip x 6 pcs <i>RM</i>	\$ 13.20
4	Front Headlamp (LH) <i>SEA</i>	\$ 700.59
5	Front Corner Panel (LH) <i>20/200</i>	\$ 246.29
6	Step garnish (LH) <i>Dis</i>	\$ 80.25
7	Front Door (LH) <i>20/200</i>	\$ 930.90
8	Front Door Hinge (LH) x 2 pcs <i>sent/100</i>	\$ 128.40
9	Front Door Handle (Outer) (LH) <i>SIC SEA</i>	\$ 72.23
10	Side Mirror (LH) <i>n</i>	\$ 441.38
11	Front Pillar (LH) <i>n</i>	\$ 304.95
12	Petrol Tank Cover <i>n</i>	\$ 80.25
Total :		\$ 3,697.50
Less 25% :		\$ 924.38
Amount :		\$ 2,773.13

2798.7
252
2099.02

S/N	Special Nett Item	Amount (\$)
1	Front Headlamp Chrome Lining <i>SEA</i>	\$ 120.00
2	Front Door Sticker <i>Carbon</i> <i>RM</i>	\$ 80.00
3	Petrol Tank Cover Sticker <i>11</i>	\$ 40.00
4	Corner Panel Sticker <i>RM</i>	\$ 80.00
5	Step Garnish Sticker <i>RM</i>	\$ 60.00
6	Front Door Visor <i>RM</i>	\$ 120.00
Total :		\$ 500.00

Labour	Amount (\$)
To check front electrical system, and focus headlamp	\$ 120.00
To transfer LHF door components from old door to new door	\$ 80.00

20
60

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19003373/UTD3N2

Date: 01/03/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE001770
Claimant Vehicle No :	PC814M	Insured Vehicle No :	GU5113G
Date of Loss:	18/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1900972

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC814M	Engine No:	1KD2096537
Make & Model:	TOYOTA HIACE, 3.0 D High-roof 14 Seater (A)	Chassis No:	JTFST22P000010721
Reg. Date:	08/07/2011 (Man. Year: 2011)	Odometer:	614272 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Condor 6 mm	Rear Left Side:	Condor 6 mm
Front Right Side:	Condor 6 mm	Rear Right Side:	Condor 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,273.13	2,499.02	774.11	23.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,380.00	1,170.00	45.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,823.13	3,879.02	1,944.11	33.39
Approved Total (Overridden) (S\$)		3,100.00		
	(S\$) 5,823.13	3,100.00	2,723.13	46.76
+ GST 7.00/7.00% (S\$)	407.62	217.00	190.62	46.76
Nett Amount (S\$)	6,230.75	3,317.00	2,913.75	46.76

INSPECTION

Date of Assignment:	21/02/2019	
Date Inspected:	22/02/2019 Inspected At:	Tick Hai Motor & Welding Services - Kaki Bukit (HQ) BLK 1 KAKI BUKIT AVE 6, #01-54 AUTOBAY @ KAKI BUKIT Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2019)
Parts: 213	TOYOTA HIACE 3.0 D High-roof 14 Seater (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC814M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	500.30 FL	*500.30 FL
2	1		*FRONT BUMPER SIDE BRACKET (LH)	Cracked	198.77 FL	*198.77 FL
3	6		*FRONT BUMPER CLIPS	Necessary	13.20 FL	*13.20 FL
4	1		*FRONT HEADLAMP (LH)	Scratched	700.59 FL	*700.59 FL
5	1		*FRONT CORNER PANEL (LH)	Dented/Bent	246.29 FL	*246.29 FL
6	1		*STEP GARNISH (LH)	Distorted	80.25 FL	*80.25 FL
7	1		*FRONT DOOR (LH)	Dented/Bent	930.90 FL	*930.90 FL
8	2		*FRONT DOOR HINGE (LH)	Bent/Twisted	128.40 FL	*128.40 FL
9	1		*FRONT DOOR HANDLE (OUTER)(LH)	Serviceable	72.23 FL	*- FL
10	1		*SIDE MIRROR (LH)	Repair	441.38 FL	*- FL
11	1		*FRONT PILLAR (LH)	Repair	304.95 FL	*- FL
12	1		*PETROL TANK COVER	Repair	80.25 FL	*- FL
13	1		*FRONT HEADLAMP CHROME LINING	Scratched	120.00 FS	*120.00 FS
14	1		*FRONT DOOR STICKER CARBON	Necessary	80.00 FS	*80.00 FS
15	1		*PETROL TANK COVER STICKER	Not Necessary	40.00 FS	*- FS
16	1		*CORNER PANEL STICKER	Necessary	80.00 FS	*80.00 FS
17	1		*STEP GARNISH STICKER	Necessary	60.00 FS	*60.00 FS
18	1		*FRONT DOOR VISOR	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,197.51	3,198.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	924.38	699.68
Total Parts (\$\$)	3,273.13	2,499.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FRONT ELECTRICAL SYSTEM,AND FOCUS HEADLAMP	New	120.00	20.00
2	TO TRANSFER LHF DOOR COMPONENTS FROM OLD DOOR TO NEW DOOR	New	80.00	60.00
3	TO REMOVE,REPLACE ABOVE LISTED PARTS AND PANEL,TO PANEL BEAT ACCIDENT AFFECTED PARTS	New	950.00	500.00
4	TO SRAY PAINTING ON AFFECTED AREA	New	1,400.00	800.00
Gross Labour Cost (S\$)			2,550.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >