

ASS. REC. BY:

REF:

08/CTI19003375/Jvd3ed

Special Instruction:

Surveyor
Memmen

Hwee Jie

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

63896530

of

CTI

Date/Time:

22/2/19 @ 11:24pm

Estimated Cost:

Bill to:

 OD TP/WS/TP RES / OD RES / EVA / INV / MV/CS

To Inspect Vehicle No:

SAM 2778A

Insured:

at Workshop m/s

Sin Yew Hup

Tel:

67600819

of

Blk D4 Woodlands Rd 393M, Yew Tee Ind. Est

Policy No:

DMPC8N3099131802

Claim No:

SNM19D200732C01

Sum Insured:

Excess:

\$500.00

Make of Vch:

(Client's Record)

D.O.A.

10/2/19

CA / REV /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:11pm @ 22/2/19

Person Contacted:

Jume

Vehicle

 IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SAM 2778A-x
25/2/19	Revert vehicle TIL via memmen
26/2/19	Submit ext TIL - mv: \$18K (EST) LTA: \$13,687 NV: \$4313

REF:

Hwee Jie

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$ 18K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No. SGM 2778A Yr Regn: 120 of 2006

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c. 1598

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 350298 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0532EC107131731

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / 8/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 10/2/19 D.O.I. 22/2/19

Survey held at Sin Yew Hup

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooflop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
RECEIVED 26 FEB 2019	

Date/Time. File Pass to?

: Preli. Report

Days Of Repair:

1)

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time. File Return to?

2) 26p - typist

Add Fee: : Site Insp (\$

) ___ S + PS. ___ SI

Report Format :

: Interview (\$

) Photos

Lump Sum / I.B.I. (\$

: Tech. Invs (\$

) Other's

: Weekend (\$

)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Feb 2019 Sendback Est	19 Feb 2019 19:12 S\$0.00	22 Feb 2019 11:24 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TAN AH KA, ID: S1595347J, Tel: +6596185234, Email: NOEMAIL		
Vehicle Reg. No.:	SGM2778A	Date of Loss:	10/02/2019 17:00 - :59 [147 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D200732C01	Policy/Cover Note No.:	DMPCSN3099131802 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate, 677981 Woodlands - Tel: 67600819		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/03/2019]		
Driver/Custodian:	TAN AH KA (55 / Male), NRIC: S1595347J, Tel: +6596185234 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SGM2778A (SNM19D200732C01)

OD

Feb 10 2019 5:00PM

[TAN AH KA]

Sin Yew Hup Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 25/02/2019 18:12 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$0.00) - SGM2778A - Claim Handler: Elaine Cheong

Approved:0,00:Please finalize report & forward bill for your services rendered

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Elaine Cheong	
Date: 25 Feb 2019	
<h3><u>Preliminary Advice</u></h3>	

Vehicle No	: SGM2778A	Accident Date	: 10/02/2019
Make	: TOYOTA COROLLA ALTIS	Policy No.	: DMPCSN3099131802
Assignment Date	: 22/02/2019	Excess	: S\$500.00
Date of Inspection	: 22/02/2019	Est. Duration of Repair	: 0.00
Inspection At	: SIN YEW HUP AUTO PTE LTD (HQ) BLK D4 WOODLANDS ROAD 393M, YEW TEE INDUSTRIAL ESTATE SINGAPORE 677981		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	18,000.00
COE / PARF Rebate	:S\$	13,687.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,313.00
Brake System	: In Order	
Steering System	: In Order	
Tyre Condition (Front)	: 6/6 mm	
Tyre Condition (Rear)	: 6/6 mm	

Remarks

()		The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(X)		The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()		Other comments :

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5347J
Vehicle Details	
Vehicle No.:	SGM2778A
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	3ZZ4604717
Chassis No.:	MR053ZEC107131731
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,498.00
Original Registration Date:	12 Oct 2006
First Registration Date:	12 Oct 2006
Transfer Count:	1
Actual ARF Paid:	\$17,048.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Oct 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$26,054.00
COE Rebate Amount:	\$13,687.00
Total Rebate Amount:	\$13,687.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Feb 2019

OK



中国太平保險(新加坡)有限公司
 CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Co. Reg. No. 200206384E

MX1F
 R SN
 AN0584A
 Cov. Type: C

MOTOR PRIVATE CAR

CERTIFICATE OF INSURANCE
 Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
 Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
 Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE No.	DMPCSN3099131802	Engine No : 32Z4604717 ChaNo:MR053ZEC107131731
1. Index Mark and Registration Number of Vehicle	SGM2778A	AUTOSAFE =====
2. Name of Policy Holder	TAN AH KA	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	12 October 2018	Named Drivers Ex Sect. I S\$500.00 Additional Ex Other than Named Drivers: Ex Sect. I - Age <= 25..... S\$3,000.00 Ex Sect. I - Age >= 26..... S\$500.00 * Age as at date of accident EX ON WINDSCREEN S\$100.00
4. Date of Expiry of Insurance	11 October 2019	
5. Persons or Classes of Persons entitled to drive*	(a) The Policyholder. (b) Any other person who is driving on the Policyholder's order or with his permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
6. Limitations as to use:	Use for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade. Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled. One time waiver of Excess for the first S\$500 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorised workshops for each Policy year. HIRE PURCHASE CO. : EFIZZIG CREDIT PTE LTD AS HP OWNER * Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.	

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Terry's Office
 38 Parbury Avenue #04-02 S467034
 Tel/WhatsApp : 9127 8514

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

 Authorised Signatory

Issued By: HUANG GUOQING, TERRY
 Authorised Officer

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	12/02/2019 14:33
Date Of Accident	10/02/2019 17:00
Exact Location Of Accident	JURONG TOWN HALL RD FILTER LANE/JLN AHMAD IMBRAHIM
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGM2778A
Insured/Policyholder	
Name Of Registered Owner	TAN AH KA
NRIC No	S1595347J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96185234
Alternative Phone No	OTHERS-96185234
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3099131802
Cover Note Number	
Driver	
Name of Driver	TAN AH KA
NRIC No	S1595347J
Date Of Birth	24/09/1963
Occupation	INDOOR
Date Of Driving Pass	26/07/1982
Driving Experience	36 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96185234
Fax Number	
Contact Number	OTHERS-96185234
EMail Address	NOEMAIL

Address	BLK 629 SENJA ROAD #20-198
Postcode	670629
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP9486S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



A: 5GM 2778A.
 B: YP 94865.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle B suddenly stopped when I was checking my blindspot, I cannot stop in time and hit onto the rear of vehicle B.


DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Feb 2019 Sendback Est	19 Feb 2019 19:12 S\$0.00	22 Feb 2019 11:24 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	TAN AH KA , ID: S1595347J, Tel: +6596185234, Email: NOEMAIL								
Vehicle Reg. No.:	SGM2778A	Date of Loss:	10/02/2019 17:00 - :59 [147 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D200732C01	Policy/Cover Note No.:	DMPCSN3099131802 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate, 677981 Woodlands - Tel: 67600819								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 05/03/2019]								
Driver/Custodian:	TAN AH KA (55 / Male) , NRIC: S1595347J, Tel: +6596185234 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> CHINA_TAIPING (25/02/2019): Alert - Adj Mandate Approved (S\$0.00) - SGM2778A - Claim Handler: Elaine Cheong CHINA_TAIPING (25/02/2019): Alert - Adj Mandate Approved (S\$0.00) - SGM2778A - Claim Handler: Elaine Cheong 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGM2778A (SNM19D200732C01)
OD
Feb 10 2019 5:00PM
[TAN AH KA]
Sin Yew Hup Auto Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	12/02/19 16:06	Accident Statement	Load HTM	
2	19/02/19 19:12	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 13:59	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	12/02/19 16:02	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
2	12/02/19 16:02	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
3	12/02/19 16:02	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
4	12/02/19 16:02	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
5	12/02/19 16:02	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
2	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
3	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
4	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
5	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
6	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
7	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
8	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
9	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
10	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
11	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
12	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
13	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
14	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
15	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
16	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
17	25/02/19 09:35	General View	Load JPG <input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	12/02/19 16:06	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	12/02/19 16:06	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	12/02/19 16:06	Sketch Plan #3 [Linked Accident Report Documents]	Load TIF	
4	12/02/19 16:06	Sketch Plan #4 [Linked Accident Report Documents]	Load TIF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/02/19 12:43	REPORT OF YP9486S	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 13:50	Log card (if available)	Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	12/02/19 16:06	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	12/02/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	12/02/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	12/02/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	12/02/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	12/02/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	12/02/19 16:06	Sketch Plan	Load TIF	
2	12/02/19 16:06	Sketch Plan #2	Load TIF	
3	12/02/19 16:06	Sketch Plan #3	Load TIF	
4	12/02/19 16:06	Sketch Plan #4	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19003375/JVD3E2

Date: 26/02/2019

REFERENCE

Insured/Claimant: TAN AH KA Policy No: DMPCSN3099131802 Claim No: SNM19D200732C01
Date of Loss: 10/02/2019 Nature of Claim: OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGM2778A**
Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4604717
Reg. Date: 12/10/2006 (Man. Year: 2006) Chassis No: MR053ZEC107131731
Colour: Silver Odometer: 350298 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$18,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	500.00	-500.00	
Nett Amount (S\$)	0.00	-500.00	500.00	

INSPECTION

Date of Assignment: 22/02/2019 Present Location: Sin Yew Hup Auto Pte Ltd (HQ)
Date Inspected: 22/02/2019 Inspected At: Sin Yew Hup Auto Pte Ltd (HQ)
Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate
Singapore 677981

Estimated Period of Repair: 0.0 days

Adjuster: ONG HWEE JIE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$18,000.00
OMV : \$15,498.00
PARF Rebate (1) : \$0
Quota Premium Paid : \$26,054.00
COE Rebate (2) : \$13,687.00
Total Rebate (1) + (2) = : \$13,687.00

The total amount incurred will be Market Value \$18,000.00 minus Total Rebate \$13,687.00 = \$4313.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2019)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGM2778A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >