

ASS. REC. BY

REP ESB/MSG19003377/Bed30

period of instruction

Surveyor

ASSIGNMENT (Office)

From (Person)

Monica Chung

of

MSG

Date/Time:

2/2/19 @ 4:41pm

Estimated Cost:

Bill to:

OD WS/TP RES / OD RES / EVA / INV / MV/CS

To Inspect Vehicle No:

SLP 4566G

Insured:

SLJ 8828G

at Workshop in/s

M.S. Panel Beating

Tel:

91436036

of

2 kaki Blt Ave 2 # 02-17

Policy No:

71599622

Claim No:

583164

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

20/2/19

CA / REV / REP. / REV 24 HRS

(up)

25/2/19 @ morning

H.O.D. Endorsement:

Date/Time:

11:16am @ 22/2/19

Person Contacted:

Mr. Boh

Vehicle IN

OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SLP 4566G - X</u>
	<u>SLJ 8828G - X</u>
	<u>Dismantle: 26/2/2019</u>
	<u>After repair: 28/2/2019</u>

REF: MSLG

ASSIGNMENT

PRS

From Date: 25/2/19

Estimated Cost

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLP 4566G
at Workshop no: M.S. panel Beating
of 2 kaki Bkt Ave 2 #02-17

Insured: Autobhub

Policy No

Claims No

Sum Insured: Excess:

(Client's Record)

Make of Veh: Mr. Loh @ 91436036

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt. Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: 3 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLP 4566G Regn: 19/1/2008

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA AXIO 1.5XA CC: 1496

Colour: SILVER A/C: Insured / Std / NI / NA

Sp. Reading: 159895 T/Radio: Insured / Std / NI / NA

Eng/No: INZC833495

C/No: NZE1416060587

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD AIR/In or

Tyre Size: F: 205/50/16

R: 205/50/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 20/1/19 D.O.I: 25/2/19

Survey held at: MS PANEL BEATING

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 2,000/- - 3,000/-

[Signature]
20/3/2019

* No general view photos.

Tanoms line
26/2/19

Date/Time, File Pass to?

: Prel. Report

Days Of Repair: 3

1)

: Final Report

Resurvey No. of Trip: 3

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: Site Insp (\$

Transportation

Interview (\$

) Hotel

Tech Invs (\$

) Other

Weekend (\$

)

Report Format: PRE.

Lump Sum / L.B.F. (%)

TOTAL

Empty box for final total and other details.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jan 2019		21 Feb 2019 16:41 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CHEN YU LING, ID: S8126716B, Tel: +6591118961		[Created by insurer]
Main Claimant:	NURJIHAN BINTI MOHAMMED NOOR, ID: S8820446H		
Vehicle Reg. No.:	SLP4566G	Date of Loss:	20/01/2019 19:00 - :59 [132 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 583164	Policy/Cover Note No.:	71599622 (Comprehensive) Coverage: 03/03/2018 - 02/03/2019
Vehicle Reg. No. (Insured):	SLJ8828G	Policy No. (Claimant):	
		Excess:	
Repairer:	M.S. Panel Beating Workshop (HQ) 2 Kaki Bukit Avenue 2, #02-17 Kaki Bukit Autohub, 417921 Kaki Bukit - Tel: 91436036		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/02/2019]		
Driver/Custodian (Insured):	FOK KAH KAY (HUO JIAQI) (), NRIC: S7933211I, Tel: +6598172211		
Adj Asg. Remarks:	Liab-not clear. SJE DISGAREE APPOINT LKK. PLS CONTACT MR LOH @ 9143 6036		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0446H
Vehicle Details	
Vehicle No.:	SLP4566G
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	1NZC833495
Chassis No.:	NZE1416060587
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$11,758.00
Original Registration Date:	19 Jan 2008
First Registration Date:	19 Jan 2008
Transfer Count:	2
Actual ARF Paid:	\$11,311.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jan 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$21,485.00
COE Rebate Amount:	\$16,737.00
Total Rebate Amount:	\$16,737.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Feb 2019

OK

Dep 5,800/yr
483/mth

MV 22000/2
PV 16737/2
NV 5263/2

TG Li W
26/2/19



Toyota Corolla Altis 1.6A (New 5-yr COE) **\$30,888** **\$6,170 /yr** **16-Feb-2009** **1,598 cc** **-** **Sedan** **Available**

Free 1 Servicing Upon Purchase! 1 Year Warranty Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Available! No Gimmicks! Well Maintained, Super Low Genuine Mileage Done. Well Groomed Ins...

PREMIUM AD

Posted: 22-Feb-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 12/2023) **\$27,800** **\$5,760 /yr** **24-Dec-2008** **1,598 cc** **103,544 km** **Sedan** **Available**

New 5 Years COE! Flexible In House Loan Up To 100%, \$3,000 Driveaway Inclusive Of 1st Installment And Insurance! Well Kept Condition, Non Smoker! Owning A Car Is So Much Easier, Kindly Call Our Friendl...

Viking Motor Pte Ltd

Posted: 22-Feb-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 12/2023) **\$28,800** **\$6,000 /yr** **16-Dec-2008** **1,598 cc** **118,500 km** **Sedan** **Available**

New Paintwork Done! Monthly Installment \$760 For 48 Month! Powerful, Comfortable, Reliable And Low Maintenance Cost. Flexible Bank/ In-house Loan Package Available. Viewing Is Highly Encouraged. Call ...

Viking Motor Pte Ltd

Posted: 22-Feb-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE) **\$30,800** **\$6,160 /yr** **18-Feb-2009** **1,598 cc** **93,000 km** **Sedan** **Available**

1 Owner Car. Up To 100% Loan, Immediate Approval! Extremely Well Maintained. Original Paint! High Trade In, Flexible Loan Schemes Available! Call Now To Schedule A Viewing Appointment!

PREMIUM AD

Posted: 22-Feb-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Axio 1.5A X (COE till 04/2023) **\$23,800** **\$5,800 /yr** **05-Apr-2008** **1,496 cc** **-** **Sedan** **Available**

Best Fuel Saving Car! Well Taken Care By Previous Owner! Comes With Body Kit! Drive With Passion! Trade In And High Loan Available. Please Call For Appointment.

Posted: 22-Feb-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 10/2021) **\$18,800** **\$7,050 /yr** **27-Oct-2006** **1,598 cc** **-** **Sedan** **Available**

Tip-Top Condition, Too Good To Scrap, High Paper Value And Body Value, Call For Viewing Now!

Posted: 22-Feb-2019 Tags: 2006 Toyota Corolla, 2006 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE) **\$31,800** **\$6,360 /yr** **17-Feb-2009** **1,598 cc** **-** **Sedan** **Available**

PREMIUM AD

Posted: 22-Feb-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.8A (New 5-yr COE) **\$33,800** **\$6,760 /yr** **23-Jan-2009** **1,794 cc** **88,000 km** **Sedan** **Available**

Well Maintained, Super Low Genuine Mileage Done. Well Groomed Inside Out. No Repairs Needed. Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emergency. We Pr...

PREMIUM AD

Posted: 22-Feb-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 12/2023) **\$31,800** **\$6,590 /yr** **23-Dec-2008** **1,598 cc** **95,000 km** **Sedan** **Available**

4 Brand New Tyres! Well Maintained, Super Low Genuine Mileage Done. Well Groomed Inside Out. No Repairs Needed. Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event ...

PREMIUM AD

Posted: 22-Feb-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Axio 1.5A X (COE till 08/2022) **\$22,800** **\$6,630 /yr** **06-Aug-2007** **1,496 cc** **-** **Sedan** **Available**

Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In-House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Bef...

Posted: 22-Feb-2019 Tags: 2007 Toyota Corolla, 2007 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE) **\$31,800** **\$6,360 /yr** **11-Feb-2009** **1,598 cc** **105,000 km** **Sedan** **ile**

aintained, Genuine Decent Mileage Done. Well Groomed Inside Out. No Repairs Needed. Comes With 6 Months Warranty By Our In-House op. Free Island Wide Towing In Event Of Emergency. We Provi...

PREMIUM AD

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/01/2019 19:56
Date Of Accident	20/01/2019 19:55
Exact Location Of Accident	JB CUSTOM TOWARDS SINGAPORE
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP4566G
Insured/Policyholder	
Name Of Registered Owner	NURJIHAN BINTI MOHAMMED NOOR
NRIC No	S8820446H
Email Address	NURJIHAN.MOHDNOOR@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96998469
Alternative Phone No	OTHERS-96998469

Vehicle Particulars

Manufacturer	TOYOTA
Model	AXIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00580608
Cover Note Number	

Driver

Name of Driver	NURJIHAN BINTI MOHAMMED NOOR
NRIC No	S8820446H
Date Of Birth	09/06/1988
Occupation	INDOOR
Date Of Driving Pass	20/09/2012
Driving Experience	6 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96998469
Fax Number	
Contact Number	OTHERS-96998469
EMail Address	NURJIHAN.MOHDNOOR@GMAIL.COM

Address	BLK 539 ANG MO KIO AVE 10 #04-2575 SINGAPORE
Postcode	560539
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : SITI KHALIESAH BTE IDRUS GENDER: : FEMALE
Passenger 2	NAME: : HASLINA BINTE HASSAN GENDER: : FEMALE
Passenger 3	NAME: : RAIHANA BINTE MUHAMMAD SALEHUDDIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS WEST NPC
Police Station Address	ROAD: 9 MARSILING LANE , POSTCODE: 739146 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ8828G
-----------------------------	----------

Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

PRIVATE CAR
FOK KAH KAY
S7933211I
98172211

DETAILS OF INJURED PERSON 1

Name
Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SITI KHALIESAH BTE IDF/US
REFER POLICE REPORT
SLP4566G

DETAILS OF INJURED PERSON 2

Name
Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

HASLINA BINTE HASSAN
REFER POLICE REPORT
SLP4566G

DETAILS OF INJURED PERSON 3

Name
Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode


RAIHANA BINTE MUHAMMAD SALEHUDDIN
REFER POLICE REPORT
SLP4566G

DETAILS OF INJURED PERSON 4

Name
Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

NURJIHAN BINTI MOHAMMED NOOR
REFER POLICE REPORT
SLP4566G

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY VEHICLE WAS AT JB CUSTOMS (MALAYSIA). THERE WAS HEAVY TRAFFIC.
MY VEHICLE WAS IN STATIONERY POSITION.
VEHICLE B APPROACHED MY VEHICLE FROM THE RIGHT REAR.
VEHICLE B FRONT HIT AGAINST MY RIGHT REAR.
I TURNED ON THE HAZARD LIGHTS. VEHICLE B TURNED ON HIS LEFT SIGNAL
VEHICLE B ~~RE~~ REVERSED AGAINST MY CAR AND CAUSED MORE DAMAGE ON MY CAR.

- REFER POLICE REPORT -

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jan 2019		21 Feb 2019 16:41 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHEN YU LING , ID: S8126716B, Tel: +6591118961								
Main Claimant:	NURJIHAN BINTI MOHAMMED NOOR , ID: S8820446H								
Vehicle Reg. No.:	SLP4566G	Date of Loss:	20/01/2019 19:00 - :59 [132 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 583164	Policy/Cover Note No.:	71599622 (Comprehensive) Coverage: 03/03/2018 - 02/03/2019						
Vehicle Reg. No. (Insured):	SLJ8828G	Policy No. (Claimant):							
		Excess:							
Repairer:	M.S. Panel Beating Workshop (HQ) 2 Kaki Bukit Avenue 2, #02-17 Kaki Bukit Autohub, 417921 Kaki Bukit - Tel: 91436036								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pel Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 22/02/2019]								
Driver/Custodian (Insured):	FOK KAH KAY (HUO JIAQI) (), NRIC: S79332111, Tel: +6598172211 Email:								
Adj Asg. Remarks:	Liab-not clear. SJE DISGAREE APPOINT LKK. PLS CONTACT MR LOH @ 9143 6036								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP4566G (583164)
[SLJ8828G]
TP
NURJIHAN BINTI MOHAMMED NOOR
Jan 20 2019 7:00PM
[CHEN YU LING]
M.S. Panel Beating Workshop

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print			
1	22/02/19 11:25	Video - AccidentTP						Load MP4			
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print			
1	20/02/19 16:35	Accident Statement From: SC - Reg. No: SLJ8828G, Claimant: CHEN YU LING						Load HTM			
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print			
1	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
2	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
3	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
4	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
5	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
6	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
7	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
8	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
9	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
10	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
11	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
12	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
13	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
14	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
15	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
16	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
17	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
18	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
19	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
20	20/03/19 15:49	General View						Load JPG	<input checked="" type="checkbox"/>		
21	20/03/19 15:51	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
22	20/03/19 15:51	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
23	20/03/19 15:51	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
24	20/03/19 15:51	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
25	20/03/19 15:51	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
26	20/03/19 15:51	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
27	20/03/19 15:51	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
28	20/03/19 15:51	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
29	20/03/19 15:51	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		
30	20/03/19 15:51	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
32	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
33	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
34	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
35	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
36	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
37	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
38	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
39	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
40	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
41	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
42	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
43	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
44	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
45	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
46	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
47	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
48	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
49	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
50	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
51	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
52	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
53	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
54	20/03/19 15:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
55	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
56	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
57	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
58	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
59	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
60	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
61	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
62	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
63	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
64	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
65	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
66	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
67	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
68	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
69	20/03/19 15:51	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/02/19 16:35	PRI From:SC - Reg. No: SLJ8828G, Claimant: CHEN YU LING		<input type="checkbox"/>
2	20/02/19 16:35	TP SLP4566G E-REPORT From:SC - Reg. No: SLJ8828G, Claimant: CHEN YU LING		<input type="checkbox"/>
3	20/02/19 17:15	SJE DISAGREE		<input type="checkbox"/>
4	20/02/19 17:15	APPOINT LKK		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19003377/GCD3E2
Date: 21/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 71599622	
Claimant Vehicle No: SLP4566G	Insured Vehicle No: SLJ8828G	
Date of Loss: 20/01/2019	Nature of Claim: TP	Claim No: 583164

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP4566G	Engine No: 1NZC833495	
Make & Model: TOYOTA AXIO, 1.5 (A)	Chassis No: NZE1416060587	
Reg. Date: 19/01/2008 (Man. Year: 2007)	Odometer: 159895 km	
Colour: Silver		
Engine Capacity: 1496 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 205/50 R16	Rear Tyre Size: 205/50 R16
Front Left Side: Yokohama 6 mm	Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm	Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/02/2019	Date Inspected: 25/02/2019	Inspected At: M.S. Panel Beating Workshop (HQ) 2 Kaki Bukit Avenue 2, #02-17 Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair: 3.0 days		

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2019)
Parts: 143	TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP4566G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >