

ASS. REC. BY

REF

CS3/CTI/9003393/ Jcd30

Action/ Instruction

Surveyor

Hwee Jie

ASSIGNMENT (Office)

From (Person)

Chong Boon Sun

of

CTI

Date/Time

2/2/19 @ 2:39pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SYW 6049G

Insured:

SLS 7011 E

at Workshop m/s

Car Doctor

Tel:

9189 6556

of

Blk C3, 391 A Woodlands Rd - Yew Tee Ind. Est

Policy No:

DMPCEN30803218011

Claim No:

8NM19D200872002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/2/19

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

4:11pm @ 2/2/19

Person Contacted:

Morgan

Vehicle

IN/OUT

Date/Time

Action/Instruction (X) Estimate

SYW 6049G - X

SLS 7011E - X

Dismantle: 25/2/2019

After repair: 28/2/2019

Hwee Jie
PRS

REF CTF

VEHICLE

Date: 22/2/19
Insured: Car Doctor
Bik C3, 391A Woodlands Rd Yew
We Ind. Est
Policy No.
Sum Insured:
Excess:
Makur@9189 6866

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repair:

days Res.: Yes or No

Lump Sum:

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Range: \$4500 - \$5500
5 days.

20/3/2019

Date/Time File Pass to:

☐ : Preli. Report

to

☐ : Final Report

Date/Time File Return to:

to

Report Format

PRS

Lump Sum / LB F. C.

Vehicle No: SJW60496

Date: 5 Apr 2010

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Subaru

CC: 1498

Colour: Black

ABC: Insured / Std / NI / NA

Sp Reading: 176821

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JF16E3KF396005901

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: Nil / ☒ STD / ☐ STD A/Rim or

Tyre Size: F: 205/55R16

R: -

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A. 18/2/19

D.O.I. 22/2/19

Survey held at

Car Doctor

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time File Pass to:

☐ : Preli. Report

to

☐ : Final Report

Date/Time File Return to:

to

Report Format

PRS

Lump Sum / LB F. C.

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation

to

to

to

to

to

to

150

150

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jun 2019		03 Jun 2019 09:21 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant:	ROSMINAH BTE ISMAIL, ID: S7212218F								
Vehicle Reg. No.:	SJW6049G	Date of Loss:	18/02/2019 08:00 - :59						
Claim Type:	TP / SNM19D200872C02	Policy/Cover Note No.:	DMPCSN30803218011						
Vehicle Reg. No. (Insured):	SLS7011E	Policy No. (Claimant):	MT/00469277						
		Excess:	S\$0.00						
Repairer:	M/s Car Doctor Pte Ltd (HQ) BLK3, 391A Woodlands Road Yew Tee, industrial estate, 677695 Woodlands - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 13/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Thursday, 21 February 2019 2:39 PM
To: assignments
Subject: FW: PRS for SJW 6049 G Our Ref: C145.109649.19 Your Ref: SNM19D200872

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 21 February, 2019 2:37 PM
To: Jerome Soh <jeromesoh@visionlawllc.com>
Cc: 'Jacqueline Tan Vision Law LLC' <jactan@visionlawllc.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: PRS for SJW 6049 G Our Ref: C145.109649.19 Your Ref: SNM19D200872

Without Prejudice
Save as to costs

Dear Jerome,

We will appoint LKK accordingly.

Dear LKK,

Pls pri.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Jerome Soh [<mailto:jeromesoh@visionlawllc.com>]
Sent: Thursday, 21 February, 2019 2:23 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: 'Jacqueline Tan Vision Law LLC' <jactan@visionlawllc.com>
Subject: PRS for SJW 6049 G Our Ref: C145.109649.19 Your Ref: SNM19D200872

Dear Mr Chong,

Refer to the above matter and our document as attached, let us have your reply as soon as possible. Thank you

Jerome Soh
Assistant Secretary
Vision Law LLC

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
JANICE HAN JIA LIN
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
EDISON TAM CHYI EU
SONIA LIM WEI LEI

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.C145.109649.19 (sj)
Your Ref: **SNM19D200872**

21 February 2019

CHINA TAIPING INSURANCE (S'PORE) PTE LTD

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Attention: Motor Claims Department

BY FAX: 6224 7175

email: claimsdept@sg.cntaiping.com
email: boonsen.chong@sg.cntaiping.com

Dear Sirs,

**ACCIDENT INVOLVING SJW 6049 G & SLS 7011 E & SKM 4491 M ON 18 FEBRUARY 2019 ALONG
PIE TOWARDS BKE AT ABOUT 0840 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email dated 21 February 2019 informing that your wish to conduct a pre-repair survey on our client's vehicle **SJW 6049 G**.

Please be informed that the said vehicle can be inspected at:

Car Doctor Pte Ltd
Blk C3 391A Woodlands Road
Yew Tee Industrial Estate
Singapore 677964
Ms Sylvester / Morgen (6635-5773)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

Anjalli M
(Head Office)



FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

cc: **SJW 6049 G** – By Email: motorclaims@cardoctor.com.sg_only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811 Fax: 6535-6802

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



Contact us at
 Hotline: (65) 6532 2888
 E-mail: CustomerService@DirectAsia.com

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Singapore) (the "Act")
 Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 (Singapore)
 Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Certificate No.	: MT/00469277
Type of Coverage / Driver Plan	: Car Comprehensive (Value Plan)
1) Vehicle Registration No.	: SJW6049G
Chassis No.	: JF1GE3KF39G005901
2) Name of Policy Holder	: ISMAIL, ROSMINAH (No valid driving licence)
3) Effective Date / Time of Commencement of Insurance for the Purpose of the Act	: 22/05/2018 00:00
4) Date/Time of Expiry of Insurance	: 21/05/2019 23:59
5) Persons or Classes of Persons Entitled to Drive	
(a) The Insured	
(b) Any person who is named on the policy who is driving on the Insured's order or with his permission.	
The person driving must have a valid driving licence to drive in Singapore and must not be under suspension or disqualification from driving.	
6) Limitations as to use*	
Use only for private purposes, in accordance with the declared car usage stated on your Policy Schedule. The policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business.	
*Limitations rendered inoperative by Section 8 of the Act and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under this heading.	
Sum Insured	: Market Value
Own Damage Excess	: S\$ 800.00 (before any applicable GST)
Windscreen Excess	: S\$ 100.00 (before any applicable GST)
Choice of workshop	: DirectAsia approved workshops
Finance company / Hire Purchase	: TOKYO CENTURY LEASING (SINGAPORE) PTE LTD
Main driver	: MOHAMED SALLEH, JUMARI
Named driver	: None
Important Note: This policy is on a named driver basis. Any unnamed drivers will not be covered.	

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Issued on: 03/04/2018

Direct Asia Insurance (Singapore) Pte. Ltd.

Edip Okur
Chief Underwriting Officer

Direct Asia Insurance (Singapore) Pte Ltd
 88 South Bridge Road Singapore 058716
 www.DirectAsia.com

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7212218F



Name

ROSMINAH BTE ISMAIL



Race

MALAY

Date of Birth

02-04-1972

Country of Birth

SINGAPORE

Sex

F



1103067



NRIC No. S7212218F



Blood Group Date of issue

O+ 12-07-1993

APT BLK 684D CHOA CHU KANG CRESCENT #08-352
SINGAPORE 684684

NRIC No: S7212218F

Date: 14/09/2011

No: 6880134

DRIVER IC & DL Pg. 1

REPUBLIC OF SINGAPORE
DRIVING LICENCE

Portrait of JUMARI BIN MOHAMED SALLEH

Licence Number: **S7315506A**
Name: **JUMARI BIN MOHAMED SALLEH**
Birth Date: **13 Apr 1973**
Issue Date: **01 Sep 2003**

Barcode: 000791507A

Portrait of JUMARI BIN MOHAMED SALLEH

S7315506A

JUMARI BIN MOHAMED SALLEH

BOYANESSE

13-04-1973 M 31560

SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 2	Motor Cars and Motor Tractors the weight of which unladen does not exceed 7500 kilograms	28 Sep 1995

NP 420A

Licence No: S7315506A

Barcode

Portrait of JUMARI BIN MOHAMED SALLEH

Barcode

S7315506A

28-04-2007

APT BLK 684D CHOA CHU KANG CRESCENT #08-352
SINGAPORE 684684

NRIC No: **S7315506A**

Date: 14/09/2011 No: 0880135

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2218F
Vehicle Details	
Vehicle No.:	SJW6049G
Vehicle to be Exported:	No
Intended Deregistration Date:	22 May 2019
Vehicle Make:	SUBARU
Vehicle Model:	IMPREZA 4DR 1.5R AWD 5MT ABS AIRBAG
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	EL15D742306
Chassis No.:	JF1GE3KF39G005901
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$14,597.00
Original Registration Date:	05 Apr 2010
First Registration Date:	05 Apr 2010
Transfer Count:	2
Actual ARF Paid:	\$14,597.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Apr 2020
PARF Rebate Amount:	\$7,298.00
Intended COE Rebate Details	
COE Expiry Date:	04 Apr 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$28,389.00
COE Rebate Amount:	\$2,465.00
Total Rebate Amount:	\$9,763.00

The information contained herein is correct as at 22 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	18/02/2019 14:23
Date Of Accident	18/02/2019 08:40
Exact Location Of Accident	ALONG PIE (SLOPE) TOWARDS BKE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJW6049G
Insured/Policyholder	
Name Of Registered Owner	ROSMINAH BTE ISMAIL
NRIC No	S7212218F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96426803
Alternative Phone No	OFFICE-96426803
Vehicle Particulars	
Manufacturer	SUBARU
Model	IMPREZA 4DR 1.5R AWD 5MT ABS AIRBAG
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00469277
Cover Note Number	
Driver	
Name of Driver	JUMARI BIN MOHAMED SALLEH
NRIC No	S7315506A
Date Of Birth	13/04/1973
Occupation	INDOOR
Date Of Driving Pass	28/09/1995
Driving Experience	23 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83090750
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	APT BLK 684D CHOA CHU KANG CRESCENT #08-352
Postcode	684684
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS7011E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH TONG, FRANK
NRIC/Passport Number	S8735011H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKM4491M
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

JUMARI BIN MOHAMED SALLEH

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJW6049G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time 18/07/2019

Driver's Signature

(If driver is not the policyholder)
Date & Time.

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN

X Accident



A - SJW 60496

B - SLS 7 olie

C. SKM 4491M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date & Time : 18/2/2019 8:40 am

Accident Location : PIE (slope) towards BKE

I was travelling along the mentioned location.

Traffic was slow & road was wet.

Vehicle C stopped due to an accident in front.

I stopped completely in time. Suddenly I felt an impact from the rear. The impact caused my vehicle to surge forward & bump slightly onto the front vehicle's rear portion.

I will visit the doctor later

☐ Reporting Only ☐ Own Damage ☐ Third Party ☒ Claim at other workshop (OD/TP)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 18/02/2019

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jun 2019		03 Jun 2019 09:21 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	ROSMINAH BTE ISMAIL, ID: S7212218F								
Vehicle Reg. No.:	SJW6049G	Date of Loss:	18/02/2019 08:00 - :59 [106 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200872C02	Policy/Cover Note No.:	DMPCSN30803218011						
Vehicle Reg. No. (Insured):	SLS7011E	Policy No. (Claimant):	MT/00469277						
		Excess:	S\$0.00						
Repairer:	M/s Car Doctor Pte Ltd (HQ) BLK3, 391A Woodlands Road Yew Tee, industrial estate, 677695 Woodlands - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 13/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents


*SJW6049G (SNM19D200872C02)
[SLS7011E]
TP
ROSMINAH BTE ISMAIL
Feb 18 2019 8:00AM
[-]
M/s Car Doctor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
2	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
3	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
4	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
5	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
6	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
7	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
8	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
9	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
10	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
11	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
12	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
13	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
14	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
15	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
16	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
17	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
18	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
19	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
20	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
21	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
22	06/06/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>	
23	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
24	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
25	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
26	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
27	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
28	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
29	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
30	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
31	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
32	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
33	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
34	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
35	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
36	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
37	06/06/19 14:32	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/06/19 14:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	06/06/19 14:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	06/06/19 14:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	06/06/19 14:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	06/06/19 14:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/06/19 14:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/06/19 14:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	06/06/19 14:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	06/06/19 14:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	06/06/19 14:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	06/06/19 14:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	06/06/19 14:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	06/06/19 14:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	06/06/19 14:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>












Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	18/02/19 16:16	Accident Statement	 Load HTM	





Photos/Images

3 per page

No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	18/02/19 14:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	18/02/19 14:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	18/02/19 14:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	18/02/19 14:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	18/02/19 14:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	18/02/19 14:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	18/02/19 14:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	18/02/19 14:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	18/02/19 14:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	18/02/19 16:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	18/02/19 16:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page

No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	18/02/19 16:16	Accident Sketch Plan	 Load TIF	
2	18/02/19 16:16	Accident Sketch Plan	 Load TIF	
3	18/02/19 16:16	INSURANCE CERT	 Load TIF	
4	18/02/19 16:16	OWNER IC	 Load TIF	
5	18/02/19 16:16	DRIVER IC & DL	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19003393/JCD3E2

Date: 07/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30803218011

Claimant Vehicle
No : SJW6049GInsured Vehicle
No : SLS7011E

Date of Loss: 18/02/2019

Nature of Claim: TP

Claim
No: SNM19D200872C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW6049G**
 Make & Model: SUBARU IMPREZA, 1.5 R AWD 4AT ABS AIRBAG (A)
 Reg. Date: 05/04/2010 (Man. Year: 2009)
 Colour: Black
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

Engine No: EL15D742306
 Chassis No: JF1GE3KF39G005901
 Odometer: 176821 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/06/2019

Date Inspected: 22/02/2019 Inspected At:

M/s Car Doctor Pte Ltd (HQ)
BLK3, 391A Woodlands Road Yew Tee,
industrial estate
Singapore 677695

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 -\$5,500.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2019)
Parts:	143	SUBARU IMPREZA 1.5 R AWD 4AT ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW6049G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >