

Tanp

NS/INC19003394/T19d302

From Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To be used Vehicle No

at Workshop m/s

of

Insured 8HD1215A

Policy No. 5107202885

Claim No. MY/1031778-002

Sum Insured Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lump Sum % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date Person Contacted

Vehicle: IN / OUT

Date / Time Action / Instruction

lorry  
better weak

SH7247S-X

8HD1215A-CC3/CT119002998/K1ch3 DOA: 11/2/2019

7/3/19

\$6182.53 5 days e-mail lorry  
(Red \$1596.85, 21%)

The repair cost should be final fig \$6158.96, 5 days.  
(Red \$1620.42, 21%)

RECEIVED 12 MAR 2019

Under Time File Pass to?

☐ : Preli. Report

to

☐ : Final Report

Date/Time File Return to?

at

Report Format :

Lump Sum / LB

7P  
6158.96

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp. \$

☐ Inter. Insp. \$

☐ Exam. Insp. \$

☐ Other \$

Survey Fee

Transportation

1. Trip \$

2. Fuel \$

3. Other \$

4. Total \$

160

160

Sh No SH7247S

at Regn 2017 Aug

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make Toyota Pro

CA 1798

Colour Blue

A/C Insured / Std / Nil / NA

Sp. Reading

T/Radio Insured / Std / Nil / NA

Eng/No

C/No

Gen. Cond. Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal.

L/Bal.

D.O.A.

Westlake

CPGE Lgny

Rear

O/S

N/S

U/C

Rooftop

The U/C / Chassis frame / Body Structure affected due to collision

11/3/2019

TP Claims against NTUC Income: Follow-Through Survey

Date : 11/03/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1033938-002	COMFORT TRANSPORTATION PTE LTD	SHA 7546X	FBL 4710X	27/02/2019	9:50	\$ 1,186.80
2	MT/1031778-002	COMFORT TRANSPORTATION PTE LTD	SH 7247S	SHD 1215A	11/02/2019	9:30	\$ 7,779.38

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/02/2019 16:08
Date Of Accident	11/02/2019 09:30
Exact Location Of Accident	ALONG BAYFRONT AVE TOWARDS RAFFLES AVE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH7247S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	JASNI BIN SAAT
NRIC No	S6846921Z
Date Of Birth	02/12/1968
Occupation	OUTDOOR
Date Of Driving Pass	23/02/2005
Driving Experience	13 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97523456
Fax Number	
Contact Number	
Email Address	JASS2SAAT@GMAIL.COM

Address	BLK 234 BUKIT PANJANG RING ROAD #06-03
Postcode	670234
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	BUKIT PANJANG N.P.C
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO POLICE REPORT : T/20190211/2119

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD1215A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	LOW TIEN SER
NRIC/Passport Number	S0069633A
Contact Number	92727270
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	REAR AND FRT
No. Of Passenger (Including Driver)	

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	PA8391Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TANG CHI HONG
NRIC/Passport Number	S7123889Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT RIGHT
No. Of Passenger (Including Driver)	

**DETAILS OF INJURED PERSON 1**

Name	JASNI BIN SAAT
Approximate Age	50
Injuries Sustain	FELT GIDDY. ON 5 DAYS MC.
Injured person in which vehicle?	SH7247S
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG NO. 192002321R

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Olivia Wendy

Reporting Centre Personnel's Signature  
Name: 12 FEB 2019  
NRIC/FIN No.:

RAFFLES AVE

B = SHADISIA  
SILVER CASH (HUMPH)  
C = PA 83912  
(TONGA HIRACE)



BAYFRONT AVE

Statement is per police report

T	20190211	2119
---	----------	------

I/We declare the foregoing particulars are true in every respect.

CONFIDENTIALITY OF INFORMATION  
 (C) 2008 NO 1027036018

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: 12 FEB 2019  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190211/2119

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

1 of 4

Report No. T/20190211/2119

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/02/2019 15:59	Vide Report No.:	Station Diary No.: 88
--	------------------	--------------------------

## Informant's Particulars

Name of Informant: JASNI BIN SAAT	Address: APT BLK 234 BUKIT PANJANG RING ROAD #06-03 SINGAPORE 670234		
ID Type / ID No.: NRIC NO / S6846921Z	Contact No.: Home/Office: Mobile: 97523456		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 50	Date of Birth: 02/12/1968	Type of Informant: Driver
Race: Boyanes	Language: English	Institution / School Name:	
Occupation: Taxi driver	Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

## General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 11/02/2019 09:30	Type of Location: Flyover
Location:  BAYFRONT AVENUE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PA8391Z	Van					0
SH7247S	TAXI					0
SHD1215A	TAXI					0





**SINGAPORE  
POLICE FORCE**



T/20190211/2119

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

2 of 4

Report No. T/20190211/2119

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TANG CHI HONG	ID No.	S7123889Z
Related Vehicle	PA8391Z (Van)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	JASNI BIN SAAT	ID No.	S6846921Z
Related Vehicle	SH7247S (TAXI)	Contact No.	97523456
Hospital/Clinic	RAFFLES MEDICAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	11/02/2019	Date Discharge	11/02/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	LOW TIEN SER	ID No.	S0069633A
Related Vehicle	SHD1215A (TAXI) <i>Silver car</i>	Contact No.	92727270
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 11/02/2019 at around 0930hrs, I was driving my Taix bearing SH7247S on the extreme left lane along Bayfront Ave exiting to Esplanade Drive. There was a car in front of my slowing down to exit therefore I also slowed down. Suddenly I felt an impact from my rear. I went down to make a check and discovered 2 other vehicle bearing SHD1215A and PA8391Z collided and hit onto me. I felt giddy after the impact. I was conveyed by the Ambulance to Raffles Medical Hospital. I was given 5 days of MC from 11/02/2019 to 15/02/2019. Traffic Police was also at scene. I have a In-car camera working.



**SINGAPORE  
POLICE FORCE**



T/20190211/2119

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

3 of 4

Report No. T/20190211/2119

CONTINUATION OF REPORT



**SINGAPORE  
POLICE FORCE**



T/20190211/2119

4 of 4

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

Report No. T/20190211/2119

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
J /  
Sgt 3 CHOO HONG REN

Signature Of Informant:

*[Signature]*

Signature Of Interpreter:  
Not applicable

Date/Time:  
11/02/2019 15:59

Officer In Charge Of Case:  
TP / GIT /  
Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI  
Contact No.: 65476904










Classification Of Case:



Authentication Stamp

NP168

Signature:

**Singapore Police Force**





**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

## ADDENDUM

### (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCD619019634 Vehicle Registration No: SH7247S  
Name(as shown in NRIC) : JASNI BIN SAAT NRIC/FIN/Passport No : S6846921Z  
**(\*Vehicle Driver / Vehicle Owner) (\*)** Please delete as appropriate  
Address : BLK 234 BUKIT PANJANG RING ROAD #06-03 Singapore 670234  
Contact (Tel) : \_\_\_\_\_ Mobile No. : \_\_\_\_\_  
Email Address : \_\_\_\_\_  
Date of Accident : 11/02/2019 Time of Accident : 11/02/2019  
Place of Accident : ALONG BAYFRONT AVE TOWARDS RAFFLES AVE  
Insurance Company: MS First Capital Insurance Ltd


### (B) **ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Upload Accident Photos

Was there any videos captured?: Available instead Not Available

Policyholder / Driver's Signature  
Date:

  
Reporting Centre Personnel's Signature  
Name: xiaoyan  
NRIC/FIN No.: \_\_\_\_\_  
Date: 15.02.2019



Team:	ARC Repair TP(CLS0)1	JOB CARD	Sales Order:	JC NO.: 305268282
STOMER	COMFORT TRANSPORTATION PTE LTD VARS	REGN NO.: SH 7247S	MILEAGE	
MS	7010045	MAKE : TOYOTA	FUEL	
STOMER NO.	383 SIN MING DRIVE	MODEL	DATE/TIME IN	
DRESS	Singapore SINGAPORE 575717		11.02.2019 09:30	
(R)	65508755	YR OF MANU.	TARGET DATE	
(P)		10.08.2017		
COUNT CARD NO.		CHASSIS CODE	COMPLETION DATE/TIME:	
		JTDKKB3FU303563072		

JOB DESCRIPTION

Accident Date: 11.02.2019  
NATURE: TP/3P 11.02.2019

S/NO	LABOR CODE	DESCRIPTION
	KTUC - Rear damage	
	Ltkk/	

FRONT

LEFT SIDE

RIGHT SIDE

REAR

CHECKED & PASSED OUT BY:		CUSTOMER'S SIGNATURE	
SERVICE ADVISOR			
Acknowledgement Slip		Exit Pass	
Vehicle No.: SH 7247S		Vehicle No.: SH 7247S	
Signature/Date		Date	
Name of Service Advisor		To be kept by Security Guard	

## REPAIR ESTIMATE\*

VEHICLE NO : SH 72475

DATE: 15. Feb. 2019

MAKE : TOYOTA

MODEL : PRIUS

DOA: 11. Feb. 2019

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper		de ✓	\$458.60 ✓
1	Rear Bumper Beam		bt ✓	\$318.80 ✓
1	Rear Bumper Sponge		mn ✓	\$143.40 ✓
10	Rear Bumper Clips		ne ✓ \$2.20	\$22.00 ✓
1	Rear Bumper Undercover		de ✓	\$552.60 ✓
1	Rear End Panel		? ✓	\$602.10 ✓
1	Rear Spare Tyre Panel		Ry ✓	\$667.70 ✓
1	Rear Bumper Side Retainer – RH		ne ✓	\$112.70 ✓
1	Seal Rear Bumper Side – RH		de ✓	\$148.40 ✓
1	Rear Bumper Tow Cover		de ✓	\$82.70 ✓
1	Rear Trunk Lid Cover		bt ✓	\$1,126.60 ✓
1	Rear Trunk Lid Cover Trim Board		nn ✓	\$254.40 ✓
1	Rear Trunk Lid PRIUS logo		ne ✓	\$52.90 ✓
1	Rear Trunk Lid HYBRID logo		nn ✓	\$52.90 ✓
1	Rear Trunk Lid Toyota Emblem		de ✓	\$47.00 ✓
1	Rear Windscreen Glass with molding		ne ✓ ?	\$1,778.30 ✓
SUB TOTAL				\$6,421.10
LESS 20%				\$1,284.22
DISCOUNTED TOTAL				\$5,136.88
1	Reverse Sensor		ne ✓	\$135.70 ✓
1	Rear Trunk APP sticker		ne ✓	\$40.00 ✓
1	Rear Trunk Comfort Sticker		nn ✓	\$30.00 ✓
1	Rear Trunk Tel Sticker		ne ✓	\$30.00 ✓
				\$235.70
Labour Charge				
1	Panel Beating		600	\$750.00 ✓
1	Spray Painting Charge		600	\$750.00 ✓
1	Remove/refix reverse sensor		30	\$100.00 ✓
1	Tuff Kote		30	\$100.00 ✓
1	Remove/refix Rear Windscreen		✓	\$120.00 ✓
TOTAL LABOUR				\$1,820.00
ESTIMATE TOTAL				\$7,192.58
7779.38				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Larry Ng



TYPE OF CLAIM : 3P/ NTUC  
SURVEYED BY : LKK/ TAUFIKH  
DATE : 05/03/19

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 05.03.2019  
Time: 17:36:26  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305268282  
REGN NO : SH 7247S  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 10.08.2017  
DATE/TIME IN : 11.02.2019 09:30  
ACCIDENT DATE : 11.02.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 09-01-0302-2005-A	PRIG4 REVERSE SENSOR ASSY	1	135.70	0.00	135.70	
0002 04-01-0302-2288-G	PRIG4 REINFORCEMENT SUB-A	1	318.80	<sup>25</sup> 20.00	255.04	239.10
0003 04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1	552.60	<sup>25</sup> 20.00	442.08	414.45
0004 04-01-0302-2286-G	PRIG4 COVER REAR BUMPER-T	1	82.70	<sup>25</sup> 20.00	66.16	62.03
0005 04-01-0302-2267-G	PRIVC BUMPER PIECE	10	22.00	<sup>25</sup> 20.00	17.60	16.50
0006 04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1	458.60	<sup>25</sup> 20.00	366.88	343.95
0007 04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM	1	52.90	<sup>25</sup> 20.00	42.32	39.68
0008 04-01-0302-2271-G	PRIG4 PLATE-BACK DOOR NAM	1	52.90	<sup>25</sup> 20.00	42.32	39.68
0009 28-01-0302-0006-A	PRIVC REAR BOOT 65521111	1	30.00	2.00-	30.00	
0010 28-01-0302-2013-A	PRIVC REAR BONNET APP TAX	1	40.00	0.20	40.00	
0011 28-01-0302-2015-A	PRIVC REAR BONNET COMFORT	1	30.00	0.02-	30.00	
0012 04-01-0302-2423-G	PRIG4 SEAL REAR BUMPER SI	1	148.40	<sup>25</sup> 20.00	118.72	111.30
0013 04-01-0302-2383-G	PRIG4 PANEL SUBASSY BODY	1	602.10	<sup>25</sup> 20.00	481.68	451.58

## COMFORTDELGRO ENGINEERING PTE LTD

Date: 05.03.2019

## REPAIR ESTIMATE

Time: 17:36:26

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305268282  
 REGN NO : SH 7247S  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(C  
 DATE OF REGN : 10.08.2017  
 DATE/TIME IN : 11.02.2019 09:30  
 ACCIDENT DATE : 11.02.2019

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0302-3937-G	PRIG4 RETAINER RR BUMPER	1	112.70	<sup>25</sup> 20.00	90.16	84.53	
0015 04-01-0302-2257-G	PRIG4 GLASS BACK WINDOW F	1	1,778.30	<sup>25</sup> 20.00	1,422.64	1333.73	6,089.10
0016 04-01-0302-2258-G	PRIG4 GLASS BACK DOOR	1	733.50	<sup>25</sup> 20.00	586.80	550.13	25% - 4566.83
0017 04-01-0302-2256-G	PRIG4 PANEL SUB-ASSY BACK	1	1,126.60	<sup>25</sup> 20.00	901.28	844.95	SN - 235.70
0018 04-01-0302-2269-G	PRIG4 ORNAMENT SUB-ASSY B	1	47.00	<sup>25</sup> 20.00	37.60	35.25	
SUB-TOTAL : 5,106.98							4802.53

## JOB NATURE

0000 PB	PANEL BEATING	600.00
0001 SP	SPRAY PAINTING CHARGE	600.00
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	30.00

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 05.03.2019

Time: 17:36:26

Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305268282  
REGN NO : SH 7247S  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(C  
DATE OF REGN : 10.08.2017  
DATE/TIME IN : 11.02.2019 09:30  
ACCIDENT DATE : 11.02.2019

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

0004 L REMOVE/REFIX REAR WINDSCREEN

120.00

SUB-TOTAL : 1,380.00

TOTAL : 6,486.98

MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO

4802.53  
1380  
\$6182.53  
#

Our Job Ref No : 305268282  
Date : 5. Mar. 2019

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK  
Attn : TAUFIKH

Fax :

Vehicle Reg No. : SH 7247S

Date of Accident: 11. Feb. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SHD1215A

2. The finalized amount shall be:

(a) Spare Parts after List discount	\$5,106.98
(b) Labour Charges	\$1,380.00
<b>Total for Part-By-Part Repair Cost</b>	<b>\$6,486.98</b>

4566.83

6182.53


(c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
Final Lumpsum Repair cost \_\_\_\_\_

3. Estimated normal period for repairs: 5 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : Wei Liang  
Tel : 6214 8316  
Fax : 6546 8156

Signature : \_\_\_\_\_  
Name : \_\_\_\_\_  
Date : \_\_\_\_\_

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_  
\_\_\_\_\_

Our Job Ref No : 305268282  
Date : 5. Mar. 2019

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 608969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SH 7247S

Date of Accident: 11. Feb. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SHD1215A

2. The finalized amount shall be:

(a) Spare Parts after List discount

\$4778.96

(b) Labour Charges

\$1,380.00

Total for Part-By-Part Repair Cost

\$6158.96

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 5 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :

Name :

Tel :

Fax :

Wei Liang

6214 8316

6546 8156

Signature :

Name :

Date :

Kahn

11/3/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Revised Finalised

COMFORTDELGRO ENGINEERING PTE LTD

Date: 07.03.2019

REPAIR ESTIMATE

Time: 17:57:44

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305268282  
 REGN NO : SH 7247S  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4)  
 DATE OF REGN : 10.08.2017  
 DATE/TIME IN : 11.02.2019 09:30  
 ACCIDENT DATE : 11.02.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 09-01-0302-2005-A	PRIG4 REVERSE SENSOR ASSY	1	135.70	10.00	122.13
0002 04-01-0302-2288-G	PRIG4 REINFORCEMENT SUB-A	1	318.80	25.00	239.10
0003 04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45
0004 04-01-0302-2286-G	PRIG4 COVER REAR BUMPER-T	1	82.70	25.00	62.02
0005 04-01-0302-2267-G	PRIVC BUMPER PIECE	10	22.00	25.00	16.50
0006 04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95
0007 04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM	1	52.90	25.00	39.67
0008 04-01-0302-2271-G	PRIG4 PLATE-BACK DOOR NAM	1	52.90	25.00	39.67
0009 28-01-0302-0006-A	PRIVC REAR BOOT 65521111	1	30.00	10.00	27.00
0010 28-01-0302-2013-A	PRIVC REAR BONNET APP TAX	1	40.00	10.00	36.00
0011 28-01-0302-2015-A	PRIVC REAR BONNET COMFORT	1	30.00	10.00	27.00
0012 04-01-0302-2423-G	PRIG4 SEAL REAR BUMPER SI	1	148.40	25.00	111.30
0013 04-01-0302-2383-G	PRIG4 PANEL SUBASSY BODY	1	602.10	25.00	451.57

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305268282  
REGN NO : SH 7247S  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(C  
DATE OF REGN : 10.08.2017  
DATE/TIME IN : 11.02.2019 09:30  
ACCIDENT DATE : 11.02.2019

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT			
0014 04-01-0302-3937-G	PRIG4 RETAINER RR BUMPER	1	112.70	25.00	84.52
0015 04-01-0302-2257-G	PRIG4 GLASS BACK WINDOW F	1	1,778.30	25.00	1,333.72
0016 04-01-0302-2258-G	PRIG4 GLASS BACK DOOR	1	733.50	25.00	550.12
0017 04-01-0302-2256-G	PRIG4 PANEL SUB-ASSY BACK	1	1,126.60	25.00	844.95
0018 04-01-0302-2269-G	PRIG4 ORNAMENT SUB-ASSY B	1	47.00	25.00	35.25
SUB-TOTAL :					4,778.92

## JOB NATURE

0000 PB	PANEL BEATING	600.00
0001 SP	SPRAY PAINTING CHARGE	600.00
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	30.00

42683  
21213



COMFORTDELGRO ENGINEERING PTE LTD

Date: 07.03.2019

Time: 17:57:44

REPAIR ESTIMATE

Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305268282  
REGN NO : SH 7247S  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(C  
DATE OF REGN : 10.08.2017  
DATE/TIME IN : 11.02.2019 09:30  
ACCIDENT DATE : 11.02.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 L REMOVE/REFIX REAR WINDSCREEN

120.00

SUB-TOTAL : 1,380.00

TOTAL : 6,158.92

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19003394/T1qd3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 13-03-2019



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 1215A	Veh. Inspected	SH 7247S
Policy No.	5107202885	Coverage (\$)	0.00
Claim No.	MT/1031778-002	Excess (\$)	0.00
Assign From		Assign Date	15/02/2019

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU303563072	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	11/02/2019	Inspection Date	15/02/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7247S**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER BEAM	BENT	318.80	318.80
1	REAR BUMPER SPONGE	NOT NECESSARY	143.40	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER UNDERCOVER	DEFORMED	552.60	552.60
1	REAR END PANEL	BENT	602.10	602.10
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	667.70	-
1	REAR BUMPER SIDE RETAINER - RH	NECESSARY	112.70	112.70
1	SEAL REAR BUMPER SIDE - RH	DEFORMED	148.40	148.40
1	REAR BUMPER TOW COVER	DEFORMED	82.70	82.70
1	REAR TRUNK LID COVER	BENT	1,126.60	1,126.60
1	REAR TRUNK LID COVER TRIM BOARD	NOT NECESSARY	254.40	-
1	REAR TRUNK LID PRIUS LOGO	NECESSARY	52.90	52.90
1	REAR TRUNK LID HYBRID LOGO	NECESSARY	52.90	52.90
1	REAR TRUNK LID TOYOTA EMBLEM	NECESSARY	47.00	47.00
1	REAR WINDSCREEN GLASS WITH MOLDING	NECESSARY	1,778.30	1,778.30
1	REAR TRUNK LID GLASS	NECESSARY	733.50	733.50
	LESS 20% DISCOUNT		-1,430.92	-
	LESS 25% DISCOUNT		-	-1,522.27
			5,723.68	4,566.83
<b><u>NETT ITEMS</u></b>				
1	REVERSE SENSOR (N)	NOT WORKING	135.70	135.70
1	REAR TRUNK APP STICKER (N)	NECESSARY	40.00	40.00
1	REAR TRUNK COMFORT STICKER (N)	NECESSARY	30.00	30.00
1	REAR TRUNK TEL STICKER (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-	-23.57
			235.70	212.13

Report Ref No. NS/INC19003394/T1qd3e2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL.		750.00	600.00
	SPRAY PAINTING CHARGE.		750.00	600.00
	REMOVE / REFIX REVERSE SENSOR.		100.00	30.00
	TUFF KOTE.		100.00	30.00
	REMOVE / REFIX REAR WINDSCREEN.		120.00	120.00
			1,820.00	1,380.00
	<b>GRAND TOTAL</b>		<b>7,779.38</b>	<b>6,158.96</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>6,158.96</b>

Report Ref No. NS/INC19003394/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.