

ASS. REC. BY:

REF:

CC3/TM119003402/Ksd3n2

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/vs Tans Colb

of _____

Insured: GX3621D

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 1/2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S14C 5873D Yr Regn: 03, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Logan c.c. 1995

Colour: n. white / Red A/C: Insured / Std / NI / NA

Sp. Reading: 531724 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: V1-1ABL15AUC 281488

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 20/2/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S R

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
1	File pass to
	L1 by 836506
25/02/19	Confirmed HS \$ 3650/- @ 2 1/2 days with Kelvin. (\$ 20,713.35 Red - 85%)

RECEIVED 26 FEB 2019

Date/Time, File Pass to? 26/02/19
1) Typist : Prell. Report
 : Final Report

Days Of Repair: 2 1/2
Resurvey No. of Trlp: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	<u>250</u>
S + RS, SI	<u>10</u>
Fuel/Oil	
Others	
TOTAL	<u>260</u>

Report Format : _____
Lump Sum / I.B.I: (\$ 3650/- HS)

Shirley Hiew (LKK Auto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 26 February 2019 11:34 AM
To: 'Shirley Hiew (LKK Auto)'
Cc: 'SUR'
Subject: RE: TCS REF: AAD1902-157--Accident involving SHC 5873D & GX 3621D on 15.01.2019
Attachments: ESTIMATE.PDF

Dear Shirley

We confirmed COR amount \$3,650.00 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, 26 February, 2019 9:49 AM
To: 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: TCS REF: AAD1902-157--Accident involving SHC 5873D & GX 3621D on 15.01.2019

Dear Wai Yin,

Please confirm final fig \$3,650.00 (lump sum) @ 2.5 days of repairs before GST.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5873D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Feb 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002562
Chassis No.:	VF1ABL15AUC281488
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	16 Mar 2015
First Registration Date:	16 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Mar 2023
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	15 Mar 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,092.00
COE Rebate Amount:	\$25,955.00
Total Rebate Amount:	\$35,328.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/02/2019 09:22
Date Of Accident	20/02/2019 07:55
Exact Location Of Accident	YISHUN STREET 21
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5873D
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	YANG SEK KIN
NRIC No	S1420957C
Date Of Birth	07/02/1960
Occupation	OUTDOOR
Date Of Driving Pass	19/10/1979
Driving Experience	39 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97770490
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 224 YISHUN STREET 21 #10-487
Postcode	760224
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please see the attach Police Report T/20190220/2039.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX3621D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	KHOR DENG YOENG
NRIC/Passport Number	S7218806C
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name YANG SEK KIN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHC5873D

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amanda

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please see the attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Amanda
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190220/2039

2 of 3

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Report No: T/20190220/2039

CONTINUATION OF REPORT

Driver			
Name	KHOR DENG YOENG	ID No.	S7218806C
Related Vehicle	GX3621D (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	YANG SEK KIN	ID No.	S1420957C
Related Vehicle	SHC5873D (Car)	Contact No.	97770490
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	20/02/2019	Date Discharge	20/02/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 20/02/2019 at about 0755hrs, I was driving my taxi SHC5873D along Yishun St 21 towards Yishun Ave 9 on the right lane of the 2-lane road. When I was approaching the T-junction between Yishun St 21 and Yishun Ave 9, the traffic light was red so I stopped and waited for it to turn green.

When the light turned green, the vehicles in front moved off. Therefore, I started to move off slowly and suddenly, a lorry on the left lane cut into my lane without signaling and I was unable to stop in time. My vehicle ended up colliding with the lorry. Subsequently, I went out of my taxi to check on the damages and speak to the other driver who claimed that he was not in the wrong. Then we exchanged our particulars and took photos of the accident and left. I went to Mount Alvernia hospital as I felt pain on my back, neck and chest and I was given 5 days medical leave from the doctor from 20/02/2019 to 24/02/2019.

I wish to state that there is in-car camera installed in my taxi.

I am lodging this report for company actions.



**SINGAPORE
POLICE FORCE**



T/20190220/2039

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999


3 of 3
Report No. T/20190220/2039

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sr Staff Sgt NEO ZE HWEE, EDMUND 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 20/02/2019 11:21
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No. 65476436 	Classification Of Case:
Authentication Stamp NP168 Signature:  Singapore Police Force	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHC 5873D

AAD1902-157

Not Authored
1/1 Imp @ 3650h

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHC 5873D
 VF1ABL15AUC281488
 RENAULT
 LATITUDE
 20.2.2019
TOKIO MARINE
 16/3/2015

PART		LIST	
1	BUMPER COVER FRT	\$	<i>R</i> 1,259.42
1	BUMPER SPOILER FRT	\$	<i>Su</i> 181.75
1	BUMPER ABSORBER FRT	\$	<i>Su</i> 394.68
1	BUMPER RETAINER FRT LH	\$	<i>Su</i> 151.41
1	BUMPER SUPPORT FRT	\$	<i>Ru</i> 123.88
1	BUMPER RETAINER FRT RH	\$	<i>Su</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>Su</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>Su</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>Su</i> 266.80
1	BUMPER FOG LAMP GRILLE LH	\$	<i>Su</i> 207.21
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Su</i> 207.21
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
1	TOW COVER FRT	\$	<i>Su</i> 28.61
1	HEADLAMP LH	\$	<i>Su</i> 1,184.43
1	HEADLAMP HARNESS	\$	<i>Su</i> 928.29
1	FENDER PANEL FRT LH	\$	<i>Ru</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>Su</i> 278.84 ✓
1	FENDER BRACKET LOWER LH	\$	<i>Su</i> 15.79 ✗
1	FENDER INSULATOR LH	\$	<i>Su</i> 130.84 ✗
1	DOOR PANEL FRT LH	\$	<i>Ru</i> 2,844.66 ✓
1	DOOR HINGE UPPER LH	\$	<i>R</i> 261.28 ✓
1	DOOR HINGE LOWER LH	\$	<i>D.T</i> 300.55 ✓
1	DOOR CHECK FRT LH	\$	<i>Su</i> 194.77
1	DOOR LOCK FRT LH	\$	<i>R</i> 908.75
1	DOOR CATCH FRT LH	\$	<i>R</i> 131.23
1	DOOR HANDLE OUTER FRT LH	\$	<i>Su</i> 477.76
1	DOOR HANDLE COVER FRT LH	\$	<i>Su</i> 13.22
1	DOOR HANDLE MODULE FRT LH	\$	<i>Su</i> 133.60
1	DOOR REGULATOR FRT LH	\$	<i>Su</i> 505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>Su</i> 796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>Su</i> 120.97

Trans-cab Auto Services Pte Ltd

AAD1902-157

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5873D

	\$	14,493.02
10%	\$	1,449.30
	\$	<u>13,043.72</u>

Special Nett

1SET	BUMPER CLIP FRT	\$	na	66.00	} X	
1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00		
1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50		
1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00		
1SET	WHEELARCH CLIP FRT LH	\$	na	30.50		
1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00		60in
1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00		15in
1	DOOR CHECK BOLT	\$	na	22.69	} X	
1	DOOR GUIDE SCREW	\$	na	10.85		
1	DOOR HINGE BOLT	\$	na	10.85		
1	DOOR HINGE NUT RH	\$	na	14.60		
1	DOOR CHECK BOLT	\$	na	22.69		
1	DOOR CHECK NUT	\$	na	3.75		
1	DOOR LOCK SCREW L70Y	\$	na	6.12		
1	DOOR CATCH SCREW L70Y	\$	na	10.06		

TOTAL	\$	539.63
--------------	----	---------------

TOTAL PARTS	\$	13,583.35
--------------------	----	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	400
To apply paint protection system (PPS) maintain and enhancement	\$	na	380.00 X
Putty and spray painting of the affected portion.	\$	4,200.00	440

Trans-cab Auto Services Pte Ltd

AAD1902-157

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5873D

To rust-proofing of the affected areas.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To vacuum, replace, refix and recharge air condenser	\$	na 380.00	X
To replace, refix and top up coolant for radiator	\$	↳ 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	↳ 170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	↳ 170.00	X

TOTAL \$ 10,780.00

Over All Total \$ 24,363.35

30

LUMP SUM(REPAIR DAY)

20 DAYS

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19003402/KSD3N2
Date: 28/02/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MW004583
Claimant Vehicle No :	SHC5873D	Insured Vehicle No :	GX3621D
Date of Loss:	20/02/2019	Nature of Claim:	TP
		Claim No:	M1901109

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5873D	Engine No:	M9R8839C002562
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC281488
Reg. Date:	16/03/2015 (Man. Year: 2015)	Odometer:	531724 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 3 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	13,583.30	3,611.14	9,972.16	73.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,780.00	980.00	9,800.00	90.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,363.30	4,591.14	19,772.16	81.16
Approved Total (Overridden) (S\$)		3,650.00		
	(S\$) 24,363.30	3,650.00	20,713.30	85.02
+ GST 7.00/7.00% (S\$)	1,705.43	255.50	1,449.93	85.02
Nett Amount (S\$)	26,068.73	3,905.50	22,163.23	85.02

INSPECTION

Date of Assignment:	25/02/2019	
Date Inspected:	21/02/2019 Inspected At:	Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111

Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2019)
Parts: 143	RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5873D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Repair	1,259.42 FL	*-FL
2	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*-FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*-FL
4	1		*BUMPER RETAINER FRT LH	Serviceable	151.41 FL	*-FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*-FL
6	1		*BUMPER RETAINER FRT RH	Serviceable	150.77 FL	*-FL
7	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*-FL
8	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*-FL
9	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*-FL
10	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*-FL
11	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*-FL
12	1		*BUMPER BEAM FRT	Repair	914.08 FL	*-FL
13	1		*TOW COVER FRT	Serviceable	28.61 FL	*-FL
14	1		*HEADLAMP LH	Serviceable	1,184.43 FL	*-FL
15	1		*HEADLAMP HARNESS	Serviceable	928.29 FL	*-FL
16	1		*FENDER PANEL FRT LH	Bent	783.83 FL	*783.83 FL
17	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	*-FL
18	1		*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*-FL
19	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*-FL
20	1		*DOOR PANEL FRT LH	Bent	2,844.66 FL	*2,844.66 FL
21	1		*DOOR HINGE UPPER LH	Repair	261.28 FL	*-FL
22	1		*DOOR HINGE LOWER LH	Distorted	300.55 FL	*300.55 FL
23	1		*DOOR CHECK FRT LH	Serviceable	194.77 FL	*-FL
24	1		*DOOR LOCK FRT LH	Repair	908.75 FL	*-FL
25	1		*DOOR CATCH FRT LH	Repair	131.23 FL	*-FL
26	1		*DOOR HANDLE OUTER FRT LH	Serviceable	477.76 FL	*-FL
27	1		*DOOR HANDLE COVER FRT LH	Serviceable	13.22 FL	*-FL
28	1		*DOOR HANDLE MODULE FRT LH	Serviceable	133.60 FL	*-FL
29	1		*DOOR REGULATOR FRT LH	Serviceable	505.19 FL	*-FL
30	1		*DOOR REGULATOR MOTOR FRT LH	Serviceable	796.46 FL	*-FL
31	1		*DOOR REGULATOR GUIDE FRT LH	Serviceable	120.97 FL	*-FL
32	1		*SET BUMPER CLIP FRT	Not Necessary	66.00 FS	*-FS
33	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*-FS
34	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*-FS
35	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*-FS
36	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*-FS
37	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*-FS
38	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*-FS
39	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*-FS
40	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
41	1		*FRONT DOOR STICKER CHASSIS	Necessary	50.00 FS	*15.00 FS
42	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*-FS
43	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*-FS
44	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*-FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
45	1		*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*- FS	
46	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS	
47	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	*- FS	
48	1		*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	*- FS	
49	1		*DOOR CATCH SCREW L70Y	Not Necessary	10.06 FS	*- FS	
					Sub Total (\$\$)	15,032.60	4,004.04
					- List Item Discount on L Items 10.00/10.00% (\$\$)	1,449.30	392.90
					Total Parts (\$\$)	13,583.30	3,611.14

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	400.00
2	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	440.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER	New	380.00	0.00
10	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
11	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	0.00
12	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (S\$)			10,780.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >