

000000

ASS. REC. ID

REF: CS/FCI/19003404/At d307

Special Instruction

SMV/VOL

ASSIGNMENT (Office)

CWS

From (Person)

Eiken Lee

of

FCI

Date/Time

5:10pm @ 22/1/19

Estimated Cost:

Bill to:

OD (T) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN 7351X

Insured:

SH 6298B

at Workshop m/s

Comfort Delgro
320 Ubi Rd

Tel:

68485725

Policy No:

Claim No:

D19000876MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

1/2/2019

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement:

Date/Time:

11:44am @ 22/1/19

Person Contacted:

Johan

Vehicle IN/OUT

(OUT)

Date/Time	Action/Instruction (✓) Estimate
	YN7351X-X
	SH 6298B - CS/FCI/6016743/K/Hbm2
8/3/2019-	Revert pending estimate
	Confirm part by Parts \$2453.30, 5 days (Red: 442.30! 15%)

Dur. 4/9/16

REF:

FCL

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: YN 7351
 at Workshop m/s CDGE
 of No. 320 ubi Rd 3
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

10am - 12pm

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: YN7351X Yr Began: 2014 / Dec
 Type: M.Car / M.Cycle / Bus / Van / Com / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Isuzu NJR85 C.C. 2999
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 99039 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: NJR857042649
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inoper / Jammed / Leaked / Burnt or
 Brake: Inoper / Jammed / Leaked / Burnt or
 Modi: NI / S/Rim / STD A/Rim or
 Tyre Size: F: 195 R15C
 R: 195 R15C
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 05/03/19
 Survey held at Car Parl (ubi)
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap

RECEIVED 06 JUN 2019

[Signature]
 4/6/2019

Date/Time, File Pass to?

4/6 Typist
 Date/Time, File Return to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp. (\$)
☐ Interview (\$)
☐ Tech. Inv. (\$)
☐ Weekend (\$)

Survey For:

Transportation

J. S. + R. + T.

J. Hours

J. Other

J. Total

TOTAL

139

50

50

20

259

Report Format :

Lump Sum / L.B.L. (\$) 2453.30

MOTOR SURVEY ASSIGNMENT

Date	05-02-2019	Our Ref No. D19000876MFSH
Accident Date	01-02-2019	Claim Type. Third Party
Insured Vehicle	SH6298B	Third Party Vehicle. YN7351X
Survey Location	320 UBI ROAD	
Contact Person.	JOHARI	
Contact No.	68485725/ 68485726	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	COMFORTDELGRO ENGINEERING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 8 March 2019 9:22 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000876MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle YN 7351X on 05/03/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 22 February 2019 11:45 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000876MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 21 February 2019 5:09 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000876MFSH/1

Denise Tay (LKKAUTO)

From: CDGE Ubi Private Cars Crash Repair Counter <ubi_cr@sparkcarcare.com>
Sent: Tuesday, 4 June 2019 11:53 AM
To: Denise Tay (LKKAUTO)
Cc: SUR; Adrian Ling (LKKAUTO)
Subject: Re: (STICKER INV) YN 7351X / TP / FIRST CAPITAL / DOA: 1.2.2019

Dear Denise,

Confirmed COR \$2453.30 & 5 repair days :)

Thks & Regards,
Tinie
Crash Repair
ComfortDelGro Engineering Pte Ltd
320 Ubi Road 3 S (408649)
Tel: +65 6848 5725/26
Email: Ubi_CR@sparkcarcare.com



From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Tuesday, 4 June 2019 10:41 AM
To: CDGE Ubi Private Cars Crash Repair Counter
Cc: SUR; Adrian Ling (LKKAUTO)
Subject: RE: (STICKER INV) YN 7351X / TP / FIRST CAPITAL / DOA: 1.2.2019

Dear Tinie,

As spoken, re calculate at \$2453.30, 5days.

Please confirm

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 4 June 2019 10:30 AM
To: CDGE Ubi Private Cars Crash Repair Counter <ubi_cr@sparkcarcare.com>
Cc: SUR <sur@lkkauto.com>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>
Subject: RE: (STICKER INV) YN 7351X / TP / FIRST CAPITAL / DOA: 1.2.2019

Dear Tinie,

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/02/2019 07:49
Date Of Accident	01/02/2019 11:30
Exact Location Of Accident	ALONG ROBINSON ROAD (SLIP ROAD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN7351X
Insured/Policyholder	
Name Of Registered Owner	AETOS SECURITY MANAGEMENT PTE LTD
Co Reg No	200208601N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98962243

Vehicle Particulars

Manufacturer	ISUZU
Model	LORRY
Exact Purpose for which vehicle was being used at time of accident	GOODS TRANSPORTATION
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D-19092514MFCV/6
Cover Note Number	

Driver

Name of Driver	THAYALAN A/L THANGARAJOO
Passport No/FIN	F7404559Q
Date Of Birth	23/02/1973
Occupation	OUTDOOR
Date Of Driving Pass	22/02/2010
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98962243
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address NO 55 JALAN SERI AUSTIN6/22 . TAMAN SERI AUSTIN
JOHOR BAHRU MALAYSIA

Postcode 81100

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Passenger 1
NAME: : EDDIE CHI THER
GENDER: : MALE

Passenger 2
NAME: : SYAHRUM BIN SAIMIN
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SH6298B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage


No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

A vehicle - YN7351X

B vehicle - SH6298B



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to attachment

Please refer to attachment

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 2/2/19

1038 WS

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

CONFIDENTIAL




AETOS AUXILIARY POLICE FORCE

INCIDENT REPORT

NATURE OF INCIDENT:		LOCATION OF INCIDENT:	
AETOS vehicle damages at the right rear edge hit by Taxi Comfort Delgro.		Robinson Road (Slip Road).	
DATE / DAY:	01 Feb 2019 (Friday)	INFORMANT:	SGT (APF) Ng Guet Lu
TIME:	1130hrs	TEAM:	Cash In Transit Cash & Valuables Escort
PARTICULARS OF SUBJECT:			
NAME	: Thayalan A/L Thangarajoo (Driver)		
SEX	: Male		
NRIC / FIN no	: F7404559Q		
SERVICE	: SGT (APF) T06339		
NATIONALITY	: Malaysian		
OCCUPATION	: AETOS Auxiliary Police Officer		
COMPANY	: AETOS Security Management Pte Ltd		
<p>On 01 Feb 2019 (Friday), SGT (APF) T06339 Thayalan was deployed together with teammate PC (APF) T10916 Eddie Chi Yi Ther (Transaction Officer) and PC (APF) P0790 Syahrurn Bin Saimin (Guardsmen), were performing Cash & Valuables Escort Team 2 and vehicle utilized YN7351X.</p> <p>At about 1130hrs, SGT (APF) T06339 Thayalan and the team arrived at Cecil Street. After alight his teammate PC Eddie Chin Yi Ther and PC Syahrurn at Cecil Street Bus stop, SGT Thayalan proceed to make some journey since there was no waiting area. SGT Thayalan diverted his route to Robinson Road (Slip Road). It is a one-way street joining back to Cecil Street traffic light junction. As he was slowing down and about to reach ASO Building, in sudden he heard a loud bang from his rear right. SGT Thayalan looked at his right mirror, he saw a taxi (Comfort Delgro) been stuck at his rear right. Immediately he alighted from vehicle after switch off his vehicle engine and locked the vehicle. SGT Thayalan approached the taxi driver to check on taxi driver status. He was not injured but a bit shaken up due to the impact, SGT Thayalan asked him whether he need any medical assistance but he said he is fine.</p> <p>SGT Thayalan called Duty Deployment Officer CPL (APF) Wan Thing Foong to inform the incident. And later about 1140hrs, PC Eddie Chin Yi Ther and PC Syahrurn arrived at the said location after their banking duties and they snap some photo of the both vehicle and exchanged particular.</p> <p>AETOS vehicle damages at the right rear edge of metal plate and wire mesh protector for rear light bend.</p> <p>The third party vehicle damages on front passenger door severe damage and deep scratch from front passenger door to front left fender.</p> <p>At about 1150hrs, this incident was report to OIC SSGT (APF) Chee Chee Kong. Since the damage on AETOS vehicle are very minor and no injury in this incident, The team get permission from OIC SSGT Chee Chee Kong to proceed with their detailed assignment. That's all.</p> <p>Please see the enclosed photo of the accident.</p>			



CONFIDENTIAL

CONFIDENTIAL



CONFIDENTIAL

CONFIDENTIAL

		
		
		
REPORTED BY:	SIGNATURE:	DATE:
SGT (APF) 9216 Ng Guet Lu Team Leader Cash & Valuables Escort		01 February 2019 (Friday)

CONFIDENTIAL

Spark Car Care

ComfortDelgro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Finalization Form

Bill : FIRST CAPITAL

Vehicle Number : YN 7351X

Attn to : MR ADRIAN LING (LKK)

Type Of Claim : TP

A. Spare parts \$2,348.00

F. Total Parts \$1,995.80

B. Supplementary

G. Total Labour \$900.00

C. Nett Price \$-

H. Total Repair \$2,895.80

D. Supp Nett Price \$-

I. Excess

E. S/Nett \$-

P/P Total 2,895.80

Total Spare Parts Price		\$2,348.00
Cost plus / List Down	15%	352.20
Total		1,995.80

Lump Sum Less \$-

Total Nett Price		\$-
Nett Price Less		\$-
Total		-

Lump Sum Rounding

Total Finalized

N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm and revert by Fax or Email

Date In : Total Repair Day 5

Date Survey : LOU/ Day

Date Out : Total LOU

Sat/Sun/Ph. : Rental/Day

Authorized Repair Day Total Rental

Submitted By / Date : Confirmed By / Date :

6410-20

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : YN7351X Case Owner : JOHARI

Make & Model : ISUZU Year Manufacture : _____

Chassis No : NJR857042649 Engine No : _____

Sales Order : 3911436 Supplier : _____

Order By : _____ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	BLIND RIVET 3/16"X3/4 <i>Neu</i>	1BIOX		\$ 48.00	—		
2	ALUMINIUM PLATE <i>Best</i>	2		\$ 250.00	—		
3	ALUMINIUM SHEETS 4'X8'2MM <i>Rep's</i>	4		\$ 620.00	+		
4	CABIN STICKER <i>Neu</i>	1SET	3	2050	? (Pricing)		
5	TAIL GATE STICKER <i>Neu</i>	2			? (Pricing)		
6				1300 (S/N)			
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd

Tel: 68438723/68438736 FAX : 67436072

Labour

Vehicle No. : YN7351X

Case Owner : _____

Make & Model : ISUZU

Year of Manufacture : _____

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



SOH GUAN CHUAN AUTO SUPPLY

BLK 3005 UBI AVE 3 #01-50 SINGAPORE 408861 (RETAIL)
BLK 3015 UBI ROAD 1 #01-268/270 SINGAPORE 408704 (WORKSHOP)
TEL : 67482202 FAX : 67492889
Website : www.sgautosupply.com.sg Email : sgcautosupply@yahoo.com.sg
ROC NO : 09054200B

Bill To:

Ship To:

Tax Invoice

COMFORTDELGRO ENGINEERING PTE LTD
320 UBI ROAD 3
SINGAPORE 408649
UBI

GST Reg No: 09054200B

Phone : 68438745 Fax : 67480510
Attention : MR ZHANG ZHUO (9488 9499)

560621974

Invoice No :	L19-0608
Date :	24-04-2019
Pages :	1

P/O Number	Sales Person	Ship Via	Ship Date	Terms
4500810041	YENNY POAN	ON-SITE INSTALL	24-04-2019	30 Days

Qty	UOM	Item No	Description	Price	Amount(S\$)
1	VEH	VPW-UBI-RH.P	TO PROVIDE LABOUR, TOOLS AND MATERIAL TO PRINT AND INSTALL A PARTIAL WRAP OF 3M VINYL STICKER AND WHITE REFLECTIVE STICKER (FOR THE CHECKERED SQUARES) AS PER YOUR REQUESTED DESIGN ("AETOS") ON THE RIGHT PANEL OF YOUR VEHICLE ISUZU NJR85 AT YOUR SITE VEHICLE NO.: YN7351X	\$1,300.00	\$1,300.00

N.B : ALL CHEQUES SHOULD BE MADE PAYABLE
TO SOH GUAN CHUAN AUTO SUPPLY

Total	\$1,300.00
Add : 7% GST	\$91.00
Total Inc GST	\$1,391.00
Less : Deposit	\$0.00
Balance Due	\$1,391.00

E.& O.E

RECEIVED BY	DATE	SOH GUAN CHUAN AUTO SUPPLY
COMFORTDELGRO ENGINEERING PTE LTD 320 UBI ROAD 3 SINGAPORE 408649		

TEL: 6748 7558 FAX: 6748 1433




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19003404/Atd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-06-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6298B	Veh. Inspected	YN 7351X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000876MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	22/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	ISUZU NJR85	c.c	2999	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	NJR857042649	Colour	WHITE	
Odometer	99039	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
L/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
R/H Rear Tyre	195 R15C	YOKOHAMA	6 mm	
L/H Rear Tyre	195 R15C	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/02/2019	Inspection Date	05/03/2019	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD NO : 320 UBI ROAD 3 SINGAPORE 408649			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 7351X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOX BLIND RIVET 3/16"X3/4	NECESSARY	48.00	48.00
2	ALUMINIUM PLATE	BENT	250.00	250.00
4	ALUMINIUM SHEETS 4'X8'2MM	TO REPAIR SEE LABOUR	620.00	-
	LESS 15% DISCOUNT		-137.70	-44.70
			780.30	253.30
SPECIAL NETT ITEMS				
1	SET CABIN STICKER (SN) }	NECESSARY	2,050.00	1,300.00
2	TAIL GATE STICKER (SN) }	NECESSARY	-	-
			2,050.00	1,300.00
LABOUR				
	CUT & REPLACE RHR SIDE CABIN PANEL, TAIL GATE PANE AFFECTED AREA, INCLUSIVE OF THE REPAIR OF ALUMINIUM SHEETS 4'X8'2MM.		450.00	300.00
	TO PUTTY & SPRAY PAINT RHR CABIN PANEL, TAIL GATE AND AFFECTED AREA.		850.00	400.00
	TO INSTALL CABIN STICKER AND TAIL STICKER.		280.00	200.00
			1,580.00	900.00
GRAND TOTAL			4,410.30	2,453.30

RECOMMENDED COST OF REPAIRS			2,453.30
------------------------------------	--	--	-----------------

Report Ref No. CS/FCI19003404/Atd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.