

2/10/2001

ASS. REC. BY:

REF: es/SMO19003409/Kqd3

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

chen shu hui ghes

of

SMO

Date/Time: 22/2/19 @ 1:45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

FBC2762G

Insured:

SFU2580Y

at Workshop m/s

Complete VMS

Tel:

64550012

of

176 Sin Ming Drive #03-14

Policy No:

D18MTPV010 4323

Claim No:

CMTD1901032

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/2/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up

25/2/19

H.O.D. Endorsement:

Date/Time:

4:20pm @ 22/2/19

Person Contacted:

Li Hui

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FBC2762G-CS/Lpc10014941 / Atg1
	SFU2580Y-X
26/2/19 @ 4pm	Informed Agnes Chan, we are pending estimate from repairer.
18/3/19	Submit Uneconomical Total Loss Report.

DoA: 4/6/2010

REF: 8MO

ORIGINAL

Date: 25/2/19	Veh No: FBC 2762G	Reg: 01-08
Estimated Cost:	Type: M/Car / <u>M/Cycle</u> / Bus / Van / Lorry / Taxi / Prime Mover /	
OD / TP / WS / TP RES / OD RES / EVA / MV / MY	Truck / Trailer or	
To Insured Vehicle No: FBC 2762G	Make: Yamaha	XIR CC 135
at Workshop no: complete VMS	Colour: Multi Colour	A/C Insured / Std / Nil / NA
of: 176 Sin Ming Drive #03-14	Sp Reading: 46P3	I/Radio: Insured / Std / Nil / NA
Insured:	Eng No: 4S	3001787
Policy No:	C/Nr:	
Claims No:	Gen. Cond: <u>Good</u> / Fair / Poor / Burnt	
Sum Insured:	Steering: <u>In order</u> / Jammed / Leaked / Burnt or	
(Client's Record)	Brake: <u>In order</u> / Jammed / Leaked / Burnt or	
Make of Veh:	Modl: Nil / S/Rim / STD / <u>Alum</u> or	
(Policy Condition)	Tyre Size: F: 80/180R17	
Remark: The veh had commenced its repair at the time of inspection.	R: 80/180R17	
	BS / DUN / EXNOVA / GY / FS / LIZA / <u>MMC</u> / OHTSU / PIR / SUMI /	
	TOYO / YOKO or	
Bal. or Market Value: 83k	Front: 4 mm	Rear: 4 mm
IDAC Accident Report: Consistent? : Yes or No	R/Bal: 4 mm	L/Bal: 4 mm
GIA / PR Seen: Consistent? : Yes or No	D.O.A: 21/2/19	D.O.I: 25/2/19
Est. Repairs: days Res.: Yes or No	Survey held at: ✓	
Lump Sum: 20 % 3 Val.: Yes or No	Des. of Damages: <u>Front</u> / Rear / O/S / N/S / U/C / Rooftop or	
11'22	<u>& o/s body</u>	
CA / REV / REP. / 24 HRS (up)	The U/C / Chassis frame / Body Structure affected due to collision.	
Date: Person Contacted:	Vehicle: IN / OUT	
Date / Time	Action / Instruction	

RECEIVED 15 MAR 2019

Date/Time, File Pass by: ☐ : Preli. Report
☐ : Final Report
 Date/Time, File Return by:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S.A.P.S.)

) Fleet)

) Other)

))

TOTAL

2)

Report Format: MER-TP / U

Lump Sum / L.B. : (\$)

Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Feb 2019		22 Feb 2019 13:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIM ENG HONG, ID: S6918148A		
Main Claimant:	OOI BON SEONG		
Vehicle Reg. No.:	FBC2762G	Date of Loss:	21/02/2019 08:00 - :59
Claim Type:	TP / CMTD1901032	Policy/Cover Note No.:	D18MTPV01014323 (Comprehensive)
Vehicle Reg. No. (Insured):	SFU2580Y	Policy No. (Claimant):	
		Excess:	
Repairer:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/03/2019]		
Adj Asg. Remarks:	Please assign to Mr Kenneth Kong to survey the vehicle		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Tuesday, 26 February 2019 4:00 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE FBC 2762G (YOUR REF: CMTD1901032)

This mail is associated with :

***FBC2762G (CMTD1901032)**

[SFU2580Y]

TP

OOI BON SEONG

Feb 21 2019 8:00AM

[LIM ENG HONG]

COMPLETE VMS PTE LTD

Dear Agnes,

Please be informed that we have inspected the motorbike FBC 2762G on 25/02/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/02/2019 08:58
Date Of Accident	21/02/2019 08:40
Exact Location Of Accident	CHANGI NORTH STREET ONE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBC2762G
Insured/Policyholder	
Name Of Registered Owner	OOI BON SEONG
NRIC No	S7882966D
Email Address	OOIKELVIN0328@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90687630
Alternative Phone No	OTHERS-90687630

Vehicle Particulars

Manufacturer	YAMAHA
Model	X1-111CC (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	D18MTMC01002221
Cover Note Number	08/05/2018 - 07/05/2019

Driver

Name of Driver	OOI BON SEONG
NRIC No	S7882966D
Date Of Birth	28/03/1978
Occupation	INDOOR
Date Of Driving Pass	14/11/2005
Driving Experience	13 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90687630
Fax Number	
Contact Number	OTHERS-90687630
E-Mail Address	OOIKELVIN0328@GMAIL.COM

Address	BLK 681D WOODLANDS DRIVE 62 #10-57
Postcode	734681
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT AND SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFU2580Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	OOI BON SEONG
------	---------------

Approximate Age

Injuries Sustain

STOMACH BRUISE

Injured person in which vehicle?

FBC2762G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Sompo

Vehicle:- FBC
27629

Policyholder's Signature

Date & Time: 20/2/19

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:


NRIC/FIN No.:

21/02/19

Sketch Plan Pg. 2

SKETCH PLAN

Date of Accident: 21/02/19 Time: 08.40am Location: Changi North Street one
 My Vehicle A: FBC2762G Vehicle B: SFU2580Y Vehicle C/Others: _____



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Changi North Street 1. I slowed down upon approaching the yellow box as the front vehicles after the yellow box are stationary.
 Suddenly vehicle B making a right turn and not noticing me and knocked into my bike.

() Claim OD/TP at Ah Lim Motor () Claim OD/TP at other workshop () Reporting Only

Remarks : Please forward a copy of my efile accident report to:

My workshop :

email address : lihui@completevms.com.sg & darren@completevms.com.sg

& myself :

email address :

Note : Please take note that your insurer have **14 days timeframe** for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Vehicle :-

FBC 2762G

Policyholder's Signature

Date & Time: 21/2/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: 21/02/19

GIARMC Motor (P) Ltd. V2



[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2966D
Vehicle Details	
Vehicle No.:	FBC2762G
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2019
Vehicle Make:	YAMAHA
Vehicle Model:	X-1R
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	453001787
Chassis No.:	453001787
Maximum Power Output:	-
Open Market Value:	\$1,966.00
Original Registration Date:	23 Jan 2008
First Registration Date:	23 Jan 2008
Transfer Count:	4
Actual ARF Paid:	\$295.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2022
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$2,503.00
COE Rebate Amount:	\$1,882.00
Total Rebate Amount:	\$1,882.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Feb 2019

OK



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

OOI BON SEONG
BLK 681D WOODLANDS DRIVE 62 #10-57
SINGAPORE 734681

Attention : THE OWNER
Contact : 90687630

Estimate : ES006606

Date : 21/02/2019
Vehicle Num. : FBC2762G
Make/Model : YAMAHA X-1R-2008
Chassis/Eng# : 4S3001787/4S3001787
Accident Date : 21/02/2019
Claim No. :
Reference :
Policy No. :

Not Authorise
1/1 Sep 8?

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT HEADLAMP		
2.	1	FRONT HEAD LAMP COVER		
3.	1	FRONT CENTER COVER		
4.	1	FRONT FAIRING R/H		
5.	1	FRONT FAIRING SIGNAL LAMP R/H		
6.	1	FRONT FAIRING INNER R/H		
7.	1	FRONT CENTER BASKET		
8.	1	FRONT FAIRING INNER TOP R/H		
9.	1	FRONT CENTER FENDER		
10.	1	FRONT TIRE		
11.	1	FRONT RIM		
12.	1	FRONT BRAKE CLIPPER		
13.	1	FRONT BRAKE DISC ROTOR		
14.	2	FRONT SHOCK ABSORBER COMPLETE		
15.	1	FRONT STEERING CONE		
16.	1	FRONT FORK CLAMP		
17.	2	HANDLE BAR		
18.	2	SIDE MIRROR		
19.	1	ERP UNIT		
20.	1	ERP UNIT BRACKET		
21.	1	FRONT FAIRING L/H		
22.	1	FRONT FAIRING INNER L/H		
23.	1	FRONT FAIRING INNER TOP L/H		
24.	1	SIDE STAND R/H		
25.	1	REAR EXHAUST		
26.	1	REAR EXHAUST CHROME		
27.	1	BRAKE STAND R/H		
28.	1	REAR PILLION STAND R/H		
29.	1	REAR COMPARTMENT BOX		

CONTINUE / ...

LKK Auto Care Sdn Bhd hereby notify the Receiver of the following:

- To resurvey the vehicle, reporting
- To display the vehicle during resurvey
- Parts price enquiry for confirmation
- This survey is on a "No Input Prejudice" basis
- No legal liability is allowed
- Surveys are not to be resurveyed and is subject to the decision from Insurance Company

Approved by: _____

Date: _____

by



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

OOI BON SEONG
BLK 681D WOODLANDS DRIVE 62 #10-57
SINGAPORE 734681

Attention : THE OWNER
Contact : 90687630

Estimate : ES006606

Date : 21/02/2019
Vehicle Num. : FBC2762G
Make/Model : YAMAHA X-1R-2008
Chassis/Eng# : 4S3001787/4S3001787
Accident Date : 21/02/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	1	REAR COMPARTMENT BOX BRACKET		
31.	1	RADIATOR		
List TotalS\$:				-----

Total S\$: 0.00
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

OOI BON SEONG
BLK 681D WOODLANDS DRIVE 62 #10-57
SINGAPORE 734681

Attention : THE OWNER
Contact : 90687630

Estimate : ES006606

Date : 21/02/2019
Vehicle Num. : FBC2762G
Make/Model : YAMAHA X-1R-2008
Chassis/Eng# : 4S3001787/4S3001787
Accident Date : 21/02/2019
Claim No. :
Reference :
Policy No. :

Not Notified
1/1/19 8?

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT HEADLAMP <i>Am</i>		
2.	1	FRONT HEAD LAMP COVER <i>cm</i>		
3.	1	FRONT CENTER COVER <i>cm</i>		
4.	1	FRONT FAIRING R/H <i>my cm</i>		
5.	1	FRONT FAIRING SIGNAL LAMP R/H <i>scr</i>		
6.	1	FRONT FAIRING INNER R/H		
7.	1	FRONT CENTER BASKET <i>div</i>		
8.	1	FRONT FAIRING INNER TOP R/H		
9.	1	FRONT CENTER FENDER		
10.	1	FRONT TIRE <i>?</i>		
11.	1	FRONT RIM		
12.	1	FRONT BRAKE CLIPPER <i>scr x</i>		
13.	1	FRONT BRAKE DISC ROTOR <i>?</i>		
14.	2	FRONT SHOCK ABSORBER COMPLETE <i>BT</i>		
15.	1	FRONT STEERING CONE <i>BT</i>		
16.	1	FRONT FORK CLAMP <i>div</i>		
17.	2	HANDLE BAR <i>glis ?</i> <i>MISS AX</i>		
18.	2	SIDE MIRROR <i>glis m? Lt</i>		
19.	1	ERP UNIT		
20.	1	ERP UNIT BRACKET <i>R x</i>		
21.	1	FRONT FAIRING L/H <i>scr x</i>		
22.	1	FRONT FAIRING INNER L/H <i>scr x</i>		
23.	1	FRONT FAIRING INNER TOP L/H <i>Am x</i>		
24.	1	SIDE STAND R/H <i>R x</i>		
25.	1	REAR EXHAUST <i>nd</i>		
26.	1	REAR EXHAUST CHROME <i>nd</i>		
27.	1	BRAKE STAND R/H <i>?</i>		
28.	1	REAR PILLION STAND R/H		
29.	1	REAR COMPARTMENT BOX <i>nd/bt</i>		

CONTINUE / ...



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

OOI BON SEONG
BLK 681D WOODLANDS DRIVE 62 #10-57
SINGAPORE 734681

Attention : THE OWNER
Contact : 90687630

Estimate : ES006606

Date : 21/02/2019
Vehicle Num. : FBC2762G
Make/Model : YAMAHA X-1R-2008
Chassis/Eng# : 4S3001787/4S3001787
Accident Date : 21/02/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	1	REAR COMPARTMENT BOX BRACKET		
31.	1	RADIATOR		
List TotalS\$:				

Total S\$: 0.00
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

OOI BON SEONG
BLK 681D WOODLANDS DRIVE 62 #10-57
SINGAPORE 734681

Attention : THE OWNER
Contact : 90687630

Estimate : ES006606

Date : 21/02/2019
Vehicle Num. : FBC2762G
Make/Model : YAMAHA X-1R-2008
Chassis/Eng# : 4S3001787/4S3001787
Accident Date : 21/02/2019
Claim No. :
Reference :
Policy No. :

Not Authored
Loss

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT HEADLAMP	CM 288.00	—
2.	1	FRONT HEAD LAMP COVER	CM 169.00	—
3.	1	FRONT CENTER COVER	Di 175.00	—
4.	1	FRONT FAIRING R/H	CM 115.00	—
5.	1	FRONT FAIRING SIGNAL LAMP R/H	CM 38.00	—
6.	1	FRONT FAIRING INNER R/H	CM 168.00	—
7.	1	FRONT CENTER BASKET	R 85.00	—
8.	1	FRONT FAIRING INNER TOP R/H	CM 68.00	—
9.	1	FRONT CENTER FENDER	CM 135.00	—
10.	1	FRONT TIRE	Sm 75.00	X
11.	1	FRONT RIM	R 126.00	X
12.	1	FRONT BRAKE CLIPPER	Sm 145.00	X
13.	1	FRONT BRAKE DISC ROTOR	Sm 55.00	X
14.	2	FRONT SHOCK ABSORBER COMPLETE	R 751.00	1,502.00
15.	1	FRONT STEERING CONE	CM 82.00	—
16.	1	FRONT FORK CLAMP	Di 65.00	—
17.	2	HANDLE BAR	di 45.00	90.00
18.	2	SIDE MIRROR	di 33.00	66.00
19.	1	FRONT FAIRING L/H	Sm 175.00	X
20.	1	FRONT FAIRING INNER L/H	Sm 168.00	X
21.	1	FRONT FAIRING INNER TOP L/H	Sm 90.00	X
22.	1	SIDE STAND R/H	X 77.00	X
23.	1	REAR EXHAUST		568.00
24.	1	REAR EXHAUST CHROME	Rd 295.00	—
25.	1	BRAKE STAND R/H	R 105.00	X
26.	1	REAR PILLION STAND R/H	Rd 34.00	—
27.	1	REAR COMPARTMENT BOX	Rd 385.00	—
28.	1	REAR COMPARTMENT BOX BRACKET	R 64.00	X
29.	1	RADIATOR	Pne 385.00	—

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

OOI BON SEONG
BLK 681D WOODLANDS DRIVE 62 #10-57
SINGAPORE 734681

Attention : THE OWNER
Contact : 90687630

Estimate : ES006606

Date : 21/02/2019
Vehicle Num. : FBC2762G
Make/Model : YAMAHA X-1R-2008
Chassis/Eng# : 4S3001787/4S3001787
Accident Date : 21/02/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	2	FRONT FORK OIL SEAL	30.00	60.00
31.	1	FRONT FORK OIL		38.00
32.	2	FRONT FORK INNER TUBE	28.00	56.00
33.	2	FRONT FORK OUTER TUBE	265.00	530.00
List TotalS\$:				6,477.00
10.00% Discount S\$:				647.70
				5,829.30
1.	1	SPECIAL NETT ITEMS : ERP UNIT		185.80
2.	1	ERP UNIT BRACKET		35.00
Special Nett Total S\$:				220.80
LABOUR :				
SPRAY PAINT DAMAGED AREA AFFECTED				450.00
BODY CHASSIS ALIGNMENT				350.00
CHECK LIGHTING				50.00
TOWING CHARGE				60.00
TO DISMANTLE & ASSEMBLE MOTORCYCLE TO REPLACE PARTS				450.00
Labour Total S\$:				1,360.00

SingDollars : Seven Thousand Four Hundred Ten & Cents Ten Only

Total S\$: 7,410.10

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Feb 2019		22 Feb 2019 13:45 Edit Adj Rpt	S\$3,992.00 Edit Estimates	S\$3,992.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM ENG HONG, ID: S6918148A		
Main Claimant:	OOI BON SEONG, ID: S7882966D		
Vehicle Reg. No.:	FBC2762G	Date of Loss:	21/02/2019 08:00 - :59 [132 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1901032	Policy/Cover Note No.:	D18MTPV01014323 (Comprehensive)
Vehicle Reg. No. (Insured):	SFU2580Y	Policy No. (Claimant):	
		Excess:	
Repairer:	COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 05/03/2019]		
Adj Asg. Remarks:	Please assign to Mr Kenneth Kong to survey the vehicle		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBC2762G (CMTD1901032)**
[SFU2580Y]
TP
OOI BON SEONG
Feb 21 2019 8:00AM
[LIM ENG HONG]
COMPLETE VMS PTE LTD

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	25/02/19 09:20	Accident Statement From: SC - Reg, No: SFU2580Y, Claimant: LIM ENG HONG	1	Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	26/02/19 13:53	General View	1	Load JPG	✓
2	26/02/19 13:53	General View	1	Load JPG	✓
3	26/02/19 13:53	General View	1	Load JPG	✓
4	26/02/19 13:53	General View	1	Load JPG	✓
5	26/02/19 13:53	General View	1	Load JPG	✓
6	26/02/19 13:53	General View	1	Load JPG	✓
7	26/02/19 13:53	General View	1	Load JPG	✓
8	26/02/19 13:53	General View	1	Load JPG	✓
9	26/02/19 13:53	General View	1	Load JPG	✓
10	26/02/19 13:53	General View	1	Load JPG	✓
11	26/02/19 13:53	General View	1	Load JPG	✓
12	26/02/19 13:53	General View	1	Load JPG	✓
13	26/02/19 13:53	General View	1	Load JPG	✓
14	26/02/19 13:53	General View	1	Load JPG	✓
15	26/02/19 13:53	General View	1	Load JPG	✓
16	26/02/19 13:53	General View	1	Load JPG	✓
17	26/02/19 13:53	General View	1	Load JPG	✓
18	26/02/19 13:53	General View	1	Load JPG	✓
19	26/02/19 13:53	General View	1	Load JPG	✓
20	26/02/19 13:53	General View	1	Load JPG	✓
21	26/02/19 13:53	General View	1	Load JPG	✓
22	26/02/19 13:53	Odometer Reading	1	Load JPG	✓
23	26/02/19 13:53	General View	1	Load JPG	✓

Documentation

No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	22/02/19 13:44	PRI - LKK	1	Load HTM	
2	25/02/19 09:20	Third Party E-filed GIA report(M)	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/03/19 14:40	LTA REBATE	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19003409/KQD3S2

Date: 15/03/2019

REFERENCE

Handling Insurer: Somp Insurance Singapore Pte. Ltd. Policy No: D18MTPV01014323
 Claimant Vehicle No: FBC2762G Insured Vehicle No: SFU2580Y
 Date of Loss: 21/02/2019 Nature of Claim: TP Claim No: CMTD1901032

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBC2762G
 Make & Model: YAMAHA X-1R, 135cc (M) Engine No: 4S3001787
 Reg. Date: 23/01/2008 (Man. Year: 2007) Chassis No: 4S3001787
 Colour: Multi-colour Odometer: 4693 km
 Engine Capacity: 135 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90 R17 Rear Tyre Size: 90/80 R17
 Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,050.10	3,672.00	2,378.10	39.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	320.00	1,040.00	76.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,410.10	3,992.00	3,418.10	46.13
+ GST 7.00/7.00% (S\$)	518.71	279.44	239.27	46.13
Nett Amount (S\$)	7,928.81	4,271.44	3,657.37	46.13

INSPECTION

Date of Assignment: 22/02/2019
 Date Inspected: 25/02/2019 Inspected At: COMPLETE VMS PTE LTD (HQ)
 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex
 Singapore 575721
 Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$3,000.00 (EST)
OMV :	\$1,966.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$2,503.00
COE Rebate (2) :	\$1,882.00
Total Rebate (1) + (2) = :	\$1,882.00

The total amount incurred will be Market Value \$3,000.00 minus Total Rebate \$1,882.00 = \$1,118.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(EXCLUDE CHECK ITEMS S\$511.20 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Mar 2019)	
Parts:	N/A	YAMAHA X-1R 135cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBC2762G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP	Cracked	288.00 FL	*288.00 FL
2	1		*FRONT HEAD LAMP COVER	Cracked	169.00 FL	*169.00 FL
3	1		*FRONT CENTER COVER	Distorted	175.00 FL	*175.00 FL
4	1		*FRONT FAIRING R/H	Cracked	115.00 FL	*115.00 FL
5	1		*FRONT FAIRING SIGNAL LAMP R/H	Cut	38.00 FL	*38.00 FL
6	1		*FRONT FAIRING INNER R/H	Cracked	168.00 FL	*168.00 FL
7	1		*FRONT CENTER BASKET	Repair	85.00 FL	*- FL
8	1		*FRONT FAIRING INNER TOP R/H	Cracked	68.00 FL	*68.00 FL
9	1		*FRONT CENTER FENDER	Cracked	135.00 FL	*135.00 FL
10	1		*FRONT TIRE	Serviceable	75.00 FL	*- FL
11	1		*FRONT RIM	Repair	126.00 FL	*- FL
12	1		*FRONT BRAKE CLIPPER	Serviceable	145.00 FL	*- FL
13	1		*FRONT BRAKE DISC ROTOR	Serviceable	55.00 FL	*- FL
14	2		*FRONT FORK COMPLETE	Bent	1,502.00 FL	*1,502.00 FL
15	1		*FRONT STEERING CONE	Necessary	82.00 FL	*82.00 FL
16	1		*FRONT FORK CLAMP	Distorted	65.00 FL	*65.00 FL
17	1		*HANDLE BAR	O/s Distorted	90.00 FL	*45.00 FL
18	1		*SIDE MIRROR	O/s Dented	66.00 FL	*33.00 FL
19	1		*FRONT FAIRING L/H	Serviceable	175.00 FL	*- FL
20	1		*FRONT FAIRING INNER L/H	Serviceable	168.00 FL	*- FL
21	1		*FRONT FAIRING INNER TOP L/H	Serviceable	90.00 FL	*- FL
22	1		*SIDE STAND R/H	Repair	77.00 FL	*- FL
23	1		*REAR EXHAUST	*Check	568.00 FL	*- FL
24	1		*REAR EXHAUST CHROME	Dented	295.00 FL	*295.00 FL
25	1		*BRAKE STAND R/H	Repair	105.00 FL	*- FL
26	1		*REAR PILLION STAND R/H	Dented	34.00 FL	*34.00 FL
27	1		*REAR COMPARTMENT BOX	Dented	385.00 FL	*385.00 FL
28	1		*REAR COMPARTMENT BOX BRACKET	Repair	64.00 FL	*- FL
29	1		*RADIATOR	Punctured	385.00 FL	*385.00 FL
30	2		*FRONT FORK OIL SEAL	Necessary	60.00 FL	*60.00 FL
31	1		*FRONT FORK OIL	Necessary	38.00 FL	*38.00 FL
32	2		*FRONT FORK INNER TUBE	Serviceable	56.00 FL	*- FL
33	2		*FRONT FORK OUTER TUBE	Serviceable	530.00 FL	*- FL
34	1		*ERP UNIT	Serviceable	185.80 FS	*- FS
35	1		*ERP UNIT BRACKET	Repair	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,697.80	4,080.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	647.70	408.00
Total Parts (\$\$)	6,050.10	3,672.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINT DAMAGED AREA AFFECTED.	New	450.00	0.00
2	BODY CHASSIS ALIGNMENT.	New	350.00	120.00
3	CHECK LIGHTING.	New	50.00	20.00
4	TOWING CHARGE.	New	60.00	30.00
5	TO DISMANTLE & ASSEMBLE MOTORCYCLE TO REPLACE PARTS.	New	450.00	150.00
Gross Labour Cost (\$\$)			1,360.00	320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >