

ASS. REC. BY:

REF:

CS / AIG 19003410 / 5032

Special Instruction:

Surveyor:

From (Person):

Hwee Jie
Mithoo Singh

ASSIGNMENT (Office)

of

AIG

Date/Time:

22/2/19 @ 12:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBN 6296B

Insured:

SLU 6382E

at Workshop m/s

soon Hin Motor

Tel:

6752 4893

of

Blk 1018, Yishun Ind. park A #01-342

Policy No:

Claim No:

614240908736

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

10/02/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:19pm @ 22/2/19

Person Contacted:

Issue

Vehicle

IN OUT

Date/Time

Action/Instruction (✓) Estimate

FBN 6296B - X

SLU 6382E - NBA / AIG 19002335 / Y

D.O.A: 10/2/2019

22/3/19-

called issue, confirmed got provide estimate. He will fix the estimate.

27/3/19 @ 9:10am

Hwee Jie informed that he have checked with Marcus as the estimate provided by wksp is not under wksp letter head whichever is another survey firm, suggest him to submit as pps first & wait for insurance's further instruction.

REF:

AIG

Hue Jie

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. EBN 62968 Yr Regn: Nov / 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Sniper 150 c.c. 150Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3UG0740J0132823Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90-17R: 120/70-17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. _____ mmL/Bal. 6 mm L/Bal. _____ mmD.O.A. _____ D.O.I. 22/2/19Survey held at Soon HinDes. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
22/3/19 @	1. bus checked with ISSAC, he said they pass this case to their lawyer to handle it.
20/6/19	Submit LS \$2600, 4 days. as WOSP engage their lawyer. (old \$3515.40, 57%)
RECEIVED 20 JUN 2019	

Date/Time. File Pass to?

1) 20/6/19 turn in

Date/Time. File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 2600☐ : Preli. Report☐ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Survey Fee: 250

Transportation:

) S + PS. SI

) Photos

) Others

)





TOTAL

11

261

- Pre repair inspection request - FBN6296B VS SLU6382E (OI) DOA 10/02/2019

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@ikkkauto.com, assignments@ikkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Lim, Sheng Yang, Chan, Yoke Shi, Kaur, Baljit, Hor, Yinrul, Azlan, Syazairdina
Sent: 22/2/2019 12:06:36 PM

Attachments:  Letter dated 21.02.19 - BCC.FBN6296B.pdf  Letter dated 21.2.19 - BCC.FBN6296B workshop details.pdf
 Letter dated 21.2.19 - BCC.FBN6296B workshop details.pdf  Letter dated 21.02.19 - BCC.FBN6296B.pdf

Hi,

Please refer to the enclosed request from **BENEDICT CHAN & COMPANY**.

Claim no : 6142409087SG003
Case Owner : CHIT YAN FOO

If you have any queries/concerns, please let us know.
Kindly assist to assign Calvin Ang as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: BCCLAW [mailto:bcclaw@singnet.com.sg]
Sent: Friday, February 22, 2019 11:56 AM
To: Mithoosingh, Aashweenjeetkaur
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU6382E AND FBN6296B ON 10/02/2019

Dear Sir

We refer to your email dated 22.02.2019.

We have our client's instructions to confirm Calvin Ang as Single Joint Expert.

Thanks and Regards

BENEDICT CHAN & COMPANY
14 Fort Road Singapore 439075
Tel : 6220 6088 Fax : 6220 6087
We do not accept service of Court documents by facsimile or email
CONFIDENTIALITY NOTICE

This email including any attachment (s) is confidential and may be privileged. Accordingly, if you are not the intended recipient, please notify us immediately, delete this email including any attachment (s) from your computer system and do not disclose or distribute it to any person or continue to read this email. Thank you.

From: Mithoosingh, Aashweenjeetkaur [mailto:Aashweenjeetkaur.Mithoosingh@aig.com]
Sent: Friday, February 22, 2019 9:09 AM
To: BCCLAW
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Chan, Yoke Shi; Kaur, Baljit; Hor, Yinrul; Azlan, Syazairdina
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU6382E AND FBN6296B ON 10/02/2019

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมัน
ให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-03-01 09:09 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina.Azlan@aig.com

To: bcclaw@singnet.com.sg

Cc: Andy-SY.Fong@aig.com, Lee-

Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, yokeshi.chan@aig.com, Baljit.Kaur@aig.com, Yinrul.Hor@aig.com

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU6382E AND FBN6296B ON 10/02/2019

Date: Thu, 21 Feb 2019 06:45:20 +0000

Without Prejudice

Your Reference : BCC.FBN6296B

Our Reference : 6142409087SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto

SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: BCCLAW [mailto:bcclaw@singnet.com.sg]

Sent: Thursday, February 21, 2019 2:28 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Hor, Yinrul

Subject: REQUEST FOR PRE-REPAIR INSPECTION - ACCIDENT INVOLVING FBN6296B AND SLU 6382E ALONG BUKIT BATOK CENTRAL ON 10.02.2019

Dear Sirs

Kindly refer to our enclosed letter.

Thanks and Regards

BENEDICT CHAN & COMPANY

14 Fort Road Singapore 439075

Tel : 6220 6088 Fax : 6220 6087

We do not accept service of Court documents by facsimile or email

CONFIDENTIALITY NOTICE

This email including any attachment (s) is confidential and may be privileged. Accordingly, if you are not the intended recipient, please notify us immediately, delete this email including any attachment (s) from your computer system and do not disclose or distribute it to any person or continue to read this email. Thank you.

From: bcclaw@singnet.com.sg
To: Syazairdina.Azlan@aig.com
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, yokeshi.chan@aig.com, Baljit.Kaur@aig.com, Yinrul.Hor@aig.com
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU6382E AND FBN6296B ON 10/02/2019
Date: Thu, 21 Feb 2019 09:02:21 +0000
Dear Sirs

Kindly refer to our enclosed letter.

Thanks and Regards

BENEDICT CHAN & COMPANY

14 Fort Road Singapore 439075

Tel : 6220 6088 Fax : 6220 6087

We do not accept service of Court documents by facsimile or email

CONFIDENTIALITY NOTICE

This email including any attachment (s) is confidential and may be privileged. Accordingly, if you are not the intended recipient, please notify us immediately, delete this email including any attachment (s) from your computer system and do not disclose or distribute it to any person or continue to read this email. Thank you.

From: Azlan, Syazairdina [mailto:Syazairdina.Azlan@aig.com]

Sent: Thursday, February 21, 2019 2:45 PM

To: bcclaw@singnet.com.sg

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Hor, Yinrul
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU6382E AND FBN6296B ON 10/02/2019

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมัน
โปรดเปิดไฟล์แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-02-28 14:45 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.



Virus-free. www.avast.com

From: Aashweenjeetkaur.Mithoosingh@aig.com
To: bcclaw@singnet.com.sg
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, ShengYang.Lim@aig.com, yokeshi.chan@aig.com, Baljit.Kaur@aig.com, Yinrul.Hor@aig.com, Syazairdina.Azlan@aig.com
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU6382E AND FBN6296B ON 10/02/2019
Date: Fri, 22 Feb 2019 01:09:23 +0000
Hi,

Please confirm that you are nominating Calvin Ang named in the list of surveyors to conduct the pre-repair survey and appointed as the "Single Joint Expert".

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: BCCLAW [mailto:bcclaw@singnet.com.sg]

Sent: Thursday, February 21, 2019 5:02 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Hor, Yinrul
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU6382E AND FBN6296B ON 10/02/2019

Dear Sirs

Kindly refer to our enclosed letter.

Thanks and Regards

BENEDICT CHAN & COMPANY

14 Fort Road Singapore 439075

Tel : 6220 6088 Fax : 6220 6087

We do not accept service of Court documents by facsimile or email

CONFIDENTIALITY NOTICE

This email including any attachment (s) is confidential and may be privileged. Accordingly, if you are not the intended recipient, please notify us immediately, delete this email including any attachment (s) from your computer system and do not disclose or distribute it to any person or continue to read this email. Thank you.

From: Azlan, Syazairdina [mailto:Syazairdina.Azlan@aig.com]

Sent: Thursday, February 21, 2019 2:45 PM

To: bcclaw@singnet.com.sg

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Hor, Yinrul

Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU6382E AND FBN6296B ON 10/02/2019

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยกับข้อความที่เข้ารหัสลับ เพื่ออ่านมัน
ให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-02-28 14:45 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.



Virus-free: www.avast.com

From: Syazairdina.Azlan@aig.com

To: bcclaw@singnet.com.sg

Cc: Andy-SY.Fong@aig.com, Lee-

Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, yokeshi.chan@aig.com, Baljit.Kaur@aig.com, Yinrul.Hor@aig.com

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU6382E AND FBN6296B ON 10/02/2019

Date: Thu, 21 Feb 2019 06:45:20 +0000

Without Prejudice

Your Reference : BCC.FBN6296B

Our Reference : 6142409087SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd

Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: BCCLAW [mailto:bcclaw@singnet.com.sg]

Sent: Thursday, February 21, 2019 2:28 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Hor, Yinrul

Subject: REQUEST FOR PRE-REPAIR INSPECTION - ACCIDENT INVOLVING FBN62968 AND SLU 6382E ALONG BUKIT BATOK CENTRAL ON 10.02.2019

Dear Sirs

Kindly refer to our enclosed letter.

Thanks and Regards

BENEDICT CHAN & COMPANY

14 Fort Road Singapore 439075

Tel : 6220 6088 Fax : 6220 6087

We do not accept service of Court documents by facsimile or email

CONFIDENTIALITY NOTICE

This email including any attachment (s) is confidential and may be privileged. Accordingly, if you are not the intended recipient, please notify us immediately, delete this email including any attachment (s) from your computer system and do not disclose or distribute it to any person or continue to read this email. Thank you.

Virus-free: www.avast.com

BENEDICT CHAN & COMPANY

Advocates & Solicitors

Commissioner for Oaths/Notary Public

14 Fort Road Singapore 439075

Tel : 6220 6088 Fax : 6220 6087

Our Ref : BCC.FBN6296B

Your Ref : 6142409087SG003

Please quote our reference number when replying

*We do not accept service of
court documents by fax*

21 February 2019

AIG Asia Pacific Insurance Pte Ltd

Attn: Syaza Irdina Azlan,
Motor Claims Department

By email

Dear Sirs

**ACCIDENT INVOLVING FBN 6296B AND SLU 6382E ALONG BUKIT BATOK
CENTRAL ON 10.02.2019**

We refer to your email dated 21 February 2019.

Kindly be informed that our client is prepared to appoint **Kalvin Ang of LKK Auto Consultants Pte Ltd** to conduct the pre-repair survey at the following address :-

SOON HIN MOTORS PTE LTD

Blk 1018 Yishun Industrial Park A

#01-342

Singapore 768760

Person In Charge: Mr Issac See (Tel: 6752 4893)

Kindly arrange for the pre-repair survey within two (2) working days.

Yours faithfully



BENEDICT CHAN & COMPANY

> Back to OneMotoring

Enquire Transfer Fee

Enquire Transfer Fee			
Vehicle Details			
Vehicle No. :	FBN6296B		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	SNIPER T150		
Chassis No. :	MH3UG0740J0132823		
Propellant :	Petrol		
Engine No. :	G3E6E0445362		
Engine Capacity :	150 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	266 kg		
Unladen Weight :	116 kg		
Year Of Manufacture :	2018		
Original Registration Date :	16 Nov 2018		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$2,509.00		
COE Expiry Date :	15 Nov 2028		
Road Tax Expiry Date :	15 May 2019		
Inspection Due Date :	15 Nov 2021		
Intended Transfer Date :	02 Apr 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 15 May 2019. You may renew the road tax from 16 Feb 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 15 May 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 16 May 2019 to 15 Nov 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	32.00	-	32.00
Total Amount Payable :			57.00
Amount Payable (From 16 May 2019 to 15 May 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	64.00	-	64.00
Total Amount Payable :			89.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3458A
Vehicle Details	
Vehicle No.:	FBN6296B
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Apr 2019
Vehicle Make:	YAMAHA
Vehicle Model:	SNIPER T150
Primary Colour:	Green
Manufacturing Year:	2018
Engine No.:	G3E6E0445362
Chassis No.:	MH3UG0740J0132823
Maximum Power Output:	-
Open Market Value:	\$2,103.00
Original Registration Date:	16 Nov 2018
First Registration Date:	16 Nov 2018
Transfer Count:	1
Actual ARF Paid:	\$316.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Nov 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$2,509.00
COE Rebate Amount:	\$2,413.00
Total Rebate Amount:	\$2,413.00

The information contained herein is correct as at 02 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	22/02/2019 13:14
Date Of Accident	10/02/2019 14:25
Exact Location Of Accident	BUKIT BATOK CENTRAL
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBN6296B
Insured/Policyholder	
Name Of Registered Owner	AZMIE BIN ROSLAN
NRIC No	S8533458A
Email Address	FRIENDLYMONSTER.OCT1985@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91004583
Alternative Phone No	OTHERS-91004583
Vehicle Particulars	
Manufacturer	YAMAHA
Model	SNIPER T150-150CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSD/VMS/18-391621-CA
Cover Note Number	
Driver	
Name of Driver	AZMIE BIN ROSLAN
NRIC No	S8533458A
Date Of Birth	30/10/1985
Occupation	OUTDOOR
Date Of Driving Pass	22/05/2009
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91004583
Fax Number	
Contact Number	OTHERS-91004583
EEmail Address	FRIENDLYMONSTER.OCT1985@GMAIL.COM

Address	BLK 253 JURONG EAST ST 24 #04-243 SINGAPORE
Postcode	600253
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU6382E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	AZMIE BIN ROSLAN
Approximate Age	
Injuries Sustain	REFER POLICE REPORT
Injured person in which vehicle?	FBN6296B
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 20/02/19

Policyholder's Signature
Date & Time:

 20/02/19.


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Reflex police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

20/02/19

Policyholder's Signature
Date & Time:

✓ 20/02/17

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Centre Personnel

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190213/2060

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3
Report No. T/20190213/2060

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/02/2019 11:38	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: AZMIE BIN ROSLAN			Address: APT BLK 253 JURONG EAST STREET 24 #04-243 YUHUA VILLAGE SINGAPORE 600253		
ID Type / ID No.: NRIC NO / S8533458A			Contact No.: Home/Office: Mobile: 91004583		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 33	Date of Birth: 30/10/1985	Type of Informant: Rider		
Race: Malay			Language: English	Institution / School Name:	
Occupation: SMRT QUALITY CONTROL			Driving Licence Information: Class: 2B,2A,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 10/02/2019 14:25	Type of Location: Straight Road
Location: BUKIT BATOK CENTRAL BUKIT BATOK CENTRAL				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBN6296B	Motorcycle	YAMAHA	SNIPER T150	Green		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBN6296B	MSIG INSURANCE (SINGAPORE) PTE. LTD.	72137140	17/11/2018	16/11/2019

43597656



**SINGAPORE
POLICE FORCE**



T/20190213/2060

2 OF 3

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

Report No. T/20190213/2060

CONTINUATION OF REPORT

Brief Details.

ON THE ABOVE MENTIONED DATE TIME AND LOCATION,
I WAS RIDING OF (FBN6296B) AT THE SAID LOCATION. THERE WAS 2 LANES. I WAS AT THE LEFT
MOST LANE. AT THAT PART OF TIME I COULD NOT REMEMBER ANYTHING. AND REALISED THAT
I WAS IN THE HOSPITAL. THE ONLY I KNOW FROM THE OTHER RIDERS WAS THAT A VEHICLE
WAS COMING OUT FROM THE MINOR ROAD WHEN I WAS AT THE STRAIGHT ROAD. THAT'S ALL.

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190213/2060

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000




3 of 3
Report No. T/20190213/2060

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / MUHAMMAD HAZIQ BIN SAIFUDDIN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 13/02/2019 11:38
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt SYED ZAYID MUHAMMAD BIN SYED ABDUL WAHID ALHINDUAN Contact No.: 65476394	Classification Of Case: 
Authentication Stamp NP168	Signature: 

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Fax: 6215 3298, Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 66M0219.SH
Vehicle no : FBN6296B

1 REFERENCE

Date of inspection : 25 February 2019
Requested by : Azmie Bin Roslan
Blk 253 Jurong East Street 24
#04-243
Singapore 600253
Type of survey : Independent
Repairer : Soon Hin Motors Pte Ltd
Blk 1018 Yishun Industrial Park A, #01-342, Singapore 768760
Date of accident : 10 February 2019

2 VEHICLE DATA

Make/model : Yamaha Sniper T150
Chassis no : MH3UG0740J0132823
Engine no : G3E6E0445362
Date of registration : 16 Nov 2018
Engine capacity : 150 cc
Colour : Matt Green

3 STATIC CONDITION CHECK

Steering : Affected
Foot brakes : Serviceable
Hand brakes : Serviceable
Paintwork : Good
General Condition : Fair

4 TIRE CONDITION CHECK mm/Make

Front tread : 5 mm/Dunlop
Rear tread : 5 mm/Dunlop

SIZE

70/90-17
120/70-17

5 BRIEF DESCRIPTION OF DAMAGE

Front rim broken, front tyre cut, front forks bent, steering under bracket bent, chassis front section bent, front fender broken, front leg shield panels cracked/bracket fractured/dislodged, front panel cut/scuffed, handle bar bent, exhaust pipe front section bent, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : \$4,800.00 (lump sum)
Estimated no of days : Seven (7)

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 66M0219.SH
 Vehicle no: FBN629GB

A SPARE PARTS

<u>Description</u>	<u>Qty</u>	<u>Assessed Condition</u>	<u>Repairer's Amount</u>	<u>Revised Amount</u>
Front rim	1	broken	285.00	200-285.
Front brake disk	1	bent	115.00	115.
Front fender	1	broken	125.00	125.0
Front fork assy LH/RH	2	bent	720.00	500-720.0
Steering under bracket	1	bent	225.00	180-225.0
LH front leg shield panel	1	cracked/bracket fractured	175.00	175.0
LH front leg shield air guide panel - mid	1	bent/deformed	20.00	20.0
RH front leg shield panel	1	dislodged/brackets broken	175.00	175.0
RH front leg shield air guide panel - mid	1	bent/deformed	20.00	20.0
RH front leg shield air guide panel - lower	1	abraded/deformed	18.00	18.00
Front side fairing logo	2	necessary	24.00	24.00
Front panel	1	cut/scuffed	115.00	115.00
Front panel inner panel	1	broken	65.00	65.00
Front pilot lamp assy LH/RH	2	broken	96.00	96.00
Handle bar	1	bent	85.00	85.00
Handle bar top cover	1	scraped	125.00	125.00
Handle bar rear cover	1	broken	150.00	150.00
Headlamp assy	1	lens scraped/leg fractured	95.00	95.00
Headlamp support panel	1	cut	54.00	54.00
Front signal lamp assy	1	scraped	38.00	38.00
Key switch fairing	1	broken	115.00	115.00
Radiator assy	1	bent	288.00	288.00
Radiator electric fan	1	jammed	95.00	95.00
Meter assy	1	leg broken	328.00	328.00
Front footrest bar	1	bent	55.00	55.00
Front footrest bar rubber step pad set	1	necessary	30.00	30.00
Rear brake pedal	1	bent	55.00	55.00
Rear side board LH/RH	2	bent/warped	320.00	320.00
Exhaust end cap	1	grazed/deformed	45.00	45.00
Exhaust pipe assy	1	front section bent	750.00	750.00
		Subtotal of the above	4,806.00	4,806.00
		Discount 10%	480.60	480.60
		Subtotal 1:	4,325.40	4,325.40
	1	cut	160.00	80-160.00
	2	necessary	80.00	50-80.00
	1	bent	28.00	28.00
	1	necessary	20.00	20.00
	1	socket broken	205.00	205.00
	1	bent	45.00	10-45.00
	1	broken	40.00	40.00
	1	scraped	12.00	12.00
		Subtotal 2:	590.00	590.00
		Total cost of parts:	4,915.40	4,915.40

(Special nett)

Front tyre
 Steering upper/lower con/bearing set
 Radiator fan grille
 Radiator coolant
 Rectifier & regulator unit
 Handphone holder
 Flasher relay unit
 Front number plate

Report no: 66M0219.SH
Vehicle no: FBN6296B

B LABOUR

Labour charges.

To jack, straighten and align chassis front section (bent).

Towing (2x).

	300
750.00	600.00
	100
380.00	380.00
70.00	60.00

Total cost of labour:

1,200.00	1,040.00
----------	----------

Total cost of repair:

6,115.40	5,955.40
----------	----------

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is

\$5,955.40

(a) However, the recommended cost of repair based on lump sum basis would be

\$4,800.00

(b) The estimated number of days for the repairs are

(1st re-inspection conducted on 1st March 2019)

(Post Repair Inspection conducted on 11th March 2019)

Seven (7)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Yours faithfully

Liaw Leong San
Licensed Automotive Appraiser

Dated: 15 March 2019

Handwritten signature
\$2600/- L/s 4 days.
20/6/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189
Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

Azmie Bin Roslan
Blk 253 Jurong East Street 24
#04-243
Singapore 600253

Invoice no:	POS066/18
Date:	15 March 2019
Report no:	66M0219.SH
Vehicle :	FBN6296B

INVOICE

No	Item Description	Qty	Unit Price	Total Amount (\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			515.00
SGD(\$): Five hundred and Fifteen only			Grand Total:	515.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES

Authorised Signature

...CLAIM SUBFOLDER...(Pending for Survey Report)




































PRI
































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Feb 2019 Edit Reg		22 Feb 2019 00:00 Edit Adj Rpt	S\$2,600.00 Edit Estimates	S\$2,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Vincar Leasing and Rental Pte, Co. Reg. No.: -									
Main Claimant: AZMIE BIN ROSLAN									
Vehicle Reg. No.: FBN6296B		Date of Loss: 10/02/2019 00:00 - :59 [2 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6142409087SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SLU6382E		Policy No. (Claimant):							
		Excess:							
Repairer: Soon Hin Motor (HQ) BLK 1018 YISHUN INDUSTRIAL PARK A #01-342, 768760 Yishun - Tel: 67524893									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 05/03/2019]									
Claimant's Solicitor: BENEDICT CHAN & COMPANY - Tel: 62206088									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (25/02/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBN6296B (6142409087SG)
[SLU6382E]
TP
AZMIE BIN ROSLAN
Feb 10 2019 12:00AM
[Vincar Leasing and Rental Pte]
Soon Hin Motor

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images												3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print
1	04/03/19 10:19	General View											Load JPG	<input checked="" type="checkbox"/>
2	04/03/19 10:19	General View											Load JPG	<input checked="" type="checkbox"/>
3	04/03/19 10:19	General View											Load JPG	<input checked="" type="checkbox"/>
4	04/03/19 10:19	General View											Load JPG	<input checked="" type="checkbox"/>
5	04/03/19 10:19	General View											Load JPG	<input checked="" type="checkbox"/>
6	04/03/19 10:19	General View											Load JPG	<input checked="" type="checkbox"/>
7	04/03/19 10:19	General View											Load JPG	<input checked="" type="checkbox"/>
8	04/03/19 10:19	General View											Load JPG	<input checked="" type="checkbox"/>
9	04/03/19 10:19	General View											Load JPG	<input checked="" type="checkbox"/>
10	04/03/19 10:19	General View											Load JPG	<input checked="" type="checkbox"/>
11	04/03/19 10:19	General View											Load JPG	<input checked="" type="checkbox"/>
12	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
13	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
14	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
15	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
16	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
17	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
18	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
19	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
20	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
21	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
22	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
23	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
24	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
25	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
26	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
27	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
28	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
29	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
30	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
31	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
32	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
33	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
34	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
35	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
36	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>
37	04/03/19 10:20	General View											Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	04/03/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/03/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/03/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/03/19 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	04/03/19 10:20	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/06/19 15:27	TP GIA & POLICE REPORT	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/02/19 10:26	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19003410/JQD3E2

Date: 26/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBN6296B

Insured Vehicle No : SLU6382E

Date of Loss: 10/02/2019

Nature of Claim: TP

Claim No: 6142409087SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN6296B**

Make & Model: YAMAHA SNIPER T150, 150cc

Engine No: G3E6E0445362

Reg. Date: 16/11/2018 (Man. Year: 2018)

Chassis No: MH3UG0740J0132823

Colour: Black

Odometer: 0 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17

Rear Tyre Size: 120/70-17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,915.40	2,825.30	2,090.10	42.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	460.00	740.00	61.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,115.40	3,285.30	2,830.10	46.28
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	6,115.40	2,600.00	3,515.40	57.48
+ GST 7.00/7.00% (S\$)	428.08	182.00	246.08	57.48
Nett Amount (S\$)	6,543.48	2,782.00	3,761.48	57.48

INSPECTION

Date of Assignment: 22/02/2019

Date Inspected: 22/02/2019 Inspected At:

Soon Hin Motor (HQ)
BLK 1018 YISHUN INDUSTRIAL PARK A
#01-342
Singapore 768760

Estimated Period of Repair: 4.0 days

Adjuster: ONG HWEE JIE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIM	Broken	285.00 FL	*200.00 FL
2	1		*FRONT BRAKE DISK	Not Necessary	115.00 FL	*- FL
3	1		*FRONT FENDER	Broken	125.00 FL	*125.00 FL
4	2		*FRONT FORK ASSY LH/RH	Bent	720.00 FL	*500.00 FL
5	1		*STEERING UNDER BRACKET	Bent	225.00 FL	*180.00 FL
6	1		*LH FRONT LEG SHIELD PANEL	Cracked / Bracket fractured	175.00 FL	*175.00 FL
7	1		*LH FRONT LEG SHIELD AIR GUIDE PANEL - MID	Bent / Deformed	20.00 FL	*20.00 FL
8	1		*RH FRONT LEG SHIELD PANEL	Dislodged / Brackets broken	175.00 FL	*175.00 FL
9	1		*RH FRONT LEG SHIELD AIR GUIDE PANEL - MID	Bent / Deformed	20.00 FL	*20.00 FL
10	1		*RH FRONT LEG SHIELD AIR GUIDE PANEL - LOWER	Abraded / Deformed	18.00 FL	*18.00 FL
11	2		*FRONT SIDE FAIRING LOGO	Necessary	24.00 FL	*24.00 FL
12	1		*FRONT PANEL	Cut/Scuffed	115.00 FL	*115.00 FL
13	1		*FRONT PANEL INNER PANEL	Not Necessary	65.00 FL	*- FL
14	2		*FRONT PILOT LAMP ASSY LH/RH	Broken	96.00 FL	*96.00 FL
15	1		*HANDLE BAR	Bent	85.00 FL	*85.00 FL
16	1		*HANDLE BAR TOP COVER	Scraped	125.00 FL	*125.00 FL
17	1		*HANDLE BAR REAR COVER	Broken	150.00 FL	*150.00 FL
18	1		*HEADLAMP ASSY	Lens Scraped / Leg Fractured	95.00 FL	*95.00 FL
19	1		*HEADLAMP SUPPORT PANEL	Not Necessary	54.00 FL	*- FL
20	1		*FRONT SIGNAL LAMP ASSY	Scraped	38.00 FL	*38.00 FL
21	1		*KEY SWITCH FAIRING	Broken	115.00 FL	*115.00 FL
22	1		*RADIATOR ASSY	Bent	288.00 FL	*288.00 FL
23	1		*RADIATOR ELECTRIC FAN	Not Necessary	95.00 FL	*- FL
24	1		*METER ASSY	Leg Broken	328.00 FL	*328.00 FL
25	1		*FRONT FOOTREST BAR	Not Necessary	55.00 FL	*- FL
26	1		*FRONT FOOTREST BAR RUBBER STEP PAD SET	Not Necessary	30.00 FL	*- FL
27	1		*REAR BRAKE PEDAL	Not Necessary	55.00 FL	*- FL
28	2		*REAR SIDE BOARD LH/RH	Not Necessary	320.00 FL	*- FL
29	1		*EXHAUST END CAP	Grazed / Deformed	45.00 FL	*45.00 FL
30	1		*EXHAUST PIPE ASSY	Not Necessary	750.00 FL	*- FL
31	1		*FRONT TYRE	Cut	160.00 FS	*80.00 FS
32	2		*STEERING UPPER/LOWER CON/BEARING SET	Necessary	80.00 FS	*50.00 FS
33	1		*RADIATOR FAN GRILLE	Bent	28.00 FS	*28.00 FS
34	1		*RADIATOR COOLANT	Necessary	20.00 FS	*20.00 FS
35	1		*RECTIFIER & REGULATOR UNIT	Not Necessary	205.00 FS	*- FS
36	1		*HANDPHONE HOLDER	Bent	45.00 FS	*10.00 FS
37	1		*FLASHER RELAY UNIT	Not Necessary	40.00 FS	*- FS
38	1		*FRONT NUMBER PLATE	Scraped	12.00 FS	*12.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,396.00	3,117.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	480.60	291.70

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					4,915.40	2,825.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE.	New	750.00	300.00
2	TO JACK, STRAIGHTEN AND ALIGN CHASSIS FRONT SECTION (BENT).	New	380.00	100.00
3	TOWING (2X).	New	70.00	60.00
Gross Labour Cost (\$\$)			1,200.00	460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >