



Your Ref: 19.26449PD-O

Date: 15th Mar 2019

Our Ref : CS3/ASM19000119/Bsd3e2-1

M/s AXA Insurance Pte Ltd

C/O: Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKB 7225G

INSURED VEHICLE: SHC 5512X

ACCIDENT DATE: 31/12/2018

We thank you for your instruction on 21/02/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKB 7225G from M/s Perfect Automobile Appraisal Services.
- b) Singapore Accident Statement and Police Report of Vehicle SKB 7225G, SHD 5966P and SHC 5512X.
- c) Colour damaged vehicle photographs of SKB 7225G.

Pre-Repair Inspection Date : 03/01/2019 at M/s Y S K Auto Workshop, 1 Kaki Bukit Ave 6, Autobay #01-71, Singapore 417883.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKB 7225G
Make & Model	: Kia Cerato Forte 1.6 SX 6AT ABS D/AB 2WD 5DR
Year of Registration	: 2011
Chassis Number	: KNAFW511MB5465102
Engine Capacity	: 1591 cc

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.