

Surveyor:

KSC

DOI:

ASSIGNMENT

K

Date/Time:

22/2/19

Register in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

VN 7282 L

Name of Insured:

Merrinfo Agency P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

19/2/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

688 4336 X



INSRS:

WSP:

Tel:

Liability:

RMKS:

Alan's United



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 0210101-50

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Repair Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time: 28/02/19

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: 45 S\$ 2,050 (3 days) Reduction: \$1,275.75/80%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 9/10/19

Confirm with: Kenny

Email ☒ Call ☐

Final Liability: % 100 % (Agreed / Assessed) BOLA S/N No: NIL

(If NO or B 28, Ass. Lia:

Repair Cost: Cui/AST S\$ 2,193.50

CUIB (unintended)

Loss of Rental (LOR): S\$ - ( - days)

Loss of Use (LOU): S\$ 180 (\$ 60 x 3 days)

Loss of Income (LOI): S\$ - (\$ - x - days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search S\$ 2.00

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/Independent)

Legal Cost S\$ -

Total: S\$ 2,375.50 Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: 3P

3) Survey fee: \$400

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: S\$ 2,375.50

Name 1: ALAN'S UNITED AUTO PTE LTD

Payee 2: (Strike if N.A.) S\$ -

Name 2:

Payee 3: (Strike if N.A.) S\$ -

Name 3:

COPY SENT

ASS. REC. BY:

REF: CT2/

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop mv's \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time Action / Instruction

1 File pass to

CLIS \$ 2,050.00 / Red \$ 1,275.75 / 38%

Veh No: GBB 4336X Yr Regn: 03 9.9

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Citroen Berlingo c.c. 1560

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 350535 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VIF 7 E914XC 67032276

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: B.S. 195/65R15

R: FS

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 3 mm R/Bal. 2 mm

L/Bal. 3 mm L/Bal. 2 mm

D.O.A. 19/2/19 D.O.I. 22/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC6/CTI19003449/Kha3

Date: 25/02/2019

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**GBB 4336X**

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.02.2019 at the premises of M/s Alan's United Auto Pte Ltd - Sin Ming and have the following to report:-

|                               |       |          |
|-------------------------------|-------|----------|
| Workshop Estimate Amount      | : S\$ | 3,325.76 |
| Revised Estimate Amount       | : S\$ | 1,370.00 |
| "Check" Items Amount          | : S\$ | 1,360.26 |
| Total (Including Check Items) | : S\$ | 2,730.26 |

|                         |       |   |        |
|-------------------------|-------|---|--------|
| Market Value            | : S\$ | - | (est.) |
| LTA Reimbursement Value | : S\$ | - | (est.) |
| Nett Value              | : S\$ | - | (est.) |

**Description of Damage:**

The vehicle sustained damages at the  
Front Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

KENNETH KONG  
Licensed Appraiser

**Register New Vehicle (Acknowledgement)****Vehicle Particulars**

|                          |                                               |                             |                                   |
|--------------------------|-----------------------------------------------|-----------------------------|-----------------------------------|
| Vehicle No.:             | GBB4336X                                      | Vehicle Scheme:             | Normal                            |
| Vehicle Type:            | A50 - Goods (Closed) Van/Van Panel (Delivery) |                             |                                   |
| Vehicle Attachment 1:    | No Attachment                                 |                             |                                   |
| Vehicle Attachment 2:    | -                                             | Vehicle Attachment 3:       | -                                 |
| Vehicle Make:            | CITROEN                                       | Vehicle Model:              | BERLINGO 1.6 MT ABS AB 2WD 5DR DW |
| Chassis No.:             | VF77E9HXC67032276                             | Engine No.:                 | 10JBCB0010356                     |
| Motor No.:               | -                                             | Trailer Chassis No.:        | -                                 |
| Propellant:              | Diesel                                        | Passenger Capacity:         | 1                                 |
| Engine Capacity:         | 1560 cc                                       | Power Rating:               | -                                 |
| Unladen Weight:          | 1420 kg                                       | Maximum Laden Weight:       | 2130 kg                           |
| Primary Colour:          | Grey                                          | Secondary Colour:           | -                                 |
| First Registration Date: | 25 Mar 2009                                   | Original Registration Date: | 25 Mar 2009                       |
| Manufacturing Year:      | 2008                                          | Open Market Value:          | \$19,776.00                       |
| PARF Eligibility:        | No                                            | Minimum PARF Benefit:       | \$0.00                            |
| No. of Transfers:        | 0                                             |                             |                                   |

**Owner Particulars**

Owner Name: REX MARINE & ENGINEERING PTE LTD  
 Owner ID Type: Company  
 Owner ID: 200403137K  
 Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes  
 Registered Block/House No.: 61  
 Registered Street Name: KAKI BUKIT AVENUE 1  
 Registered Unit No.: # 01 - 26  
 Registered Building Name: SHUN LI INDUSTRIAL PARK  
 Registered Postal Code: 417943  
 COE No. / Expiry Date: 2009040105000045H / 24 Mar-2019  
 COE Bid Category: C - Goods Vehicle & Bus  
 QP Paid: \$5,300.00

**Transaction Details**

Business Transaction Ref. No.: 20090325081414009731  
 Business Transaction Date: 25 Mar 2009  
 Business Transaction Time: 08:14:14

**Message**

The above vehicle has been successfully registered.

Kh

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05930

Vehicle Insured : YN7282L  
Accident Date : 19-Feb-2019

Date : 21-Feb-2019

Our Ref : 219030 (CHINA) / CHAN

PAGE : 1

REX MARINE & ENGINEERING PTE LTD  
61 KAKI BUKIT AVE 1  
#01-26  
SHUN LI INDUSTRIAL PARK  
Singapore 417943

*Not Authorised*

*11 Day 8?*

*Remove the Paint*

*3 day*

## ESTIMATED COST OF REPAIR FOR CITROEN BERLINGO 1.6D GBB4336X

- 1 pc Front bumper fascia
- 1 pc Front bumper lower grille
- 1 pc Front bumper top grille
- 1 pc Front bumper top
- 6 pcs Front bumper top rivet
- 1 pc Front bumper tow cover
- 1 pc Front bumper sponge
- 1 pc Front bumper reinforcement

|            |        |    |
|------------|--------|----|
| Bumper     | 750.00 | ✓  |
| mgm        | 245.00 | ✓  |
| mgm        | 245.00 | ✓  |
| cm         | 400.00 | ✓  |
| @ S\$ 3.90 | 23.40  | ✓  |
| in         | 45.00  | x  |
| in         | 178.00 | xx |
| in         | 420.00 | ✓  |

2,306.40  
Less 10% : 230.64

*2083.40*  
*208.34*  
*1875.06*  
*2,075.96*

- 1 pc Front no.plate with box
- To putty and spray replaced parts
- To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

*in 45 in 50.00 sn*

*550.00 400*

*250*  
*650.00*

Total : S\$ 3,325.76

Singapore Dollars Three Thousand Three Hundred and Twenty Five and Cents Seventy Six Only

*L/sum*  
*2050.00 ✓dc*  
*→ KENNETH PLS Costing*  
*71cs.*

*P 1875.06*  
*SN 45*  
*L 650.00*  
*2520.06*  
*514.01*  
*2056.05*

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : YN7282L  
Accident Date : 19-Feb-2019

Our Ref : 219030 (CHINA) / CHAN

REX MARINE & ENGINEERING PTE LTD  
61 KAKI BUKIT AVE 1  
#01-26  
SHUN LI INDUSTRIAL PARK  
Singapore 417943

No. : 05930

Date : 21-Feb-2019

PAGE : 1

*Not Authorized*  
*1/1/2019*  
*Before After Paint*  
*3 days*

## ESTIMATED COST OF REPAIR FOR CITROEN BERLINGO 1.6D GBB4336X

|                                 |            |          |   |
|---------------------------------|------------|----------|---|
| 1 pc Front bumper fascia        | Bu1R       | 750.00   | ✓ |
| 1 pc Front bumper lower grille  |            | 245.00   | ✓ |
| 1 pc Front bumper top grille    |            | 245.00   | ✓ |
| 1 pc Front bumper top           |            | 400.00   | ✓ |
| 6 pcs Front bumper top rivet    | @ S\$ 3.90 | 23.40    | ✓ |
| 1 pc Front bumper tow cover     | sn         | 45.00    | X |
| 1 pc Front bumper sponge        |            | 178.00   | ✓ |
| 1 pc Front bumper reinforcement |            | 420.00   | ✓ |
|                                 |            | 2,306.40 |   |
| Less 10% :                      |            | 230.64   |   |

1 pc Front no.plate with box

*2,075.76*  
*45sn* 50.00 sn

To putty and spray replaced parts

550.00 *400*

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

*250*  
650.00

Total : S\$ 3,325.76

Singapore Dollars Three Thousand Three Hundred  
and Twenty Five and Cents Seventy Six Only

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display (damaged parts) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary (item(s)) must be resurveyed and  
is subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:

Date:

## Mei Kwan (LKKAUTO)

---

**From:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Sent:** Monday, 1 April, 2019 3:16 PM  
**To:** Vic (LKKAUTO); Mei Kwan (LKKAUTO); Admin A; CS A Team  
**Cc:** Elaine Cheong; Alfred Toh; Chee So Chow; Hsiao Tong (LKKAUTO)  
**Subject:** RE: Direct Settlement - Accident Involving YN7282L (OI: SNM19D200995C02/2) and GBB4336X (TP : LKK REF - CC6/CTI19003449/Kha3) on 19/02/2019  
**Attachments:** REPORT OF YN7282L.pdf  
**Categories:** HMK

LKK REF - CC6/CTI19003449/Kha3  
CTI REF - SNM19D200995C02/2 (YN7282L)

Dear Vic

We refer to your various emails pertaining to the above matter.

Attach herewith Insured's SAS report for your attention and necessary action.

*p/s Catherine Thia no longer in service with Claims Department*

**Best Regards**

Alfred Toh  
Senior Executive  
Claims Department  
China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #XX-00 Springleaf Tower Singapore 079909  
DID : (65) 6389 6183  
FAX: (65) 6224 7478  
W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]  
**Sent:** Monday, 1 April, 2019 1:26 PM  
**To:** Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Cc:** Catherine Thia <catherine.thia@sg.cntaiping.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>  
**Subject:** RE: Direct Settlement - Accident Involving YN7282L (OI: SNM19D200995C02/2) and GBB4336X (TP : LKK REF - CC6/CTI19003449/Kha3) on 19/02/2019  
**Importance:** High

**WITHOUT PREJUDICE**  
**SAVE AS TO COSTS**

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.



Cc: Catherine Thia; Vic (LKKAuto); CS A Team; Admin A

Subject: RE: Direct Settlement - Accident Involving YN7282L (OI : CTI - TBA) and GBB4336X (TP : LKK REF - CC6/CTI19003449/Kha3) on 19/02/2019

Importance: High

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

From: Mei Kwan (LKKAuto)

Sent: Tuesday, 26 February, 2019 8:38 AM

To: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Cc: Catherine Thia <[catherine.thia@sg.cntaiping.com](mailto:catherine.thia@sg.cntaiping.com)>; Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

Subject: Direct Settlement - Accident Involving YN7282L (OI : CTI - TBA) and GBB4336X (TP : LKK REF - CC6/CTI19003449/Kha3) on 19/02/2019

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle GBB 4336X at M/s Alan's United Auto Pte Ltd - Sin Ming on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Vic and he can be contacted at DID: 6841 2096.

***To check availability of the case handler, you may contact the undersigned.***

Thank you.

Best Regards,

Mei Kwan | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108



## Khanchna (LKK Auto)

---

**From:** Khanchna (LKK Auto)  
**Sent:** Wednesday, 14 August 2019 10:45 AM  
**To:** kennychan@alanutd.com  
**Cc:** Admin A  
**Subject:** OFFER - MVA BETWEEN YN 7282L (OI) & GBB 4336X (TP) ON 19/02/2019

| Tracking: | Recipient             | Delivery                      |
|-----------|-----------------------|-------------------------------|
|           | kennychan@alanutd.com |                               |
|           | Admin A               |                               |
|           | shupeil@lkkauto.com   | Delivered: 14/8/2019 10:45 AM |
|           | Meikwan@lkkauto.com   | Delivered: 14/8/2019 10:45 AM |
|           | olivialau@lkkauto.com | Delivered: 14/8/2019 10:45 AM |

Our Ref: CC6/CTI19003449/Kka3q2  
Your Ref: GBB 4336X

**Without Prejudice**  
**(save as to costs)**

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

|                                 |                    |
|---------------------------------|--------------------|
| 1. Cost of Repair (W/GST)       | \$ 2,193.50        |
| 2. Loss of Use (3 days x \$ 60) | \$ 180.00          |
| 3. LTA/GIA Search Fee           | \$ 2.00            |
| <b>TOTAL</b>                    | <b>\$ 2,375.50</b> |

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,  
Khanchna | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Khanchna (LKK Auto)

---

**From:** Khanchna (LKK Auto)  
**Sent:** Wednesday, 9 October 2019 11:34 AM  
**To:** kennychan@alanutd.com  
**Cc:** Admin A  
**Subject:** RE: OFFER - MVA BETWEEN YN 7282L (OI) & GBB 4336X (TP) ON 19/02/2019  
**Attachments:** CTI DV.pdf

| Tracking: | Recipient             | Delivery                      |
|-----------|-----------------------|-------------------------------|
|           | kennychan@alanutd.com |                               |
|           | Admin A               |                               |
|           | shupeil@lkkauto.com   | Delivered: 9/10/2019 11:34 AM |
|           | Meikwan@lkkauto.com   | Delivered: 9/10/2019 11:34 AM |
|           | oliviaia@lkkauto.com  | Delivered: 9/10/2019 11:34 AM |

Without Prejudice  
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

Thank you for the acceptance.

We attach herewith a copy of the DV for your further action.

Kindly also send us (LKK) all the documents below for our necessary action: -

- Hardcopy of the DV

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Khanchna** | Case Handler

**LKK Auto Consultants Pte Ltd**

DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** kennychan@alanutd.com <kennychan@alanutd.com>  
**Sent:** Thursday, 26 September 2019 4:39 PM  
**To:** Khanchna (LKK Auto) <khanchna@lkkauto.com>  
**Subject:** RE: OFFER - MVA BETWEEN YN 7282L (OI) & GBB 4336X (TP) ON 19/02/2019

Dear Person In-Charge

Offer accepted , please send us DV for my client to sign .

Regards

Kenny

Alan's United Auto Pte Ltd

64538686

**From:** Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]

**Sent:** Thursday, September 26, 2019 2:25 PM

**To:** kennychan@alanutd.com

**Cc:** Admin A <admin-a@lkkauto.com>

**Subject:** FW: OFFER - MVA BETWEEN YN 7282L (OI) & GBB 4336X (TP) ON 19/02/2019

Our Ref: CC6/CTI19003449/Kka3q2

Your Ref: GBB 4336X

**Without Prejudice**  
**(save as to costs)**

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

|                                 |                    |
|---------------------------------|--------------------|
| 1. Cost of Repair (W/GST)       | \$ 2,193.50        |
| 2. Loss of Use (3 days x \$ 60) | \$ 180.00          |
| 3. LTA/GIA Search Fee           | \$ 2.00            |
| <b>TOTAL</b>                    | <b>\$ 2,375.50</b> |

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Khanchna** | Case Handler

**LKK Auto Consultants Pte Ltd**

DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |                                                                                                                                           |                                                                                              |                       |            |
|-------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-----------------------|------------|
| CHINA TAIPING INSURANCE (S) PTE LTD                               |                                                                                                                                           | Ref : CC6/CTI19003449/Kka3n2                                                                 |                       |            |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERS SINGAPORE 079909         |                                                                                                                                           | Date : 06-11-2019                                                                            |                       |            |
|                                                                   |                                                                                                                                           | Code : CTI                                                                                   |                       |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                 |                                                                                                                                           |                                                                                              |                       |            |
|                                                                   | Insured Veh.                                                                                                                              | YN 7282L                                                                                     | Veh. Inspected        | GBB 4336X  |
|                                                                   | Policy No.                                                                                                                                | DMCVSN1443441703                                                                             | Coverage (\$)         | 0.00       |
|                                                                   | Claim No.                                                                                                                                 | SNM19D200995C02/2                                                                            | Excess (\$)           | 0.00       |
|                                                                   | Assign From                                                                                                                               |                                                                                              | Assign Date           | 22/02/2019 |
| <b>2. Vehicle Particulars &amp; Condition</b>                     |                                                                                                                                           |                                                                                              |                       |            |
|                                                                   | Make & Model                                                                                                                              | CITROEN BERLINGO (M)                                                                         | c.c                   | 1560       |
|                                                                   | Engine No.                                                                                                                                | HIDDEN                                                                                       | Year of Reg.          | 2009       |
|                                                                   | Chassis No.                                                                                                                               | VF77E9HXC67032276                                                                            | Colour                | WHITE      |
|                                                                   | Odometer                                                                                                                                  | 350535                                                                                       | Steering              | IN ORDER   |
|                                                                   | Brakes                                                                                                                                    | IN ORDER                                                                                     | Modification          | NIL        |
|                                                                   | General                                                                                                                                   | GOOD                                                                                         |                       |            |
| <b>3. Conditions of Tyres</b>                                     |                                                                                                                                           |                                                                                              |                       |            |
|                                                                   |                                                                                                                                           | Size                                                                                         | Make                  | Balance    |
|                                                                   | R/H Front Tyre                                                                                                                            | 195/65 R15                                                                                   | BRIDGESTONE           | 3 mm       |
|                                                                   | L/H Front Tyre                                                                                                                            | 195/65 R15                                                                                   | BRIDGESTONE           | 3 mm       |
|                                                                   | R/H Rear Tyre                                                                                                                             | 195/65 R15                                                                                   | FIRESTONE             | 2 mm       |
|                                                                   | L/H Rear Tyre                                                                                                                             | 195/65 R15                                                                                   | FIRESTONE             | 2 mm       |
| <b>4. Description of Damages</b>                                  |                                                                                                                                           |                                                                                              |                       |            |
|                                                                   | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                               |                                                                                              |                       |            |
| <b>5. General Information</b>                                     |                                                                                                                                           |                                                                                              |                       |            |
|                                                                   | Accident Date                                                                                                                             | 19/02/2019                                                                                   | Inspection Date       | 22/02/2019 |
|                                                                   | Survey held at                                                                                                                            | ALAN'S UNITED AUTO PTE LTD<br>BLK 7 SIN MING INDUSTRIAL ESTATE<br>#01-76<br>SINGAPORE 575642 |                       |            |
| <b>5a. Remarks</b>                                                |                                                                                                                                           |                                                                                              |                       |            |
|                                                                   | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                              |                       |            |
| <b>5b. Estimate Days of Repair</b>                                |                                                                                                                                           |                                                                                              |                       |            |
|                                                                   | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                       |                                                                                              | <b>3 Working Days</b> |            |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 4336X

| Qty                                                                         | Description of Parts                                                                           | Condition        | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>                                                 |                                                                                                |                  |                           |                   |
| 1                                                                           | FRONT BUMPER FASCIA                                                                            | BUCKLED / DENTED | 750.00                    | 750.00            |
| 1                                                                           | FRONT BUMPER LOWER GRILLE                                                                      | MTG CRACKED      | 245.00                    | 245.00            |
| 1                                                                           | FRONT BUMPER TOP GRILLE                                                                        | MTG CRACKED      | 245.00                    | 245.00            |
| 1                                                                           | FRONT BUMPER TOP                                                                               | CRACKED          | 400.00                    | 400.00            |
| 6                                                                           | FRONT BUMPER TOP RIVET @\$3.90                                                                 | NECESSARY        | 23.40                     | 23.40             |
| 1                                                                           | FRONT BUMPER TOW COVER                                                                         | SERVICEABLE      | 45.00                     | -                 |
| 1                                                                           | FRONT BUMPER SPONGE                                                                            | SERVICEABLE      | 178.00                    | -                 |
| 1                                                                           | FRONT BUMPER REINFORCEMENT                                                                     | BENT             | 420.00                    | 420.00            |
|                                                                             | LESS 10% DISCOUNT                                                                              |                  | -230.64                   | -208.34           |
|                                                                             |                                                                                                |                  | 2,075.76                  | 1,875.06          |
| <b>SPECIAL NETT ITEMS</b>                                                   |                                                                                                |                  |                           |                   |
| 1                                                                           | FRONT NO.PLATE WITH BOX (SN)                                                                   | BENT             | 50.00                     | 45.00             |
|                                                                             |                                                                                                |                  | 50.00                     | 45.00             |
| <b>LABOUR</b>                                                               |                                                                                                |                  |                           |                   |
|                                                                             | TO PUTTY & SPRAY REPLACED PARTS.                                                               |                  | 550.00                    | 400.00            |
|                                                                             | TO REMOVE,CUT-OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS. |                  | 650.00                    | 250.00            |
|                                                                             |                                                                                                |                  | 1,200.00                  | 650.00            |
| <b>GRAND TOTAL</b>                                                          |                                                                                                |                  | <b>3,325.76</b>           | <b>2,570.06</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                |                  |                           | <b>2,050.00</b>   |

Report Ref No. CC6/CTI19003449/Kka3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.