

REF: CS/CTS19003466/R1903<sup>52</sup> Special Instruction:

ASS. REC. BY:

ASSIGNMENT (Office)

Surveyor  
From (Person):

Elaine Cheong

of CTI

Date/Time: 28/2/19 @ 12:18pm

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 99355

Insured:

at Workshop m/s

ASM Automotive

Tel: 6265 0026

of

No. 2 Kwong Min Road

Policy No:

DMCVSN1837681802

Claim No:

SNM19D20059601/...

Sum Insured:

Excess: \$350.00

D.O.A. 31/01/2019

Make of Veh:  
(Client's Record)

CA (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1:01pm @ 28/2/19

Person Contacted:

Yendy

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

Insp: 13 pioneer sefor 1

	GBH 99355 - X
06/03/19	@ 16:00 p.m. ... revised IA to Elaine Cheong via memo
06/03/19	@ 16:05 p.m. mandate requested authorize repair to Elaine Cheong via memo.
12/03/19	@ 12:11 p.m. mandate approved by Elaine Cheong via memo.
12/03/19	@ 14:41 p.m. authorize repair to Yendy via email.

REF:

CT

00692

ASSIGNMENT

From

Date

Veh No.

GBH 9935C

Yr Regn 2018 / NOV

Estimated Cost

Type: M/Car / M/Cycle / Bus / Van / Lory / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

GBH 9935C

Make:

TOYOTA AYANA 150 SMT c.c 2982

at Workshop m/s

ASM Automotive

Colour:

WHITE

A/C Insured / Std / NI / NA:

of

82 Joo Koon Circle

Sp Reading

6288

T/Radio Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

JIFAT 35450K 211878

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

350

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Mil / S/Rim / STD A/Rim or

Car 99993771 David

Tyre Size:

F:

195/55R15

(Policy Condition)

R:

155R12C

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

66k

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

7 mm

R/Bal.

6/6 mm

GIA / PR Seer:

Consistent? : Yes or No

L/Bal.

7 mm

L/Bal.

6/6 mm

Est. Repairs:

4

days

Res.: Yes or No

D.O.A.

31/01/19

D.O.I.

06/03/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

82, JOO KOON CIRCLE

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Check consistency damages.

26/04/19

Continued P/P \$13,470.00 @ 4 days with Resul.  
( \$380/- Red - 6%)

Resul;

P/S see me.

RECEIVED 07 MAY 2019

Signature  
2/5/2019

Signature  
26/4

Date/Time, File Pass to?

07/05/19

Prel. Report

Days Of Repair:

4

Date/Time, File Return to?

Typist

Final Report

Resurvey No. of Trip:

1

Survey Fee:

320

1)

Add Fee:

Site Insp (\$

Transportation

Report Format:

Interview (\$

1) Drive

Lump Sum / L.B.F: (\$

13,470/- P/P

Tech Invs (\$

1) Other

Weekend (\$

1) Other

TOTAL

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Feb 2019		25 Feb 2019 12:18 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	NICHIRYO FOODS PTE LTD, Co. Reg. No.: 201600069Z								
Vehicle Reg. No.:	GBH9935C	Date of Loss:	31/01/2019 13:00 - :59						
Claim Type:	OD / SNM19D200596C01/5	Policy/Cover Note No.:	DMCVSN1837681800 (Comprehensive) Coverage: 22/11/2018 - 21/11/2019						
		Excess:	S\$350.00						
Repairer:	Asm Automotive Services Kwong Min Rd (HQ) No. 2 Kwong Min Road, 628705 Pioneer - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/03/2019]								
Adj Asg. Remarks:	PLEASE SURVEY/CHECK ON CONSISTENCY OF DAMAGES.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Tuesday, 7 May 2019 11:55 AM  
**To:** 'ASM Jaclyn'; Rasul (LKKAuto)  
**Cc:** 'ASM Yandy'; SUR  
**Subject:** RE: GBH 9935S DOA : 31,01,19  
**Attachments:** CHINA TAIPING (DV)\_0001.pdf

Dear Jaclyn,

Confirmed final fig \$13,470.00 (part by part) @ 4 days of repairs before excess \$ 350/- & GST.

Attached DV, please filled in.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ASM Jaclyn [mailto:[jaclynlai@asmauto.com.sg](mailto:jaclynlai@asmauto.com.sg)]  
**Sent:** Tuesday, 7 May 2019 11:24 AM  
**To:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; Shirley Hiew (LKK Auto) (ShirleyHiew@lkkauto.com) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)>  
**Cc:** ASM Yandy <[yandy@asmauto.com.sg](mailto:yandy@asmauto.com.sg)>; 'sur@lkkauto.com' <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: GBH 9935S DOA : 31,01,19  
**Importance:** High

Dear Rasul,

Please finalize by TODAY. Thank you.

*Our office & workshop is now at **No. 13 Pioneer Sector 1, Singapore 628424.***

*\*\*All contact numbers and fax number are remain unchanged.*

Best Regards,

**Jaclyn Lai**

Motor Claims Executive

**ASM Automotive Services Pte Ltd**

No. 13, Pioneer Sector 1, Singapore 628424.

Hp: 9236 8218 | DID: 6265 0026 | Fax: 6265 6068

Web: [www.asmauto.com.sg](http://www.asmauto.com.sg)



---

**From:** ASM Jaclyn  
**Sent:** Tuesday, 30 April 2019 11:37 AM  
**To:** Rasul (LKKAuto)  
**Subject:** RE: GBH 9935S DOA : 31,01,19

Dear Rasul,

Kindly refer attached supplier invoice.

Thanks.

*Our office & workshop is now at **No. 13 Pioneer Sector 1, Singapore 628424.**  
\*\*All contact numbers and fax number are remain unchanged.*

Best Regards,

**Jaclyn Lai**


Motor Claims Executive

**ASM Automotive Services Pte Ltd**

No. 13, Pioneer Sector 1, Singapore 628424.

Hp: 9236 8218 | DID: 6265 0026 | Fax: 6265 6068

Web: [www.asmauto.com.sg](http://www.asmauto.com.sg)



---

**From:** Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]  
**Sent:** Monday, 29 April 2019 8:55 AM  
**To:** ASM Jaclyn  
**Subject:** RE: GBH 9935S DOA : 31,01,19

Hi Jacklyn,

Kindly assist to provide the invoice

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Rasul (LKKAuto)  
**Sent:** Friday, 26 April, 2019 5:17 PM  
**To:** ASM Jaclyn  
**Subject:** RE: GBH 9935S DOA : 31,01,19

Hi Jacklyn,

## Shirley Hiew (LKK Auto)

---

**From:** ASM Jaclyn <jaclynlai@asmauto.com.sg>  
**Sent:** Friday, 26 April 2019 3:09 PM  
**To:** Rasul (LKKAuto)  
**Cc:** Shirley Hiew (LKK Auto); ASM Yandy  
**Subject:** RE: GBH 9935S DOA : 31,01,19

Dear Rasul,

COR pbp \$13,470/- (before excess & GST) is confirmed.

Thank you.

*Our office & workshop is now at **No. 13 Pioneer Sector 1, Singapore 628424.**  
\*\*All contact numbers and fax number are remain unchanged.*

Best Regards,

*Jaclyn Lai*

Motor Claims Executive

**ASM Automotive Services Pte Ltd**

No. 13, Pioneer Sector 1, Singapore 628424.

Hp: 9236 8218 | DID: 6265 0026 | Fax: 6265 6068

Web: [www.asmauto.com.sg](http://www.asmauto.com.sg)



---

**From:** Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]  
**Sent:** Thursday, 25 April 2019 8:54 AM  
**To:** ASM Jaclyn  
**Cc:** Shirley Hiew (LKK Auto)  
**Subject:** RE: GBH 9935S DOA : 31,01,19

Hi Jacklyn,

Kindly confirm

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Rasul (LKKAuto)  
**Sent:** Tuesday, 23 April, 2019 1:17 PM

**To:** ASM Jaclyn  
**Cc:** Shirley Hiew (LKK Auto)  
**Subject:** GBH 9935S DOA : 31,01,19

Hi Jacklyn,

Refer to attachment  
Finalise amount is \$ 13,470 / 4 days part by part  
Kindly confirm

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Tuesday, 12 March 2019 1:41 PM  
**To:** yandy@asmauto.com.sg  
**Cc:** SUR  
**Subject:** GBH 9935S OD (CTI) DOA - 31/01/2019

Dear Yandy,

As instructed by our client, please proceed to repair the insured vehicle **GBH 9935C (Excess \$ 350/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### View Received Message

This mail is associated with :  
**\*GBH9935C (SNM19D200596C01/5)**  
OD  
Jan 31 2019 1:00PM  
[NICHIRYO FOODS PTE LTD]  
Asm Automotive Services Kwong Min Rd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 12/03/2019 13:11 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$13470.00) - GBH9935C - Claim Handler: Elaine Cheong

Approved:13470.00.

**DOCUMENTS SUMMARY**  
There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Cheong

Date: 06 Mar 2019

**Preliminary Advice**

Vehicle No	: GBH9935C	Accident Date	: 31/01/2019
Make	: TOYOTA DYNA 150 D	Policy No.	: DMCVSN1837681800
Assignment Date	: 25/02/2019	Excess	: S\$350.00
Date of Inspection	: 06/03/2019	Est. Duration of Repair	: 4 days
Inspection At	: Asm Automotive Services Kwong Min Rd (HQ) No. 2 Kwong Min Road Singapore 628705		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,350.00
Revised Amount	:S\$	13,470.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,470.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	28,640.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,360.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

DISCLAIMER: This message (and its attachment(s), if any) is intended solely for the recipient(s) addressed above and may contain privileged/confidential information. If you are not the intended recipient of this e-mail, we would be grateful if you could kindly notify us and delete this message (and its attachment(s), if any) from your computer. You should not read, copy, use or disseminate this message (or its attachment(s), if any) in any form or manner.

## Nivitha (LKK Auto)

---

**From:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Sent:** Monday, 25 February 2019 11:54 AM  
**To:** ASM Jaclyn; Alex; yandy@asmauto.com.sg; assignments@lkkauto.com; nf-account@nichiryo-solar.com  
**Cc:** Elaine Cheong; Alfred Toh; Chee So Chow; Eddie Sim  
**Subject:** Own Damaged Claim: GBH9935C (Nichiryo Foods Private Limited) ; DOA: 31.01.2019 (SNM19D200596C01/5)  
**Attachments:** Quotation-0002.pdf; GBH9935C - SAS (190131).pdf

M/s ASM Automotive Services Pte Ltd  
Attn: Yandy Ang

Dear Sirs

We refer to your email of even date pertaining to the above matter.

Please note that we shall be appointing M/s LKK Auto Consultants Pte Ltd to survey mutual client's vehicle.

Aside to M/s LKK Auto Consultants Pte Ltd., please assist to arrange for survey.

Merimen folder shall be created shortly.

Aside to Elaine, please assist to follow up on the matter.

Best Regards

Alfred Toh  
Senior Executive  
Claims Department  
China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Tel (65) 6389 6183  
Fax (65) 6224 7478  
Email: claimsdept@sg.cntaiping.com  
alfred.toh@sg.cntaiping.com  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** ASM Yandy [mailto:yandy@asmauto.com.sg]  
**Sent:** Monday, 25 February, 2019 11:06 AM  
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Cc:** ASM Jaclyn <jaclynlai@asmauto.com.sg>; Alex <alex@asmauto.com.sg>  
**Subject:** Own Damaged Claim: GBH9935C (Nichiryo Foods Private Limited) ; DOA: 31.01.2019

Dear Sir / Madam,

Concurrent, the owner of vehicle GBH 9935 C wish to file claim under their own insurance policy.

We hereby append a copy of our estimate and SAS for your kind perusal. Kindly arrange survey for the said vehicle.

Thank you.

Our office & workshop is now at No. 13 Pioneer Sector 1, Singapore 628424.  
\*\*All contact numbers and fax number are remain unchanged.

Best Regards,

*Yandy Lim*

Motor Claims and Safety Officer

ASM Automotive Services Pte Ltd

No. 13 Pioneer Sector 1, Singapore 628424

Tel: 6265 0026 | Fax: 6265 6068

Web: [www.asmauto.com.sg](http://www.asmauto.com.sg)



---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/02/2019 14:52
Date Of Accident	31/01/2019 13:50
Exact Location Of Accident	NEAR BLK 720 CLEMENTI WEST ST 2 OPEN CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH9935C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NICHIRYO FOODS PRIVATE LIMITED
Co Reg No	201600069Z
Email Address	NF-ACCOUNT@NICHIRYO-SOLAR.COM
Mobile Phone No	
Alternative Phone No	OFFICE-65702957

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1837681800
Cover Note Number	

### Driver

Name of Driver	CHRISTOPHER LYE POH FONG
NRIC No	S7631670H
Date Of Birth	03/10/1976
Occupation	OUTDOOR
Date Of Driving Pass	03/10/2002
Driving Experience	16 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94889771
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 75 MARINE DRIVE #04-21  
 Postcode 440075  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

### General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY  
 Weather Conditions CLEAR  
 Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 1  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : PATRICK  
 GENDER: : MALE

### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name JURONG NEIGHBOURHOOD POLICE POST  
 Police Station Address ROAD: BLK 158 YUNG LOH ROAD , POSTCODE: 610158 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-2659999 - FAX NO: 62664987  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

### Circumstances of Accident

AS PER POLICE REPORT NO: T/

### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number  
 Vehicle Make/Model/Colour  
 Details Of Properties LOW BARRIER 2.15 HEIGHT  
 Vehicle Category GOVERNMENT  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)





**SINGAPORE  
POLICE FORCE**



T/20190201/2134

Police Station Of Origin  
Jurong NPP  
158 Yung Lok Road #01-58 SINGAPORE  
610158  
Tel No. 1800 2859999

2 of 3

Report No. T/20190201/2134

CONTINUATION OF REPORT

<b>Driver</b>			
Name	CHRISTOPHER LYE POH FONG	ID No.	S7631670H
Related Vehicle	GBH9935C (Lorry)	Contact No.	94889771
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class 3 Date of Expiry NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 31 01 2019 at 1350 hrs. I was driving out of the open space carpark of Blk 726 Clementi West Street 2. During the exit, the top of my lorry GBH9935C collided onto the height limit railings. I wish to state that the entrance of the carpark has no height limit railings. There are also two exit points located at two different locations within the carpark. The exit point which I use to maneuver is erected with height limit railings. After the collision, the front top area of my lorry was damaged and the refrigerate compartment air-con and fan is not in working condition.

I am in possession of the in-car CCTV footages of the incident.



SINGAPORE  
POLICE FORCE



T/20190201/2134

3 of 3

Police Station Of Origin:  
Jurong NPP  
158 Yung Loh Road #01-58 SINGAPORE  
610158  
Tel No: 1800-2659999

Report No: T/20190201/2134

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Sr Staff Sgt YAP HOW KIAT MICHAEL	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 01/02/2019 16:49
Officer In Charge Of Case: TP / AEIT / SSI 2 JUREMAH BINTE AHMAD Contact No.: 65472076	Classification Of Case:

Authentication Stamp  
NP188



Sketch Plan Pg. 1

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*[Handwritten Signature]*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Handwritten Signature]*  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I AM AWARED THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0069Z
Vehicle Details	
Vehicle No.:	GBH9935C
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1KD2831802
Chassis No.:	JTFAT35Y50K211878
Maximum Power Output:	-
Open Market Value:	\$27,082.00
Original Registration Date:	22 Nov 2018
First Registration Date:	22 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Nov 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$29,501.00
COE Rebate Amount:	\$28,640.00
<b>Total Rebate Amount:</b>	<b>\$28,640.00</b>

The information contained herein is correct as at 06 Mar 2019

OK

Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0020 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
UEN: S6650020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCA119015415 Vehicle Registration No: 61BH9935C
Name (as shown in NRIC) : Nichevup Foods Private Limited NRIC/FIN/Passport No :
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate
Address : Singapore ( )
Contact (Tel) : Mobile No. :
Email Address :
Date of Accident : 31/01/19 Time of Accident : 12:00
Place of Accident : near 61K720 Clementi West St 2 open carpark
Insurance Company : China Taiping

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Attach police report no: 7/20190201/2134
[Multiple blank lines for additional information]

Policyholder / Driver's Signature
Date:

[Handwritten Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
UEN: S66550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MSAT19015465 Vehicle Registration No: QBH9935C
Name(as shown in NRIC) : Nishino Foods Private Limited NRIC/FIN/Passport No :
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate
Address : Singapore( )
Contact (Tel) : Mobile No. :
Email Address :
Date of Accident : 31/04/19 Time of Accident : 1350
Place of Accident : Near BUC 750 Clementi West St 2 open car park
Insurance Company : China Taiping Ins.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Owner wanted to change to claim own policy.
[Multiple blank lines for additional information]

Policyholder / Driver's Signature
Date:
[Signature]
[Stamp: NISHINO FOODS PTE LTD, ROC NO: 2016020092, SINGAPORE]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:
[Signature]



中国太平保險(新加坡)有限公司  
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
Co. Reg No. 200208384E

M2300/C  
N SN  
AN0650A  
Cov. Type: C

MOTOR COMMERCIAL VEHICLE

**CERTIFICATE OF INSURANCE**  
Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1980  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1989 (Malaysia)

ORIGINAL

CERTIFICATE No	DHCVSN1837681800	Engine No :1KD2831802 Chamo:JTFAT35Y50K211878
1 Index Mark and Registration Number of Vehicle	GBH9935C	
2 Name of Policy Holder	M/S NICHIRYO FOODS PRIVATE LIMITED	
3 Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	22 November 2018 (10:49 Hours)	Excess Sect I ..... S\$350.00 EX ON WINDSCREEN ..... S\$100.00
4 Date of Expiry of Insurance	21 November 2019	
5 Persons or Classes of Persons entitled to drive*	Any person who is driving on the Policyholder's order or with their permission.  Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
6 Limitations as to use*	(1) Use in connection with the policyholder's business. (2) Use for the carriage of passengers (other than for hire or reward) in connection with the policyholder's business. (3) Use for social, domestic or pleasure purposes. The policy does not cover. (1) Use for hire or reward or racing, pace-making, reliability trial or speed testing. (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.	

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

**I/We hereby Certify** that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: HO LI HWA IRENE  
Authorised Officer

[Signature]  
Authorised Signatory

3 Anson Road #16-00 Springleaf Tower Singapore 079909 Tel: 6389 6111 Fax: 6225 3582 Website: www.sg.entaiping.com

Elaine Lee  
97489011

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S7631670H  
Name: CHRISTOPHER LYE POH FONG  
Birth Date: 03 Oct 1976  
Issue Date: 06 Oct 2003

000893167K



REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7631670H




Name: CHRISTOPHER LYE POH FONG  
賴保芳  
Race: CHINESE  
Date of Birth: 03-10-1976 Sex: M  
Country of Birth: SINGAPORE  
S7631670H

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	03 Oct 2002

Licence No: S7631670H



NP 428A

956032



NRIC No: S7631670H




Date of Issue: 02-11-2006

APT. BLK 75 MARINE DRIVE #04-21  
SINGAPORE 440075  
NRIC No: S7631670H Date: 14/06/2012 No: 7077702

POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190201/2134

1 of 3

Police Station Of Origin:  
Jurong NPP  
158 Yung Loh Road #01-58 SINGAPORE  
610158  
Tel No: 1800-2659999

Report No. T/20190201/2134

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 01/02/2019 16:49	Vide Report No.:	Station Diary No.: 10
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: CHRISTOPHER LYE POH FONG		Address: APT BLK 75 MARINE DRIVE #04-21 SINGAPORE 440075	
ID Type / ID No.: NRIC NO / S7631670H		Contact No.:	Mobile: 94889771
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 42	Date of Birth: 03/10/1976	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: SHOPPING EXECUTIVE		Driving Licence Information: Class: 3	Date of Expiry:

**General Information of the Accident**

Type of Accident: Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 31/01/2019 13:50	Type of Location: Carpark Exit
Location: Along Road 1 CLEMENTI WEST STREET 2 Blk 726 Clementi West Street 2 OSCP			
Weather: Clear	Road Surface: Dry	Road Speed Limit: 20 Km/h	
Traffic Flow:	Traffic Control:	Traffic Volume: Moderate	
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings			Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBH9935C	Lorry	TOYOTA	Dyna	White	Seriously Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



# ASM Automotive Services Pte Ltd

No. 13, Pioneer Sector 1, Singapore 625424  
Main Line: 6265 0980 Fax: 6265 6068  
Email: enquiry@asmauto.com.sg  
Co. / GST Reg. No.: 201203613C



**FROM :** Jaclyn Lai  
**TEL. NO. :** 6265-0980 / 9236-8218  
**EMAIL :** jaclynlai@asmauto.com.sg  
  
**TO :** China Taiping Insurance (Sg) P/L  
**ATTN :** Motor Claim Department  
**TEL. NO. :** 6389-6111 (main)  
**EMAIL :** claimsdept@sg.ctaiping.com  
  
**CC :** Nichiryō Foods Private Limited

**DATE :** 25.02.2019  
**VEHICLE NO. :** GBH 9935 C  
**MODEL NO. :** TOYOTA DYNA 150 5MT  
**CHASSIS NO. :** JTFAT35Y50K211878  
**ENGINE NO. :** 1KD2831802  
**LTA REG DATE :** 22-Nov-18  
  
**CLAIM TYPE :** Own Damaged  
**D.O.A :** 31.01.2019  
**CLAIM REF NO. :** asm/AC19011/JL

## Quotation for Accident Repair

S/N	SPARE PARTS (SPECIAL NETT)	QUANTITY	UNIT PRICE	AMOUNT
1	Refrigeration unit (12v) <i>Bl-</i>	1	\$ 12,500.00	\$ 12,500.00
<b>SUB-TOTAL :</b>				<b>\$ 12,500.00</b>

### LABOUR CHARGES

1 To dismantle and replace new sets refrigerated unit, reconceal unit on interior and exterior with sealant. Including reconnect wiring, refix all piping. Conduct final test run and perform gas leakage test.	\$ 1,200.00 <i>600</i>
2 Touch-up paint	\$ 500.00 <i>250</i>
3 Refilling of gas-R404A (TDJ301)	\$ 150.00 <i>120</i>
<b>TOTAL LABOUR :</b>	<b>\$ 1,850.00</b>
<b>GRAND TOTAL :</b>	<b>\$ 14,350.00</b>

*13/3/19*

*Rasul  
Hp 95010068  
4 days  
P/P  
06/03/19 @ 0900  
EXCESS: 350*

*12,500  
970  
-----  
13,470  
4 days*

To dismantle and replace new sets refrigerated unit, reconceal unit on interior and exterior with sealant. Including reconnect wiring, refix all piping. Conduct final test run and perform gas leakage test.  
 Touch-up paint  
 Refilling of gas-R404A (TDJ301)

**C**

Acknowledged by Receiver  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

*REVERT  
Resurvey before repair*



# HWEE JAN (S) PTE LTD

Head Office: 82 Joo Koon Circle, Jurong Ind. Est., Singapore 629101. Tel: 6897 9339 Fax: 6897 7337(Accs), 6863 4836(Sales), 6863 4632(Service)  
 Co. Reg. No.: 199201209N GST Reg. No.: 19-6201209-N Website: <http://www.hweejan.com.sg>  
 North Link Service Center: No. 10 Admiralty Street, #02-82 North Link Building, Singapore 757695. Tel/Fax: 6752 9339 Hotline: 8139 8778

# TAX INVOICE

## ORIGINAL

Page 1 of 1

<b>Customer Name / Address</b>		<b>Invoice No.</b>	<b>Date</b>	<b>Currency</b>	<b>Terms</b>	<b>P.O. / Work Order</b>
A0081 ASM AUTOMOTIVE SERVICES PTE LTD 13 PIONEER SECTOR 1 SINGAPORE 628424 Tel: 6265 0980 , 6265 8806 Fax: 6265 6068		90804	26-04-2019	SGD	NET DUE	
<b>Vehicle No.</b>	<b>Vehicle Mileage</b>	<b>Running Hour</b>	<b>Confirmed By</b>	<b>Serviced By</b>		
GBH9935C			MR ALEX	NAGAPRAKASH		

S/N	Item	Description	UoM	Qty	U/Price	Disc.	Amount
1	TDJ301DL1	REFRIGERATION UNIT (12V)	UNIT	1.00	13,000.00	500.00	12,500.00
2	R404A (TDJ301)	REFILLING OF GAS-R404A (TDJ301)	NOS	1.00	120.00	0.00	120.00
3	LAFRBORE	LABOUR CHARGE - TO DISMANTLE AND REPLACE NEW SETS REFRIGERATION UNIT, RECONSEAL UNIT ON THE INTERIOR AND EXTERIOR WITH SEALANT. INCLUDING RECONNECT WIRING, REFIX ALL PIPING, CONDUCT FINAL TEST RUN AND PERFORM GAS	NOS	1.00	650.00	0.00	650.00

DURATION : 7 WORKING DAYS



Sub Total 13,270.00  
 GST (7%) 928.90  
 Total 14,198.90

- \* Cheque should be crossed and made payable to HWEE JAN (S) PTE LTD.
- \* Interest of 1% per month is chargeable for late payment.
- \* I certified that the above service & price has been carried out to my entire satisfaction, unless notify within 3 days, all work done will be deemed agreed.
- \* Goods sold are not refundable or commodities exchange.

HWEE JAN (S) PTE LTD

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Feb 2019		25 Feb 2019 12:18 <a href="#">Edit Adj Rpt</a>	<b>S\$13,470.00</b> <a href="#">Edit Estimates</a>	<b>S\$13,470.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	NICHIRYO FOODS PTE LTD, Co. Reg. No.: 201600069Z		
Vehicle Reg. No.:	GBH9935C	Date of Loss:	31/01/2019 13:00 - :59 [2 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D200596C01/5	Policy/Cover Note No.:	DMCVSN1837681800 (Comprehensive) Coverage: 22/11/2018 - 21/11/2019
		Excess:	S\$350.00
Repairer:	Asm Automotive Services Kwong Min Rd (HQ) No. 2 Kwong Min Road, 628705 Pioneer - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 06/03/2019]		
Adj Asg. Remarks:	PLEASE SURVEY/CHECK ON CONSISTENCY OF DAMAGES.		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- CHINA\_TAIPING (12/03/2019): Alert - Adj Mandate Approved (S\$13470.00) - GBH9935C - Claim Handler: Elaine Che...

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*GBH9935C (SNM19D200596C01/5)  
 OD  
 Jan 31 2019 1:00PM  
 [NICHIRYO FOODS PTE LTD]  
 Asm Automotive Services Kwong Min Rd

Upload Documents    Upload Photos    Compose New Letter

View View in Browser ▾

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/03/19 16:00	<b>Adjuster Immediate Advice</b>	Load HTM	<input type="checkbox"/>

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/03/19 13:54	<b>Odometer Reading</b>	Load JPG	<input checked="" type="checkbox"/>
2	12/03/19 13:54	<b>Chassis Number</b>	Load JPG	<input checked="" type="checkbox"/>
3	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
27	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
28	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
29	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
30	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
31	12/03/19 13:54	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
32	26/04/19 16:15	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
33	26/04/19 16:15	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
34	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
35	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
36	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
37	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
38	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
39	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
40	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
41	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
42	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
43	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
44	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
45	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
46	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
47	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
48	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
49	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
50	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
51	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
52	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
53	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
54	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
55	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
56	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
57	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
58	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
59	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
60	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
61	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
62	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
63	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
64	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
65	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
66	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
67	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
68	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
69	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
70	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
71	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
72	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
73	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
74	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
75	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
76	26/04/19 16:15	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	25/02/19 12:12	ESTIMATES		Load PDF <input type="checkbox"/>
2	25/02/19 12:13	EMAIL CORRESPONDENCES		Load PDF <input type="checkbox"/>
3	25/02/19 12:15	Singapore Accident Statement		Load PDF <input type="checkbox"/>

Assessment Reports			1 per page ▾	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Print
1	06/03/19 16:01	<b>ESTIMATE.jpeg</b>		

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CTI19003466/R1SD3S2

Date: 17/06/2019

### REFERENCE

Insured/Claimant: NICHIRYO FOODS PTE LTD Policy No: DMCVSN1837681800  
Date of Loss: 31/01/2019 Nature of Claim: OD Claim No: SNM19D200596C01/5

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH9935C**  
Make & Model: TOYOTA DYNA 150 D, 3.0 D (M) Engine No: 1KD2831802  
Reg. Date: 22/11/2018 (Man. Year: 2018) Chassis No: JTFAT35Y50K211878  
Colour: White Odometer: 6288 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: S\$66,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/75R15 Rear Tyre Size: 155 R12C (D)  
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 6/6 mm  
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,500.00	12,500.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	970.00	880.00	47.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,350.00</b>	<b>13,470.00</b>	<b>880.00</b>	<b>6.13</b>
<b>- Excess (S\$)</b>	<b>350.00</b>	<b>350.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>14,000.00</b>	<b>13,120.00</b>	<b>880.00</b>	<b>6.29</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>980.00</b>	<b>918.40</b>	<b>61.60</b>	<b>6.29</b>
<b>Nett Amount (S\$)</b>	<b>14,980.00</b>	<b>14,038.40</b>	<b>941.60</b>	<b>6.29</b>

### INSPECTION

Date of Assignment: 25/02/2019  
Date Inspected: 06/03/2019 Inspected At: 82, JOO KOON CIRCLE  
Estimated Period of Repair: 4.0 days Repairer: Asm Automotive Services Kwong Min Rd

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 17 Jun 2019)**Parts:** N/A TOYOTA DYNA 150 D 3.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBH9935C)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REFRIGERATION UNIT (12V)	Bent	12,500.00 F	*12,500.00 F	
					<b>Total Parts (\$\$)</b>	<b>12,500.00</b>	<b>12,500.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE AND REPLACE NEW SETS REFRIGERATION UNIT, RECONCEAL UNIT ON INTERIOR AND EXTERIOR WITH SEALANT. INCLUDING RECONNECT WIRING, REFIX ALL PIPING. CONDUCT FINAL TEST RUN AND PERFORM GAS LEAKAGE TEST.	New	1,200.00	600.00
2	TOUCH-UP PAINT.	New	500.00	250.00
3	REFILLING OF GAS-R404A (TDJ301)	New	150.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,850.00</b>	<b>970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >