

15000201

2018, PLO, BY

REF: CS/ASM19003471/Eqd3^{SR} Special Instruction

Supervisor: Steve

ASSIGNMENT (Office)

From (Person): Justin

of ASM(CAXA)

Date/Time: 25/2/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFX 66M

Insured:

at Workshop info:

progressive
Blk 3022A Ubi Rd 1 #01-45/46

Tel:

67415336 / 8258 5195

of

Claim No:

S9M01EWY

Policy No:

Excess:

\$900-00

Sum Insured:

D.O.A:

22/2/19

Make of Veh:
(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 3:11pm 25/2/19

Person Contacted:

pei wen

Vehicle: IN / OIT

Date/Time	Action/Instruction (→) Estimate
	SFX 66M-X
26/2/19 @ 3:30pm	visited to Justin on Smart claim.
27/2/19 @ 11:30am	conferred with Ray from fig @ 4120.14, 5 days. (led to 2601.84, 39%)

Steve

REF: ASM(CAXA)

INSURANCE

Date: 28/2/19

Vehicle No: SFX 66M

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Accord 2.4

Colour: Silver

Sp. Reading: 219599

Eng/No: MRHCM 56505 P 499634

Chassis No: MRHCM 56505 P 499634

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / STD Rim / STD A/Rim or

Tyre Size: F: 215/60R16
R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Excess: \$900.00

Remarks: The veh had commenced its repair at the time of inspection.

X	X
N/S	O/S

Est. Repair: 5 days Res: Yes or No

Turn Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: 5/11/2005

Workshop Name: Progressive

Blk: 3022A Ubi Rd 1 # 01-45/46

Front R/Bal: 7 mm

Front L/Bal: 7 mm

D.O.A: 22/2/19

Survey held at: Progressive

Rear R/Bal: 7 mm

Rear L/Bal: 7 mm

D.O.I: 25/2/19

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooflop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction

MV - 50,000

PV - 40,543

NV - 9457

* checked with Kenneth, MV: (50k) ; Marking: (40k, 50k)

26/2/2019

RECEIVED 17 APR 2019

Date/Time: File Pass to? Prel. Report Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: 200

Transportation: 1

Add Fee: Site Insp. (\$) Interview (\$) Tech. Inv. (\$) Weekend. (\$)

Report Format: Smart claim

Lump Sum / I.B.E. (\$): 402014

◀ Service Request Details

Claim

S9M01EWY

Reference

None 

Loss Date

February 22, 2019

Report Date

Feb 23, 2019 12:00:00 AM

Request Date

February 25, 2019

Due Date

March 4, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SFX66M

MODEL

ACCORD 2.4

Service Address

...

Primary Contact/Insured

HEE THIAM SOON
NO.181 #08-19, TANJONG RHU ROAD, 436922, Singapore
92379660
TSHEE@STARHUB.COM

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

Additional Instructions

PROGRESSIVE OD XS \$400 + UNNAMED \$500=\$900

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 17 April 2019 11:34 AM
To: Ray; Steve Chen (LKK Auto)
Cc: Wayne; Peiwen; Chermaine; SUR
Subject: RE: SFX66M - TO FINALIZE

Dear Ray,

WITHOUT PREJUDICE

Confirm final fig \$4,120.14 before excess \$900.00 & GST and 5 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray <ray@procarcare.com.sg>
Sent: Monday, 15 April 2019 3:46 PM
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: Wayne <wayne@procarcare.com.sg>; Peiwen <peiwen@procarcare.com.sg>; Chermaine <chermaine@procarcare.com.sg>
Subject: SFX66M - TO FINALIZE

Hi Steve/ Veron,

Please refer to finalize
Total amount is \$4120.14

Regards,

Ray Lin

Damage Assessment

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

With effect from 1 Sep 2018, **Progressive Automotive Pte Ltd will be rebranded as **Progressive Car Care Pte Ltd**. You may now reach us at our new email addresses (@procarcare.com.sg) and our old email addresses (@progauto.com.sg) shall cease to function with effect from 1 Sep 2018. We look forward to your continued support.*

Model

ACCORD 2.4

Service Address

...

Primary Contact/Insured

HEE THIAM SOON
 NO.181 #08-19, TANJONG RHU ROAD, 436922, Singapore
 92379660
 TSHEE@STARHUB.COM

Claim Handler

TAN Jas
 6568804844
 jas.tan@axa.com.sg

Additional Instructions
 PROGRESSIVE OD XS \$400 + UNNAMED \$500=\$900

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

4/17/19 11:04 AM

FROM

TAN Jas

SUBJECT

Re:2ND IA OF VEHICLE SFX 66M UPLOADED

BODY

Please proceed.



TYPE



SENT

4/17/19 10:59 AM

SUBJECT 2ND IA OF VEHICLE SFX 66M UPLOADED

BODY Dear Jas, please be informed that the 2nd IA of ve...



TYPE ⓘ

SENT 4/17/19 10:56 AM

FROM LKK AUTO CONSULTANTS PTE LTD (OD)

SUBJECT 2ND IA OF VEHICLE SFX 66M UPLOADED

BODY Dear Jas, please be informed that the 2nd IA of ve...



TYPE ⓘ

SENT 4/17/19 10:56 AM

FROM LKK AUTO CONSULTANTS PTE LTD (OD)

SUBJECT 2ND IA OF VEHICLE SFX 66M UPLOADED

BODY Dear Jas, please be informed that the 2nd IA of ve...



TYPE ⓘ

SENT 2/26/19 3:30 PM

FROM LKK AUTO CONSULTANTS PTE LTD (OD)

SUBJECT IA OF VEHICLE SFX 66M UPLOADED

BODY Dear Jas, please be informed that the IA of vehicl...



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

17/4/2019

Survey Details:

Date of loss	22-Feb-19
Date of appointment	25-Feb-19
Date of survey	25-Feb-19
Location of survey	PROGRESSIVE CAR CARE PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SFX 66M
Make and Model	HONDA ACCORD 2.4A
Date of registration	5/11/2005
Excess	\$ 900.00
Market Value	\$ 48,000.00
Parf Rebate	\$ 40,543.00
Nett Loss	\$ 7,457.00

Repair details:

Initial Estimate	\$ 6,721.98	(ESTIMATE \$6,650.48 + SUPPLEMENTARY \$71.50)
------------------	-------------	--

Proposed/Revised repair cost:

Parts	\$ 3,026.00
Check items (estimate)	\$ -
Labour	\$ 1,094.14
Total	\$ 4,120.14
Lump Sum(if applicable)	-

Number of days for repair	<u>5</u>
---------------------------	----------



Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. We have received supplementary \$71.50 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

26/2/2019

Survey Details:

Date of loss	22-Feb-19
Date of appointment	25-Feb-19
Date of survey	25-Feb-19
Location of survey	PROGRESSIVE CAR CARE PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SFX 66M
Make and Model	HONDA ACCORD 2.4A
Date of registration	5/11/2005
Excess	\$ 900.00
Market Value	\$ 48,000.00
Parf Rebate	\$ 40,543.00
Nett Loss	\$ 7,457.00

Repair details:

Initial Estimate	\$ 6,507.48
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 3,325.20
Check items (estimate)	\$ -
Labour	\$ 1,182.48
Total	\$ 4,507.68
Lump Sum(if applicable)	-

Number of days for repair	<u>5</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

*DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.
PENDING FOR RADIATOR AND FRONT BUMPER FOAM
(SUPPLEMENTARY) PRICES. WE HAVE AUTHORISE REPAIR.*

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

Note: Remarks are private unless you show it to other parties.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 26 February 2019 11:49 AM
To: wendy@procarcare.com.sg; Claims; claims@progressiveauto.sg
Cc: SUR
Subject: AXA-OD VEHICLE SFX 66M (DOA: 22/02/2019)

Dear Wendy,

As spoken with you earlier.

Please proceed to repair the insured vehicle **SFX 66M at repair cost not more than \$4,500.00 on part by part basis (Excess \$ 900/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/02/2019 11:07
Date Of Accident	22/02/2019 17:30
Exact Location Of Accident	KPE TO PIE (CHANGI)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFX66M
Insured/Policyholder	
Name Of Registered Owner	HEE THIAM SOON
NRIC No	S1523934D
Email Address	TSHEE@STARHUB.COM
Mobile Phone No	(LOCAL) +65-98558145
Alternative Phone No	OTHERS-92379660

Vehicle Particulars

Manufacturer	HONDA
Model	ACCORD-2.4 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA133155
Cover Note Number	

Driver

Name of Driver	MOLLY TAN LEE JOO
NRIC No	S1603426F
Date Of Birth	26/10/1963
Occupation	INDOOR
Date Of Driving Pass	27/12/2007
Driving Experience	11 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-92379660
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

VEH C

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

NA/UNKNOWN

Name of Driver

VEH D

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in the accident and the insurer's lawyer/law firm, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

23/2/19.

Common Statement

ACCIDENT STATEMENT (Part I)

This is NOT an admission of blame / liability, but a summary of identities and facts which will speed up the settlement of claims

To be signed by BOTH drivers

1 Date of accident: 22/1/19 Time: 19:30
 2 Exact location of accident: KPE To PE (Changi)
 3 Injuries even if slight: No Yes
 4 Material damage: To vehicles other than vehicles A and B: No Yes To objects other than vehicles: No Yes
 5 Witness' name, address and tel no. (to be underlined if he/she is passenger in vehicle A or vehicle B):
 Vehicle Video Camera Available: No Yes


Registration No. (VEHICLE A): SFX66M
 6 Insured / policyholder (See insurance cert.):
 Name: Hee Thiam Sor
 Address:
 NRIC / Passport no: S1523934D
 Tel no. (from Sam 611 Sng):
 HP: 918558145
 7 Vehicle:
 Make, type: Honda Accord
 8 Insurance company: AXA TC TPFT TPO
 Does the policy cover damage to vehicle A? No Yes
 Policy No.: GA-133125
 9 Driver: Seat or Owner
 Name: Mally Tan 48000
 NRIC / Passport no: S1603426F
 Class of licence:
 HP: 92379660
 Gender: Male Female

12 CIRCUMSTANCES
 Put a cross (X) in each of the relevant boxes applicable to your vehicle

- Collided into Caravan
- Collided into Bus/Truck
- Collided into Motorcycle
- Collided into Parked Vehicle
- Collided into Pedestrian
- Collided into Property
- Collision - Change/Change Lane
- Collision - Cross Junction
- Collision - Head on Collision
- Collision - Head to Tail
- Collision - Motor/Motor Rd
- Collision - Opening Door of Vehicle
- Collision - Roundabout
- Collision - 90 Turn
- Drink Driving / Drug Influence
- Fire, Explosion or Lightning
- Flood
- Hit and Run / Vanishing / Damaged when Parked
- Hit by Fallen Tree / Other Objects
- No Collision
- Side Swipe
- Theft

Registration No. (VEHICLE B): SFJ56773
 6 Insured / policyholder (See insurance cert.):
 Name:
 (capital letters)
 Address:
 NRIC / Passport no:
 Tel no. (from Sam 611 Sng):
 HP:
 7 Vehicle:
 Make, type:
 8 Insurance company:
 C TPFT TPO
 Does the policy cover damage to vehicle B?
 No Yes
 Policy No. (if available):
 9 Driver (See driving licence) (if different from insured B above):
 Name:
 (capital letters)
 NRIC / Passport no.:
 Class of licence:
 HP:
 Gender: Male Female

← State TOTAL number of boxes marked with a cross →



13 Visible damage to vehicle A

13 Visible damage to vehicle B

14 My remarks

15 Signatures of drivers

A *Mally Tan*

15 My remarks

B

* In the event of injuries or in the event of damage to property other than to vehicles A and B, give information marked

Do not alter anything in the statement after signing. Subsequently, each driver should take one copy.

For insured's individual statement (Part II) see overleaf →

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 3934D

Vehicle Details

Vehicle No.: SFX66M
 Vehicle to be Exported: No
 Intended Deregistration Date: 23 Feb 2019
 Vehicle Make: HONDA
 Vehicle Model: ACCORD 2.4 A
 Primary Colour: Silver
 Manufacturing Year: 2005
 Engine No.: K24A45P00726
 Chassis No.: MRHCM56505P400634
 Maximum Power Output: 118.0 kW (158 bhp)
 Open Market Value: \$31,838.00
 Original Registration Date: 05 Nov 2005
 First Registration Date: 05 Nov 2005
 Transfer Count: 1
 Actual ARF Paid: \$35,022.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
 PARF Eligibility Expiry Date: -
 PARF Rebate Amount: \$0.00


Intended COE Rebate Details

COE Expiry Date: 04 Nov 2025
 COE Category: B - Car (1601cc & above)
 COE Period(Years): 10
 PQP Paid: \$60,519.00
 COE Rebate Amount: \$40,543.00
Total Rebate Amount: \$40,543.00

The information contained herein is correct as at 23 Feb 2019

OK

6-8.4 months



Honda Accord Price Range Depreciation > 10 year(s) Vehicle Type

Advanced Search

Home » Used Cars » Gen Y Automobile » Honda Accord 2.0A (New 10-yr COE)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle



Honda Accord 2.0A (New 10-yr COE)

- Overview Financial Insurance Accessories Similar Research Photos Map

- Add to Shortlist Add to Compare Add a Note Report Error More Actions: Share

Car Details

Price	\$54,800	?
Depreciation	\$5,480 /yr	?
Reg Date	10-Jan-2009 (10yrs COE left)	?
Manufactured	2008	?
Mileage	107,000 km (10.6k /yr)	?
Transmission	Auto	?
Engine Cap	1,997 cc	?
Road Tax	\$1,210 /yr	?
Power	115.0 kW (154 bhp) View specs of the Honda Accord (2008-2013)	?
Curb Weight	1,505 kg	?
Features	Powerful And Responsive 2.0L DOHC I-VTEC Engine, Smooth 5 Speed Auto, ABS, Digital Climate Aircon, Auto Headlights And Rain Sensors, Cruise Control.	?
Accessories	Powerful And Responsive 2.0L DOHC I-VTEC Engine, Smooth 5 Speed Auto, ABS, Digital Climate Aircon, Auto Headlights And Rain Sensors, Cruise Control.	?
Description	1 Year Extended Engine And Gearbox Warranty! Negotiable For Sincere Buyer! Average Mileage. Stock Condition And No Modifications, No Engine Oil Leakage, Original Rims, Firm Undercarriage, Trade In Welcome. Do Not Miss This Chance To Own A Executive Feel Performance Car! Call Us Now To Arrange A Non-Obligated Viewing!	?
COE	-	?
OMV	\$30,444	?
ARF	\$30,444	?
No. of Owners	4	?
Type of Veh	Luxury Sedan	?
Category	COE Car	?
Availability	Available	?

- Add to Shortlist Add to Compare Add a Note



Seller Information

Company	Gen Y Automobile » dealer's pricelist » 18 vehs sold 33 vehs available	
Address	18 Sin Ming Lane #05-08 Search cars nearby this location	
Location	Midview City	
Contact Person(s)	Scott Win	9189499 9896868

Useful Services

- STA VEHICLE INSPECTION** - Afraid of lemons? Request to have this car evaluated professionally. Vehicle Evaluation
- Free Valuation** - Find out the market value for your car. Get a free Car Valuation.

Compare



Receive up to **\$120** CAPITAVOUCHERS Find out more >>

honda accord Price Range Depreciation Year Reg Vehicle Type

Advanced Search

Home » Used Cars » Remy Motor Trading Company » Honda Accord 2.0A (COE till 02/2024)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Vehicle Number Plates



BUY & SELL
Your AUSPICIOUS & UNIQUE Vehicle No.
Do you know? We are Singapore's **BIGGEST PLAYER** with the most vehicle plate numbers for sale!
Click here to see all Auspicious Numbers!

Honda Accord 2.0A (COE till 02/2024)

Overview Financial Insurance Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$38,800	<i>21 month + 13,500</i>
Depreciation	\$7,790 /yr	?
Reg Date	19-Feb-2009 (4yrs 11mths 23days COE left)	
Manufactured	2008	?
Mileage	116,000 km (11.6k /yr)	
Transmission	Auto	
Engine Cap	1,997 cc	
Road Tax	\$1,210 /yr	?
Power	115.0 kW (154 bhp) View specs of the Honda Accord (2008-2013)	
Curb Weight	1,505 kg	?
Features	Powerful And Smooth 2.4 Vtec Engine, 6 x SRS Airbags, Auto Headlights, Retractable Side Mirrors, Paddle Shifters, Steering Controls	
Accessories	Factory Fitted Audio, 6 Speaker System, Multi Function Steering, Reverse Camera, Leather Seats	
Description	One Meticulous Owner, Always Sheltered Car In Best Condition. Low Mileage, Well Maintained, Sporty With Responsive Power Output, Multi Function Steering With Paddle Shifters, Cruise Control, No Major Repair Needed, Road Tax Till 08/2019, Priced To Sell, See To Believe.	
COE	\$15,967	?
OMV	\$30,444	?
ARF	\$30,444	?
Dereg Value	\$15,906 as of today (change)	?
No. of Owners	1	?
Type of Veh	Luxury Sedan	
Category	COE Car	
Availability	Available	

Add to Shortlist Add to Compare Add a Note



Seller Information

Company	Remy Motor Trading Company » dealer's pricelist » 91 vehs sold 10 vehs available
Address	61 Ubi Avenue 2 #03-04 Search cars nearby this location
Location	Automobile Megamart
Office No	64680082
Contact Person(s)	David Koh 9455189 Desmond 9732367 Yeo 9748268 Wayne 9321001

Useful Services

Afraid of lemons? Request to have this car evaluated professionally.

Compare

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0219 - 6896
 Assessment number: OD 0219 - 6896
 Version: 1810
 Date calculated: 02/23/2019 04:01 PM

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary work(s) must be resurveyed and
 is subject to final approval from Insurance Company

Full Report
Registration: SFX66M
Printed: 23/02/2019 4:01 PM

Acknowledged by Repairer
 Signature:
 Date:

Summary Information

Claim
 Location: Singapore (SG)
 Printed by: Ray Lin
 Claim Reference: OD 0219 - 6896
 Estimated Repair Time:
 Actual Repair Days:

Work Provider: AXA Insurance Pte Ltd
 Currency: SGD
 Date of Incident: 2019-02-22
 Hire Car Start:
 Hire Car End:

Steve (LKK) 83228815 *stevchen@lkkauto.com*

26/2/19

Vehicle Details

Vehicle
 Manufacturer: HONDA
 Model: ACCORD (CM/CL)
 Sub Model: BASE MODEL
 Model Sheet Number: 35 54 01
 Registration: SFX66M
 VIN number: MRHCM56505P400634
 Odometer: 219598

Authorise AD at Am
25/2/19 5.45pm
EXCESS - 900
5 days

Model Specs
 FROM MODEL 2006 AIR CONDITIONING FOG LAMPS 2.4 LTR 125KW
 TWO COAT METALLIC PREPARE OFF VEHICLE

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
8101D5	R + R FRONT BUMPER		4.0	18.00
8101A2)	RENEW FRONT BUMPER (REMOVED)		3.0	13.50
8101B1)	R + R FRONT BUMPER CARRIER		6.0	27.00
NO NUMBER	RENEW FRONT NUMBER PLATE (REMOVED)		2.0	9.00
019106	R + R L/F FOGLAMP		3.0	13.50
019107	R + R R/F FOGLAMP		3.0	13.50
8251A0	R + R RIGHT SKIRT - BODYSHELL		5.0	22.50
712102)	R + R HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS		8.0	36.00
813110)	RENEW RADIATOR GRILLE (REMOVED)		2.0	9.00
812100)	R + R BONNET		4.0	18.00
812100)	RENEW BONNET (REMOVED)		3.0	13.50
8121B6)	R + R L/BONNET HINGE		2.0	9.00
8121B7)	R + R R/BONNET HINGE		2.0	9.00
7201B0	R + R L/WING INDICATOR LAMP		1.0	4.50

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0219 - 6896
 Assessment number: OD 0219 - 6896
 Version: 1810
 Date calculated: 02/23/2019 04:01 PM

Full Report
 Registration: SFX66M
 Printed: 23/02/2019 4:01 PM

Code	Description	WU	Price SGD
7421B0)	R + R WASHER RESERVOIR	2.0	9.00
NO NUMBER	R + R RIGHT FRONT WING INCLUDES: R + R RIGHT FRONT INNER WING COVER	5.0	22.50
NO NUMBER	RENEW FRONT PANEL CPL	26.0	117.00
8121B1)	R + R L/FRONT SCREEN FRAME AIR GRILLE	2.0	9.00
8121B1)	R + R R/FRONT SCREEN FRAME AIR GRILLE	2.0	9.00
710100	R + R BATTERY	2.0	9.00
114100)	R + R RADIATOR CPL	6.0	27.00
114100)	RENEW RADIATOR	6.0	27.00
616100)	R + R AIR CONDITIONING CONDENSER	1.0	4.50
620020	REFILL + VENT AIR CONDITIONING	7.0	31.50
0741	L/F WING REPAIR	10.0*	45.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		11.70	117.0
Total of Labour			526.50

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
Paint Work		SYSTEM AZT	
		Time Basis 10WU/h	
	FRT BUMPER SUPPORT SURFACE PAINT	4.0	
	BONNET NEW PART PAINTING	23.0	
	R/F WING NEW PART PAINTING	10.0	
	FRONT PANEL CPL SURFACE PAINT	7.0	
	FRONT BUMPER NEW PART PAINT K1R	12.0	
	L/F WING REPAIR PAINTING <50%	11.0	

Paint Material Per Part

Code	Description	Price SGD
0333	FRT BUMPER SUPPORT SURFACE PAINT ✓	3.74
0471	BONNET NEW PART PAINTING ✓	72.76
0742	R/F WING NEW PART PAINTING ✓	19.61
1009	FRONT PANEL CPL SURFACE PAINT ✓	15.94
0283	FRONT BUMPER NEW PART PAINT K1R ✓	57.56
0741	L/F WING REPAIR PAINTING <50% ✓	12.27

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0219 - 6896
 Assessment number: OD 0219 - 6896
 Version: 1810
 Date calculated: 02/23/2019 04:01 PM

Full Report
 Registration: SFX66M
 Printed: 23/02/2019 4:01 PM

Labour Cost - Paint	Hrs	WU	Price SGD
Factor			45.00 SGD/h
Time Paint		67.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
Total	9.70	97.0	436.50

4700

Material Cost - Paint	Price SGD
New Part Painting	92.37
New Part Painting - Plastic K1R	57.56
Repair Painting	12.27
Surface-/Blend Paint	19.68
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	219.48

47

Spare Parts

Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	KNPL3 X R		0.00
0283	FRONT BUMPER	71101SDET10ZZ	BR	200.00
0317	L/F OUT BUMPER BRKT	71198SDET01	BR	11.00
0318	R/F OUT BUMPER BRKT	71193SDET01	BR NN	11.00
0319	L/F UPP BUMPER BRKT	71190SDAA10	BT	29.00
0320	R/F UPP BUMPER BRKT	71140SDAA10	EX NN	29.00
0333	FRT BUMPER SUPPORT	71130SDCA00	EX NN	190.00
0350	FRT BUMPER CLAMP KIT	USE SINGLE PARTS	X NN Nec	10.00
0410	GRILLE	71121SDJT01ZA	BR	60 90.00
0411	RAD GRILLE COVER	71122SDFT80	EX NN	55.00
0413	L/GRILLE TRIM	71127SDJT01	EX NN	30.00
0414	R/GRILLE TRIM	71122SDJT01	EX NN	30.00
0431	GRILLE BADGE	75700S9AG00	BR	18.00
0471	BONNET	60100SAGH00ZZ	EX DD	450.00
0475	L/BONNET HINGE	60170SDAA00ZZ	X NN	30.00
0476	R/BONNET HINGE	60120SDAA00ZZ	X NN	30.00
0481	BONNET INSULATION	74141SDET00	X NN	65.00
0492	BONNET LOCK	74120SDAA12	EX BT	65.00
0524	BONNET SEAL	74148SDAC00	X NN	15.00
0527	FRONT BONNET SEAL	74121SDAA00	X NN	15.00
0561	L/F HEADLAMP CPL	33151SDAQ11	BR	730 600.00
0562	R/F HEADLAMP CPL	33101SDAQ11	BR	600.00

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0219 - 6896
 Assessment number: OD 0219 - 6896
 Version: 1810
 Date calculated: 02/23/2019 04:01 PM

Full Report
 Registration: SFX66M
 Printed: 23/02/2019 4:01 PM

Code	Description	Part Number	Supplier	Price SGD
0637	L/F FOG LAMP	33951SDEP01	XX NN	200.00
0638	R/F FOG LAMP	33901SDEP01	XX NN	200.00
0742	R/F WING	04620SDAK00ZZ	XR	160.00
0789	L/F WING CLAMP KIT	90108S0A003	X NN	20.00
0790	R/F WING CLAMP KIT	90108S0A003	X NN	20.00
0842	R/WHEELHOUSE SHELL	74101SDET00	X NN	45.00
1009	FRONT PANEL CPL	60400SDFP70ZZ	YR NN	190.00
1436	WASHER RESERVOIR	76840SDET01	X NN	100.00
4464	CONDENSER CPL	80110SDEQ02	00	450.00
7761	RADIATOR	19010RAAA03	? NN	0.00
7767	FAN SHROUD	19015RAAA01	X NN	95.00
7773	LWR RADIATOR HOSE	19502RAFZ00	X NN	28.00
7776	UPPER RADIATOR HOSE	19501RAHH00	✓ NN	28.00
7787	EXPANSION TANK	19101RAAA00	X NN	33.00
7789	L/FAN MOTOR	19030RAAA01	X NN	150.00
7790	R/FAN MOTOR	38616RAAA01	✓ NN	190.00
7793	L/BLOWER FAN	19020PND003	X NN	40.00
7794	R/BLOWER FAN	38611RAAA01	X NN	35.00
9645	HIGH TONE HORN	38150SDBA02	X NN	30.00
9646	LOW TONE HORN	38100SDBA02	X NN	30.00
1000	INSULATOR CLIPS	VALUE	✓ NEC	22.00
1001	BONNET CHROME	VALUE	X FPA NN	0.00
1002	TOP GARNISH CLIPS	VALUE	X FREE NN	16.00
1003	FRT BUMP LWR GARN	VALUE	X NN	45.00
	Savings			0.00
	Subtotal			4,700.00
	Addition(+10.00%)			470.00
	Total			5,170.00

f: OEM Parts
 n: Non-OEM Parts
 u: Used parts

Extras

Code	Description	Price SGD
1004	FRONT NO PLATE ✓ BR	35.00*
1005	AIR CON GAS ✓ NEC	100.00*
1006	AIR CON COOLANT ✓ NEC	20.00*
	Total Extras	155.00

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0219 - 6896
Assessment number: OD 0219 - 6896
Version: 1810
Date calculated: 02/23/2019 04:01 PM

Full Report
Registration: SFX66M
Printed: 23/02/2019 4:01 PM

Final Calculation

	SGD	SGD
Parts	4,700.00	
Addition(+10.00%)	470.00	
Total Parts		5,170.00
Labour Time Base 10 WU/h		
Total 117.0 WU X 45.00 SGD/h	526.50	
Total of Labour		526.50
Total Of Extras		155.00
Paint Work Time Base 10 WU/h		
Labour Cost 97.0 WU X 45.00 SGD/h	436.50	
Material Cost	219.48	
Total Paint Including Material		655.98
Repair Cost Excludes GST		6,507.48
GST (+7.0%)		455.52
Repair Cost Included GST		6,963.00

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0219 - 6896
 Assessment number: OD 0219 - 6896
 Version: 1810
 Date calculated: 04/13/2019 12:49 PM

Full Report
Registration: SFX66M
Printed: 15/04/2019 3:29 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Ray Lin	Currency:	SGD
Claim Reference:	OD 0219 - 6896	Date of Incident:	2019-02-22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	ACCORD (CM/CL)
Sub Model:	BASE MODEL
Model Sheet Number:	35 54 01
Registration:	SFX66M
VIN number:	MRHCM56505P400634
Odometer:	219598

Model Specs

FROM MODEL 2006	AIR CONDITIONING	FOG LAMPS	2.4 LTR 125KW
TWO COAT METALLIC	PREPARE OFF VEHICLE		

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
8101D5	R + R FRONT BUMPER		4.0	18.00
8101A2)	RENEW FRONT BUMPER (REMOVED)		3.0	13.50
019106	R + R L/F FOGLAMP		3.0	13.50
019107	R + R R/F FOGLAMP		3.0	13.50
712102)	R + R HEADLAMPS (BUMPER REMOVED)		8.0	36.00
	INCLUDES: ADJUST HEADLAMPS			
813110)	RENEW RADIATOR GRILLE (REMOVED)		2.0	9.00
812100)	R + R BONNET		4.0	18.00
812100)	RENEW BONNET (REMOVED)		3.0	13.50
812120)	R + R BONNET LOCK		3.0	13.50
7201B0	R + R L/WING INDICATOR LAMP		1.0	4.50
8121B1)	R + R L/FRONT SCREEN FRAME AIR GRILLE		2.0	9.00
8121B1)	R + R R/FRONT SCREEN FRAME AIR GRILLE		2.0	9.00
710100	R + R BATTERY		2.0	9.00
616100)	R + R AIR CONDITIONING CONDENSER		1.0	4.50

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: OD 0219 - 6896
 Assessment number: OD 0219 - 6896
 Version: 1810
 Date calculated: 04/13/2019 12:49 PM

Full Report
 Registration: SFX66M
 Printed: 15/04/2019 3:29 PM

Code	Description	WU	Price SGD
620020	REFILL + VENT AIR CONDITIONING	7.0	31.50
0741	L/F WING REPAIR	10.0*	45.00
0742	R/F WING REPAIR	20.0*	90.00
1009	FRONT PANEL CPL REPAIR	20.0*	90.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		9.80	98.0
Total of Labour			441.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT	4.0
	BONNET NEW PART PAINTING	23.0
	FRONT BUMPER NEW PART PAINT K1R	12.0
	L/F WING REPAIR PAINTING <50%	11.0
	R/F WING REPAIR PAINTING <50%	11.0
	FRONT PANEL CPL SURFACE PAINT	7.0

Paint Material Per Part

Code	Description	Price SGD
0333	FRT BUMPER SUPPORT SURFACE PAINT	3.74
0471	BONNET NEW PART PAINTING	72.76
0283	FRONT BUMPER NEW PART PAINT K1R	57.56
0741	L/F WING REPAIR PAINTING <50%	12.27
0742	R/F WING REPAIR PAINTING <50%	12.27
1009	FRONT PANEL CPL SURFACE PAINT	15.94

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		68.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
Total	10 WU/h	98.0	441.00