

ASS. REC. BY:

REF

CS3/AIG19003499/Bcd342

Serial Instruction:

Surveyor:

Mr. Jim

ASSIGNMENT (Office)

From (Person):

Meridian

Chin Lee King

of

AIG

Date/Time: 25/2/19 @ 12-02pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

812 79972

Insured:

SMG 5414R

at Workshop m/s

SAT Motor

Tel:

9126 9957

of

24 Defu June 12

Policy No:

1900005328

Claim No:

7980298324SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/02/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:12pm 25/2/19

Person Contacted:

JERRY

Vehicle

IN/OUT

Date/Time

Action/Instruction (X) Estimate

812 79972 -X

SMG 5414R -X

After repair: 14/3/2019

REF: AIG

ASSIGNMENT

From:

Date: 25/2/19

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SJZ 7997Y

at Workshop m/s Sat Motors

of 24 Defu Lane 12

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SJZ 7997Y

Yr Regn: 20/5/2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 535 3.0L

C.C 2979

Colour

GREY/Red wrap

A/C: Insured / Std / NI / NA

Sp. Reading

135484

T/Radio: Insured / Std / NI / NA

Eng/No:

10787399N55B30A

C/No:

WBAFR72050C264767

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 285/30/20

R: 285/30/20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/2/19

D.O.I.

25/2/19

Survey held at

Sat Motors

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV 53,000/2

PV 38,247/2

NW 14,753/2

Trim in
28/2/19

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

180

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

190

Report Format :

DAR

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 25/2/2019 12:02:17 PM
Attachments:  PRI-SJZ7997Y(SAT).pdf

Hi LKK,

Kindly assist to survey. Vehicle in.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Our Ref : CY.SJZ7997Y.19.SAT.wp

Your Ref : Your insured vehicle **SMG 5414R**

21 February 2019

Kalla Xu Ping
c/o The Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

By Fax No: 6835 7416

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES
ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SJZ 7997Y & SMG 5414R ON
19.02.2019 @ 18:45HRS ALONG PIE TOWARDS CHANGI**

We are instructed by Fengplus Trading Pte Ltd to notify you of a road traffic accident on 19.02.2019 @ 18:45hrs along PIE towards Changi involving our client's vehicle no. SJZ 7997Y and vehicle no. SMG 5414R driven by you at the material time. A copy of the Singapore accident statement report is enclosed.


As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

At the same time, our proposed list of surveyors is appended as below:

1. Lim Chang Liang
2. Lim Yong Tian, Sebastian

As the appointed workshop is a small workshop, we are unable to provide you with more than the above listed motor surveyors. We trust you will able to choose a surveyor from above.

Yours faithfully,


C. Yogarajah LLC
Enc

cc: M/s. SAT Motors
24 Defu Lane 12, Singapore 539131
Jonathan (9126 9987) / Jessie (9859 9677)
Fax No. 6749 1141

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5559M
Vehicle Details	
Vehicle No.:	SJZ7997Y
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2019
Vehicle Make:	B.M.W.
Vehicle Model:	535i 3.0L AT D/AB 2WD 4DR GAS/D SR HUD
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	10787399N55B30A
Chassis No.:	WBAFR72050C264767
Maximum Power Output:	225.0 kW (301 bhp)
Open Market Value:	\$61,666.00
Original Registration Date:	20 May 2010
First Registration Date:	20 May 2010
Transfer Count:	1
Actual ARF Paid:	\$61,666.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 May 2020
PARF Rebate Amount:	\$33,916.00
Intended COE Rebate Details	
COE Expiry Date:	19 May 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$4,331.00
Total Rebate Amount:	\$38,247.00

The information contained herein is correct as at 28 Mar 2019

OK

COE 1 yr 2 mths

Aug dep 18,000/yr
1500/mth

MV 53,000/2

PV 38,247/2

NV 14,753/2



ANNOUNCING Autolink Holdings as sgCarMart Premium Dealer 2019

AUTOLINK HOLDINGS

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Citroen Berlingo 1.6A BlueHDi.



1 Owner, Low Mileage, Full
Service Maintained, Still Under
3 Year Warranty.
Direct Owner

**Lake View
Credit Pte Ltd**

view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Date Posted








20 results/page

18 vehicles

BMW 535i

Advanced Search



	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status	
Search Selection	BMW 535i	Any	Any	2010	Any	Any	All	
	BMW 5 Series 535i	-	N.A	31-May-2010	2,979 cc	-	Luxury	SOLD
High PARF. High Body Value. 10% Down Available. Don't Miss.								
Posted: 19-Feb-2019 Tags: 2010 BMW 535i, 2010 bmw 535i, BMW 535i, bmw 535i, BMW, 535i, Used BMW								
	BMW 5 Series 535i	\$56,500	\$20,640 /yr	07-Jun-2010	2,979 cc	112,000 km	Luxury	Available
Full Service Done. New Throttle Body, New High Pressure Fuel Pump, New Shock Absorbers, New Bushings, New Brake Disc And Brake Pads, All Gaskets Changed. New Gearbox Filter And Oil. Zero Oil Leaks, Ze...								
Posted: 07-Feb-2019 Tags: 2010 BMW 535i, 2010 bmw 535i, BMW 535i, bmw 535i, BMW, 535i, Used BMW								
	BMW 5 Series 535i Sunroof (New 10-yr COE)	-	N.A	01-Jul-2010	2,979 cc	-	Luxury	SOLD
Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.								
Boeki Auto & Marine								
Posted: 16-Mar-2019 Tags: 2010 BMW 535i, 2010 bmw 535i, BMW 535i, bmw 535i, BMW, 535i, Used BMW								
	BMW 5 Series 535i Sunroof	\$51,800	\$15,270 /yr	30-Jul-2010	2,979 cc	126,553 km	Luxury	Available
Taken Care Of By A Very Careful And Picky Owner, This Vehicle Has Been Serviced Regularly And Is In Immaculate Condition Of It's Drive! Hurry Now To Take A Look At This Beautiful And Raging Bull Which...								
Wheeler Dealers 2018 Pte Ltd								
Posted: 07-Mar-2019 Tags: 2010 BMW 535i, 2010 bmw 535i, BMW 535i, bmw 535i, BMW, 535i, Used BMW								
GET YOUR COE RENEWAL LOAN								
Is your COE expiring? Let us help you renew it!								
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	BMW 5 Series 535i Sunroof	-	N.A	03-Aug-2010	2,979 cc	-	Luxury	SOLD
Carway								
Posted: 05-Jan-2019 Tags: 2010 BMW 535i, 2010 bmw 535i, BMW 535i, bmw 535i, BMW, 535i, Used BMW								
	BMW 5 Series 535i	-	N.A	06-Aug-2010	2,979 cc	-	Luxury	SOLD
Very Well Maintained By Previous Owner, Buy With A Piece Of Mind! No Repair Needed, Best Among All The F10 Series! Power And Comfort Will Never Be Compromised! Trade In, Insurance And Various Loan Pac...								
Karz Automobile								
Posted: 13-Jan-2019 Tags: 2010 BMW 535i, 2010 bmw 535i, BMW 535i, bmw 535i, BMW, 535i, Used BMW								
	BMW 5 Series 535i Sunroof	-	N.A	19-Aug-2010	2,979 cc	-	Luxury	SOLD
Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only.								
Carro								
Posted: 24-Jan-2019 Tags: 2010 BMW 535i, 2010 bmw 535i, BMW 535i, bmw 535i, BMW, 535i, Used BMW								

CONSIGNMENT

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/02/2019 16:02
Date Of Accident	19/02/2019 18:45
Exact Location Of Accident	PIE TWDS CHANGI AT EXIT 13
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJZ7997Y
Insured/Policyholder	
Name Of Registered Owner	FENGPLUS TRADING PTE LTD
Co Reg No	199905559M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81392151
Vehicle Particulars	
Manufacturer	BMW
Model	535I 3.0L AT D/AB 2WD 4DR GAS/D SR HUD
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPG18005000
Cover Note Number	20/11/2018 TO 19/11/2019
Driver	
Name of Driver	JOSEPH FONG CHIN WEI
NRIC No	S7640477A
Date Of Birth	18/12/1976
Occupation	OUTDOOR
Date Of Driving Pass	29/05/1996
Driving Experience	22 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81392151
Fax Number	
Contact Number	
EMail Address	JOSEPH.FONG@ROCKETMAIL.COM

Address APT BLK 139A LORONG 1A TOA PAYOH #31-48 (S) 311139

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Vehicle -

Insurance Company of Driver's Own Vehicle -

-

-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMG5414R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

20.2.2019
@ 1534h



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


Accident Sketch Plan Pg. 1

SKETCH PLAN

PIE TOWARDS CHANGI

A: S1Z79974

B: SM65414R



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG PIE TOWARD TUAS AND TRAFFIC WAS HEAVY.
I CAME TO A HALT DUE TO TRAFFIC AND SUDDENLY I FELT IMPACT
TO THE REAR OF MY CAR. I REALISED VEHICLE B SM65414R
REAR ENDED MY VEHICLE BEARING CAR PLATE S1Z79974.

ERGO	
Policy No. S1Z79974	Date of Accident 19-3-2019
<input type="checkbox"/> Reporting Only <input type="checkbox"/> Own Damage Claim <input checked="" type="checkbox"/> Third Party Claim <input checked="" type="checkbox"/> Joint Insurance	
SAT MOTORS	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

MOTORCAR (Rear)

Rear Portion

Vehicle No:

SJZ 7997Y

NAC	INC	Item	CON	ACQ	QTY
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CUT ✓		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC ✓	6	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer		2	
1149	993045	Rear Bumper Reinforcement		2	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge		1	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler	CUT ✓		
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	ACQ	QTY
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
* Bump is using wrapping					

No of Items: 1

Assessor: T. G. Lim

28/3/19

...CLAIM SUBFOLDER...(Pending for Survey Report)






































PRI










CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Feb 2019 Edit Reg		25 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: KAILA XU PING , Co. Reg. No.: -									
Main Claimant: FENGPLUS TRADING PTE LTD , Co. Reg. No.: 199905559M									
Vehicle Reg. No.: SJZ7997Y		Date of Loss: 19/02/2019 18:00 - :59 [104 Months and 30 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7980298324SG		Policy/Cover Note No.: 1900005328							
Vehicle Reg. No. (Insured): SMG5414R		Policy No. (Claimant):							
		Excess:							
Repairer: Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 06/03/2019]									
Claimant's Solicitor: C YOGARAJAH LLC - Tel: 62925838									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (26/02/2019): TP GIA REPORT AIG_SG (26/02/2019): NO OI GIA REPORT 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJZ7997Y (7980298324SG)
[SMG5414R]
TP
FENGPLUS TRADING PTE LTD
Feb 19 2019 6:00PM
[KAILA XU PING]
Sat Motors

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print		
1	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
2	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
3	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
4	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
5	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
6	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
7	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
8	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
9	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
10	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
11	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
12	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
13	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
14	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
15	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
16	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
17	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
18	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
19	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
20	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
21	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
22	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
23	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
24	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
25	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
26	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
27	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
28	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
29	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
30	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
31	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
32	02/04/19 17:24	General View										Load JPG	<input checked="" type="checkbox"/>	
33	02/04/19 17:24	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
34	02/04/19 17:24	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
35	02/04/19 17:24	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
36	02/04/19 17:24	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	
37	02/04/19 17:24	Photo After Spray										Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	02/04/19 17:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	02/04/19 17:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	02/04/19 17:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	02/04/19 17:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	02/04/19 17:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	02/04/19 17:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	02/04/19 17:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	02/04/19 17:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	02/04/19 17:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG19003499/BCD3E2**Date:** 03/04/2019REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1900005328

Claimant Vehicle No : SJZ7997Y**Insured Vehicle No :** SMG5414R

Date of Loss: 19/02/2019

Nature of Claim: TP

Claim No: 7980298324SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJZ7997Y**

Make & Model: BMW 535I GT, 3.0 D/AB 2WD GAS/D TC HUD SR (A)

Engine No: 10787399N55B30A

Reg. Date: 20/05/2010 (Man. Year: 2010)

Chassis No: WBAFR72050C264767

Colour: Red/Grey

Odometer: 135484 km

Engine Capacity: 2979 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 285/30 R20

Rear Tyre Size: 285/30 R20

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/02/2019

Date Inspected: 25/02/2019

Inspected At:

Sat Motors (HQ)
24 Defu Lane 12
Singapore 539131

Estimated Period of Repair: 3.0 days

Adjuster: Lim Teow Guan**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	0.00 F	*- F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	* Check	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	* Check	0.00 F	*- F
5	1		*REAR BUMPER SPONGE	* Check	0.00 F	*- F
6	1		*REAR BUMPER LOWER SPOILER	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >