




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                     |  |  |                       |   |
|---|--|--|-----------------------|---|
| -   |  | Ref : CS/TP19003537/T1qd3s2              |                       |   |
| MUHD NUR HADI BIN MOHD GHAZALI<br>BLK 693C WOODLANDS AVE 6<br>#11-765SINGAPORE 733693 |  | Date : 27-11-2019                        |                       |  |
|   |  | Code : TP2                               |                       |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                     |  |  |                       |   |
|   | Insured Veh.   | Veh. Inspected                           | FBK 7686T             |   |
|   | Policy No.   | Coverage (\$)                            | 0.00                  |   |
|   | Claim No.  | Excess (\$)                              | 0.00                  |   |
|   | Assign From  | Assign Date                              | 14/02/2019            |   |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |  |                       |   |
|   | Make & Model   | PIAGGIO GILERA RUNNER                    | c.c                   | 198   |
|   | Engine No.   | HIDDEN                                   | Year of Reg.          | 2013  |
|   | Chassis No.  | ZAPM4640100007046                        | Colour                | BLUE  |
|   | Odometer   | -  | Steering              | IN ORDER  |
|   | Brakes   | IN ORDER                                 | Modification          | NIL   |
|   | General  | GOOD                                     |                       |   |
| <b>3. Conditions of Tyres</b>   |  |  |                       |   |
|   |  | Size                                     | Make                  | Balance   |
|   | R/H Front Tyre   | 120/70R14                                | METZELER              | 4 mm  |
|   | L/H Front Tyre   |  |                       | mm  |
|   | R/H Rear Tyre  | 140/60-13                                | MICHELIN              | 4 mm  |
|   | L/H Rear Tyre  |  |                       | mm  |
| <b>4. Description of Damages</b>  |  |  |                       |   |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.<br>DAMAGES SEE DETAILS.   |  |                       |   |
| <b>5. General Information</b>   |  |  |                       |   |
|   | Accident Date  | 27/12/2018                               | Inspection Date       | 14/02/2019  |
|   | Survey held at   | 25 KAKI BUKIT ROAD 4 #01-83 SYNERGY @ KB |                       |   |
|   | Repairer   | A.S. PHOON PTE LTD                       |                       |   |
| <b>5a. Remarks</b>  |  |  |                       |   |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                       |   |
| <b>5b. Estimate Days of Repair</b>  |  |  |                       |   |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | <b>3 Working Days</b> |   |