

2019/00001

ASS. REC. BY:

REP

CS3/SMO19003555/End32

Instruction

SA/VEH/V

Adrian

ASSIGNMENT (Office)

From (Person)

Thelma Choo

of

SMO

Date/Time

3:33pm @ 25/2/19

Estimated Cost:

Bill to:

OD (TD) / WS / TP RES / OD RES / EVA / INV / MVTCS

To Inspect Vehicle No.

SMF 8529D

Insured:

GBH 8241C

at Workshop n/s

Paul Hoe Batteries

Tel:

9623 5068

of

1 Kaki Bkt Ave 6 # 01-109

Policy No:

D17MTHCVE000063

Claim No:

CMTD1901065

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:15am @ 26/2/19

Person Contacted:

paul

Vehicle

IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SMF 8529D - NA/INC19003433/HT Don: 23/2/2019.
	GBH 8241C - X.
	Dismantle: 28/2/2019

REF:

ASSIGNMENT

From _____ Date: _____
 Estimated Cost _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

at Workshop m/s

of

Insured

Policy No

Claims No

Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

SMF 85290

Ti Regn

27/05/16

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ~~to~~ Audi A3

CC 1395

Colour ~~PE~~ Black

A/C Insured / Std / NI / NA

Sp. Reading 52210

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W4 2228VXG 108 9921

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil ☒ S/Rim / STD A/Rim or

Tyre Size: F:

225/40ZR18

R:

/1

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

23/2/19

D.O.J.

26/2/19

Survey held at

Paul Hoe

Des. of Damages: ☒ Frl / ☒ Rear / O/S / N/S / U/C / Rooftop or

Interior,

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

MV - 80,000

PV - 47,141

NV - 32,859

Repa. range 30K - 31K, 18 days

RECEIVED 25 MAR 2019

26/3/2019

Date/Time. File Pass to?

☐

: Preli. Report

4)

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair: 18

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + R5 04

) Photos

) Collect

) 12

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format: PRO

Lump Sum / I.B.I. (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Feb 2019		25 Feb 2019 15:33 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		[Created by insurer]	
Main Claimant:	HO HAN MENG, ID: S7930630D			
Vehicle Reg. No.:	SMF8529D	Date of Loss:	23/02/2019 11:00 - :59	
Claim Type:	TP / CMTD1901065	Policy/Cover Note No.:	D17MTHCVE000063 (Third Party Only)	
Vehicle Reg. No. (Insured):	GBH8241C	Policy No. (Claimant):		
		Excess:		
Repairer:	Paul Hoe Batteries & Motor Services (HQ) 1 KAKI BUKIT AVE 6 #01-109, 417883 Kaki Bukit - Tel:			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/03/2019]			
Driver/Custodian (Insured):	TAN HIAP WAH (), NRIC: S7036828E, Tel: +6596469116 Email:			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

ONG & SHAN LLC

ADVOCATES & SOLICITORS
COMMISSIONERS FOR OATHS
NOTARIES PUBLIC

Our Counter-Signatory's Email Notifications:
Lawyer : ongshan@ongshanllc.com
Secretary :

CMTD1901065/THE

Please send all correspondences to:

- ☐ 2 Kallang Avenue #08-19 Singapore 339407
Tel: 6444 7845 | Fax: 6444 5847
- ☐ 101 Upper Cross Street #06-15B Singapore 058357
Tel: 6536 7991 | Fax: 6536 7995
- ☒ 184 Toa Payoh Central #02-364 Singapore 310184
Tel: 6224 9847 | Fax: 6254 7261

WE DO NOT ACCEPT SERVICE BY FAX

Our Ref : SRSTP.8396A.19.CM

Your Ref : Your insured vehicle GBH8241C

25th February 2019

ETHOZ Group Ltd
c/o Sampo Insurance Pte Ltd
(Motor Claims Department)
80 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

Sampo Insurance Singapore Pte. Ltd.	
Claims	
25 FEB 2019	

BY FAX 6221-3147

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)
ROAD TRAFFIC ACCIDENT INVOLVING SMF 8529D/GBH 8241C & SKX 8358J ON 23.02.2019 ALONG
CLEMENTI AVE 2 TOWARDS CLEMENTI ROAD NEAR BLK 331 @ 1155 HRS**

We act for Mr. Ho Han Meng the owner of motor vehicle SMF 8529D, who has appointed the under-mentioned workshop to repair his motor vehicle.

Name of workshop : M/s Paul Hoe Batteries & Motor Services
Address : 1 Kaki Bukit Ave 6 #01-109 Singapore 417883
Contact person : Mr. Paul Tan (Ah Hoe)
Telephone no : 9623-5068
Fax no : 6747-6918

We hereby give you 2 clear days' notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours. (Please contact Mr. Paul Tan to confirm the date and time of your inspection).

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days (excluding any intervening Saturday, Sunday and/or Public Holiday) you will be deemed to have waived your rights to a pre-repair inspection. The above-mentioned workshop will commence repairs thereafter without further notice to you. They will also be entitled to claim for the additional loss of use /rental (including any intervening Saturday, Sunday and/or Public Holiday) arising as a consequence of this notification.

Yours faithfully,

Ong & Shan LLC

cc: M/s Paul Hoe Batteries & Motor Services (67476918)

For Surveyor

Please initial here after completion of pre-repair inspection.
Thank you.

Name:
Signature:

Date & Time of Pre-repair inspection: /

ONG & SHAN LLC

A LIMITED LIABILITY CORPORATION | COMPANY REGISTRATION NUMBER 201408968D

THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY & MAY CONTAIN CONFIDENTIAL INFORMATION &/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2019 11:28
Date Of Accident	23/02/2019 11:55
Exact Location Of Accident	CLEMENTI AVE 2 TWDS CLEMENTI RD NEAR BLK 331
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF8529D
Insured/Policyholder	
Name Of Registered Owner	HO HAN MENG
NRIC No	S7930630D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97965174
Alternative Phone No	OFFICE-97965174

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.4 TFSI (ATTRACTION)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106364260
Cover Note Number	-

Driver

Name of Driver	HO HAN MENG
NRIC No	S7930630D
Date Of Birth	30/09/1979
Occupation	OUTDOOR
Date Of Driving Pass	21/10/2002
Driving Experience	16 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97965174
Fax Number	
Contact Number	OFFICE-97965174
Email Address	NOEMAIL

Address	BLK 513 WEST COAST RD #04-465
Postcode	120513
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (Including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : HENG KAY WEE ALVIN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: NO. 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8729999 - FAX NO: 67748639
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH TP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH8241C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKX8358J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

HO HAN MENG

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SMF8529D

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

HENG KAY WEE ALVIN

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SMF8529D

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

BK331



A = SMF 85290
B = GBH 8241C
C = SKX 8358J

Clementi Ave 2

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190223/2076

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

1 of 4

Report No. T/20190223/2076

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/02/2019 14:06		Vide Report No.: D/20190223/0064		Station Diary No.: 93	
Informant's Particulars					
Name of Informant: HO HAN MENG			Address: APT BLK 513 WEST COAST ROAD #04-465 SINGAPORE 120513		
ID Type / ID No.: NRIC NO / S7930630D			Contact No.: Home/Office: Mobile: 97965174		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 39	Date of Birth: 30/09/1979	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Sales			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 23/02/2019 11:55	Type of Location: Straight Road
Location: Along Road 1 CLEMENTI AVENUE 2 CLEMENTI AVENUE 2 Along Clementi Ave 2 heading towards Clementi Rd, near Blk 331 Clementi Ave 2.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBH8241C	Van				Slightly Damaged	0
SKX8358J	Car				Slightly Damaged	1
SMF8529D	Car	AUDI	A3 SEDAN 1.4 TFSI (ATTRACTI ON)	Black	Seriously Damaged	1



**SINGAPORE
POLICE FORCE**



T/20190223/2076

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

2 of 4

Report No. T/20190223/2076

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMF8529D	NTUC Income Insurance Co-Operative Limited	5106364260	15/12/2018	14/12/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
Driver				
Name	HO HAN MENG	ID No.	S7930630D	
Related Vehicle	SMF8529D (Car)	Contact No.	97965174	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight	
Passenger				
Name	HENG KAY WEE ALVIN	ID No.	S7727446D	
Related Vehicle	SMF8529D (Car)	Contact No.	88080526	
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	23/02/2019	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious	

Brief Details.

On 23/02/2019 at about 1150hrs while I was driving SMF8529D on the left of two lanes road along Clementi Ave 2 heading towards Clementi Rd, a white BMW SKX8358J which was ahead of me slowed down as the car ahead is turning left into an open space HDB carpark. I follow suite and slowed down my car as well. While my car and SKX8358J had stopped, due to the vehicles in front turning left, suddenly my car got hit by a vehicle behind car and it resulted my car to move forward and collided my front into the rear of SKX8358J.

The collision caused me to blur for few seconds. I then stepped of my car and called for the police and ambulance. Upon ambulance arrival, my friend was assessed to have laceration on his forehead. Therefore, he was conveyed to National University Hospital. The other drivers and passenger involved was not conveyed.

The vehicle that had collided into my rear is a van GHB8241C. I exchanged particulars with the two drivers and did not gather much facts on how the collision happened. Paramedic had medically assessed



**SINGAPORE
POLICE FORCE**



T/20190223/2076

Police Station Of Origin:

Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999

3 of 4

Report No. T/20190223/2076

CONTINUATION OF REPORT

me. I have informed both traffic police officer and paramedic that I will be going to the nearest hospital after I had lodge a traffic accident report.



**SINGAPORE
POLICE FORCE**



T/20190223/2076

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

4 of 4

Report No. T/20190223/2076

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

D /

Sgt 3 IBNU MUSALLI BIN HAMID

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt LEE GUANG HUI

Contact No.: 65476138

Signature Of Informant:

Date/Time:

23/02/2019 14:06

Classification Of Case:

Authentication Stamp

NP168



> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SMF8529D		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	AUDI		
Vehicle Model :	A3 SEDAN 1.4 TFSI (ATTRACTION)		
Chassis No. :	WAUZZZ8VXG1089921		
Propellant :	Petrol		
Engine No. :	CZC540620		
Engine Capacity :	1395 cc		
Maximum Power Output :	92.0 kW (123 bhp)		
Maximum Laden Weight :	1785 kg		
Unladen Weight :	1310 kg		
Year Of Manufacture :	2016		
Original Registration Date :	27 May 2016		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$47,300.00		
COE Expiry Date :	26 May 2026		
Road Tax Expiry Date :	26 May 2019		
PARF Eligibility Expiry Date :	26 May 2026		
Inspection Due Date :	26 May 2019		
Intended Transfer Date :	26 Feb 2019		
CO2 Emission :	116.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$10,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 26 May 2019. You may renew the road tax from 27 Feb 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 26 May 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 27 May 2019 to 26 Nov 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	312.00	-	312.00
Total Amount Payable :			337.00
Amount Payable (From 27 May 2019 to 26 May 2020)			

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	624.00	-	624.00
Total Amount Payable :			649.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0630D
Vehicle Details	
Vehicle No.:	SMF8529D
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.4 TFSI (ATTRACTION)
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	CZC540620
Chassis No.:	WAUZZZ8VXG1089921
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$25,095.00
Original Registration Date:	27 May 2016
First Registration Date:	27 May 2016
Transfer Count:	1
Actual ARF Paid:	\$17,133.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 May 2026
PARF Rebate Amount:	\$12,849.00
Intended COE Rebate Details	
COE Expiry Date:	26 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$34,292.00
Total Rebate Amount:	\$47,141.00

The information contained herein is correct as at 26 Feb 2019

OK

- Pioneer AVH-Z9150BT
- Accident Advice
- A level results for University Courses

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years COE Renewal Toyota Estima 2.4A.



2.38% P.A Low-Interest At GV
Finance. \$0 Admin Fees,
Monthly \$968!
GV Credit Pte Ltd StarAd

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

« Back (1 2) Next »







Sort by Date Posted

20 results/page

21 vehicles

Audi A3

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Audi A3		Any	Any	2016	Any	Any	Any	Availabl
	Audi A3 Sedan 1.4A TFSI Attraction		\$84,800	\$10,370 /yr	04-Jul-2016	1,395 cc	27,058 km	Luxury	Availabl
Comes With Agent Warranty Till July 2019 For Peace Of Mind! Suave And Sophisticated A3 Sedan Powered By A Responsive And Frugal 1.4L TFSI Engine And Mated To A 7 Speed DSG Giving A Powerful Daily Driv...									
Select By Performance Premium Selection									
Posted: 26-Feb-2019 Tags: 2016 Audi A3, 2016 audi a3, Audi A3, audi a3, Audi, A3, a3, Used Audi									
	Audi A3 Sedan 1.4A TFSI Attraction		\$79,800	\$9,610 /yr	25-Jul-2016	1,395 cc	-	Luxury	Availabl
Benefit Auto Offer Best Deal In Market! Offer Best Price! Offer Best Price For Trade In! Offer Best Interest Rate With High Loan! Hurry Arrange Call To Our Sales For Appointment!									
Benefit Auto Enterprise Pte Ltd									
Posted: 26-Feb-2019 Tags: 2016 Audi A3, 2016 audi a3, Audi A3, audi a3, Audi, A3, a3, Used Audi									
	Audi A3 Sedan 1.4A TFSI Attraction		\$90,000	\$11,220 /yr	30-May-2016	1,395 cc	20,000 km	Luxury	Availabl
1 Owner! Very Low Mileage! Audi Warranty Till June 2019! Full Audi Service History! Upgraded 17 Inch Rims! With Reverse Camera! 100% Accident Free!									
Posted: 25-Feb-2019 Tags: 2016 Audi A3, 2016 audi a3, Audi A3, audi a3, Audi, A3, a3, Used Audi									
	Audi A3 Sedan 1.4A TFSI Ambiente		\$82,999	\$10,550 /yr	16-Jan-2016	1,395 cc	71,000 km	Luxury	Availabl
18" Aftermarket Rims! 5 Years Audi Agent Warranty Option Till January 2021! High In House Loan Approval! Fully Audi Agent Servicing Since Day One! One Owner! Lowest Bank Interest Rate 2.48%. Showroom ...									
Premium Automobiles									
Posted: 23-Feb-2019 Tags: 2016 Audi A3, 2016 audi a3, Audi A3, audi a3, Audi, A3, a3, Used Audi									
	Mirror Covers								
Audi and Volkswagen Mirror cover from \$168									
More info about this product									
	Audi A3 Sedan 1.4A TFSI Attraction		\$89,999	\$10,750 /yr	24-Sep-2016	1,395 cc	26,461 km	Luxury	Availabl
Lowest Mileage Attraction Model! 5 Years Audi Agent Warranty Option Till September 2021! 90% Loan Approval! High In-House Loan Approval! Fully Audi Agent Servicing Since Day One! One Management Owner!...									
Premium Automobiles									

Compare

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main:	25 Feb 2019		25 Feb 2019 15:33 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ETHOZ GROUP LTD , Co. Reg. No.: 198104531H		
Main Claimant:	HO HAN MENG , ID: S7930630D		
Vehicle Reg. No.:	SMF8529D	Date of Loss:	23/02/2019 11:00 - :59 [32 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1901065	Policy/Cover Note No.:	D17MTHCVE000063 (Third Party Only)
Vehicle Reg. No. (Insured):	GBH8241C	Policy No. (Claimant):	
		Excess:	
Repairer:	Paul Hoe Batteries & Motor Services (HQ) 1 KAKI BUKIT AVE 6 #01-109, 417883 Kaki Bukit - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 06/03/2019]		
Driver/Custodian (Insured):	TAN HIAP WAH (), NRIC: S7036828E, Tel: +6596469116 Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMF8529D (CMTD1901065)**
[GBH8241C]

TP

HO HAN MENG

Feb 23 2019 11:00AM

[ETHOZ GROUP LTD]

Paul Hoe Batteries & Motor Services

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports
































1 per page ▼ ☒

No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	25/02/19 15:32	Accident Statement From: SC - Reg. No: GBH8241C, Claimant: ETHOZ GROUP LTD	Load HTM	
















Photos/Images
























3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
2	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
3	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
4	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
5	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
6	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
7	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
8	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
9	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
10	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
11	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
12	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
13	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
14	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
15	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
16	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
17	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
18	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
19	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
20	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
21	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
22	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
23	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
24	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
25	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
26	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
27	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
28	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
29	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
30	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>
31	27/02/19 08:13	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte, Ltd. (HQ)	Thumbnail	Print
32	27/02/19 08:13	General View	 Load JPG	✓
33	27/02/19 08:13	General View	 Load JPG	✓
34	27/02/19 08:13	General View	 Load JPG	✓
35	27/02/19 08:13	General View	 Load JPG	✓
36	27/02/19 08:13	General View	 Load JPG	✓
37	27/02/19 08:13	General View	 Load JPG	✓
38	27/02/19 08:13	General View	 Load JPG	✓
39	27/02/19 08:13	General View	 Load JPG	✓
40	27/02/19 08:13	General View	 Load JPG	✓
41	27/02/19 08:13	General View	 Load JPG	✓
42	27/02/19 08:13	General View	 Load JPG	✓
43	27/02/19 08:13	General View	 Load JPG	✓
44	27/02/19 08:13	General View	 Load JPG	✓
45	27/02/19 08:13	General View	 Load JPG	✓
46	27/02/19 08:13	General View	 Load JPG	✓
47	27/02/19 08:13	General View	 Load JPG	✓
48	27/02/19 08:13	General View	 Load JPG	✓
49	27/02/19 08:13	General View	 Load JPG	✓
50	27/02/19 08:13	General View	 Load JPG	✓
51	27/02/19 08:13	General View	 Load JPG	✓
52	27/02/19 08:13	General View	 Load JPG	✓
53	27/02/19 08:13	General View	 Load JPG	✓
54	27/02/19 08:13	General View	 Load JPG	✓
55	27/02/19 08:13	General View	 Load JPG	✓
56	27/02/19 08:13	General View	 Load JPG	✓
57	27/02/19 08:13	General View	 Load JPG	✓
58	27/02/19 08:13	General View	 Load JPG	✓
59	27/02/19 08:13	General View	 Load JPG	✓
60	27/02/19 08:13	General View	 Load JPG	✓
61	27/02/19 08:13	General View	 Load JPG	✓
62	27/02/19 08:13	General View	 Load JPG	✓
63	27/02/19 08:13	General View	 Load JPG	✓
64	27/02/19 08:13	General View	 Load JPG	✓
65	27/02/19 08:13	Odometer Reading	 Load JPG	✓
66	27/02/19 08:13	Chassis Number	 Load JPG	✓
67	27/02/19 08:13	General View	 Load JPG	✓
68	27/02/19 08:13	General View	 Load JPG	✓
69	29/03/19 11:56	Photographs of Damaged Parts	 Load JPG	✓
70	29/03/19 11:56	Photographs of Damaged Parts	 Load JPG	✓
71	29/03/19 11:56	Photographs of Damaged Parts	 Load JPG	✓
72	29/03/19 11:56	Photographs of Damaged Parts	 Load JPG	✓
73	29/03/19 11:56	Photographs of Damaged Parts	 Load JPG	✓
74	29/03/19 11:56	Photographs of Damaged Parts	 Load JPG	✓
75	29/03/19 11:56	Photographs of Damaged Parts	 Load JPG	✓
76	29/03/19 11:56	Photographs of Damaged Parts	 Load JPG	✓
77	29/03/19 11:56	Photographs of Damaged Parts	Load JPG	✓
78	29/03/19 11:56	Photographs of Damaged Parts	Load JPG	✓
79	29/03/19 11:56	Photographs of Damaged Parts	Load JPG	✓

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
80	29/03/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	29/03/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	29/03/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	29/03/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	29/03/19 11:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	29/03/19 11:57	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
128	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
129	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
130	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
131	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
132	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
133	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
134	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
135	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
136	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
137	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
138	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
139	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
140	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
141	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
142	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
143	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
144	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
145	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
146	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
147	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
148	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
149	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
150	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
151	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
152	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
153	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
154	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
155	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
156	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
157	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
158	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
159	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
160	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
161	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
162	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
163	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
164	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
165	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
166	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
167	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
168	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
169	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
170	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
171	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
172	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
173	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
174	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
175	29/03/19 11:57	Photographs of Damaged Parts	Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
176	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
177	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
178	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
179	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
180	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
181	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
182	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
183	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
184	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
185	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
186	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
187	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
188	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
189	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
190	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
191	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
192	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
193	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
194	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
195	29/03/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	25/02/19 14:28	PRI FAX FR ONG & SHAN LLC - SMF8529D	 Load PDF	
2	25/02/19 15:06	Third Party E-filed GIA report(M)	 Load PDF	
3	25/02/19 15:34	Pre-Repair Survey - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19003555/ECD3S2
Date: 01/04/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D17MTHCVE000063
Claimant Vehicle No :	SMF8529D	Insured Vehicle No :	GBH8241C
Date of Loss:	23/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1901065

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF8529D	Engine No:	CZC540620
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (ATTRACTION) (A)	Chassis No:	WAUZZZ8VXG1089921
Reg. Date:	27/05/2016 (Man. Year: 2016)	Odometer:	52210 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40ZR18	Rear Tyre Size:	225/40ZR18
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	25/02/2019	
Date Inspected:	26/02/2019	Inspected At: Paul Hoe Batteries & Motor Services (HQ) 1 KAKI BUKIT AVE 6 #01-109 Singapore 417883
Estimated Period of Repair:	18.0 days	

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$30,000.00 - \$31,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Apr 2019)

Parts: 144 AUDI A3 1.4 SEDAN TFSI (ATTRACTION) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMF8529D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >