

2000000

ASS. REC. BY

REP

CS/CT19008558/UT d3

Special Instruction

SMV/VOY

meimer

ASSIGNMENT (Office)

From (Person): Catherine Thia

of

CTI

Date/Time 26/2/19 @ 10:21am

Estimated Cost

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MV/CS

To Inspect Vehicle No.

YP58004

Insured

YL 7309E

at Workshop n/s

Jin Auto

Tel

6284 8126

of

BLK 14 Defu Lane 10 # 01-410

Policy No.

DMCVSN 180811800

Claim No.

Sum Insured

Excess

Make of Veh:

(Client's Record)

D.O.A.

28/2/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

12:47pm @ 26/2/19

Person Contacted

Jouis

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

YP58004-X

YL7309E-X

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CTI/

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 37588

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

VP58004

Yr Regn:

3, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

mit center

c.c 2998

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

15019

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FER21EA20931

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 / 65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6/6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

18/2/19

D.O.I.

27/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/3/19 6x2833 4/5 cost + labour.  
4/5 \$ 1950 covered with James. (Red: 468, 190%)

RECEIVED 01 MAR 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 1/3 Typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

220

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

220

Report Format :

TP

Lump Sum / I.B.I: (\$

1950/-)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Feb 2019 10:47 <a href="#">Sendback Est</a>	21 Feb 2019 10:59 <b>S\$2,418.00</b>	26 Feb 2019 10:21 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	YL7309E, Co. Reg. No.: -		
Main Claimant:	ZHAN MING HONG ENGINEERING & TRADING PTE LTD, Co. Reg. No.: 200803560E		
Vehicle Reg. No.:	YP5800U	Date of Loss:	18/02/2019 16:00 - :59 [23 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	YL7309E	Policy No. (Claimant):	DMCVSN180811800
		Excess:	S\$0.00
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/03/2019]		
Driver/Custodian (Insured):	QUEK CHUNG HIU ( / Male) , NRIC: S0107481D Email:		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**> Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3560E

**Vehicle Details**

Vehicle No.:	YP5800U
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Feb 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C34914
Chassis No.:	FEB21EA20931
Maximum Power Output:	-
Open Market Value:	\$34,954.00
Original Registration Date:	13 Mar 2017
First Registration Date:	13 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$1,748.00

**Intended PARF Rebate Details**

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

**Intended COE Rebate Details**

COE Expiry Date:	12 Mar 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$46,780.00
COE Rebate Amount:	\$37,588.00
<b>Total Rebate Amount:</b>	<b>\$37,588.00</b>

The information contained herein is correct as at 27 Feb 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	19/02/2019 16:21
Date Of Accident	18/02/2019 16:00
Exact Location Of Accident	JUNCTION OF BRADDELL ROAD AND BISHAN STREET 11
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	YP5800U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ZHAN MING HONG ENGINEERING &TRADING PTE LTD
Co Reg No	200803560E
Email Address	ADS1047@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-91069968
<b>Vehicle Particulars</b>	
Manufacturer	MITSUBISHI
Model	CANTER FEB21ER4SDEB (CBU)
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN180811800
Cover Note Number	
<b>Driver</b>	
Name of Driver	HOSSAIN MD DELWAR
NRIC No	G8406897M
Date Of Birth	01/03/1983
Occupation	OUTDOOR
Date Of Driving Pass	15/04/2014
Driving Experience	4 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98560403
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 1047 EUNOS AVE 5B #01-14
Postcode	409668
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : DRIVER'S COLLEAGUE GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

YP5800U STATIONARY AT THE STOP LINE TO GIVE WAY TO VEHICLE ON THE MAIN ROAD , SUDDENLY THE REAR VEHICLE B:YL7309E CANNOT STOP IN TIME AND HAD COLLIDED ONTO MY VEHICLE REAR PORTION , NO ONE WAS INJURED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YL7309E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	QUEK CHUNG HIU
NRIC/Passport Number	S0107481D
Contact Number	91648229
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Completed & Signed

Policyholder's Signature  
Date & Time:

Zhan Ming Hong  
Engineer of Traffic

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

19/07/19 10:15hr

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:




### Accident Sketch Plan

### SKETCH PLAN

DoA: 18/2/2019

A: YP5800U

IS: 727307E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

YP 5800U stationary at the stop line to give way to vehicles  
on the main road, suddenly the rear vehicle B: YL 739E  
cannot stop in time and had collided onto my vehicle  
rear portion. no one <sup>was</sup> injured

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_

Date &amp; Time:

Driver's Signature \_\_\_\_\_

(if driver is not the policyholder)

Date & Time: 10:15am

1912.

Reporting Centre Personnel's Signature

Names:

ERIC/PIN No.:

# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-410/412

Singapore 539195

Tel: 6289 8126 Fax: 6287 0590

Email: Jin@jinauto.com.sg

Company Reg. No: 200704370C GST Reg.No: 200704370C

TP INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

YL7309E

Singapore

Claimant Insurer:

China Taiping Insurance (Singapore) Pte. Ltd.

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	YP5800U
Policy No:		Date of Loss:	18/02/2019
Vehicle Reg. No.:	YP5800U	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (TP):	HOSSAIN MD DELWAR	Driver (Insured):	QUEK CHUNG HIU
Make/Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Vehicle Reg. Date:	13/03/2017
Vehicle Colour:	WHITE		
Engine No:	4P10C34914	Chassis No:	FEB21EA20931
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	YP5800U STATIONARY AT THE STOP LINE TO GIVE WAY TO VEHICLE ON THE MAIN ROAD, SUDDENLY THE REAR VEHICLE B:YL7309E CANNOT STOP IN TIME AND HAD COLLIDED ONTO MY VEHICLE REAR PORTION, NO ONE WAS INJURED.		
Present Location:	JIN AUTO SERVICES PTE LTD (DEFU)		

## COST OF CLAIMS

	Amount
Parts	1,333.00
Miscellaneous Items	0.00
Labour	1,085.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$)</b>	<b>2,418.00</b>
<b>+ GST 7.00% (\$)</b>	<b>169.26</b>
<b>Nett Amount (\$)</b>	<b>2,587.26</b>

This claim is handled by: JOUIS SEOW

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

## REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 21 Feb 2019)

Parts: N/A MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Jin Auto Services Pte Ltd/YP5800U/21/02/2019 10:59

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE <i>Bad 677</i>	0.00	0.00	*580.00 F ✓
2	1		*MITSUBISHI STICKER <i>ner</i>	0.00	0.00	*138.00 F ✓
3	1		*NUMBER PLATE LAMP <i>17</i>	0.00	0.00	*80.00 F X
4	1		*TAILGATE WOODEN BOARD <i>cm</i>	0.00	0.00	*480.00 F ✓
5	1		*NUMBER PLATE <i>but</i>	0.00	0.00	*35.00 F 14
6	1		*60KM/HR STICKER <i>ner</i>	0.00	0.00	*10.00 F ✓
7	1		*22 PAX STICKER <i>ner</i>	0.00	0.00	*10.00 F ✓

F=Franchise part.

Total Parts (S\$)

1,333.00

Jin Auto Services Pte Ltd/YP5800U/21/02/2019 10:59. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

1232  
1982

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR CHARGE RENEW PARTS AND REPAIR END PANEL TIPPER	New	400 580.00
2	SPRAY PAINTING	New	300 400.00
3	TUFF KOTE	New	30 80.00
4	WIRING CHECK	New	20 25.00
Gross Labour Cost (\$\$)			1,085.00

Jin Auto Services Pte Ltd/YP5800U/21/02/2019 10:59. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;




































## ...CLAIM SUBFOLDER...(Pending for Survey Report)


CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Feb 2019 10:47 <a href="#">Sendback Est</a>	21 Feb 2019 10:59 <b>S\$2,418.00</b>	26 Feb 2019 10:21 <a href="#">Edit Adj Rpt</a>	<b>S\$1,950.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,950.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>YL7309E</b> , Co. Reg. No.: -								
Main Claimant:	<b>ZHAN MING HONG ENGINEERING &amp; TRADING PTE LTD</b> , Co. Reg. No.: 200803560E								
Vehicle Reg. No.:	<b>YP5800U</b>	Date of Loss:	18/02/2019 16:00 - :59 [23 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>YL7309E</b>	Policy No. (Claimant):	DMCVSN180811800						
		Excess:	S\$0.00						
Repairer:	<b>Jin Auto Services Pte Ltd (Defu)</b> Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Catherine Thia</b> ]								
Claimant's Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 07/03/2019]								
Driver/Custodian (Insured):	QUEK CHUNG HIU ( / Male) , NRIC: S0107481D Email:								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**YP5800U**  
**[YL7309E]**  
**TP**  
**ZHAN MING HONG ENGINEERING & TRADING PTE LTD**  
**Feb 18 2019 4:00PM**  
**[YL7309E]**  
**Jin Auto Services Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	21/02/19 10:59	<b>Repairer Estimates</b>	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
30	01/03/19 11:26	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
31	01/03/19 11:26	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
32	01/03/19 11:26	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
33	01/03/19 11:26	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
34	01/03/19 11:26	<b>Reinspection Photo</b>	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
				<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	21/02/19 10:48	E-filed GIA report	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19003558/UTD3E2

Date: 05/03/2019

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

**Claimant Vehicle No :** YP5800U

**Insured Vehicle No :** YL7309E

Date of Loss: 18/02/2019

Nature of Claim: TP Claim No: N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP5800U**  
Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M) Engine No: 4P10C34914  
Reg. Date: 13/03/2017 (Man. Year: 2016) Chassis No: FEB21EA20931  
Colour: White Odometer: 85019 km  
Engine Capacity: 2998 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/85R15 Rear Tyre Size: 195/85R15(D)  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,333.00	1,232.00	101.00	7.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,085.00	750.00	335.00	30.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,418.00</b>	<b>1,982.00</b>	<b>436.00</b>	<b>18.03</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,950.00</b>		
<b>(S\$)</b>	2,418.00	1,950.00	468.00	19.35
<b>+ GST 7.00/7.00% (S\$)</b>	169.26	136.50	32.76	19.35
<b>Nett Amount (S\$)</b>	<b>2,587.26</b>	<b>2,086.50</b>	<b>500.76</b>	<b>19.35</b>

### INSPECTION

Date of Assignment: 26/02/2019 Present Location:  
Date Inspected: 27/02/2019 Inspected At:

Jin Auto Services Pte Ltd (Defu)  
Jin Auto Services Pte Ltd (Defu)  
Blk 14 Defu Lane 10, #01-410/412  
Singapore 539195

Estimated Period of Repair: 3.0 days



---

**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 04 Mar 2019)	
<b>Parts:</b>	N/A	MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YP5800U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	580.00 F	*580.00 F
2	1		*MITSUBISHI STICKER	Necessary	138.00 F	*138.00 F
3	1		*NUMBER PLATE LAMP	Not Necessary	80.00 F	*- F
4	1		*TAILGATE WOODEN BOARD	Cracked	480.00 F	*480.00 F
5	1		*NUMBER PLATE	Bent	35.00 F	*14.00 F
6	1		*60KM/HR STICKER	Necessary	10.00 F	*10.00 F
7	1		*22 PAX STICKER	Necessary	10.00 F	*10.00 F
				<b>Total Parts (S\$)</b>	<b>1,333.00</b>	<b>1,232.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE RENEW PARTS AND REPAIR END PANEL TIPPER	New	580.00	400.00
2	SPRAY PAINTING	New	400.00	300.00
3	TUFF KOTE	New	80.00	30.00
4	WIRING CHECK	New	25.00	20.00
Gross Labour Cost (S\$)			<b>1,085.00</b>	<b>750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >