

NATIONAL Assessment Centre Services.

(wef 1 Jan 2003)

Ref: 19026601

Date In: 26/01/2019 13:45	Job description	Date & Time Completed	Done by
Ref No: N/A/NIC/90035701	SAS e-filing		
Veh No: SPQ 79964	E-mail (w/ins 3hrs, AIC 2hrs)		
D.O.A: 26/01/2019 05:45	I-Motor Claim Form	26/01/2019 15:29	
QD: TP: Reporting Only	I-Motor W/O (Withins: OD 2hrs, TP 4hrs)		
	I-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel:	Fax:
TP Particulars:	Veh No: CB 68107	INC () / Non-INC ()
Owner / Driver: (	Tel:	
Policy No: (	Period: (	Cover Type: (
Confirmed by: (	Date:	Time:
Insured/Driver Liability: (	% [Note-Est. Status (WO): N: 0-20%; P: 21-79%. P: 80-100%]	
Year of Registration: (	Warranty: YES () / NO ()	
Excess: (\$	Loading: \$1,000 () / \$2,000 ()	

General Remarks:

() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: _____

Date/Time	Location	Done by

NA190151.7	Invoice
Driver/Owner:	1) AR: Accident Reporting (\$30);
Contact No:	2) DA: Damage Assessment (\$100); INC (\$50)
Damaged Portion:	3) TP: Towing Fee \$40/\$45
QC Checked by (Engr-In-Charge):	4) PT: Follow-Through Survey \$120
	5) PT: Follow-Through Survey (Resurvey) \$30
	For claiming against INC Only (wef 10 Jan 2003)
	6) TR: Re-inspection \$75
	7) NI: Idao DA + SMRT Survey \$160
	8) NTUC Additional Services:
	ON:
	*N5: Courtesy Car / Tpl Allowance \$5
	*N6: Repair Co-ordination \$10
	*N7: Post Repair Inspection \$25
	*N8: DV / Collect Excess Coordination \$5
	TP (Nil) / TP (Non INC) against INC \$20
	9) NI: Idao Mobile \$0
	Invoice dated
	Fee Charged
	Invoice dated
	Fee Charged

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/02/2019 13:45
Date Of Accident	26/02/2019 05:45
Exact Location Of Accident	JUNCTION OF ALEXANDRA ROAD AND DEPOT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFQ7996U
Insured/Policyholder	
Name Of Registered Owner	MOHAMMED ZAHIRUL HOQUE
NRIC No	S2643408D
Email Address	MZAHIRUL@EAGLE.ORG
Mobile Phone No	(LOCAL) +65-91013914
Alternative Phone No	OTHERS-91013914

Vehicle Particulars

Manufacturer	HONDA
Model	INSIGHT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own Insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5038796801-09
Cover Note Number	

Driver

Name of Driver	MOHAMMED ZAHIRUL HOQUE
NRIC No	S2643408D
Date Of Birth	01/12/1956
Occupation	INDOOR
Date Of Driving Pass	23/01/1998
Driving Experience	21 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91013914
Fax Number	
Contact Number	OTHERS-91013914
Email Address	MZAHIRUL@EAGLE.ORG

Address	BLK 75C REDHILL ROAD #14-78
Postcode	153075
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB6810T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	MOHAMED JUMARI BIN SALIMON
NRIC/Passport Number	S1326826F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

SKETCH PLAN



A) SKQ 7996 U
B) CB6810 T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Bus was at the junction & my car
right corner hit the Bus's Right
Side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time:

[Signature]
M. ZAHEDI

Driver's Signature

(If driver is not the policyholder)

Date & Time:

[Signature] 26/01/2018
Reporting Centre Personnel's Signature
Name: Rosh, Vito3
NRIC/FIN No.:

Accident: MT/1033731

Claim 001 [New](#)

Attachment

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description	Mag Sent ? (CO)
	NAC_BUKIT_MERAH_000676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 26 Feb 2019 13:22	Photos	Normal	Photos 2019-2-26	
	NAC_BUKIT_MERAH_000676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 26 Feb 2019 15:29	Photos	Normal	Photos 2019-2-26	
	NAC_BUKIT_MERAH_000676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 26 Feb 2019 15:29	Photos	Normal	Photos 2019-2-26	

Wheeler, S. J. et al.

uploaded By/Date	Folder Name	File Name	Source	Action
		Display in New Window Scan and uploading		

1. Nature of Accident:

- 1) Vehicle hit Vehicle: ☐ Vehicle hit ??
- a) Motorcycle ☐ b) Pedestrian ☐
- c) Bicycle ☐ d) Animal ☐
- 2) Vehicle hit Road Side Objects:
- a) Govn. Property ☐ b) Road Work Object ☐
- (Ex: signposts, barriers, etc.) c) Private Property ☐
- 3) Vehicle drop into drain ☐
- 4) Damage due to Act of God:
- a) Fallen Object ☐ b) Flood ☐
- c) Other: _____
- 5) Parked & Found Damaged:
- a) Vandalism ☐ b) Hit by Moving Object ☐
- 6) Theft Case
- a) Stolen ☐ b) Damage found ☐
- when recovered.
- 7) Fire
- a) Whilst driving ☐ b) Parked ☐
- 8) Accident date more than 24hrs ☐

Remarks for Internal Information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ☐
- 2) SRS Light on ☐
- 3) ABS Light on ☐

2. Vehicle Information

Vehicle: SFQ 7996 U Year: AUG 2009

Type: M/Car / M/Cycle / Bus / Van / Lowry / Taxi / Prime Mover / ☐

/ Truck / Trailer or ☐

Make & Model: HONDA INSIGHT 1.36A cc: 1339

Colour: BLACK Transmission Type: Auto / Manual

EngNo: LDA 2046892 Sp. Reading: _____

C/Nr: ZE211 46866

Gen. Cond: Good / Fair / Poor / Burnt ☐

Steering: In order / Jammed / Leaked / Burnt or ☐

Brake: In order / Jammed / Leaked / Burnt or ☐

Modi: Ni / S/Rim / STD A/Rim or ☐

Tyre Size: F: 195/60 R18

R: 195/60 R18

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front	mm	Rear	mm
R/Bal. <u>6</u>		R/Bal. <u>6</u>	
L/Bal. <u>6</u>		L/Bal. <u>6</u>	

Parallel Import: Yes / No

Towed-In: Yes / No

Repair Type: LS / LB.I

Towing Required: Yes / No

No of Repair Days: _____

Vehicle in Idac: Yes / No

D.O.I. 26/07/2019

Time: 14:25 hrs

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
- a. Vehicle ☐ b. Motorcycle ☐ c. Bicycle ☐ d. Pedestrian ☐
- e. Animal ☐ f. Govn Object ☐ g. Road Work Object ☐
- h. Private Property ☐ i. Drain ☐ j. Road Kerb/Grass Verge ☐
- 3) Vehicle does not seem damaged as a result of:
- a. Fallen Object ☐ b. Flood ☐ c. Vandalism ☐ d. Fire ☐
- e. Moving Object ☐ f. Stolen ☐ g. Stolen & Recovered ☐

Time Started

Time Completed

1) CSO

2) ABS

3) Entire Operation Completed Time:

Front Porch

NAC	INC	Item	CON	AC	QTY
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991362	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991497	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992023	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991325	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990373	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990123	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990656	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990220	Battery Tray			

Vehicle No:

SFQ 75564

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990725	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992382	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

Claim Handling

Task Transfer Exit

Accident MT/1033732

100 100 100

Policy No.	5038796801-09	Vehicle No.	BFQ7996U	GST Registration No.	
Certificate No.					
Policyholder Name	MOHAMMED ZAHIRUL HOQUE			Policyholder NRIC	S26434080
Product Code	PRIVATE CAR INSURANCE	Cover Type	Drive CLASSIC	Loading	0
Contact No. (Mobile)	91013914	Contact No. (Office)		Contact No. (Home)	
Email Address		Special Remark		eCode	No
KYC	No Yes	TCA	No Yes	eCode Reason	
NCD Protection	Yes	NCD Entitlement(%)	50	Private Hire	No

Accident Details

Report Date	26/02/2019 15:23	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Major Minor Road
Date of Accident	26/02/2019	Time of Accident hh:mm	15:45	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTRE	Orange Force	No	ICM No.	
Accident Location	JUNCTION OF ALEXANDRA ROAD AND DEPOI ROAD				

Excess

Own damage Excess	100.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess			500.00
Third Party Excess	0.00	Outside Singapore TP Excess			0.00

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 75C #14-78	Address 2	REDHILL ROAD	Address 3	REDHILL RISE
Address 4	SINGAPORE 153075	Address Type	Singapore address	Post Code	153075
Unit No.		Related Policy Number	5038796801-09		

OI Driver Info

Driver Name	MOHAMMED ZAHIRUL HOQUE	Driver Type	Main Driver	Driver DOB	01/12/1956
Unnamed driver Name		Driver NRIC	S26434080	Driving Experience	21
Register Date of Driver License	23/01/1998	Driver Age	62	Contact No. (Home)	
Contact No. (Mobile)	91013914	Contact No. (Office)		Address 1	REDHILL ROAD
Address 1	BLK 75C #14-78	Address 2	REDHILL ROAD	Address 2	REDHILL RISE
Address 4	SINGAPORE 153075	Address Type	Singapore address	Post Code	153075
Unit No.					
Does he own a Singapore Registered car?	Yes - No	Driver Vehicle No.	BFQ7996U	Driver Insurer Company	NTUC

Declaration

Breathalyzer or Blood Test Reading?	0 mg	Any injury?	Yes - No
Modification History			

Investigation

Claim 001 OD-MD

Claims Case Officer Zuraimie Bin Mantau

100 100 100

Claim Type	OD-MD	Insured Name	MOHAMMED ZAHIRUL HOQUE	Insured NRIC	S26434080
Contact No. (Mobile)	91013914	Contact No. (Home)	67936997	Contact No. (Office)	63712583
Email Address	MZAHIRUL@EAGLE-PRO	OI Vehicle Number	BFQ7996U	TP Vehicle Number	CS68107
Claim Description	BFQ7996U / CS68107 ON 26 Feb 2019			Name of Preferred Workshop	
Preferred Workshop	Yes	Preferred Repair Option	Preferred Workshop	Insured Party	Fully Recovered Fault
Date Registered		Name unknown	26/02/2019 15:29	Claim Close Date	
Report Taken By		ROSLI WAHAB	Workshop Repairer	Date Received	26/02/2019 00:00
Print AK letter				Total Loss But Repaired	
Modification History				OD Excess Collected by Workshop	

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment Attachment

Vehicle Info

Vehicle Make	HONDA	Vehicle Model	IN510HT	Engine Capacity	
Date of Registration	24/08/2009	Class No.	2921146166		
Towing Required *	* Yes No	Vehicle in IDAC *	* Yes No	Parallel Import *	Yes * No
Type of Tender	Own Damage	Assessor Name *	ROSLI WAHAB	Survey Current Status	

IDAC/Workshop Name	NATIONAL ASSESSMENT CENTRE	IDAC/Workshop Location	33 UBI AVENUE # 401-25 PARK
Windscreens		Total Loss *	Yes * No
Parts & Labour Cost		Scrap Value(\$)	Economical Repair Value(\$)
Market Value(\$)	1)FRONT BUMPER PAD-REPLACE		
Remarks			
Remark for Supplementary			

Damage Listing

FE	No.	Part No.	Description	Qty *	Repair Code *	
DRIVE SHAFT	1	18001301	BUMPER (FRONT)	1	Replace	X
DRIVER CAB MOUNTING	2	18001301	BUMPER BRACKET (FRONT LEFT)	1	Replace	X
DRIVER CABIN COMPARTMENT	3	18001302	BUMPER BRACKET (FRONT RIGHT)	1	Replace	X
DROP DOOR	4	18002401	BUMPER CLIPS (FRONT)	1	Replace	X
ELECTRONIC CONTROL UNIT (ECU)	5	18002402	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Replace	X
ELECTRONIC IGNITION COIL	6	18002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Replace	X
EMBLEM	7	18005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	X
ENGINE	8	18005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	X
ENGINE (MC)	9	18005001	BUMPER REINFORCEMENT (FRONT)	1	Unconfirm	X
ERP	10	18005901	BUMPER SPONGE (FRONT)	1	Replace	X
EVAPORATOR	11	18003201	BUMPER GRILLE (FRONT)	1	Replace	X
EXHAUST	12	27100101	GRILLE (FRONT)	1	Replace	X
EXPANSION TANK	13	27100801	GRILLE EMBLEM (FRONT)	1	Replace	X
EXPANSION VALVE	14	41300101	SUPPORT PANEL (FRONT)	1	Repair	X
EXTENSION MEMBER	15	41300801	SUPPORT PANEL TOP GARNISH (FRONT)	1	Unconfirm	X
EXTERIOR LAMP	16	27700101	HEAD LAMP (LEFT)	1	Replace	X
FAIRING	17	27700102	HEAD LAMP (RIGHT)	1	Replace	X
FAN	18	140001	BONNET	1	Repair	X
FENDER	19	112023	AIR CON CONDENSER	1	Unconfirm	X
FENDER (FRONT)	20	344001	RADIATOR	1	Unconfirm	X
FENDER (FRONT LEFT)	21	344005	RADIATOR COWLING	1	Unconfirm	X
FENDER (FRONT RIGHT)	22	344006	RADIATOR FAN	1	Unconfirm	X
FENDER (REAR)	23	344011	RADIATOR FAN CLUTCH	1	Unconfirm	X
FENDER (REAR LEFT)	24	23400102	FENDER (FRONT LEFT)	1	Repair	X
FENDER (REAR RIGHT)	25	23400103	FENDER (FRONT RIGHT)	1	Replace	X

[Save](#) [Submit](#)

From: Ng Hak Joo <hakjoo.ng@income.com.sg>
Sent: Wednesday, 27 February, 2019 11:16 AM
To: Chin
Cc: LKK Bukit Merah
Subject: MT/1033732-001, VEHICLE NUMBER: SFQ7996U

Importance: High

Dear Modern

As we were informed by Mr Rosli of Idac that owner is overseas, please tow this vehicle from Idac and contact owner Mr Mohd Zahirul at 91013914 when the repair is done, excess \$600

Our Ref: MT/CA/OD/051/1033732-001/NHJ

27 Feb 2019

MODERN AUTOMOTIVE PTE LTD

BLK 3023A #01-61 UBI ROAD 1

SINGAPORE 408717

Dear Sir

CLAIM NUMBER: MT/1033732-001

REPAIR OF VEHICLE NUMBER: SFQ7996U

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 27 Feb 2019

Make: HONDA

Model: INSIGHT

Estimated Repair Days: 7

Location: NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)

Address: BLK 1007 #1 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE INDUSTRIAL ESTATE SINGAPORE 159721

Benefits Applicable: N/A

Excess Applicable: 600.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Ng Hak Joo at 64307890 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Thank You

Ng Hak Joo

Executive

Motor Insurance

T +65 64307890

www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315

NAC

Vehicle Movement Form

Vehicle Check-In

Vehicle No: SFQ 7996U Date In: 26/02/2019 Time In: 1345 with Keys: (Yes)

For Office use

Attended by: [Signature]

Workshop Collection of Vehicle

Workshop: MODERN AUTOMOTIVE PIA 670

Collection Date: 27/2/19 Time: 15:16 with Keys: Yes / No

Tow Truck No: YM 5128 T Tow Man: NG CHON KEAT NRIC: S7986726 H

Signature: [Signature]

For office use

Attended by: [Signature]

Approved by: [Signature]

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

ACCIDENT STATEMENT

ACCIDENT DATE: (26/02/2019) (DD/MM/YYYY), TIME: (0545) (HH:MM)

LOCATION: JUNCTION - ALEXANDRA RD & DEPOT ROAD

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SFA 7996V
 b) INSURANCE COMPANY: NTUC
 c) POLICY NUMBER:
 d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
 e) MAKE & MODEL: HONDA INSIGHT
 f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
 g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
 h) PURPOSE OF USING AT ACCIDENT TIME: APPROX 0545 26/2/2019
 i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
 IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: MOHAMMED ZAHIRUL HOQUE (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: 92643408D CONTACT: 9101 3914
 c) ADDRESS: BLOCK 75C REDHILL ROAD #14-78
 (S) 153075

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: MOHAMMED ZAHIRUL HOQUE (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: 92643408D CONTACT: 9101 3914
 c) ADDRESS: SAME AS ABOVE

- * d) DATE OF BIRTH: (04/12/1956) (DD/MM/YYYY)
 e) OCCUPATION: (INDOOR / OUTDOOR) DIRECTOR
 f) DATE OF DRIVING PASS

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
 IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: SAME

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS)
 b) ROAD SURFACE: (DRY / WET / OTHERS)

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION:

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: CB6810T MODEL: BUS
 b) DRIVER'S NAME: MOHAMED JUMALI BIN SALIMON
 c) NRIC/FIN/PASSPORT: S1326826F CONTACT:

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: N/A MODEL:
 e) DRIVER'S NAME:
 f) NRIC/FIN/PASSPORT: CONTACT:

* No of passenger
 (Including driver)
 (1)

* No of passenger
 (Including driver)
 (1)

* No of passenger
 (Including driver)
 ()

Email = mzahirul@eagle.org
 VIDEO

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2643408D



Name

MOHAMMED ZAHIRUL HOQUE

Race

BENGALI

Date of birth

01-12-1956

Sex

M

Country/Place of birth

BANGLADESH



REPUBLIC OF SINGAPORE DRIVING LICEN



License Number S2643408D

Name

MOHAMMED ZAHIRUL HOQUE

Birth Date 01 Dec 1956

Issue Date 27 Jan 2003



5928592



NRIC No. S2643408D



Date of issue

03-05-2018

Address


APT BLK 75C REDHILL ROAD
#14-7B
SINGAPORE 153075

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2000 kilograms

25 Jan 1993



NP 423A

Hello, NAC_BUKIT_MERAH_800676

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	26/02/2019 11:42
Vehicle No.(For Motor)	SFQ7996U	Certificate Number	
Search			

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5038796801-09		MOHAMMED ZAHIRUL HOQUE	S2643408D	GPC	drive CLASSIC	SFQ7996U	SFQ7996U	24/08/2018	23/08/2019