

ASS. REC. BY:

REF: CS/INC19003574 / Utd301 Special Instruction:

Surveyor: MariusASSIGNMENT (Office)From (Person): Cynthia Ang of INC Date/Time: 26/2/19 @ 9:34am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLN 21204 Insured: 81Y 59524at Workshop m/s ZOOM Autowerks Tel: 9450of 15 kaki Bukit Rd 4 #01-53Policy No: \_\_\_\_\_ Claim No: MT / 103 2907 - 002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 19/02/19  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 9:38am @ 26/2/19 Person Contacted: Elin Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLN 21204 - NA / INC 19003396/24	D.O.A. 19/2/19
	81Y 59524 - NA / INC 19003396/24	D.O.A. 19/2/19

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 2120 H

at Workshop m/s Zoom

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 04900

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLN 2120 H Yr Regn: 4117

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Mazda 3 c.c. 1896

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 116041 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM 6BN 22A8H 0152433

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 205/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or roadstone

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19/4/11 D.O.I. 26/2/19 @ 1100F

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

LH N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/3/19 LTA 48007

4/5/19 4800 confirmed with EIR (red: 6670.30; 58%)

RECEIVED 05 MAR 2019

Date/Time, File Pass to?

☐: Preli. Report☒: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee: 290

Transportation: \_\_\_\_\_

Add Fee: ☐: Site Insp (\$ \_\_\_\_\_) S + RS, SI☐: Interview (\$ \_\_\_\_\_) Photos☐: Tech. Invs (\$ \_\_\_\_\_) Others☐: Weekend (\$ \_\_\_\_\_)

TOTAL

290

Report Format: TP

Lump Sum / I.B.I. (\$) 48007-

## **Nivitha (LKK Auto)**

**From:** Cynthia Ang <Cynthia.Ang@income.com.sg>  
**Sent:** Tuesday, 26 February 2019 9:34 AM  
**To:** assignments@lkkauto.com  
**Cc:** Daniel Koh; Thio Tse Kiat; Toh Choon Hin  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 26/2/2019

Dear Veron / Nivitha,

Please assist to survey the vehicles as per Mr Toh's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Type	Survey Time	OI Veh	DOA	Additional Remarks
1	Juliana Lee	MT/1033428-001	SKU2955R	96 MOTORSPORTS PTE LTD	62/64 KAKI BUKIT AVENUE 6	Royce / 6702 6996	Physical Survey		PC4781Y	21/02/2019	
2	Serene Lim	MT/1033102-002	SMD1877E	PREMIUM CARZ SERVICES PTE. LTD.	1 Kaki Bukit Ave 6 #01-90 Autobay @ Kaki Bukit Singapore 417883	Aun Teng / 6636 9100	Physical Survey	10:30-12:30	SJN5768T	21/02/2019	
3	Helena Tan	MT/1032907-002	SLN2120H	ZOOM AUTOWERKS PTE LTD	15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE, #01-53	Elin Cai / 9450 7920	Physical Survey		SJY5952U	19/02/2019	

**Please contact workshops.**

Please ack.

Thank You

With Regards

**Cynthia Ang**  
Admin Assistant  
Motor Insurance  
T +65 6430 7900  
[www.income.com.sg](http://www.income.com.sg)

**income**  
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

**Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)**

**in** with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

---

## Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	0490D
<b>Vehicle Details</b>	
Vehicle No.:	SLN2120H
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Feb 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520444024
Chassis No.:	JM6BN22A8H0152433
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,476.00
Original Registration Date:	26 Apr 2017
First Registration Date:	26 Apr 2017
Transfer Count:	1
Actual ARF Paid:	\$9,476.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Apr 2027
PARF Rebate Amount:	\$7,107.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	25 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$40,900.00
<b>Total Rebate Amount:</b>	<b>\$48,007.00</b>

The information contained herein is correct as at 27 Feb 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

SUPREME



CLICK HERE OR CALL  
**64**

### Post an Advertisement

Sell it yourself! Advertise it at just

**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)







### Very Sporty Audi Selling At Lowest Dep!



All Wear And Tear Repaired !  
Megatronic Changed! No More  
worries!  
StarAd


[Browse by Category](#)
[« Back \( 1 2 \) Next »](#)
[Sort by Date Posted](#)
**21 vehicles**

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	Mazda 3		Any	Any	2017	Any	Any	
	Mazda 3 1.5A Deluxe		\$72,800	\$8,220 /yr	28-Feb-2017	1,496 cc	39,000 km	
1 Owner Deluxe Model With Navigation And Active Display, I-Eloop Technology Fuel Savings, Like New, Guarantee Condition, In House Car Available In Showroom For Viewing Now. Contact For...								
Posted: 26-Feb-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda								
	Mazda 3 1.5A		\$74,800	\$7,890 /yr	29-Dec-2017	1,496 cc	14,000 km	
Elegant Outlook And Plenty Of Accessories Upgrade. Tiptop Condition, Accident Free And Under 3 Years Warranty. List Of Items Upgrad 17" Sport Rim With Michelin 3rd Tyres, 3m Solar Film, 9h...								
Posted: 24-Feb-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda								
	Mazda 3 1.5A Deluxe		\$70,800	\$7,900 /yr	22-Feb-2017	1,496 cc	-	
Deluxe Model With Sunroof And Many Other Additional Features Compared To Basic Model! 100% Not PHV! 1 Owner! Full Service Record Eurokars. High Trade In And In-House Financing Available! Call For...								
Henly Enterprises Co								
Posted: 23-Feb-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda								
	Mazda 3 1.5A		\$62,800	\$7,240 /yr	20-Feb-2017	1,496 cc	39,000 km	
High Loan Up To 100%. Low Interest Rate! Trade In Welcome. Consignment Unit. Viewing By Appointment Only!								
Posted: 21-Feb-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda								
	Scuff Plate							
Available in both interior and exterior (with or without light).								
More info about this product								
	Mazda 3 1.5A		\$75,800	\$8,400 /yr	28-Apr-2017	1,496 cc	-	
As Good As New. Consignment Unit! Trade In Welcome! Loan And Insurance Available! Call Now For Viewing Appointment!								
From Row Motoring								
ad: 17-Feb-2019 Tags: 2017 Mazda 3, 2017 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda								

Compare

[Compare](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/02/2019 16:51
Date Of Accident	19/02/2019 13:55
Exact Location Of Accident	UNPAVED RD BETWEEN BT TIMAH RD & CHANCERY LN
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN2120H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	METRO CAR LEASING PTE LTD
Co Reg No	201810490D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

### Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA3 SEDAN 1.5 AT EU6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101761376
Cover Note Number	

### Driver

Name of Driver	TAN CHONG BENG
NRIC No	S1714261E
Date Of Birth	28/09/1965
Occupation	OUTDOOR
Date Of Driving Pass	28/11/2005
Driving Experience	13 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87509662
Fax Number	
Contact Number	OFFICE-87509662
Email Address	NOEMAIL

Address	BLK 634 YISHUN STREET 61 #04-54
Postcode	760634
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8522999 - FAX NO: 68522239
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20190220/2179.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJY5952U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



No. Of Passenger (Including Driver)

1

**DETAILS OF INJURED PERSON 1**

Name

TAN CHONG BENG

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SLN2120H

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) protecting, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices) to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages; and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Scanned by CamScanner


# Accident Sketch Plan

SKETCH PLAN

VEHICLE A: SLN2120H

VEHICLE B: SJY5952U

[← Bait Timah Rd]



[CHANCERY LANE →]

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

## DECLARATION

I/We declare the following particulars are true in every respect.

Policyholder's Signature  
Date & Time



Driver's Signature  
(if driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name:  
NRIC/ID No:

Scanned by CamScanner

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20190220/2179

1 of 4

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

Report No: T/20190220/2179

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/02/2019 18:54		Vide Report No.:		Station Diary No.: 98	
<b>Informant's Particulars</b>					
Name of Informant: TAN CHONG BENG		Address: APT BLK 634 YISHUN STREET 81 #04-54 SINGAPORE 760634			
ID Type / ID No.: NRIC NO / S1714261E		Contact No.: Home/Office:		Mobile: 87509662	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 53	Date of Birth: 28/09/1965	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: PRIVATE HIRED CAR DRIVER		Driving Licence Information: Class: 3		Date of Expiry:	

## General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/02/2019 13:55	Type of Location:
Location: Along Road 1 Traveling Toward Road 2 BUKIT TIMAH ROAD CHANCERY LANE Unpaved road in between Bukit Timah Rd and Chancery Lane				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 40	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJY5952U	Car	TOYOTA	ALPHARD AUTO	Gold	Slightly Damaged	0
SLN2120H	Car	MAZDA	MAZDA3 SEDAN 1.5 AT EU6	Grey	Slightly Damaged	0

## Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Scanned by CamScanner

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20190220/2179

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

2 of 4

Report No. T/20190220/2179

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	ALLAN CHUA	ID No.	NIL
Related Vehicle	SJY5952U (Car)	Contact No.	97690596
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	TAN CHONG BENG	ID No.	S1714261E
Related Vehicle	SLN2120H (Car)	Contact No.	87509662
Hospital/Clinic	YISHUN POLYCLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	20/02/2019	Date Discharge	20/02/2019
No. of Days granted Medical Leave	06	Degree of Injury	Slight

### Brief Details.

On 19/02/2019 at around 1356hrs, I was driving my car along Bukit Timah Road. I had then turned left into Chancery Lane and drive into the unpaved road located in between Bukit Timah Rd and Chancery Lane. There is a metal barricade at the said area and it was opened. As such, when I turned in, there is already a few vehicles parked there on the right side. I then noticed an empty space beside a Mercedes car, as such I had put on my hazard light to indicate that I was going to park. I then had moved, getting ready to park my car head in when suddenly, a car had came out from my left side.

As the car had came out of a sudden, I jammed brake and even pull my handbrake to avoid collision. However, the left front bumper of my car had hit onto the right side of the said car. After which, both me and the other driver had came out of our vehicle. I then apologies to the driver and check on him. I then told him that since it was a minor accident, we should settle it amicably. There was no dispute between us. The other driver kept asking for a piece of paper to write an agreement however I refused and told him that this things could be solve peacefully. We then exchanged particulars and the said driver drove off.

On the same day, I had message him and volunteer to send his car for repair. I also told him informed me that the payment will be divided between us (70% on me and 30% on him) However he refused as such I volunteer to pay for the full cost. HE then did not response to my messages and eventually he informed me that his car is at the workshop and told me to report to the insurance company.

I wished to state that I have went to the polyclinic to seek medical attention due to the accident. I was given 6 days MC from 20/02/2019 25/02/2019.

Scanned by CamScanner

Police Report



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 708456  
Tel No: 1800-8522999



T/20190220/2179

3 of 4

Report No. T/20190220/2179

CONTINUATION OF REPORT

Scanned by CamScanner

Police Report



SINGAPORE  
POLICE FORCE



T/20190220/2179

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street B1 SINGAPORE 768456  
Tel No: 1800-8522999

4 of 4

Report No: T/20190220/2179

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

L /

Sr Staff Sgt ELRENO BIN SUBARI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

20/02/2019 18:54

Officer In Charge Of Case:

TP / AEIT /


SSI 2 JUREMAH BINTE AHMAD

Contact No: 65472076

Classification Of Case:

Authentication Stamp

NP168



Scanned by CamScanner

**ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

email | zoomautowerks@gmail.com

D.O.A : 19 FEBRUARY 2019

25th February 2019

OWNER : METRO CAR LEASING PTE LTD

REG. NO. : SLN 2120 H

MAKE/MODEL : MAZDA 3

not Authorized  
make  
L/S \$ 4800  
4 days  
take photo. After repair

**ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE**

QTY	DESCRIPTION	AMOUNT(S\$)
	<u>LIST ITEMS</u>	
1	Front Bonnet 1031.70	\$ 20/Buc 1,067.00 ✓
1	Front Bonnet Hinges	\$ 11 130.00 X
1	Front Bonnet Lock	\$ 11 223.10 X
1	Front Bonnet Front Rubber	\$ 11 68.00 ✓
1	Front Bonnet Rear Rubber	\$ 11 45.00 ✓
1	Front Headlamp 115 2245	\$ 11 2,254.00 ✓
1	Front Grille 285.40	\$ 11 581.00 ✓
1	Front Grille Chrome Mouldings 115 231.70	\$ 11 570.00 ✓
1	Front Grille Logo	\$ 11 65.00 ✓
1	Front Bumper	\$ 20/Torn 1,031.70 ✓
1	Front Bumper Fog Lamp	\$ 11 351.00 ✓
1	Front Bumper Fog Lamp Cover	\$ 11 149.20 X
1	Front Bumper Lower Grille	\$ 11 128.30 X
1	Front Bumper Reinforcement 409.30	\$ 11 568.40 ✓
2	Front Bumper Side Retainers 42.00	\$ 11 85.00 ✓
1	Front Bumper Rubber Seal	\$ 11 112.00 ✓
1	Front Fender	\$ 11 550.00 ✓
1	Front Fenders Inner Shield	\$ 11 175.00 ✓
1	Front Support Panel	\$ 11 855.00 ✓
1	Front Support Panel Top Garnish	\$ 11 195.00 ✓
1	Radiator	\$ 11 777.30 X
		\$ 9,981.00
		\$ 1,996.20
		\$ 7,984.80

LESS 20%

5917.80  
202  
473424

LKCAuto Consultant, please notify the Repairer of the following:

- To resurvey vehicle after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:



SPECIAL NETT ITEMS

1 Front Bumper Clip (1 Set)	\$	rec	50.00	✓
1 Front Number Plate	\$	bel	50.00	40
1 Front Fender Inner Shield Clips (2 Sets)	\$	11	100.00	X
1 Air Con Condenser	\$	11	425.50	X
			\$	625.50

S/NLABOUR CHARGES

1	To check wiring and reset headlamps focusing	\$	80.00	20
2	To remove, refit air-con condenser, refill gas & conduct leakage test	\$	11 180.00	X
3	To apply undercoating	\$	200.00	30
4	Panel Beating	\$	1,300.00	500
5	To re-spray the affected areas	\$	1,100.00	680
			\$	2,860.00

---

**\$ 11,470.30**

---

6054.24  
866)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19003574/Utd3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 06-03-2019



ATTN : HELENA TAN

Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SJY 5952U	Veh. Inspected	SLN 2120H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1032907-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	26/02/2019

**2. Vehicle Particulars & Condition**

Make & Model	MAZDA 3 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0152433	Colour	BROWN
Odometer	116041 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	205/60 R16	ROADSTONE	6 mm
L/H Front Tyre	205/60 R16	ROADSTONE	6 mm
R/H Rear Tyre	205/60 R16	ROADSTONE	6 mm
L/H Rear Tyre	205/60 R16	ROADSTONE	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

Accident Date	19/02/2019	Inspect Date / Time	26/02/2019 ( 11:00 AM )
Survey held at	15 KAKI BKT RD 4# 01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 2120H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BONNET	DENTED / BUCKLED	1,067.00	1,031.70
1	FRONT BONNET HINGES	NOT NECESSARY	130.00	-
1	FRONT BONNET LOCK	NOT NECESSARY	223.10	-
1	FRONT BONNET FRONT RUBBER	NECESSARY	68.00	68.00
1	FRONT BONNET REAR RUBBER	NECESSARY	45.00	45.00
1	FRONT HEADLAMP N/S	CRACKED	2,254.00	2,245.00
1	FRONT GRILLE	CRACKED	581.00	285.40
1	FRONT GRILLE CHROME MOULDINGS N/S	CRACKED	570.00	231.70
1	FRONT GRILLE LOGO	NECESSARY	65.00	65.00
1	FRONT BUMPER	DEFORMED / TORN	1,031.70	1,031.70
1	FRONT BUMPER FOG LAMP	CRACKED	351.00	351.00
1	FRONT BUMPER FOG LAMP COVER	NOT NECESSARY	149.20	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	128.30	-
1	FRONT BUMPER REINFORCEMENT	BENT	568.40	409.30
2	FRONT BUMPER SIDE RETAINERS	BENT-1PC ONLY	85.00	42.00
1	FRONT BUMPER RUBBER SEAL	NECESSARY	112.00	112.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	550.00	-
1	FRONT FENDERS INNER SHIELD	NOT NECESSARY	175.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	855.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	195.00	-
1	RADIATOR	NOT NECESSARY	777.30	-
	LESS 20% DISCOUNT		-1,996.20	-1,183.56
			7,984.80	4,734.24
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	FRONT NUMBER PLATE (SN)	BENT	50.00	40.00
2	SETS FRONT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	100.00	-
1	AIR CON CONDENSER (SN)	NOT NECESSARY	425.50	-
			625.50	90.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING.		80.00	20.00

Report Ref No. CS/INC19003574/Utd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REFIT AIR-CON CONDENSER, REFILL GAS & CONDUCT LEAKAGE TEST.	NOT NECESSARY	180.00	-
	TO APPLY UNDERCOATING.		200.00	30.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER.		1,300.00	500.00
	TO RE-SPRAY THE AFFECTED AREAS.		1,100.00	680.00
			2,860.00	1,230.00
GRAND TOTAL			11,470.30	6,054.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,800.00

Report Ref No. CS/INC19003574/Utd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.