

ASS. REC. BY:

REF: CA/FCI/19003583/Ked3n2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

5:50pm 26/2/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGC 7603R

Insured:

SHA 1258S

at Workshop m/s

City Auto

Tel:

64531235

of

Blk 8 Sin Ming Rd #01-58

Policy No:

Claim No:

D19001368 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/2/2019

CA / REV / REP. / REV 24 HRS

DS

H.O.D. Endorsement:

Date/Time: 10:58am 26/2/1

Person Contacted:

Vivian

Vehicle IN / OUT

Date/Time	Action/Instruction (—) Estimate
	SGC 7603R - CC6 / AXA 13005402 / Av / b3w2 D.O.A. 19/3/13
	SHA 1258S - CC3 / CFI 18019142 / Klwb3 D.O.A. 22/10/18
05/03/19	@ 15:04 p.m. revised PA to Eileen Lee via email
	LI by 860d Cufm

REF: FCI

ASSIGNMENT

From:

Date: 01/03/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGC 7603R

at Workshop n/s

City Auto

of Blk E - Sin Ming Ind. Est # 01-60/62

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

10am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$16K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 15 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGC 7603R Yr Regn: 01 C6

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Verna 1599

Colour:

Silver

A/C Insured / Std / NI / NA

Sp Reading:

197196

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHCN41CR64014702

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size: F:

185/65R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 24/2/18

D.O.I. 1/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/3 Kurni to take B4 part, Lun 156

(\$ 279.36 Red - 32%)

MV - \$16,000.00

LTA - \$10,322.00

NHT - \$5,673

RECEIVED 06 MAR 2019

Date/Time, File Pass to?

06/03/18

1)

Type

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech Invs (\$☐ Weekend (\$

Survey Fee:

Transportation

J. Photos

J. Others

J. TOTAL

Report Format:

Lump Sum / L.B.F. (\$) 600/- L/S

90
50
50
12

202



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001368MFSH

Date: 05 March 2019

Our Ref: CS/FCI19003583/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGC 7603R .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/03/2019 at the premises of M/s City Auto Pte Ltd, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>879.36</u> .
Revised Estimate Amount	: S\$ <u>689.36</u> .
"Check" Items Amount	: S\$ <u> </u> .
Market Value	: S\$ <u> </u> .
LTA Reimbursement Value	: S\$ <u> </u> .
Nett Value	: S\$ <u> </u> .

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 2 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	25-02-2019	Our Ref No. D19001368MFSH
Accident Date	24-02-2019	Claim Type. Third Party
Insured Vehicle	SHA1258S	Third Party Vehicle. SGC7603R
Survey Location	BLK 8 SIN MING ROAD #01-58/60/62 SIN MING IND EST	
Contact Person.	VRONICA LAW	
Contact No.	64531235/ 0	Fax No. 64537944
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CITY AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 5 March 2019 3:04 PM
To: 'Eileen Lee'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19001368MFSH/1
Attachments: SGC 7603R - Preli Advise -.pdf

Dear Eileen,

Enclosed preliminary revised of vehicle SGC 7603R.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 26 February 2019 11:02 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001368MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 25 February 2019 5:50 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001368MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0748E
Vehicle Details	
Vehicle No.:	SGC7603R
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Mar 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	VERNA 1.6M
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	G4ED5315509
Chassis No.:	KMHCHN41CR6U014702
Maximum Power Output:	82.4 kW (110 bhp)
Open Market Value:	\$11,594.00
Original Registration Date:	24 Jan 2006
First Registration Date:	24 Jan 2006
Transfer Count:	0
Actual ARF Paid:	\$12,754.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2020
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$28,416.00
COE Rebate Amount:	\$10,327.00
Total Rebate Amount:	\$10,327.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Mar 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SGC7603R
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	HYUNDAI
Vehicle Model:	VERNA 1.6M
Chassis No.:	KMHCHN41CR6U014702
Propellant:	Petrol
Engine No.:	G4ED5315509
Engine Capacity:	1599 cc
Maximum Power Output:	82.4 kW (110 bhp)
Maximum Laden Weight:	1600 kg
Unladen Weight:	1263 kg
Year Of Manufacture:	2005
Original Registration Date:	24 Jan 2006
Lifespan Expiry Date:	-
COE Category:	E - Open Category
PQP Paid:	\$28,416.00
COE Expiry Date:	31 Dec 2020
Road Tax Expiry Date:	23 Jan 2020
Inspection Due Date:	23 Jan 2020
Intended Transfer Date:	27 Feb 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201902-000419(00)

MS FIRST CAPITAL INSURANCE LTD

NO. 36

ROBINSON RD

CITY HOUSE

SINGAPORE 068877

Attention: Teo Hock Siong

Contact : 98365160

Fax No. : 65073849

Date : 25/02/2019

Vehicle No. : SGC7603R

Make/Model : HYUNDAI Verna 1.6M

Mileage (km) : 0

Chassis No. : KMHCN41CR6U014702

Accident Date : 24/02/2019 00:00:00

Claim No. : SHA1258S

Reference : SGC7603R

Policy No. : DMPG19000152

*Minor
Settle*

*NOT WORKED
11/24 & 600L
Rear Area Paint*

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Side mirror - RH	1.0	286.70	286.70
	List Total :			286.70
	20% Discount S\$			57.34
				229.36
LABOUR :				
	-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	200.00	200.00
	- Spray painting on affected & replace parts	1.0	450.00	450.00
				650.00



E. & O.E.

Total S\$: 879.36
GST 7% S\$: 61.56
Amount Due S\$: 940.92

for CITY AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003583/Ksd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-03-2019		
		Code : FC12		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1258S	Veh. Inspected	SGC 7603R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001368MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	26/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI VERNA (M)	c.c	1599	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	KMHCN41CR6U014702	Colour	SILVER	
Odometer	197196	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R14	YOKOHAMA	6 mm	
L/H Front Tyre	185/65 R14	YOKOHAMA	6 mm	
R/H Rear Tyre	185/65 R14	YOKOHAMA	6 mm	
L/H Rear Tyre	185/65 R14	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/02/2019	Inspection Date	01/03/2019	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGC 7603R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	CRACKED		
	SIDE MIRROR-RH		286.70	286.70
	LESS 20% DISCOUNT		-57.34	-57.34
			229.36	229.36
	LABOUR			
	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.		200.00	180.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		450.00	320.00
			650.00	500.00
GRAND TOTAL			879.36	729.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				600.00

Report Ref No. CS/FCI19003583/Ksd3n2

MARKET VALUE: \$16,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$10,327.00=NETT VALUE: \$5,673.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.