

ASS. REC. BY:

REF: CS/ICS19003597/RHd3

n2

Special Instruction:

Surveyor

From (Person):

Jenice Goh

ASSIGNMENT (Office)

ICS

Date/Time: 26/2/19 @ 905am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY/CS

To Inspect Vehicle No:

SLL 67811

Insured:

at Workshop n/s

Motor Image

Tel:

9073 2232/67038631

of

25 Leng Kee Road

Policy No:

Claim No:

DMPC1900054H/CT

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A. 22/02/2019

(Client's Record)

Before 12pm @ 27/2/19

CA / RPT / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:17am @ 26/2/19

Person Contacted:

Jeff

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

27/2@15:55 - Revert via. menmen

27/2@16:33 - authorise repair Crystalabelle Tan

27/2 - 4:53pm - email to motor image authorise repair excess \$500/-

Part by Part \$7657.96 (Red: 3989.08; 3470.)

Pass

REF:

41292

2019 MAY 14

Event: Date:

1. Incident Type:

☒ C / ☐ FWS / ☐ TP RES / ☐ OT RES / ☐ EVA / ☐ RV / ☐ MV

2. Insured Vehicle No: SLL 67813

3. Make-Model: Motor Image

4. Year, Length, Kms: 25, Length Kms 40

5. Insured: ECUS

6. Policy No:

7. Class No:

8. Sum Insured: Excess: 300

9. Claim's Record:

10. Make of Veh:

(Policy Condition) Jeff

Remark: The veh had commenced its repair at the time of inspection.

11. Ball or Market Value: 96k

12. BAC - Accident Report: Consented? Yes or No

13. BAC - ERT Form: Consented? Yes or No

14. Est. Repair: days: Yes Yes or No

15. Est. Sum: %: 1 Val: Yes or No

16. CA / ☒ KEV / ☐ REP / 24 HRS

17. Date: Person Contacted:

18. Date / Time: Action / Instruction:

19. Vehicle: SLL 67813 2017 motor

20. Type: ☒ Motor / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

21. Make: SUBARU Forester 2.0 XT 1998

22. Colour: BLUE APC Insured / Sp / NI / NA

23. Sp. Branding: 066206 T/Radio: Insured / Sp / NI / NA

24. Engine No:

25. Chassis: IF15J6K8564083014

26. Gen. Cond: Good ☒ Fair / ☐ Poor / ☐ Damt

27. Steering: ☒ Good / ☐ Jammed / ☐ Leaked / ☐ Burnt or

28. Brake: ☒ Good / ☐ Jammed / ☐ Leaked / ☐ Burnt or

29. Mod: Nil ☒ / ☐ STD A/Rim or

30. Tyre Size: F: 225/55 R18 R:

31. BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or HANKOOK

32. Front: 6 mm Rear: 6 mm

33. R/Bal: 6 mm L/Bal: 6 mm

34. D.O.A: 22/02/19 D.O.I: 27/02/19

35. Survey held at: MOTOR IMAGE

36. Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S

37. The U/C / Chassis frame / Body Structure affected due to collision:

RECEIVED 14 MAY 2019

38. Submission File Name:

39. 1315 typer ☐ Prel. Report ☒ Final Report

40. Submission File Path:

41. Report Format:

42. Claim Sum / LH: 7657.96

43. Days Of Repair: 5

44. Resurvey No. of Trip: 2

45. Add Fee: ☐ Sub Insp \$

☐ Interview \$

☐ Equip. Fee \$

☐ Vehicle Fee \$

46. Survey Fee:

47. Transportation:

48. 1. 5. 10. 15. 20. 25. 30. 35. 40. 45. 50. 55. 60. 65. 70. 75. 80. 85. 90. 95. 100.

49. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

50. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

51. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

52. TOTAL:

350  
10

360

**Nivitha (LKK Auto)**

---

**From:** ECICS Claims <claims@ecics.com.sg>  
**Sent:** Tuesday, 26 February 2019 9:05 AM  
**To:** Jeff Teh /MIE-LK Svc; assignments  
**Cc:** ECICS Claims; Crystabelle Tan Gek Peng (ECICS, Claims)  
**Subject:** RE: SLL6781J OD Claim  
**Attachments:** Estimate of repair.pdf; GIA Report.pdf

Hi Jeff

Thank you for your email  
We will appoint LKK for the OD survey.

Aside to LKK

Please assist to arrange for OD survey.  
Excess \$500.

This case is handled by Ms Crystabelle Tan and our claim is DMPC1900054H/CT.

Thank you.

Best regards

Janice Goh

Senior Associate | Claims



DID (65) 6303 0182

Tel (65) 6337 4779

Email [janice\\_goh@ecics.com.sg](mailto:janice_goh@ecics.com.sg) Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

---

**From:** Jeff Teh /MIE-LK Svc [mailto:t00335s@tanchong.org]  
**Sent:** Monday, 25 February 2019 9:11 PM  
**To:** ECICS Claims  
**Subject:** SLL6781J OD Claim

Dear Officer,

Kindly refer above attachment and arrange survey date.

Thanks

Best Regards,

Jeff Teh

## Service Advisor

Motor Image Enterprises Pte Ltd

25 Leng Kee Road

Singapore 159097

DID:(65)6703 8631

HP:(65)9073 2232

FAX:(65)6479 1137

Email:tengchuen@motorimage.net



**SUBARU TECNICA  
INTERNATIONAL**

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

## View Received Message

This mail is associated with :

**\*SLL6781J (DMPC1900054H/CT)**

OD

Feb 22 2019 4:00PM

[CHNG TIONG KIAT]

Motor Image Enterprises Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** ECICS Limited (HQ) (ECICS), sent on 10/05/2019 14:04 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Maintained - SLL6781J - Claim Handler: Crystabelle Tan

Maintained;Please show proof that extra costs needed for repair.

### DOCUMENTS SUMMARY

There are no documents.

## View Received Message

This mail is associated with :

**\*SLL6781J (DMPC1900054H/CT)**

OD

Feb 22 2019 4:00PM

[CHNG TIONG KIAT]

Motor Image Enterprises Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** ECICS Limited (HQ) (ECICS), sent on 27/02/2019 16:33 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$7417.48) - SLL6781J - Claim Handler: Crystabelle Tan

Approved:7417.48.

### DOCUMENTS SUMMARY

There are no documents.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 27 February 2019 4:53 PM  
**To:** 'shawnychua@tanchong.com'; 'dennisleong@motorimage.net';  
'davidkoh@motorimage.net'; 'fadzlee@motorimage.net'  
**Cc:** SUR  
**Subject:** SLL 6781J / OD / ECICS

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLL 6781J (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                       |
|-------------------------------------|---------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                       |
| Owner ID Type:                      | Singapore NRIC                        |
| Owner ID:                           | 4129I                                 |
| <b>Vehicle Details</b>              |                                       |
| Vehicle No.:                        | SLL6781J                              |
| Vehicle to be Exported:             | No                                    |
| Intended Deregistration Date:       | 27 Feb 2019                           |
| Vehicle Make:                       | SUBARU                                |
| Vehicle Model:                      | FORESTER 2.0XT CVT AWD SR             |
| Primary Colour:                     | Blue                                  |
| Manufacturing Year:                 | 2016                                  |
| Engine No.:                         | FA20B901485                           |
| Chassis No.:                        | JF15JGK85GG083014                     |
| Maximum Power Output:               | 177.0 kW (237 bhp)                    |
| Open Market Value:                  | \$19,237.00                           |
| Original Registration Date:         | 06 Mar 2017                           |
| First Registration Date:            | 06 Mar 2017                           |
| Transfer Count:                     | 0                                     |
| Actual ARF Paid:                    | \$19,237.00                           |
| <b>Intended PARF Rebate Details</b> |                                       |
| PARF Eligibility:                   | Yes                                   |
| PARF Eligibility Expiry Date:       | 05 Mar 2027                           |
| PARF Rebate Amount:                 | \$14,427.00                           |
| <b>Intended COE Rebate Details</b>  |                                       |
| COE Expiry Date:                    | 05 Mar 2027                           |
| COE Category:                       | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years):                  | 10                                    |
| QP Paid:                            | \$50,621.00                           |
| COE Rebate Amount:                  | \$40,579.00                           |
| <b>Total Rebate Amount:</b>         | <b>\$55,006.00</b>                    |

The information contained herein is correct as at 27 Feb 2019

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                    |
|----------------------------|--------------------|
| Date Of Report             | 25/02/2019 13:28   |
| Date Of Accident           | 22/02/2019 16:20   |
| Exact Location Of Accident | TELOK BLANGAH ROAD |
| Country/State of Loss      | SINGAPORE          |

### DETAILS OF OWN VEHICLE

|                             |                       |
|-----------------------------|-----------------------|
| Vehicle Registration Number | SLL6781J              |
| <b>Insured/Policyholder</b> |                       |
| Name Of Registered Owner    | CHNG TIONG KIAT       |
| NRIC No                     | S7014129I             |
| Email Address               | RAISTLINC@HOTMAIL.COM |
| Mobile Phone No             | (LOCAL) +65-98534415  |
| Alternative Phone No        | OFFICE-98534415       |

### Vehicle Particulars

|              |                     |
|--------------|---------------------|
| Manufacturer | SUBARU              |
| Model        | FORESTER-2.0 XT (A) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

|                  |             |
|------------------|-------------|
| Vehicle Category | PRIVATE CAR |
|------------------|-------------|

### Insurance Company

|                           |                |
|---------------------------|----------------|
| Name of Insurance Company | ECICS LIMITED  |
| Type Of Coverage          | COMPREHENSIVE  |
| Fleet Policy              | NO             |
| Policy Number             | MPC18B00024500 |
| Cover Note Number         |                |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | CHNG TIONG KIAT       |
| NRIC No              | S7014129I             |
| Date Of Birth        | 26/04/1970            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 01/02/1990            |
| Driving Experience   | 29 YEARS AND 0 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-98534415  |
| Fax Number           |                       |
| Contact Number       | OFFICE-98534415       |
| EMail Address        | RAISTLINC@HOTMAIL.COM |

|   |                                   |
|---|-----------------------------------|
| Address   | 624 BUKIT BATOK CENTRAL # 04- 660 |
| Postcode  | 650624                            |
| Was driver an employee of the Insured's Company     | NO                                |
| If No, Relationship of the Driver with the Insured  | OWNER                             |
| Vehicle Registration Number of Driver's Own Vehicle | -                                 |
|   | -                                 |
|   | -                                 |
| Insurance Company of Driver's Own Vehicle           | -                                 |
|   | -                                 |
|   | -                                 |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|   |     |
|---|-----|
| Was any foreign vehicle involved in this accident?  | NO  |
| Number of vehicles (including own vehicle) involved in the accident                         | 2   |
| Was any body injured in the Accident?   | NO  |
| Was any injured conveyed to hospital by ambulance?  |     |
| Was any other material or property damaged?   | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)   | 1   |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER TO SKETCH PLAN.

#### Attachment(s)

|   |             |
|---|-------------|
| Are accident photos available for attachment? | YES         |
| Was there any video captured by Car Camera?   | YES         |
| Remarks/ Reasons:                             | WITH DRIVER |
| Was there any audio recorded?                 | NO          |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |               |
|-------------------------------------|---------------|
| Vehicle Registration Number         | SGD3873Z      |
| Vehicle Make/Model/Colour           | HONDA/CIVIC   |
| Details Of Properties               |               |
| Vehicle Category                    | PRIVATE HIRE  |
| Name of Driver                      | TAN NEE KEONG |
| NRIC/Passport Number                |               |
| Contact Number                      |               |
| Address                             |               |
| Postcode                            |               |
| Insurance Company Name              |               |
| Nature Of Damage                    |               |
| No. Of Passenger (Including Driver) |               |

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**3. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

25/02/19



Driver's Signature

(If driver is not the policyholder)

Date & Time:

25/02/19



Reporting Centre Person's Signature

Name:

NRIC/FIN No.:


Please note that you might be able to submit an Own Damage Claim under own policy within 14 days.

( ) Claim Own Damage ( ) Claim TP ( ) Reporting Only ☒ Claim OD/TP at other workshop

Workshop Name: Motoring Singapore



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/02/2019 was traveling along Telok Blangah Road

Vehicle was stopped at traffic light just along Seah Im Car Park.

When Green light appear Drive off from stationing position but vehicle in front (SGD 38732) was slow to move off. Vehicle hit the back of SGD 38732.

No other vehicle was involved. No one was injured in accident.

## DECLARATION


I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

25/02/19



Driver's Signature

(If driver is not the policyholder)

Date & Time:

25/02/19

  
Reporting Centre Officer's Signature

Name

NRIC/FIN No.:



MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO :  
REFERENCE : INS/IC/LH1/015/2019  
DATE : 25-FEB-2019

ECICS LIMITED  
10 EUNOS ROAD B  
#09-04A SINGAPORE POST CENTER  
S(408600)  
TEL : 6337 4779  
FAX : 6338 9267

OWNER'S NAME : CHNG TIONG KIAT  
ADDRESS : APT BLK 624 BUKIT BATOK CENTRAL  
#04-660  
S(650624)  
TELEPHONE NO : 9853 4475

TYPE OF CLAIM : COMPREHENSIVE CLAIM  
POLICY NO : MPC18800024500  
VEHICLE NO : SLL6781J  
MODEL CODE : SJG0KK9  
MODEL/YEAR : FORESTER 2.0XT AWD CVT  
ENGINE NO : FA20B901485  
CHASSIS NO : JF1SJGKB5GG0B3014  
MILEAGE : 1 KM  
DATE IN : 25/02/2019  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : JEFF TEH TENG CHUEN  
ACCIDENT DATE : 25/02/2019

Print Date : 25/02/2019  
Print Time : 21:01:27

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLL6781J

|                            |                                       | DAMAGED PARTS & PRICES |         |      |        |                |
|----------------------------|---------------------------------------|------------------------|---------|------|--------|----------------|
| S/NO                       | PARTS DESCRIPTION                     | PARTS NUMBER           | NETT    | LIST | S/NETT | S/LIST REMARKS |
| 1                          | RAD PNL COMPL RH USR ?                | 53029SG0309P           | 45.00   | X    | 17     |                |
| 2                          | HOOD F CPL repair dent ✓              | 57229SG0009P           | 882.00  | ✓    |        |                |
| 3                          | BRKT CORNER F RH ? xmc                | 57707SG000             | 36.00   | X    | ✓      |                |
| 4                          | BRKT CORNER F LH ? xmc                | 57707SG010             | 36.00   | X    | 800    |                |
| 5                          | BUMPER FACE F (FOR HL/W) DE ✓         | 57709SG011             | 594.00  | ✓    |        |                |
| 6                          | BACK BEAM CPL F ? bt ✓                | 57711SG0009P           | 288.00  | ✓    |        |                |
| 7                          | ENERGY ABSOR F ? de ✓                 | 57722SG020             | 126.00  | ✓    |        |                |
| 8                          | COVER HOOK F SP X de ✓                | 57731SG070             | 5.40    | ✓    |        |                |
| 9                          | COVER FOG F SP RH X mis ✓             | 57731SG080             | 43.20   | ✓    |        |                |
| 10                         | COVER SD F SP RH X mis ✓              | 57731SG120             | 12.60   | ✓    |        |                |
| 11                         | LAMP ASSY HEAD EOF (SUPP) cam ? cha ✓ | 84002SG220             | 2380.00 | ✓    |        |                |
| 12                         | LAMP ASSY HEAD EOF ? RA ✓             | 84002SG230             | 2380.00 | ✓    |        |                |
| 13                         | GRILLE ASSY F UPRHG ? Xsuc            | 91121SG210             | 140.40  | X    |        |                |
| 14                         | GRILLE ASSY F CTRHG DE ✓              | 91121SG240             | 180.00  | ✓    |        |                |
| 15                         | GRILLE ASSY F LWRHG ? Xsuc            | 91121SG280             | 316.80  | X    |        |                |
| 16                         | ORNAMENT F ? xmc                      | 93013SG050             | 68.40   | X    |        |                |
| SUB TOTAL                  |                                       |                        | 7533.80 | 0.00 | 0.00   | 0.00           |
| LESS DISCOUNT ( NETT-20 %) |                                       |                        | 1506.76 | 0.00 | 0.00   | 0.00           |
| GRAND TOTAL                |                                       |                        | 6027.04 | 0.00 | 0.00   | 0.00           |
| OVERALL TOTAL              |                                       |                        | 6027.04 |      |        |                |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLL6781J

| S/NO | JOB CODE | NATURE OF JOB  | ESTIMATED CHARGES  | SURVEYOR'S RECOMMENDATION |
|------|----------|--|--------------------|---------------------------|
| 1    | ZZ/001   | TO REPAIR AND REPLACE FRONT BUMPER, FRONT BUMPER ENERGY ABSORBER AND FRONT BUMPER BEAM | <del>3120.00</del> | 1120 ✓                    |
| 2    | ZZ/002   | TO RESPRAY FRONT BONNET, FRONT BUMPER AND FRONT BUMPER BEAM                            | <del>2200.00</del> | 880 ✓                     |
| 3    | ZZ/003   | TO CONDUCT LIGHTING SYSTEM TEST  | <del>150.00</del>  | 80 ✓                      |
| 4    | ZZ/004   | SUNDRIES   | <del>150.00</del>  | 20 ✓                      |
|      |          |  | rec                |                           |
|      |          | TOTAL LABOUR CHARGES   | 5620.00            |                           |

5 22/005 ~~To supply and replace Front~~  
number plate with casing ✓ 45.00 TA ✓

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLL67B1J

|                           |            |
|---------------------------|------------|
| TOTAL LABOUR CHARGES      | 5620.00    |
| TOTAL SPARE PARTS CHARGES | 6027.04    |
| GRAND TOTAL               | 11647.04 * |

*[Signature]*  
28/2/19

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

|                 |   |  |                      |
|-----------------|---|--|----------------------|
| NAME            | : | Rasul - Hp 90010068                          | (if supplementary ?) |
| SURVEYED DATE   | : | 27/2/19 @ 1050                               |                      |
| AUTHORIZED DATE | : |  |                      |
| EXCESS CLAUSE   | : | 0.00   | 5 days               |
| LIABILITY       | : | 0.00   |                      |
| REMARKS         | : | Excess: 500<br>Rusul<br>Resurvey before part |                      |

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



ENTERPRISES PTE. LTD.

FREE ROAD

159097

ATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLL6781J

| S/NO                 | JOB CODE | NATURE OF JOB  | ESTIMATED          | SURVEYOR'S     |
|----------------------|----------|--|--------------------|----------------|
|                      |          |  | CHARGES            | RECOMMENDATION |
| 1                    | ZZ/001   | TO REPAIR AND REPLACE FRONT BUMPER, FRONT BUMPER ENERGY ABSORBER AND FRONT BUMPER BEAM | <del>3120.00</del> | 1120           |
| 2                    | ZZ/002   | TO RESPRAY FRONT BONNET, FRONT BUMPER AND FRONT BUMPER BEAM                            | <del>2200.00</del> | 880            |
| 3                    | ZZ/003   | TO CONDUCT LIGHTING SYSTEM TEST  | <del>150.00</del>  | 80             |
| 4                    | ZZ/004   | SUNDRIES   | <del>150.00</del>  | 20             |
| TOTAL LABOUR CHARGES |          |  | 5620.00            | 5000           |

5 22/005 To supply and replace Front  
number plate with casing

45.00 PA ✓

ENTERPRISES PTE. LTD.  
 1 ROAD  
 159097

LIST FOR ACCIDENT VEHICLE REGN NO SLL67B1J

DAMAGED PARTS & PRICES

| PARTS DESCRIPTION                        | PARTS NUMBER | DAMAGED PARTS & PRICES |           |        |
|--|--------------|------------------------|-----------|--------|
|  |              | NETT                   | LIST      | S/NETT |
| 1 RAD PNL COMPL RH USR ?                 | 53029SG0309P | 45.00                  |           |        |
| 2 HOOD F CPL <i>repair</i>               | 57229SG0009P | 882.00                 | <i>FE</i> |        |
| 3 BRKT CORNER F RH ?                     | 57707SG000   | 36.00                  |           |        |
| 4 BRKT CORNER F LH ?                     | 57707SG010   | 36.00                  |           |        |
| 5 BUMPER FACE F (FOR HL/W) <i>DE</i>     | 57709SG011   | 594.00                 |           |        |
| 6 BACK BEAM CPL F ?                      | 57711SG0009P | 288.00                 |           |        |
| 7 ENERGY ABSOR F ?                       | 57722SG020   | 126.00                 |           |        |
| 8 COVER HOOK F SP <i>X</i>               | 57731SG070   | 5.40                   |           |        |
| 9 COVER FOG F SP RH <i>X</i>             | 57731SG080   | 43.20                  |           |        |
| 10 COVER SD F SP RH <i>X</i>             | 57731SG120   | 12.60                  |           |        |
| 11 LAMP ASSY HEAD EOF (SUPP) <i>can?</i> | 84002SG220   | 2380.00                |           |        |
| 12 LAMP ASSY HEAD EOF <i>2RA</i>         | 84002SG230   | 2380.00                |           |        |
| 13 GRILLE ASSY F UPRHG ?                 | 91121SG210   | 140.40                 |           |        |
| 14 GRILLE ASSY F CTRHG <i>DE</i>         | 91121SG240   | 180.00                 |           |        |
| 15 GRILLE ASSY F LWRHG ?                 | 91121SG280   | 316.80                 |           |        |
| 16 ORNAMENT F ?                          | 93013SG050   | 68.40                  |           |        |
| SUB TOTAL                                |              | 7533.80                | 0.00      | 0.0    |
| LESS DISCOUNT ( NETT-20 %)               |              | 1506.76                | 0.00      | 0.0    |
| GRAND TOTAL                              |              | 6027.04                | 0.00      | 0.0    |
| OVERALL TOTAL                            |              |                        |           |        |

ENTERPRISES PTE. LTD.  
FREE ROAD  
159097

OF ESTIMATE FOR VEHICLE REGN NO SLL6781J

|                     |            |
|---------------------|------------|
| LABOUR CHARGES      | 5620.00    |
| SPARE PARTS CHARGES | 6027.04    |
| GRAND TOTAL         | 11647.04 * |

\* All charges do not include GST.

INSURER'S PARTICULARS

NAME  
INSURED DATE  
AUTHORIZED DATE  
CESS CLAUSE  
ABILITY  
MARKS

: Rasul - Hp 90000068 (if supplementary)  
: 27/02/19 @ 1050

: 0.00  
: 0.00

5 days

EXCESS: 500

REVERT

Resurvey before paint

NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO :  
REFERENCE : INS/IC/LHI/015/2019  
DATE : 25-FEB-2019

ECICS LIMITED  
10 EUNOS ROAD 8  
#09-04A SINGAPORE POST CENTER  
S(408600)  
TEL : 6337 4779  
FAX : 6338 9267

OWNER'S NAME : CHNG TIONG KIAT  
ADDRESS : APT BLK 624 BUKIT BATOK CENTRAL  
#04-660  
S(650624)  
TELEPHONE NO : 9853 4475

TYPE OF CLAIM : COMPREHENSIVE CLAIM  
POLICY NO : MPC18800024500  
VEHICLE NO : SLL67B1J  
MODEL CODE : SJGDKK8  
MODEL/YEAR : FORESTER 2.0XT AWD CVT  
ENGINE NO : FA20B901485  
CHASSIS NO : JF1SJK85GG083014  
MILEAGE : 1 KM  
DATE IN : 25/02/2019  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : JEFF TEH TENG CHUEN  
ACCIDENT DATE : 25/02/2019

Print Date : 17/04/2019  
Print Time : 18:30:40

MOTORIMAGE ENTERPRISES PTE. LTD.  
25, LENG KEE ROAD  
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLL6781J

| S/NO                       | PARTS DESCRIPTION         | PARTS NUMBER | DAMAGED PARTS & PRICES |      |        |        | REMARKS |
|----------------------------|---------------------------|--------------|------------------------|------|--------|--------|---------|
|                            |                           |              | NETT                   | LIST | S/NETT | S/LIST |         |
| 1                          | RAD PNL COMPL RH USR      | 53029SG0309P | 45.00                  |      |        |        | X       |
| 2                          | HOOD F CPL                | 57229SG0009P | 882.00                 |      |        |        | OK      |
| 3                          | BRKT CORNER F RH          | 57707SG000   | 36.00                  |      |        |        | X       |
| 4                          | BRKT CORNER F LH          | 57707SG010   | 36.00                  |      |        |        | X       |
| 5                          | BUMPER FACE F (FOR HL/W)  | 57709SG011   | 594.00                 |      |        |        | OK      |
| 6                          | BACK BEAM CPL F           | 57711SG0009P | 288.00                 |      |        |        | OK      |
| 7                          | ENERGY ABSOR F            | 57722SG020   | 126.00                 |      |        |        | OK      |
| 8                          | COVER HOOK F SP           | 57731SG070   | 5.40                   |      |        |        | OK      |
| 9                          | COVER FOG F SP RH         | 57731SG080   | 43.20                  |      |        |        | OK      |
| 10                         | COVER SD F SP RH          | 57731SG120   | 12.60                  |      |        |        | OK      |
| 11                         | LAMP ASSY HEAD EOF (SUPP) | 84002SG220   | 2380.00                |      |        |        | OK      |
| 12                         | LAMP ASSY HEAD EOF        | 84002SG230   | 2380.00                |      |        |        | OK      |
| 13                         | GRILLE ASSY F UPRHG       | 91121SG210   | 140.40                 |      |        |        | X       |
| 14                         | GRILLE ASSY F CTRHG       | 91121SG240   | 180.00                 |      |        |        | OK      |
| 15                         | GRILLE ASSY F LWRHG       | 91121SG280   | 316.80                 |      |        |        | X       |
| 16                         | ORNAMENT F                | 93013SG050   | 68.40                  |      |        |        | X       |
| SUB TOTAL                  |                           |              | 6891.20                | 0.00 | 0.00   | 0.00   |         |
| LESS DISCOUNT ( NETT-20 %) |                           |              | 1378.24                | 0.00 | 0.00   | 0.00   |         |
| GRAND TOTAL                |                           |              | 5512.96                | 0.00 | 0.00   | 0.00   |         |
| OVERALL TOTAL              |                           |              | 5512.96                |      |        |        |         |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.  
25-LENG KEE ROAD  
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLL6781J

| S/NO JOB CODE        | NATURE OF JOB  | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|----------------------|--|-------------------|---------------------------|
| 1 ZZ/001             | TO REPAIR AND REPLACE FRONT BUMPER, FRONT BUMPER ENERGY ABSORBER AND FRONT BUMPER BEAM | 3120.00           | 1120.00                   |
| 2 ZZ/002             | TO RESPRAY FRONT BONNET, FRONT BUMPER AND FRONT BUMPER BEAM                            | 2200.00           | 880.00                    |
| 3 ZZ/003             | TO CONDUCT LIGHTING SYSTEM TEST  | 150.00            | 80.00                     |
| 4 ZZ/004             | SUNDRIES   | 150.00            | 20.00                     |
| 5 ZZ/005             | TO SUPPLY AND REPALCE FRONT NUMBER PLATE WITH CASING                                   | 45.00             | 45.00                     |
| TOTAL LABOUR CHARGES |  | 5665.00           | 2145.00                   |

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLL6781J

---

|             |          |
|-------------|----------|
| NETT ITEM   | 6891.20  |
| LESS 20 %   | -1378.24 |
| NETT AMOUNT | 5512.96  |

|             |      |
|-------------|------|
| LIST ITEM   | 0.00 |
| LESS 50 %   | 0.00 |
| LIST AMOUNT | 0.00 |

|                     |      |
|---------------------|------|
| SPECIAL NETT AMOUNT | 0.00 |
|---------------------|------|

|               |      |
|---------------|------|
| S/LIST ITEM   | 0.00 |
| LESS 30 %     | 0.00 |
| S/LIST AMOUNT | 0.00 |

|                           |         |
|---------------------------|---------|
| TOTAL LABOUR CHARGES      | 2145.00 |
| TOTAL SPARE PARTS CHARGES | 5512.96 |

|               |         |
|---------------|---------|
| TOTAL CHARGES | 7657.96 |
| ADD 7 % GST   | 536.06  |

|             |         |
|-------------|---------|
| GRAND TOTAL | 8194.02 |
|-------------|---------|

---

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited  
10 Eunos Road 8, #09-04A Singapore Post Centre  
Singapore 408600

Our File No: CS/ICS19003597/R1TD3N2

Date: 22/05/2019

## REFERENCE

Insured/Claimant: CHNG TIONG KIAT Policy No: MPC18B00024500  
Date of Loss: 22/02/2019 Nature of Claim: OD Claim No: DMPC1900054H/CT

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLL6781J  
Make & Model: SUBARU FORESTER, 2.0 XT (A) Engine No: FA20B901485  
Reg. Date: 06/03/2017 (Man. Year: 2016) Chassis No: JF1SJGK85GG083014  
Colour: Blue Odometer: 66206 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: S\$96,000.00  
Price:  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/55R18 Rear Tyre Size: 225/55R18  
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm  
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                      | Repairer's       | Adjuster's      | Difference      | Diff %       |
|-------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                               | 6,222.04         | 5,577.96        | 644.08          | 10.35        |
| Miscellaneous Items                 | 0.00             | 0.00            | 0.00            |              |
| Labour                              | 5,470.00         | 2,080.00        | 3,390.00        | 61.97        |
| Paintwork Labour                    | 0.00             | 0.00            | 0.00            |              |
| Towing                              | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b> | <b>11,692.04</b> | <b>7,657.96</b> | <b>4,034.08</b> | <b>34.50</b> |
| <b>- Excess (S\$)</b>               | <b>500.00</b>    | <b>500.00</b>   | <b>0.00</b>     | <b>0.00</b>  |
| <b>(S\$)</b>                        | <b>11,192.04</b> | <b>7,157.96</b> | <b>4,034.08</b> | <b>36.04</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>       | <b>783.44</b>    | <b>501.06</b>   | <b>282.38</b>   | <b>36.04</b> |
| <b>Nett Amount (S\$)</b>            | <b>11,975.48</b> | <b>7,659.02</b> | <b>4,316.46</b> | <b>36.04</b> |

## INSPECTION

Date of Assignment: 26/02/2019  
Date Inspected: 27/02/2019 Inspected At:

Motor Image Enterprises Pte Ltd (Leng Kee)  
25 Leng Kee Road  
Singapore 159097

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

|                      |  |  |
|----------------------|--|--|
| <b>Reference</b>     |  |  |
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 21 May 2019)                |
| <b>Parts:</b>        | M1-SUV   | SUBARU FORESTER 2.0 XT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                            |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLL6781J)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

## Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *RAD PNL COMPL RH USR           | Not Necessary | 45.00 FN    | *- FN        |
| 2   | 1   |          | *HOOD F CPL                     | Dented        | 882.00 FN   | *882.00 FN   |
| 3   | 1   |          | *BRKT CORNER F RH               | Serviceable   | 36.00 FN    | *- FN        |
| 4   | 1   |          | *BRKT CORNER F LH               | Serviceable   | 36.00 FN    | *- FN        |
| 5   | 1   |          | *BUMPER FACE F (FOR HL/W)       | Deformed      | 594.00 FN   | *594.00 FN   |
| 6   | 1   |          | *BACK BEAM CPL F                | Bent          | 288.00 FN   | *288.00 FN   |
| 7   | 1   |          | *ENERGY ABSOR F                 | Deformed      | 126.00 FN   | *126.00 FN   |
| 8   | 1   |          | *COVER HOOK F SP                | Deformed      | 5.40 FN     | *5.40 FN     |
| 9   | 1   |          | *COVER FOG F SP RH              | Missing       | 43.20 FN    | *43.20 FN    |
| 10  | 1   |          | *COVER SD F SP RH               | Missing       | 12.60 FN    | *12.60 FN    |
| 11  | 1   |          | *LAMP ASSY HEAD EOF (SUPP)      | Cracked       | 2,380.00 FN | *2,380.00 FN |
| 12  | 1   |          | *LAMP ASSY HEAD EOF             | Cracked       | 2,380.00 FN | *2,380.00 FN |
| 13  | 1   |          | *GRILLE ASSY F UPRHG            | Serviceable   | 140.40 FN   | *- FN        |
| 14  | 1   |          | *GRILLE ASSY F CTRHG            | Deformed      | 180.00 FN   | *180.00 FN   |
| 15  | 1   |          | *GRILLE ASSY F LWRHG            | Serviceable   | 316.80 FN   | *- FN        |
| 16  | 1   |          | *ORNAMENT F                     | Not Necessary | 68.40 FN    | *- FN        |
| 17  | 1   |          | *FRONT NUMBER PLATE WITH CASING | Bent          | 45.00 FS    | *45.00 FS    |
| 18  | 1   |          | *SUNDRIES                       | Necessary     | 150.00 FS   | *20.00 FS    |

F=Franchise part, S=SpcNett, N=NettItemDisc.

|   |                 |                 |
|---|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                    | <b>7,728.80</b> | <b>6,956.20</b> |
| <b>- Nett Item Discount on N Items 20.00/20.00% (S\$)</b> | <b>1,506.76</b> | <b>1,378.24</b> |
| <b>Total Parts (S\$)</b>                                  | <b>6,222.04</b> | <b>5,577.96</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars   | Lab.Type | Repairer's | Amount   |
|-------------------------|---|----------|------------|----------|
| <u>Labour Items</u>     |   |          |            |          |
| 1                       | TO REPAIR AND REPLACE FRONT BUMPER,FRONT BUMPER ENERGY ABSORBER AND FRONT BUMPER BEAM | New      | 3,120.00   | 1,120.00 |
| 2                       | TO RESPRAY FRONT BONNET,FRONT BUMPER AND FRONT BUMPER BEAM                            | New      | 2,200.00   | 880.00   |
| 3                       | TO CONDUCT LIGHTING SYSTEM TEST   | New      | 150.00     | 80.00    |
| Gross Labour Cost (S\$) |   |          | 5,470.00   | 2,080.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >