

ASS. REC. BY

REP

CS3/ALG19003601/Acd302

Special Instruction

SMV Ver. 01

Munich

From (Person):

Adnan

ASSIGNMENT (Office)

Chin lee Ying

of

ALG

Date/Time 26/2/19 @ 12:44pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 3338C

Insured:

SJJ 5705X

at Workshop m/s

Paul Hor Batteries

Tel:

9623 5068

of

1 Kalki Pkt Ave 6 # 01-109

Policy No:

1800103493

Claim No:

294824835086

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/02/2019

CA / REV / REP. / REV 24 HRS

H.O.B. Endorsement:

Date/Time:

12:44pm @ 26/2/19

Person Contacted:

paul

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SJU 3338C - NA / INC 19003521 / 24

DOA: 23/2/19

SJJ 5705X - NA / INC 19003521 / 24

DOA: 23/2/19

Dismantle: 26/2/2019

After repair: 4/3/2019

Adrian

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

STU3338C

Yr Regn:

2009 / August

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Vios

c.c 1497

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

211102

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRO53HY9305126393

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

185/60R15

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Sincera

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

26/02/19

Survey held at

Paul Hoe

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AIG PRS.

MV: 14K

PV: 7.2K

Nett: 6.8K

RECEIVED 25 MAR 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

190

S + RS, SI

Photos

Others

TOTAL

10

190

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 26/2/2019 12:44:30 PM
Attachments:  tmpF108.tif

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

ARASAN LAW CHAMBERS
ADVOCATES & SOLICITORS
UEN NO. 53229182D

151 Chin Swee Road
#06-08 Manhattan House
Singapore 169876
Tel: 68353350
Fax: 68353352
E-mail: mariah@alc.com.sg

You Ref : SJJ 5705X

Our ref : ALC.2019.147.APW.dk

25 February 2019

IMMEDIATE ATTENTION

AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#07-16 AIG Building
Singapore 079120

WITHOUT PREJUDICE
By Fax Only: 6835 7416

Attn: Manager/Motor Claims Department

Dear Sirs,

NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASE

We refer to the above matter.

We act for **Mr. Ang Peng Whatt**, the driver of motor vehicle **SJU 3338C** who has appointed us to act on his behalf to claim against your insured's vehicle no. **SJJ 5705X** in regards to the road traffic accident on 23.02.19.

Please be informed that the said motor vehicle can be inspected at:-

PAUL HOE BATTERIES & MOTOR SERVICES
1 Kaki Bukit Avenue 6
#01-109
Singapore 417883

Kindly contact **Mr Paul or Ms Pauline** at Tel: (+65) 9623 5068 or 6741 9686

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



M/S ARASAN LAW CHAMBERS

Cc Pauline Fax: 6747 6918

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9323Z
Vehicle Details	
Vehicle No.:	SJU3338C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	1NZX952247
Chassis No.:	MR053HY9305126393
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,717.00
Original Registration Date:	08 Sep 2009
First Registration Date:	08 Sep 2009
Transfer Count:	4
Actual ARF Paid:	\$12,717.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Sep 2019
PARF Rebate Amount:	\$6,358.00
Intended COE Rebate Details	
COE Expiry Date:	07 Sep 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,019.00
COE Rebate Amount:	\$800.00
Total Rebate Amount:	\$7,158.00

The information contained herein is correct as at 26 Feb 2019

OK

6303

Wide selection of Inchcape Certified Pre-owned LEXUS & TOYOTA

2019

Interest Rate 1.98% till 31 Jan 2019

Extended Warranty 1yr

Free Tyre & Service Credits up to \$3,000

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Jaguar XE 2.0.

In Built Car Camera.
Direct Owner - StarAd

AutoInn
An Inspiration For Car Buyers

click here to view our **PRISTINE USED CARS** at **GREAT PRICES**

Browse by Category Save Search Print « Back (1 2 3 4) Next » Sort by Date Posted 20 results/page

69 vehicles **Search** Vios Advanced Search Search View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	Vios	Any	Any	2009	Any	Any	Any	Available
------------------	------	-----	-----	------	-----	-----	-----	-----------



☐ **Toyota Vios 1.5A E (New 5-yr COE)** \$28,800 \$5,760 /yr 18-May-2009 1,497 cc - Sedan Available

1 Single Owner! Brand New Paintwork! Beautiful Black Interior! Most Popular Mid Size Japanese Car In The Market! Low Fuel Consumption/Maintenance And Most Importantly Low Monthly Instalment With High ...

Car (S) Pte Ltd

★ Posted: 19-Feb-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

PREMIUM AD



☐ **Toyota Vios 1.5A G (New 5-yr COE)** \$27,800 \$5,560 /yr 11-Jun-2009 1,497 cc - Sedan Available

★ Posted: 25-Feb-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



☐ **Toyota Vios 1.5A E (New 5-yr COE)** \$26,888 \$5,370 /yr 19-Jun-2009 1,497 cc 130,000 km Sedan Available

Car In Very Good Condition, No Repairs Needed, 100% Accident Free, View Or Test Drive To Believe. Call Now

Cycle & Carriage.Fulco Motor Dealer

★ Posted: 21-Feb-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



☐ **Toyota Vios 1.5A E Sports (New 5-yr COE)** \$27,500 \$5,500 /yr 02-Jul-2009 1,497 cc 86,000 km Sedan Available

No Gimmicks, Honest Dealing, Low Mileage Clock, Car In Good Condition, Loan Available, 100% Approval. Trade In Welcome, Bank Loan Available. Call Us For An Appointment At Our Showroom Today.

★ Posted: 22-Feb-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ **Toyota Vios 1.5A E** \$14,800 N.A 14-Jul-2009 1,497 cc 103,339 km Sedan Available

Purchase From An Award Winning Dealership! Accident Free Quality Pre-Owned With Low Mileage Done For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing Options. View Today!

Cosmo Automobiles

★ Posted: 22-Feb-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



☐ **Toyota Vios 1.5A G Sports (New 5-yr COE)** \$26,800 \$5,360 /yr 13-Aug-2009 1,497 cc 97,000 km Sedan Available

100% Loan Available. Very Well Maintained, With All Wear And Tear Parts Recently Replaced. Fuel Economy Car Suitable For Daily Usage, Act Now Before It's Gone

1axis

★ Posted: 23-Feb-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

SHORTLISTED HISTORY

Compare

☐ **Toyota Vios 1.5A E** \$14,500 \$15,720 /yr 04-Sep-2009 1,497 cc 125,000 km Sedan Available

New Alternator Fan Belt, Water Pump And Coolant Replaced Recently For Smoother Drive. Extremely Well Maintain But Previous Owner. Smooth

DIRECT OWNER



Engine And Gearbox Transmission. Easy To Drive And Fuel Saving ...



Posted: 18-Feb-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (OPC)
(New 5-yr COE)

\$26,999

\$5,400 /yr

15-Sep-2009

1,497 cc

138,000 km

Sedan

Available

New Arrival! Sporty Blue In Black Toyota Vios 1.5E Auto Model. Reliable, Very Well Maintained By Careful Owner. Owner Upgrade To New Car. Stable Good Road Holding And Best Fuel Saving. 100% Accident F...



Posted: 12-Jan-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A G

\$15,800

\$12,390 /yr

11-Nov-2009

1,497 cc

-

Sedan

Available

Selling At \$30800 With 5 Years Coe. Monthly Instalment At \$225 For 5 Years. Low Fuel Consumption, Low Maintenance Cost, Very Well Maintained, GST Included, Good For COE Renewal. Easy Loan Application....

Car (S) Pte Ltd



Posted: 21-Feb-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

PREMIUM AD

Save this search criteria, to get email alerts whenever a match is found.



Save Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view [Expired ads](#)

« Back (1 2 3 4) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Vios, Vios Singapore, used Vios Singapore, used Vios, used vehicles Singapore or even buy used Vios Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)



Download on the
App Store



GET IT ON
Google play

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SHORTLISTED HISTORY

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/02/2019 14:30
Date Of Accident	23/02/2019 10:05
Exact Location Of Accident	CTE (AYE)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJU3338C
Insured/Policyholder	
Name Of Registered Owner	ANG PENG WHATT
NRIC No	S0149323Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98589001
Alternative Phone No	OFFICE-98589001
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS E AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102613093
Cover Note Number	
Driver	
Name of Driver	ANG PENG WHATT
NRIC No	S0149323Z
Date Of Birth	10/11/1950
Occupation	OUTDOOR
Date Of Driving Pass	16/12/2011
Driving Experience	7 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98589001
Fax Number	
Contact Number	OFFICE-98589001
Email Address	NOEMAIL

Address	BLK 107 TOWNER ROAD #11-378
Postcode	321107
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	EUNOS NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4439999 - FAX NO: 62444376
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190225/2097.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ5705X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MS TAN
NRIC/Passport Number	
Contact Number	81189850

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name

ANG PENG WHATT

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SJU3338C

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report - 1/10/190225/2077.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

(1) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(7) Deformed (8) Shifted (9) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repaired (3) Check (✓)
(4) Not Consistent (✓)

Rear Portion

Vehicle No: **SS43338C**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	Dis	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEL	✓	
1147	992976	Rear Bumper Bracket	Best	✓	02
1148	993068	Rear Bumper Side Retainer	NEL	✓	02
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	Crackd	✓	02
1157	993023	Rear Bumper Lower Spoiler	Dis	✓	
1158	994023	Reverse Sensor	Damage	✓	
1159	993327	Rear End Panel	Dis	✓	
1160	993339	Rear End Panel Top Garnish	Dis	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	Crackd	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	Crackd	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	Dis	✓	
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	Crackd	✓	
1171	991328	Bootlid Emblem	NEL	✓	02
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	Dis	✓	
1178	990377	Bootlid Rubber	Dis	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board	Torn	✓	
1203	994328	Spare Tyre Panel			Repair
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw	Spooage	Dis	✓ 02
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			Repair
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			Repair
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	Crackd	✓	Repair
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim	NEL	✓	
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding	NEL	✓	
1247	993955	Rear Windscreen Sealant	NEL	✓	
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

10 Days
25/03/19
H/S

No of Items: _____ Assessor: _____



































...CLAIM SUBFOLDER...(Pending for Survey Report)

































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Feb 2019 Edit Reg		26 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case






































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN ANG CHI (CHEN ANQI) , Co. Reg. No.: -								
Main Claimant:	ANG PENG WHATT								
Vehicle Reg. No.:	SJU3338C	Date of Loss:	23/02/2019 00:00 - :59 [113 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2948248350SG	Policy/Cover Note No.:	1800103493 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJJ5705X	Policy No. (Claimant):							
		Excess:							
Repairer:	Paul Hoe Batteries & Motor Services (HQ) 1 KAKI BUKIT AVE 6 #01-109, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (27/02/2019): TP GIA report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJU3338C (2948248350SG)**
[SJJ5705X]
TP
ANG PENG WHATT
Feb 23 2019 12:00AM
[TAN ANG CHI (CHEN ANQI)]
Paul Hoe Batteries & Motor Services

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images												3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print
1	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
3	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
4	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
5	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
6	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
7	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
8	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
9	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
10	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
11	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
12	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
13	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
14	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
15	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
16	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
17	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
18	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
19	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
20	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
21	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
22	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
23	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
24	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
25	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
26	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
27	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
28	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
29	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
30	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
31	25/03/19 13:36	General View											Load JPG	<input checked="" type="checkbox"/>
32	25/03/19 13:37	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
33	25/03/19 13:37	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
34	25/03/19 13:37	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
35	25/03/19 13:37	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
36	25/03/19 13:37	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
37	25/03/19 13:37	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	25/03/19 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	25/03/19 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/02/19 16:29	OI GIA REPORT	 Load PDF	
2	08/03/19 11:51	TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19003601/ACD3E2

Date: 04/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1800103493

Claimant Vehicle No : SJU3338C

Insured Vehicle No : SJJ5705X

Date of Loss: 23/02/2019

Nature of Claim: TP

Claim No: 2948248350SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU3338C

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZX952247

Reg. Date: 08/09/2009 (Man. Year: 2009)

Chassis No: MR053HY9305126393

Colour: Red

Odometer: 211102 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: Sincera 6 mm

Rear Left Side:

Sincera 6 mm

Front Right Side: Sincera 6 mm

Rear Right Side:

Sincera 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/02/2019

Date Inspected: 26/02/2019 Inspected At:

Paul Hoe Batteries & Motor Services (HQ)
1 KAKI BUKIT AVE 6 #01-109
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER BRACKET	Bent	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
5	2		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
6	1		*REAR BUMPER LOWER SPOILER	Distorted	0.00 F	*- F
7	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
8	1		*REAR END PANEL	Damaged	0.00 F	*- F
9	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
10	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
11	1		*REAR LH TAILLAMP PANEL	Repair	0.00 F	*- F
12	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
13	1		*REAR RH TAILLAMP PANEL	Dented	0.00 F	*- F
14	1		*BOOTLID	Distorted	0.00 F	*- F
15	2		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
16	1		*BOOTLID LOCK	Damaged	0.00 F	*- F
17	1		*BOOTLID RUBBER	Cut	0.00 F	*- F
18	1		*SPARE TYRE BOARD	Torn	0.00 F	*- F
19	2		*SPARE TYRE SPONGE	Deformed	0.00 F	*- F
20	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
21	1		*REAR LH FENDER	Repair	0.00 F	*- F
22	1		*REAR RH FENDER	Buckled	0.00 F	*- F
23	1		*REAR RH FENDER INNER TRIM	Necessary	0.00 F	*- F
24	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
25	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
26	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >