

ASS. REC. BY

REF CS3/AIG19003615/ECd322

Special Instruction

Surveyor

Steve

ASSIGNMENT (Office)

From (Person)

menimh chinlee Ying

of

AIG

Date/Time

26/2/14 @ 11.36 am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SJV 5826S

Insured:

SKL582T

at Workshop m/s

Ego Automobile

Tel:

9176 5733

of

13 Kaki Bkt Rd 4 #03-29

Policy No.

2100498871

Claim No.

684750854388

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/2/14

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12.36pm @ 26/2/14

Person Contacted:

Mr. A/fie

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SJV 5826S - X

SKL582T-CS/AXA14010652/Rlgbk3

AVA: 5/6/14

Dismantle: 27/2/2014

Steve

REF:

ASSIGNMENT

From
Estimated Cost
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

at Workshop m/s

of

Insured

Policy No

Claims No

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X	X
N/S	O/S
X	X
X	X

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: **STV 58265** Yt Regn: **29/1/10**
Type: **M. Car** / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: **KIA Cerato** C.C. **1.6**
Colour: **Blue** A/C Insured / Std / NI / NA
Sp. Reading: **173002** T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: **KMA FW 411 MA 5122 015**
Gen. Cond: Good / **Fair** / Poor / Burnt
Steering: **In order** / Jammed / Leaked / Burnt or
Brake: **In order** / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: **205/45 R17**
R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **Continental**

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.I.

24/2/19

D.O.I.

26/2/19

Survey held at

ECO Automobile

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

LH Side

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV - 15,000

PV - 8,766

NV - 6234

RECEIVED 21 MAR 2019

Date/Time, File Pass to?

☐

: Proli. Report

4)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

180

Transportation

) S + R + SI

) Photos

) Other

) ..

TOTAL

10

190

Report Format:

DAR

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 26/2/2019 11:36:47 AM
Attachments:  20190225140613008.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : SJV 5826S (Jr)

Your Ref : To be advised

25 February 2019

AIG ASIA PACIFIC INSURANCE PTE LTD

BY EMAIL

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : FALCON ALLIANCE INTERNATIONAL PTE LTD
ACCIDENT INVOLVING SJV 5826S & SKL 582T ALONG PENANG ROAD ON
24 FEBRUARY 2019
PRE-REPAIR SURVEY NOTICE

1. We act for Falcon Alliance International Pte Ltd, the owner of motor vehicle no. SJV 5826S which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SKL 582T for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	ECO Automobile Claims and Repair Pte Ltd
Address	13 Kaki Bukit Road 4 #03 - 29 Bartley Biz Centre Singapore 417807
Contact Person	Mr. Alfie (9176 5733)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5213R
Vehicle Details	
Vehicle No.:	SJV5826S
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE 1.6 AT SX ABS D/AB 2WD 4DR
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	G4FC9H290458
Chassis No.:	KNAFW411MA5122015
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$13,753.00
Original Registration Date:	29 Jan 2010
First Registration Date:	29 Jan 2010
Transfer Count:	2
Actual ARF Paid:	\$13,753.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2020
PARF Rebate Amount:	\$6,876.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jan 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,879.00
COE Rebate Amount:	\$1,890.00
Total Rebate Amount:	\$8,766.00

The information contained herein is correct as at 26 Feb 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resour



Enjoy rates from **3.7% p.a. (EIR 7% p.a.)**
plus **S\$88 Cash Back.**

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A



2.38%P.A Low Interest@Gv
Finance. \$0 Admin Fees. \$3800
Downpayment Monthly \$738
GV Credit Pte Ltd StarAd



click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category ▼

« Back (1 2) Next »

Sort by Date Posted ▼

20 results/page

31 vehicles

Kia Cerato

Advanced Search



	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Kia Cerato		Any	Any	2010	Any	Any	Any	Availabl
	Kia Cerato Forte 1.6A SX		\$16,300	\$8,890 /yr	05-Mar-2010	1,591 cc	-	Sedan	Availabl
Mature Enthusiast Owner. New Lower Arms, Bushing, Absorbers, Mountings Etc. Zero Engine Oil Leak With Very Comfortable Suspension. No Funny Noise. Leather Seats Are Very New With Strong Leather Smell ...									
Posted: 26-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia									
	Kia Cerato Forte 1.6A SX		\$16,800	\$8,260 /yr	29-Apr-2010	1,591 cc	145,000 km	Sedan	Availabl
In House Finance Available! Rare 1 Owner, Premium SX Model With Keyless Start/Go! Factory Fitted Folding Side Mirrors And Chrome Door Handles. Well Maintained, Low Mileage Done, 16k Km Yearly! Comes W...									
Speedo Motoring									
Posted: 26-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia									
	Kia Cerato Forte 1.6A SX (New 5-yr COE)		\$31,800	\$6,360 /yr	26-Feb-2010	1,591 cc	106,000 km	Sedan	Availabl
100% Loan Available, Keyless Entry, Very Well Maintained, With All Wear And Tear Parts Recently Replaced. Fuel Economy Car Suitable For Daily Usage, Act Now Before It's Gone.									
1axis									
Posted: 26-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia									
	Kia Cerato Forte 1.6A EX (OPC)		\$16,388	\$6,870 /yr	28-Sep-2010	1,591 cc	92,425 km	Sedan	Availabl
(100% Showroom Condition!) Buy With Confidence From CaseTrust Accredited Dealer. Purchase Comes With 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assistance Coverage. STA/VICOM/AA Eva...									
Sincere Motoring									
Posted: 26-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia									
<div>GET YOUR COE RENEWAL LOAN</div>									
Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.									
	Kia Cerato Forte Koup 1.6A SX		\$16,700	\$8,950 /yr	22-Feb-2010	1,591 cc	-	Sports	Availabl
Sunroof Model! Road Tax Til Aug 2019! Owned By Lady Teacher Owner! High OMV! Minimum PARF Takeback Of \$7,877 When COE Expires! Excellent Condition! Battery Changed In Aug 2018! Do Call Now To Arrange...									
Posted: 26-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia									

Compare



Kia Cerato Forte Koup 2.0M SX **\$19,800** **\$8,750 /yr** **28-Jul-2010** **1,998 cc** **104,000 km** **Sports** **Availabl**

Posted: 25-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato Forte Koup 2.0M SX (OPC) **\$17,888** **\$7,290 /yr** **30-Jul-2010** **1,998 cc** **142,797 km** **Sports** **Availabl**

Exclusive 2.0L Koup! 1st Owner Unit. Normal Plate Available For Sales At \$20,888! Purchase Comes With 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assitance. STA/VICOM/AA Evaluation ...

PREMIUM

Sincere Motoring

Posted: 25-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato Forte 1.6A SX **\$18,000** **\$9,940 /yr** **31-Mar-2010** **1,591 cc** **107,000 km** **Sedan** **Availabl**

1.6L 4 Cylinders 16 Valves DOHC Engine, Responsive Auto Transmission Gearbox, ABS, Auto Climatic Aircon Control, Steering Audio Control, Fog Lights.

DIRECT OWN

Posted: 24-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato Forte Koup 1.6A SX **\$18,888** **\$9,300 /yr** **13-May-2010** **1,591 cc** **139,753 km** **Sports** **Availabl**

100% Quality Buy! Vehicle Fully Done Up In Showroom Condition With Premium Grooming And Brand New Paint Coat. Purchase Comes With 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assitan...

PREMIUM

Sincere Motoring

Posted: 24-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato Forte Koup 1.6A SX **\$21,200** **\$8,670 /yr** **28-Sep-2010** **1,591 cc** **-** **Sports** **Availabl**

Sporty Lime Green Forte Koup 1.6A Of Superb Condition, See To Certify! Low Mileage Clocked Of 19200km Annually. No Repairs Needed. Fussy Owner. 100% Accident Free. Price Slightly Negotiable. Call Now!

PREMIUM

Lake View Credit Pte Ltd

Posted: 24-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Personalise Your Ride Now!

Differentiate from others and create a personal ride identity with customised stickers, car wraps and designed car plates. List of the best aesthetic specialists available. Each with merchant information and user reviews to help you make the best decision.

Find out more!



Kia Cerato Forte Koup 1.6M SX **\$14,800** **\$9,090 /yr** **06-Jan-2010** **1,591 cc** **-** **Sports** **Availabl**

Elegant White, With Sunroof, One Owner Only, Very Well Maintained, Flexible In-House Loan Packages Available.

Prime Motor & Leasing

Posted: 23-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato Forte 1.6A SX **\$18,998** **\$8,820 /yr** **29-Jun-2010** **1,591 cc** **-** **Sedan** **Availabl**

Be Our Next Happy Client To Owned This Quality Pre-Owned Vehicle At Most Reasonable And Affordable Price! Selling Cheap! Very Well Maintained Exterior! Clean Upholstery! Flexible Bank/In House Loan Av...

Posted: 23-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato Forte 2.0A SX **\$20,800** **\$8,450 /yr** **30-Jul-2010** **1,998 cc** **-** **Sedan** **Availabl**

Low Interest Rate. 1 Year Warranty. Balloon Scheme, In-house Financing Options Available. Buy With A Peace Of Mind. 1 Owner. 100% Genuine Mileage. Well Maintained. No Chassis/ Structural Damage. Immac...

PREMIUM

GOWheeler Pte Ltd

Posted: 23-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia



Kia Cerato Forte Koup 1.6M SX **\$24,000** **\$10,660 /yr** **13-Oct-2010** **1,591 cc** **119,000 km** **Sports** **Availabl**

A Perfect Daily Driver's Car For Daily Usage! Proper Tuning And Upgrades Done For Optimum Drivability. This Unit Comes With More Than 10k Worth Of Upgrades For Both Interior And Exterior! 100% Acciden...

PREMIUM

Posted: 23-Feb-2019 Tags: 2010 Kia Cerato, 2010 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

[Compare](#)

Kia Cerato Forte Koup 1.6A SX **\$17,888** **\$8,910 /yr** **15-Apr-2010** **1,591 cc** **159,000 km** **Sports** **Availabl**

SUNROOF UNIT! Well Maintained! Interior And Exterior In Great Condition. Call For More Details.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2019 15:12
Date Of Accident	24/02/2019 19:50
Exact Location Of Accident	ALONG PENANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV5826S
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	FALCON ALLIANCE INTERNATIONAL PTE. LTD.
Co Reg No	200605213R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84889225
Alternative Phone No	OFFICE-84889225

Vehicle Particulars

Manufacturer	KIA
Model	CERATO FORTE 1.6 AT SX ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106922502
Cover Note Number	

Driver

Name of Driver	MUHAMMAD BUKHARI BIN ABDUL RAHMAN
NRIC No	S7521883D
Date Of Birth	18/07/1975
Occupation	OUTDOOR
Date Of Driving Pass	11/09/2001
Driving Experience	17 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87545721
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 176 BOON LAY DRIVE #04-350
Postcode	640176
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKL582T
Vehicle Make/Model/Colour	VOLKSWAGEN GOLF A7 1.4 TSI AT BMT 5G14JZ SR HID
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4

Reporting Centre Singapore
Name: Singapore 415933
Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vackb@singnet.com.sg

The diagram illustrates a road intersection. A horizontal road at the bottom is labeled "Penang Road". A diagonal road at the top right is labeled "Baying Road". Four vertical dashed lines with upward-pointing arrows represent lanes on Penang Road. Two vehicles are shown in the third lane from the left: Vehicle A is a rectangle, and Vehicle B is a diamond. Both have arrows pointing towards the intersection. To the right of the intersection, two dashed curved lines indicate the path for vehicles turning right onto Baying Road. Text on the right side of the diagram lists the vehicle details:

- Vehicle A: SJV5826S
- Vehicle B: SKL582T

On 24/2/19 at about 1955hrs, I was travelling along Penang Road when vehicle B, SKL582T, suddenly cut into my lane and bang into my vehicle, while he was trying to turn on to Bueping Road. I was in the right of way.

NYCE declare the foregoing particulars are true in every respect.



Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Reporting Centre **Singapore 415933**
 Name: **Tel: 67416697**
 NRIC/FIN No.: **Fax: 67492305**
Email: vackb@singnet.com.sg

STV58265

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DD	✓	
1005	992341	Frt Bumper Clips	MEC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	BR	✓	2
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover	CUT	✓	
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp	BR	✓	
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	BR	✓	
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990131	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991711	Front Exhaust Pipe			
1067	990219	Battery			
1068	990214	Battery Cover			

Front LH Door
Rear LH Door
Rear LH Fender

Vehicle No. _____

NAC	INC	Item	CON	AC	Qty
1071	992205	Purge Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	RT	✓	
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim	CUT	✓	2
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Ft. Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

R
R
R

Condition (CON)
 (1) Bent (2) Deformed (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (7) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (UC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
 (4) Not Consistent (NC)

SV58265

Vehicle No:

Undercarriage

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber		?	
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring		?	
1375	995198	Frt LH Knuckle Arm		?	
1376	995199	Frt LH Knuckle Arm Bearing		?	
1377	995178	Frt LH Lower Arm			
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1404	990534	Centre Exhaust Pipe Assy			
1405	990532	Centre Exhaust Mounting			
1406	991134	Floor Panel			
1407	993719	Rear LH Shock Absorber			
1408	993723	Rear LH Shock Absorber Mounting			
1409	993170	Rear LH Coil Spring			
1410	993550	Rear LH Knuckle Arm			
1411	993551	Rear LH Knuckle Arm Bearing			
1412	993597	Rear LH Lower Arm			
1413	993884	Rear LH Upper Arm			
1414	995161	Rear LH Drive Shaft			
1415	995216	Rear LH Control Arm			
1416	993881	Rear LH Trailing Arm			
1417	993573	Rear LH Leaf Spring			
1418	992941	Rear LH Brake Disc Rotor			
1419	992937	Rear LH Brake Caliper Assy			
1420	990434	Rear LH Brake Pipe			
1421	992946	Rear LH Brake Hose			
1422	993819	Rear Sub Frame			
1423	993820	Rear Sub Frame Mounting			
1424	992813	Rear Anti Roll Bar			
1425	990168	Rear Anti Roll Bar Linkage			
1426	990202	Axle Beam			
1427	990170	Rear Axle Panhard Rod			
1428	990810	Differential Assy			
1429	992706	Propeller Shaft			

20/3/2019

NAC	INC	Item	CON	AC	Qty
1428	991935	Frt RH Shock Absorber			
1429	991944	Frt RH Shock Absorber Mounting			
1430	990632	Frt RH Coil Spring			
1431	991844	Frt RH Knuckle Arm			
1432	991845	Frt RH Knuckle Arm Bearing			
1433	991851	Frt RH Lower Arm			
1434	992064	Frt RH Upper Arm			
1435	992040	Frt RH Tie Rod			
1436	991692	Frt RH Drive Shaft			
1437	990661	Frt RH Control Arm			
1438	992062	Frt RH Trailing Arm			
1439	991848	Frt RH Leaf Spring			
1440	991293	Frt RH Brake Disc Rotor			
1441	991281	Frt RH Brake Caliper			
1442	991292	Frt RH Brake Pipe			
1443	991287	Frt RH Brake Hose			
1444	991295	Frt RH Brake Sensor Wire			
1445	993720	Rear RH Shock Absorber			
1446	993723	Rear RH Shock Absorber Mounting			
1447	993173	Rear RH Coil Spring			
1448	993550	Rear RH Knuckle Arm			
1449	993551	Rear RH Knuckle Arm Bearing			
1450	993601	Rear RH Lower Arm			
1451	993885	Rear RH Upper Arm			
1452	993322	Rear RH Drive Shaft			
1453	993178	Rear RH Control Arm			
1454	995117	Rear RH Trailing Arm			
1455	995110	Rear RH Leaf Spring			
1456	992942	Rear RH Brake Disc Rotor			
1457	992938	Rear RH Brake Caliper Assy			
1458	990434	Rear RH Brake Pipe			
1459	992947	Rear RH Brake Hose			

No of Items:

Assessor:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Feb 2019 Edit Reg		26 Feb 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Phey Khee Teik Augustine Benedict (Peng Qide Augustine Benedict) , ID: S7512994G									
Main Claimant: -									
Vehicle Reg. No.: SJV5826S		Date of Loss: 24/02/2019 00:00 - :59 [108 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6847508543SG		Policy/Cover Note No.: 2100498871 (Comprehensive)							
Vehicle Reg. No. (Insured): SKL582T		Policy No. (Claimant):							
		Excess:							
Repairer: Eco Automobile Claims And Repair Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #03-29, 417807 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 07/03/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (27/02/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents






























***SJV5826S (6847508543SG)**
[SKL582T]

















































TP


-

Feb 24 2019 12:00AM

[Phey Khee Teik Augustine Benedict (Peng Qide Augustine Benedict)]
Eco Automobile Claims And Repair Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images										3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print		
1	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
2	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
3	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
4	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
5	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
6	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
7	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
8	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
9	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
10	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
11	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
12	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
13	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
14	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
15	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
16	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
17	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
18	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
19	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
20	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
21	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
22	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
23	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
24	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
25	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
26	27/02/19 08:57	Odometer Reading								 Load JPG	<input checked="" type="checkbox"/>		
27	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
28	27/02/19 08:57	General View								 Load JPG	<input checked="" type="checkbox"/>		
29	27/02/19 08:57	Chassis Number								 Load JPG	<input checked="" type="checkbox"/>		
30	27/02/19 08:57	General View								Load JPG	<input checked="" type="checkbox"/>		
31	27/02/19 08:57	General View								Load JPG	<input checked="" type="checkbox"/>		
32	27/02/19 08:57	General View								Load JPG	<input checked="" type="checkbox"/>		
33	27/02/19 08:57	General View								Load JPG	<input checked="" type="checkbox"/>		
34	27/02/19 08:57	General View								Load JPG	<input checked="" type="checkbox"/>		
35	27/02/19 08:57	General View								Load JPG	<input checked="" type="checkbox"/>		
36	27/02/19 08:57	General View								Load JPG	<input checked="" type="checkbox"/>		
37	27/02/19 08:57	General View								Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
39	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
40	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
41	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
42	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
43	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
44	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
45	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
46	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
47	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
48	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
49	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
50	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
51	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
52	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
53	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
54	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
55	27/02/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
56	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	20/03/19 18:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	27/02/19 09:27	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19003615/ECD3E2

Date: 22/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100498871
Claimant Vehicle No : SJV5826S **Insured Vehicle No :** SKL582T
 Date of Loss: 24/02/2019 Nature of Claim: TP Claim No: 6847508543SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV5826S**
 Make & Model: KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A) Engine No: G4FC9H290458
 Reg. Date: 29/01/2010 (Man. Year: 2009) Chassis No: KNAFW411MA5122015
 Colour: Blue Odometer: 173002 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17
 Front Left Side: Continental 7 mm Rear Left Side: Continental 7 mm
 Front Right Side: Continental 7 mm Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/02/2019
 Date Inspected: 26/02/2019 Inspected At: Eco Automobile Claims And Repair Pte Ltd (HQ)
 13 KAKI BUKIT ROAD 4, #03-29
 Singapore 417807
 Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*FRT LH BUMPER FOG LAMP COVER	Cut	0.00 F	*- F
5	1		*FRT LH BUMPER FOG LAMP	Broken	0.00 F	*- F
6	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
7	1		*FRT LH FENDER	Bent	0.00 F	*- F
8	2		*FRT LH WHEEL RIM	Cut	0.00 F	*- F
9	1		*FRT LH DOOR	Repair	0.00 F	*- F
10	1		*REAR LH DOOR	Repair	0.00 F	*- F
11	1		*REAR LH FENDER	Repair	0.00 F	*- F
12	1		*FRT LH SHOCK ABSORBER	* Check	0.00 F	*- F
13	1		*FRT LH KNUCKLE ARM	* Check	0.00 F	*- F
14	1		*FRT LH KNUCKLE ARM BEARING	* Check	0.00 F	*- F
15	1		*FRT LH LOWER ARM	* Check	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >